



11815 NE 99th Street, Suite 1294
Vancouver, WA 98662
Voice: 360-574-3058
Fax: 360-576-0925
Web: <https://www.swcleanair.gov>
Email: Tina@swcleanair.gov

Notice of Intent to Remove Asbestos

Case #: 24-097

Amendment: 0

Date Received: 2/15/2024

Date Paid: 2/15/2024

SWCAA Fee: \$369.00

Receipt #: 151219444

This notification MUST be present at all times at the asbestos project sit

Quantity to be removed: 750 Square Feet 0 Linear Feet

Workshift days: M T Th F

Project starting date: 2/29/2024 Project Completion date: 3/5/2024

Workshift hours: 7:00am - 3:30pm

Site Name: Office 2	Site address: 1892 Wind River Hwy
Location of Asbestos: Ceiling 1st floor	City/State/Zip: Carson WA 98610
<input type="checkbox"/> Demolition of Structure (Notification of Demolition required)	County: SKAMANIA COUNTY

☒ Asbestos survey conducted?

No survey reason:

AHERA Inspector: Dalton LaFever

Certification #: IR-23-0908C

Material to be Removed:

- | | | | | | |
|---|--|-----------------------------------|--------------------------------------|--|------------------------------------|
| <input type="checkbox"/> Fireproofing | <input type="checkbox"/> Popcorn Ceiling | <input type="checkbox"/> CAB | <input type="checkbox"/> Sheet Vinyl | <input type="checkbox"/> Boiler Insulation | <input type="checkbox"/> Duct Tape |
| <input type="checkbox"/> Duct Paper | <input type="checkbox"/> Mag Pipe Insulation | <input type="checkbox"/> Air Cell | <input type="checkbox"/> CA Pipe | <input type="checkbox"/> VAT | |
| <input checked="" type="checkbox"/> Other Brocade Ceiling | | | | | |

Control Methods:

- | | | | | | |
|---|------------------------------------|---|---------------------------------------|---|--|
| <input checked="" type="checkbox"/> N.P Enclosure | <input type="checkbox"/> Glove Bag | <input type="checkbox"/> Mini Enclosure | <input type="checkbox"/> Wrap and Cut | <input checked="" type="checkbox"/> Water | <input checked="" type="checkbox"/> HEPA Vac |
| <input checked="" type="checkbox"/> Other Regulated Work Area | | | | | |

Asbestos Contractor: Performance Abatement Services

Phone: 360-574-8400

Mailing Address: 13600 NE 10th Ave, Vancouver, WA, 98685

Email:

Certification ##: ABCN00001016

Supervisor: Francisco Tejeda Martinez

Phone: 360-562-3505

Property Owner: WKO Inc - Paul Anderson

Phone: 541-490-2787

Mailing Address: 2022 Wind River Hwy, Carson WA 98610

Asbestos Disposal Site: Wasco County Landfill: 2550 Steele Rd, The Dalles, OR, 97058-

**I DO HEREBY CERTIFY THAT THE INFORMATION CONTAINED IN THIS NOTIFICATION IS,
TO THE BEST OF MY KNOWLEDGE, ACCURATE AND COMPLETE.**

Submitter Name: Hunter Morrison

Representing: Performance Abatement Servi

Submitter Title: Senior Project Engineer

Date Submitted: 2/15/2024

Reviewed by SWCAA: Brian Fallon

☒ Approved



11815 NE 99th Street, Suite 1294
Vancouver, WA 98662
Voice: 360-574-3058
Fax: 360-576-0925
Web: <https://www.swcleanair.gov>
Email: Tina@swcleanair.gov

Notice of Intent to Remove Asbestos

Case #: 24-097

Amendment: 0

Date Received: 2/15/2024


Date Paid: 2/15/2024

SWCAA Fee: \$369.00

Receipt #: 151219444

This notification MUST be present at all times at the asbestos project sit

Asbestos Survey Report



Presented To: WKO Inc.

Survey Location: 2022 Wind River Hwy, Carson, WA 98610 Office #2

Inspection Date: January 11th, 2024

Prepared by:

**Dalton Lafever
Of
Atlas Labs Inc.
Environmental Testing Services
CCB #: 231684**

1.0 EXECUTIVE SUMMARY

2.0 GENERAL INFORMATION

2.1 Project Information

2.2 Procedures

2.2.1 Plan and Specification Review

2.2.2 Walk Through and Visual Survey

2.2.3 Bulk Sampling

2.2.4 Analyses of Bulk Samples

3.0 CONTROLLING

3.1 Removal and Disposal

3.2 Encapsulation

3.3 Enclosure

3.4 Repair

3.5 Operations and Maintenance Programs

4.0 Material Quantifications

4.1 Homogenous Materials/Areas

5.0 Qualifications of the Report

APPENDICES

APPENDIX A - Laboratory Results of Suspect Asbestos Bulk Sample Analyses

APPENDIX B - Suspect Asbestos Containing Material Sample Locations/Drawings

APPENDIX C - EPA / AHERA Building Inspector Certification

Building/Structure Information

Owner/Operator Name:

WKO Inc.

Owner/Operator Number:

(541) 490-2787

Survey Date:

January 9th, 2024

What is the building's description?

Commercial Office

What is this structure's current use?

Commercial

What is this structure's past use?

Residential

Building Square Footage:

UNK

Number of Floors:

2

Area Surveyed:

Entire Building

Approximate Build Date:

UNK

1.0 EXECUTIVE SUMMARY

Atlas Labs Inc. has performed this work to aid in the demolition of the commercial office located at 2022 Wind River Hwy, Carson, WA 98610 - Office #2. This survey included visual observation, materials sampling and laboratory analyses of materials suspected of containing asbestos. The locations of the suspect materials are noted and documented in this report.

A total of twenty-nine (29) sample sets, thirty-nine (39) total samples were taken during this survey; laboratory procedure will be the separation of multiple layered samples and analysis of individual layers. Twenty-nine (29) material sample sets were collected and delivered to Atlas Labs Inc. Atlas laboratories divided these samples into ninety-five (95) separate layers for individual analysis. The samples of suspect asbestos containing materials included: drywall, texture, joint compound, skim coat, vinyl, mastic, vapor barrier, carpet, carpet pad, mortar, tile, sink undercoat, wall panel, formica, insulation, window glaze, window sealant, VCT, siding, shingle & tar paper.

Of the thirty-nine (39) asbestos samples taken, three (3) of the suspect materials contained asbestos in quantities greater than 1% by weight, the asbestos containing materials are listed in section 4.0 - **Asbestos containing materials were identified during this inspection. (skim coat, texture & VCT)**

Removal, encapsulation, enclosure, and an Operations and Maintenance (O&M) Program are all recognized alternatives for controlling asbestos containing materials in buildings. Federal OSHA and EPA regulations require removal of most asbestos containing materials from a building prior to demolition or before any planned renovation activities, which may disturb asbestos containing materials. Federal OSHA and EPA regulations require proper handling of lead containing materials in construction. Proper handling of these materials depends greatly on the activities that will impact them.

Atlas Labs Inc. recommends that all asbestos-containing materials identified during this survey that may be affected by the work be removed by a licensed asbestos abatement contractor operating under a technical specification.

2.0 GENERAL INFORMATION

2.1 PROJECT INFORMATION

The structure is part of the WKO INC property located at 2022 Wind River Hwy, Carson, WA 98610 Office #2, the office building has its own address of 1892 Wind River HWY, Carson, WA 98610. The structure is a two level commercial building that was previously a residential house. construction is of standard stick frame with interior walls of drywall. Roofing consists of shingles over tar paper.

2.2 PROCEDURES

The services provided in this phase of work included a visual survey of the building, material sampling, laboratory analysis for the presence of asbestos. The following sections discuss the general procedures employed for each of these tasks.

2.2.1 Plan and Specification Review

A survey to locate asbestos-containing materials is best served by a review of building plans and specifications to determine the type of construction used and the materials specified. No building plans and specifications were provided for review.

2.2.2 Walk Through and Visual Survey

The asbestos identification program began with a walk-through and visual survey of the building. The survey included observation of wall and ceiling finishes, various flooring materials, piping, structural building components, and above-ceiling areas. The primary purpose of the visual survey was to locate and identify friable and non-friable asbestos materials and devise a sampling strategy. "Friable" materials are those that can be crumbled by hand pressure, releasing fibers into the air.

2.2.3 Bulk Sampling

The next phase of the survey was the selection of sampling areas and collection of bulk samples. Material sampling areas were grouped based on material homogeneity. A homogeneous area is one which contains material that seems by texture, color and surface wear to be uniform and applied during the same general time period. To refute the presumption that materials installed prior to 1982 contain asbestos, multiple samples of similar suspect materials were collected to meet the requirements of EPA and OSHA regulations.

Samples were collected from accessible, representative construction materials, which were suspected to contain asbestos. Suspect materials observed and sampled included: drywall, texture, joint compound, skim coat, vinyl, mastic, vapor barrier, carpet, carpet pad, mortar, tile, sink undercoat, wall panel, formica, insulation, window glaze, window sealant, VCT, siding, shingle & tar paper.

Samples were labeled, and appropriate chain-of-custody documentation was completed. The samples were sent to Atlas Laboratories in Vancouver, WA for analysis.

2.2.4 Analyses of Bulk Samples

Asbestos samples were analyzed using Polarized Light Microscopy (PLM) coupled with dispersion staining in general accordance with the Environmental Protection Agency's (EPA) "Method for the Determination of Asbestos in Bulk Building Materials" (EPA/600/R-93/116, July 1993).

Polarized Light Microscopy is the only analytical method presently used to identify asbestos that employs the optical crystallographic properties of the various crystalline forms in the samples. These properties: refractive indices, birefringence, sign of elongation, and extinction angle, are unique to the individual crystalline forms and

therefore is used to identify the different asbestos mineral types: Chrysotile, Amosite, Crocidolite, Anthophyllite, Tremolite, and Actinolite.

The current NESHAP regulations (40 CFR Part 61, dated November 20, 1990) clarify the analytical procedures for determining the percentage of asbestos in bulk samples and permit the use of visual area estimation. The regulations further indicate the regulated asbestos-containing materials (RACM) – materials that are friable or may become friable, may be further analyzed by point counting when the results indicate less than 10 percent asbestos by visual area estimation. The laboratory utilizes visual area estimation on a routine basis and does not include point counting unless specifically requested.

3.0 ALTERNATIVES FOR CONTROLLING ACM

There are five industry-recognized alternative procedures to control exposure to asbestos-containing materials: (1) removal and disposal; (2) encapsulation; (3) enclosure; (4) repair; and (5) an operations and maintenance (O&M) program. The selection of a particular alternative should be based on the intended usage of the facility, on the condition and location of the asbestos-containing material, and on business considerations.

Atlas Labs Inc. understands that the plan for demolition of this structure is to remove all known asbestos containing materials that are present. Air monitoring and clearance sampling should be done throughout this project to ensure compliance with regulatory requirements and worker safety. Regardless of the alternative chosen, all asbestos-related mitigation activities should be conducted under properly controlled conditions by specially trained personnel. Asbestos removal should be performed by a licensed asbestos abatement contractor operating under the guidelines of strict specifications. All asbestos-containing materials, even when removed in the course of maintenance activities, must be properly disposed of as asbestos containing waste in accordance with all state and federal regulations regarding abatement, transportation and disposal of asbestos containing materials.

3.1 REMOVAL AND DISPOSAL

Removal of the asbestos-containing material is the only permanent solution to the problem posed by exposure to asbestos fibers. Removal should be seriously considered when the material is extremely friable, badly damaged or when the material is readily accessible to people or staff. The EPA also requires removal before demolition of a facility or before renovation activities, which may disturb the asbestos-containing material. The Occupational Safety and Health Administration (OSHA) have specific requirements addressing the removal of asbestos-containing materials.

3.2 ENCAPSULATION

Encapsulation of asbestos-containing material is a temporary measure designed to reduce fiber emissions from the material. This alternative is recommended when the asbestos-containing material is in stable, relatively undamaged condition and presents little exposure potential. Encapsulation is considered a temporary measure because the

asbestos-containing material still exists in the facility and care must always be taken to avoid disturbing it. The presence and location of the material should be documented and periodic inspections of the encapsulated areas should be made to ensure that no deterioration or damage has occurred.

3.3 ENCLOSURE

Enclosure requires surrounding the asbestos-containing material with an airtight seal or barrier to prevent any fibers released by the material from reaching facility occupants. This method is practical when asbestos-containing materials are difficult, if not impossible, to remove or encapsulate. Again, the location of the materials should be documented, periodic inspections performed, and a record keeping system implemented.

3.4 REPAIR

Repair of asbestos-containing materials is a temporary measure designed to minimize local fiber emissions from the material. Typically, repair is utilized for minimally damaged Thermal System Insulation (TSI) and wall and ceiling materials. Repair should only be used if the repair is technologically feasible and human health and the environment can be protected. Repair is also considered a temporary measure because the asbestos-containing material still remains in the building.

3.5 OPERATIONS AND MAINTENANCE PROGRAM

An Operations and Maintenance (O&M) Program is established to monitor the condition of the asbestos-containing materials and promote safe work practices within the facility. The O&M Program should include notification of the building occupants and workers of the presence and locations of the asbestos-containing materials, training of maintenance personnel in proper cleaning and maintenance procedures, periodic air monitoring in affected areas, and regularly scheduled re-inspections of the asbestos-containing materials. Proper records documenting these efforts must also be maintained.

These recommendations are further elaborated by the EPA in “Managing Asbestos In-Place – A Building Owner’s Guide to Operations and Maintenance Programs for Asbestos-Containing Materials (EPA 20T-2003, July, 1990).

The Occupational Safety and Health Administration (OSHA) regulation 29 CFR 1926.1101 took effect October 1, 1995. This regulation requires building owners/employers to either identify asbestos-containing material by surveying and bulk sampling, or by treating certain building materials as “Presumed Asbestos-Containing Materials (PACM)”. Specifically, all thermal system insulation (TSI) and surfacing materials in buildings constructed prior to 1980 should be considered PACM and resilient flooring materials installed prior to 1980 should be assumed ACM. The presence of ACM or PACM requires the owner/employer to notify employees of the presence, provide training, and follow certain procedures when employees come in contact with such materials.

4.0 QUANTIFICATION TABLE

The following table indicates the approximate quantity of asbestos containing material identified at the Site.

Sample #	Location	Asbestos Containing Material	Asbestos % & Asbestiform	Approx. Sq. Footage	Friable Y/N	Condition
2-A Layer 4	Entryway Ceiling	Skim Coat (Blue)	3% Chrysotile	750'	Y	Good
2-C Layer 3	Conference Room Ceiling	2nd Layer Texture (Tan)	3% Chrysotile	—	Y	Good
27-A Layer 1	Conference Room Exterior Floor	VCT (Grey)	2% Chrysotile	11'	Y	Good

4.1 Homogenous Materials/Areas

The following table indicates the Homogeneous Materials/Areas.

Sample Set #	Material	Rooms/Areas
1	Drywall	First Office Wall
2	Drywall	First Office Ceiling & Back Office Ceiling

5.0 QUALIFICATIONS OF THE REPORT

Atlas Labs Inc. has endeavored to investigate the existing conditions within the subject building using standard accepted procedures. The asbestos survey scope of work is intended to identify asbestos-containing materials associated with the subject property. Regardless of the thoroughness of a survey, it is possible that some areas of asbestos-containing materials were overlooked or inaccessible, or is different from those at specific sample locations. Wall voids, building cavities, and mechanical equipment may contain unreported asbestos. In addition, renovation or construction may uncover altered or differing conditions. If a suspect material was not specifically sampled or does not appear to be represented by a similar material previously sampled, it should be analyzed prior to disturbance.

It should be noted that floor tiles and other resinous bound materials, when analyzed by the EPA method for asbestos, may yield false negative results because of limitations in separating closely bound fibers and in detecting fibers of small length and diameter. If a definitive result is required, Atlas Labs Inc. recommends utilizing alternative methods of identification, including Transmission Electron Microscopy (TEM).

This report presents the general descriptions of various construction materials and general locations where these materials were encountered. If questions arise during the planning of demolition, renovation or construction projects concerning the presence of asbestos-containing materials, we should be notified in order to view the conditions and present recommendations.

This report has been prepared on behalf of, and exclusively for the use of WKO Inc. This report and the findings herein shall not, in whole or in part, be disseminated or conveyed to any other party, or be used or relied upon by any other party, without the consultant's prior written consent by Atlas Labs Inc. **A copy of this survey report must be kept onsite during any remediation, renovation or demolition activities, as required by Southwest Clean Air Agency.**

If you have any questions about this information, please call our office at (360) 852-8936

Survey Performed By: Dalton Lafever
AHERA Building Inspector - Certification: # IR-23-0908C
Contact Info: Dalton@atlaslabinc.com Cell Phone: (503) 430-4112

Sincerely,

Dalton Lafever

APPENDIX A



Full Survey Chain of Custody

Name / Company Name: WKO Inc.		Phone: (541) 490-2787	
Contact Email: paul_a123@yahoo.com			
Project Name: N/A		Batch: 22-1054701	
Job/Project Address: 2022 Wind River Hwy, Carson, WA 98610 Office #2			
Inspector: Dalton Lafever Ph: (503) 430-4112 AHERA Cert. # IR-23-0908C Lead RRP Cert. #R-I-41R036-22-00070			
Survey Area Use: Commercial	Approx. Year Built: Unk.	Reason for Survey: Demolition	Sq. Ft. UNK

<input type="checkbox"/> Rush	<input checked="" type="checkbox"/> Asbestos PLM
<input type="checkbox"/> Next Day	<input type="checkbox"/> Lead Paint
<input type="checkbox"/> 2-Day	<input type="checkbox"/> Other
<input checked="" type="checkbox"/> 5-Day	

#	Material Description	Friable Y/N	Location	Condition	Approx. SQ FT.
1-A	Drywall	Y	Kitchen Wall	Good	2,100'
1-B	Drywall	Y	Entryway Wall	Good	-
1-C	Drywall	Y	Hallway Wall	Good	-
1-D	Drywall	Y	Back Office Wall	Good	-
1-E	Drywall	Y	Bathroom Wall	Good	-
2-A	Drywall	Y	Entryway Ceiling	Good	750'
2-B	Drywall	Y	First Office Ceiling	Good	-
2-C	Drywall	Y	Conference Room Ceiling	Good	-
3-A	Drywall	Y	Garage Wall	Good	500'
3-B	Drywall	Y	Garage Wall	Good	-

Notes:

Inspector Signature: Dalton Lafever	Date: 1/10/24	Time: 8:17
Accepted By: Will Sokolowsky	Date: 1/10/24	Time: 8:20am
Lab Results Completed By: [Signature]	Date Sent Out: 1/15/24	Email / Mail

Limitations of Inspection: Atlas Labs Inc. AHERA certified inspector performed a limited survey at the site, date, time and cause as stated above in this document along with lab analysis of possible asbestos and/or lead containing material. Atlas Labs Inc. survey is limited to areas defined on the Chain of Custody form.

General NESHAPS Bulk Sampling Guidelines: Material sampling areas were grouped based on homogenous materials. A homogeneous area is one which contains material that seems by texture, color and surface wear to be uniform and applied during the same general time period. Samples are collected based on a visual survey of the work area as defined in this report. Samples were collected from accessible, representative construction materials, which were suspected to contain asbestos. If additional materials are found during the demolition process that were inaccessible at time of inspection that are not listed in this report please test before you cut. Survey is subject to direction from contractor, homeowner or owners agent.



Approx. SQ
FT.

#	Material Description	Friable Y/N	Location	Condition	
3-C	Drywall	Y	Garage Ceiling	Good	-
4-A	Drywall	Y	Upstairs Left Office Ceiling	Good	520'
4-B	Drywall	Y	Upstairs Hallway Ceiling	Good	-
4-C	Drywall	Y	Upstairs Right Room Wall	Good	-
5-A	Vinyl	Y	Kitchen Computer Closet	Good	15'
6-A	Vinyl	Y	Kitchen Floor	Good	120'
7-A	Flooring	Y	Hallway Floor	Good	120'
8-A	Flooring	Y	First Office Floor	Good	100'
9-A	Flooring	Y	Conference Room Floor	Good	170'
10-A	Flooring	Y	Back Office Floor	Good	110'
11-A	Flooring	Y	Bathroom Floor	Good	15'
12-A	Mortar	N	Kitchen Computer Closet Wall	Good	2 LF
13-A	Tile	N	Conference Room Fireplace Floor	Good	7'
14-A	Mortar	N	Fireplace Wall	Good	UNK
15-A	Cove Base Mastic	N	Kitchen Wall	Good	50 LF
16-A	Sink Undercoat	Y	Kitchen Sink	Good	2'
17-A	Wall Panel	N	Kitchen Computer Closet Wall	Good	35'
18-A	Formica	N	Kitchen Counter	Good	15'
19-A	Insulation	N	Garage Attic	Good	300'
20-A	Carpet Mastic	N	Upstairs Left Office Floor	Good	UNK
21-A	Insulation	N	Attic	Good	UNK
22-A	Mortar	N	Chimney	Good	UNK
23-A	Window Glaze	Y	Garage Window	Fair	8 Windows
24-A	Window Glaze	Y	Conference Window	Fair	12 Windows
25-A	Vapor Barrier	N	Side of Garage	Good	UNK
26-A	Window Sealant	N	Exterior Window	Good	20 Windows
27-A	9" VCT	Y	Conference Room Exterior Entrance Floor	Good	11'
28-A	Siding	N	Side of Building	Good	2,500'
29-A	Shingle	N	Roof	Good	1,700'
Special Instructions:					



Batch # 2022 *

22-1054701

Analysis Date *

01/10/2024

Project #

Name / Company *

WKO Inc.

Project Name

PO #

Analyst *

Crossland Kapaun

Project Location *

2022 Windy River Hwy.,
Carson, WA 98610 - Office
#2

Turnaround Time *

5-Day

Asbestos Analysis of Bulk Material by Polarized Light Microscopy

Sample*	Layer*	Description*	Non Asbestos*	Asbestos Type*	Asbestos %*
1-A	1	Drywall (White) - Kitchen Wall	Cellulose	None Present	N/D
1-A	2	Texture (White) - Kitchen Wall	Cellulose	None Present	N/D
1-B	1	Drywall (White) - Entryway Wall	Cellulose	None Present	N/D
1-B	2	Texture (White) - Entryway Wall	Cellulose	None Present	N/D
1-B	3	Joint Compound (White) - Entryway Wall	Cellulose	None Present	N/D
1-C	1	Drywall (White) - Hallway Wall	Cellulose	None Present	N/D
1-C	2	Texture (White) - Hallway Wall	Cellulose	None Present	N/D
1-D	1	Drywall (White) - Back Office Wall	Cellulose	None Present	N/D
1-D	2	Texture (White) - Back Office Wall	Cellulose	None Present	N/D
1-D	3	Joint Compound (White) - Back Office Wall	Cellulose	None Present	N/D
1-E	1	Drywall (White) - Bathroom Wall	Cellulose	None Present	N/D
1-E	2	Texture (White) - Bathroom Wall	Cellulose	None Present	N/D
1-E	3	Joint Compound (White) - Bathroom Wall	Cellulose	None Present	N/D
2-A	1	Drywall (White) - Entryway Ceiling	Cellulose	None Present	N/D

Sample*	Layer*	Description*	Non Asbestos*	Asbestos Type*	Asbestos %*
2-A	2	Texture (White) - Entryway Ceiling	Cellulose	None Present	N/D
2-A	3	Joint Compound (White) - Entryway Ceiling	Cellulose	None Present	N/D
2-A	4	Skim Coat (Blue) - Entryway Ceiling	Cellulose	Chrysotile	3%
2-B	1	Drywall (White) - First Office Ceiling	Cellulose	None Present	N/D
2-B	2	Texture (White) - First Office Ceiling	Cellulose	None Present	N/D
2-C	1	Drywall (White) - Conference Room Ceiling	Cellulose	None Present	N/D
2-C	2	1st Layer Texture (White) - Conference Room Ceiling	Cellulose	Chrysotile	<1%
2-C	3	2nd Layer Texture (Tan) - Conference Room Ceiling	Cellulose	Chrysotile	3%
3-A	1	Drywall (White) - Garage Wall	Cellulose	None Present	N/D
3-A	2	Texture (White) - Garage Wall	Cellulose	None Present	N/D
3-B	1	Drywall (White) - Garage Wall	Cellulose	None Present	N/D
3-B	2	Texture (White) - Garage Wall	Cellulose	None Present	N/D
3-C	1	Drywall (White) - Garage Ceiling	Cellulose / Fiberglass	None Present	N/D
3-C	2	Texture (White) - Garage Ceiling	Cellulose	None Present	N/D
4-A	1	Drywall (White) - Upstairs Left Office Ceiling	Cellulose	None Present	N/D
4-A	2	Texture (White) - Upstairs Left Office Ceiling	Cellulose	None Present	N/D
4-B	1	Drywall (White) - Upstairs Hallway Ceiling	Cellulose	None Present	N/D
4-B	2	Texture (White) - Upstairs Hallway Ceiling	Cellulose	None Present	N/D
4-C	1	Drywall (White) - Upstairs Right Room Wall	Cellulose	None Present	N/D
4-C	2	Texture (White) - Upstairs Right Room Wall	Cellulose	None Present	N/D
5-A	1	1st Layer Vinyl (White / Blue) - Kitchen Computer Closet	Cellulose / Fiberglass	None Present	N/D
5-A	2	Mastic (Yellow) - Kitchen Computer Closet	Cellulose	None Present	N/D
5-A	3	2nd Layer Vinyl (Grey) - Kitchen Computer Closet	Cellulose	None Present	N/D
5-A	4	Mastic (Brown) - Kitchen Computer Closet	Cellulose	None Present	N/D
6-A	1	1st Layer Vinyl (White / Blue) - Kitchen Floor	Cellulose / Fiberglass	None Present	N/D
6-A	2	Mastic (Yellow) - Kitchen Floor	Cellulose	None Present	N/D
6-A	3	2nd Layer Vinyl (Grey) - Kitchen Floor	Cellulose	None Present	N/D

Sample*	Layer*	Description*	Non Asbestos*	Asbestos Type*	Asbestos %*
6-A	4	Mastic (Brown) - Kitchen Floor	Cellulose	None Present	N/D
6-A	5	Vapor Barrier (Brown) - Kitchen Floor	Cellulose	None Present	N/D
7-A	1	Carpet (Grey / Blue) - Hallway Floor	Synthetic	None Present	N/D
7-A	2	Mastic (Yellow) - Hallway Floor	Cellulose	None Present	N/D
7-A	3	Carpet Pad (Multi Color) - Hallway Floor	Synthetic	None Present	N/D
7-A	4	Vinyl (Red) - Hallway Floor	Cellulose	None Present	N/D
7-A	5	Mastic (Brown) - Hallway Floor	Cellulose	None Present	N/D
7-A	6	Vapor Barrier (Brown) - Hallway Floor	Cellulose	None Present	N/D
7-A	7	Mastic (Yellow) - Hallway Floor	Cellulose	None Present	N/D
8-A	1	Flooring Material (Black) - First Office Floor	Cellulose	None Present	N/D
8-A	2	Vapor Barrier (Brown) - First Office Floor	Cellulose	None Present	N/D
9-A	1	Carpet (Grey / Blue) - Conference Room Floor	Synthetic	None Present	N/D
9-A	2	Mastic (Yellow) - Conference Room Floor	Cellulose	None Present	N/D
9-A	3	Carpet Pad (Multi Color) - Conference Room Floor	Synthetic	None Present	N/D
9-A	4	Vinyl (Brown) - Conference Room Floor	Cellulose	None Present	N/D
9-A	5	Vinyl (Red) - Conference Room Floor	Cellulose	None Present	N/D
9-A	6	Mastic (Brown) - Conference Room Floor	Cellulose	None Present	N/D
9-A	7	Vapor Barrier (Brown) - Conference Room Floor	Cellulose	None Present	N/D
10-A	1	Carpet (Grey / Blue) - Back Office Floor	Synthetic	None Present	N/D
10-A	2	Mastic (Yellow) - Back Office Floor	Cellulose	None Present	N/D
10-A	3	Carpet Pad (Multi Color) - Back Office Floor	Synthetic	None Present	N/D
10-A	4	Vinyl (Brown) - Back Office Floor	Cellulose	None Present	N/D
10-A	5	Mastic (Brown) - Back Office Floor	Cellulose	None Present	N/D
10-A	6	Vapor Barrier (Brown) - Back Office Floor	Cellulose	None Present	N/D
11-A	1	Carpet (Grey / Blue) - Bathroom Floor	Synthetic	None Present	N/D
11-A	2	Mastic (Yellow) - Bathroom Floor	Cellulose	None Present	N/D
11-A	3	Vapor Barrier (Brown) - Bathroom Floor	Cellulose	None Present	N/D
12-A	1	Mortar (Grey) - Kitchen Computer Closet Wall	Cellulose	None Present	N/D
13-A	1	Tile (Blue) - Conference Room Fireplace Floor	Cellulose	None Present	N/D

Sample*	Layer*	Description*	Non Asbestos*	Asbestos Type*	Asbestos %*
13-A	2	Mortar (Grey) - Conference Room Fireplace Floor	Cellulose	None Present	N/D
14-A	1	Mortar (Grey) - Fireplace Wall	Cellulose	None Present	N/D
15-A	1	Cove Base (Grey) - Kitchen Wall	Cellulose	None Present	N/D
15-A	2	Mastic (Yellow) - Kitchen Wall	Cellulose	None Present	N/D
16-A	1	Sink Undercoat (White) - Kitchen Sink	Cellulose	None Present	N/D
17-A	1	Wall Panel (Brown) - Kitchen Computer Closet Wall	Cellulose	None Present	N/D
18-A	1	Formica (White) - Kitchen Counter	Cellulose	None Present	N/D
18-A	2	Mastic (Brown) - Kitchen Counter	Cellulose	None Present	N/D
19-A	1	Insulation (Yellow) - Garage Attic	Fiberglass	None Present	N/D
20-A	1	Carpet (Grey / Blue) - Upstairs Left Office Floor	Synthetic	None Present	N/D
20-A	2	Mastic (Yellow) - Upstairs Left Office Floor	Cellulose	None Present	N/D
21-A	1	Insulation (Yellow) - Attic	Fiberglass	None Present	N/D
21-A	2	Vapor Barrier (Black) - Attic	Cellulose	None Present	N/D
22-A	1	Mortar (Grey) - Chimney	Cellulose	None Present	N/D
23-A	1	Window Glaze (Tan) - Garage Window	Cellulose	None Present	N/D
24-A	1	Window Glaze (Tan) - Conference Window	Cellulose	None Present	N/D
25-A	1	Vapor Barrier (Black) - Side of Garage	Cellulose	None Present	N/D
26-A	1	Window Sealant (White) - Exterior Window	Cellulose	None Present	N/D
27-A	1	VCT (Grey) - Conference Room Exterior Floor	Cellulose	Chrysotile	2%
27-A	2	Mastic (Black) - Conference Room Exterior Floor	Cellulose	None Present	N/D
28-A	1	Siding (Brown) - Side of Building	Cellulose	None Present	N/D
28-A	2	Vapor Barrier (Black) - Side of Building	Cellulose	None Present	N/D
29-A	1	Shingle (Red / Black) - Roof	Cellulose	None Present	N/D
29-A	2	Shingle (Black / White) - Roof	Cellulose	None Present	N/D
29-A	3	Tar Paper (Black) - Roof	Cellulose	None Present	N/D


To Be Filled by the Technician

Technician *



Atlas Laboratories maintains liability to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full without written permission by Atlas. Atlas bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval or endorsement by NVLAP, NIST, NIOSH or any other agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore Atlas recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Transmission Electron Microscopy asbestos identification and lead paint analysis will be available and performed by laboratories by proxy. Original analysis documents are available upon request of the client.


APPENDIX B



2022 Wind River Hwy, Carson, WA 98610 Office #2



Suspect Asbestos Containing Sample Locations



2022 Wind River Hwy, Carson, WA 98610 Office #2 - Upstairs

Suspect Asbestos Containing Sample Locations

APPENDIX C

THIS IS TO CERTIFY THAT

DALTON LAFEVER

HAS SUCCESSFULLY COMPLETED THE TRAINING COURSE

for

ASBESTOS INSPECTOR REFRESHER

In accordance with TSCA Title II, Part 763, Subpart E, Appendix C of 40 CFR

CCB #SRA0615 4-Hr Training

4-Hour AHERA Inspector Refresher
Training; AHERA is the Asbestos Hazard
Emergency Response Act enacting Title II
of Toxic Substance Control Act (TSCA)

Expiration Date: 01/24/2024



Course Date:	01/24/2023
Course Location:	Online
Certificate:	IR-23-0908C

For verification of the authenticity of this
certificate contact:
PBS Engineering and Environmental Inc.
4412 S Corbett Avenue
Portland, OR 97239

A handwritten signature in black ink, reading 'Andy Fridley'.

Andy Fridley, Instructor