



11815 NE 99th Street, Suite 1294  
Vancouver, WA 98662  
Voice: 360-574-3058  
Fax: 360-576-0925  
Web: <https://www.swcleanair.gov>  
Email: [Tina@swcleanair.gov](mailto:Tina@swcleanair.gov)

## Notice of Intent to Remove Asbestos

Case #: 24-145

Amendment: 0

Date Received: 3/8/2024

Date Paid: 3/8/2024

SWCAA Fee: \$369.00

Receipt #: 152518526

**This notification MUST be present at all times at the asbestos project sit**

Quantity to be removed: 630 Square Feet 0 Linear Feet

Workshift days: M T W Th F

Project starting date: 3/18/2024 Project Completion date: 5/5/2024

Workshift hours: 7am - 3:30pm

Site Name: Float Crane / Boat

Site address: 6801 NW Old Lower River Rd

Location of Asbestos: Floor tile & Roof

City/State/Zip: Vancouver

WA

98660

☐ Demolition of Structure (Notification of Demolition required)

County: CLARK COUNTY

☒ Asbestos survey conducted?

No survey reason:

AHERA Inspector: Ysabel E Perez

Certification #: 182826

### Material to be Removed:

- |  |  |                                   |                                      |  |                                    |
|--|--|-----------------------------------|--------------------------------------|--|------------------------------------|
| <input type="checkbox"/> Fireproofing                      | <input type="checkbox"/> Popcorn Ceiling     | <input type="checkbox"/> CAB      | <input type="checkbox"/> Sheet Vinyl | <input type="checkbox"/> Boiler Insulation | <input type="checkbox"/> Duct Tape |
| <input type="checkbox"/> Duct Paper                        | <input type="checkbox"/> Mag Pipe Insulation | <input type="checkbox"/> Air Cell | <input type="checkbox"/> CA Pipe     | <input checked="" type="checkbox"/> VAT    |                                    |
| <input checked="" type="checkbox"/> Other Built up Roofing |  |                                   |                                      |  |                                    |

### Control Methods:

- |   |                                    |   |                                       |   |  |
|---|------------------------------------|---|---------------------------------------|---|--|
| <input checked="" type="checkbox"/> N.P Enclosure                             | <input type="checkbox"/> Glove Bag | <input type="checkbox"/> Mini Enclosure | <input type="checkbox"/> Wrap and Cut | <input checked="" type="checkbox"/> Water | <input checked="" type="checkbox"/> HEPA Vac |
| <input checked="" type="checkbox"/> Other Built up roofing will not have NPE. |                                    |   |                                       |   |  |

Asbestos Contractor: IRS Environmental of Portland, Inc.

Phone: 503-693-6388

Mailing Address: 777 SW Armco Ave, Hillsboro, OR, 97123

Email: [Nancy@irsenvironmental.com](mailto:Nancy@irsenvironmental.com)

Certification ##: ABCN00001384

Supervisor: Nancy Nguyen

Phone: 503-693-6388

Property Owner: HME Construction inc

Phone: 360-601-5758

Mailing Address: 6801 NW Old Lower River Rd, Vancouver WA 98660

Asbestos Disposal Site: Hillsboro Landfill: 3205 SE Minter Bridge Rd, Hillsboro, OR, 97123-

**I DO HEREBY CERTIFY THAT THE INFORMATION CONTAINED IN THIS NOTIFICATION IS,  
TO THE BEST OF MY KNOWLEDGE, ACCURATE AND COMPLETE.**

Submitter Name: Nancy Nguyen

Representing: IRS Environmental of Portland

Submitter Title: CEO

Date Submitted: 3/8/2024

Reviewed by SWCAA: Brian Fallon

☒ Approved



11815 NE 99th Street, Suite 1294  
Vancouver, WA 98662  
Voice: 360-574-3058  
Fax: 360-576-0925  
Web: <https://www.swcleanair.gov>  
Email: [Tina@swcleanair.gov](mailto:Tina@swcleanair.gov)

## Notice of Intent to Remove Asbestos

Case #: 24-145

Amendment: 0

Date Received: 3/8/2024

Date Paid: 3/8/2024

SWCAA Fee: \$369.00

Receipt #: 152518526

**This notification MUST be present at all times at the asbestos project sit**



## North American Marine Consultants, LLC

---

### GENERAL CONDITION SURVEY

**DERRICK BARGE “BD-6065”**

**OFFICIAL NUMBER: UNDOCUMENTED**

**OWNED BY: STATE OF OREGON, PORT OF PORTLAND  
DIVISION OF NAVIGATION**

At the request of Mr. Paul Freeman, Dredge Captain with the Port of Portland, the undersigned independent marine surveyor inspected the subject vessel as it lay afloat and moored at the fleeting facility operated by the Port of Portland, Division of Navigation, across from Swan Island in Portland, Oregon.

The purpose of the attendance was to determine, to the extent possible, the general condition of the vessel and to prepare a record of same.

Date of Survey:	April 14, 2020
Persons in Attendance:	Mr. Paul Freeman Port of Portland Division of Navigation
Independent Marine Surveyor:	Capt. Steven J. Bahnsen, NAMS-CMS

### GENERAL DESCRIPTION

The subject vessel was an all steel, welded derrick barge built during 1951 by Wellman Engineering for the United States Army, in Cincinnati, Ohio. The barge was fitted with a Dravo, Model 28, pedestal mounted, revolving gantry crane with a lifting capacity of 67 tons at a 40' radius. The hull was divided by three longitudinal and seven transverse, watertight bulkheads into a raked bow, raked stern and 28 midbody compartments.

Approximate hull dimensions were 140' x 58' x 12'.



## **BOW COMPARTMENT**

The port bow side plates contained scattered abrasions and minor indentations from 0-3/4", with no one area worthy of specific mention.

The port bow side was fitted with double formed rub rails at deck level and at a point approximately 5' below deck level.

The port bow rake knuckle plates contained scattered abrasions and minor indentations from 0-1", with no one area worthy of specific mention.

The port bow corner plates contained scattered abrasions and minor indentations from 0-1/2", with no one area worthy of specific mention.

The port bow corner was fitted with double formed rub rails at deck level and at a point approximately 5' below deck level.

The headlog plates were contained scattered abrasions and minor indentations from 0-1/2", with no one area worthy of specific mention.

The starboard bow corner plates contained scattered abrasions and minor indentations from 0-1/2", with no one area worthy of specific mention.

The starboard bow corner was fitted with double formed rub rails at deck level and at a point approximately 5' below deck level.

The starboard bow rake knuckle plates contained scattered abrasions and minor indentations from 0-1", with no one area worthy of specific mention.

The starboard bow side plates contained scattered abrasions and minor indentations from 0-3/4", with no one area worthy of specific mention.

The starboard bow side was fitted with double formed rub rails at deck level and at a point approximately 5' below deck level.

The deck plates contained scattered abrasions and minor indentations from 0-1/2", with no one area worthy of specific mention.





## **STARBOARD SIDE**

The starboard side and gunwale plates in way of the midbody tanks contained scattered abrasions and minor indentations from 0-1/2" and random indentations from 0-3/4", with no one area worthy of specific mention.

The starboard side was fitted with double formed rub rails at deck level and at a point approximately 5' below deck level. Vertical, double formed rub rails extended between the upper and lower rails at approximately 15' spacing.

The deck plates contained scattered abrasions and minor indentations from 0-1/2" with no one area worthy of specific mention.

## **STERN COMPARTMENT**

The starboard stern side plates contained scattered abrasions and minor indentations from 0-3/4", with no one area worthy of specific mention.

The starboard stern side was fitted with double formed rub rails at deck level and at a point approximately 5' below deck level.

The starboard stern rake knuckle plates contained scattered abrasions and minor indentations from 0-1", with no one area worthy of specific mention.

The starboard stern corner plates contained scattered abrasions and minor indentations from 0-3/4", with no one area worthy of specific mention.

The starboard stern corner was fitted with double formed rub rails at deck level and at a point approximately 5' below deck level.

The sternlog plates contained scattered abrasions and minor indentations from 0-3/4" with random indentations from 0-1.5" with no one area worthy of specific mention.

The sternlog was fitted with double formed rub rails at deck level and at a point approximately 5' below deck level.

The port stern corner plates contained scattered abrasions and minor indentations from 0-3/4", with no one area worthy of specific mention.

The port stern corner was fitted with double formed rub rails at deck level and at a point approximately 5' below deck level.



The port stern rake knuckle plates contained scattered abrasions and minor indentations from 0-1", with no one area worthy of specific mention.

The port stern side plates contained scattered abrasions and minor indentations from 0-3/4", with no one area worthy of specific mention.

The port stern side was fitted with double formed rub rails at deck level and at a point approximately 5' below deck level.

The deck plates contained scattered abrasions and minor indentations from 0-1/2", with no one area worthy of specific mention.

## **PORT SIDE**

The port side and gunwale plates in way of the midbody tanks contained scattered abrasions and minor indentations from 0-1/2" and random indentations from 0-3/4" with no one area worthy of specific mention.

The port side was fitted with double formed rub rails at deck level and at a point approximately 5' below deck level. Vertical, double formed rub rails extended between the upper and lower rails at approximately 15' spacing.

The deck plates contained scattered abrasions and minor indentations from 0-1/2" with no one area worthy of specific mention.

## **DECK FITTINGS**

The vessel was equipped with an assortment of typical deck fittings as follows:

### ***Bow:***

- 10" H-bitts, to port and starboard
- Berger anchor fairleads, to port and starboard
- 28" open chocks to port, starboard and at centerline
- Boom rest with four 8" x 8" steel I-beam legs and 3" steel angle diagonal bracing

### ***Midbody (each side):***

- (3) 48" cleats



- (4) 28" open chocks
- Multiple center bolt access hatches

***Stern:***

- 10" H-bitts, to port and starboard
- Berger, anchor fairlead to starboard only
- (6) center bolt access hatches

All deck fittings appeared to be in good condition.

**DECK**

A 15' x 15' x 8', painted steel deck house with plexi-glass windows in all four bulkheads was located to starboard on the barge deck. Inside the winch house, a Skagit, triple-drum, waterfall type anchor winch was mounted to the deck. The winch was powered by a 75 horsepower electric motor through a chain drive.

**DERRICK**

The derrick superstructure was mounted on a 28' ring circle atop a 30' x 30' x 3' pedestal constructed of 36" x 12" steel I-beams. The derrick machinery space was accessible via ladders on the port and starboard sides of the derrick pedestal and superstructure.

The overhead and bulkheads in the interior of the derrick superstructure were sheathed with white painted, insulating panels and the steel, diamond plate deck was painted red. LED light fixtures with translucent safety covers were fitted overhead.

The derrick swing gear was located forward on centerline in the derrick house, and was powered by a Westinghouse, 230 Volt, 45 horsepower, DC electric motor through a Jones reduction gear. A caged tool room containing a tool bench, parts bins and steel lockers was situated to port, and to starboard were the electric contact panel and resistor bank.

Along the aft bulkhead on an elevated deck was a Kohler, 350 kW / 438 KVA, 230 volt, DC generator with a Cummins, NTT 8855, six-cylinder, turbocharged, radiator cooled generator motor rated at 535 horsepower @ 1,800 RPM.

At the center of the derrick house interior was a Dravo, three-drum, draw works powered by a Westinghouse 135 horsepower DC electric motor. The main hoist wire drum, auxiliary drum



and boom hoist wire were all spooled with 1.25" steel cable. The main, boom and auxiliary hoist brake drums were clean with no rust scale, and the brake pads appeared to be in good condition.

***Operator's Cab:***

A steel stairway led up from the starboard side of the machinery space to the crane operator's cab.

The exposed steel overhead and bulkheads in operator's cab were painted black and the steel deck was painted red. Opening windows were set into the forward, port and starboard bulkheads and overhead. An incandescent light fixture with a glass globe and bronze safety cage lit the cab.

Consoles along the port and starboard sides of the cab and were equipped with controls and gauges for operation of the derrick. The operator's cab was further equipped with the following:

- Motorola, company radio
- Standard Horizon, Quest, VHF marine radio
- Load cell

**INTERNAL HULL COMPARTMENTS**

No rake or midbody compartments were opened for inspection however, the internal framing in the compartments was expected to be generally distorted to conform to the exterior hull conditions described previously except as otherwise noted below. The following descriptions of the compartment interiors were taken from a previously issued report.

***Starboard Bow Rake Compartment:***

The compartment was found to be dry and clean, and the coatings on the side shell, deck, bottom plating and framing all appeared to be in very good condition. No excessive damage was noted in the compartment.

***Starboard No. 2 Midbody Compartment:***

The compartment was found to contain approximately 4" of water. Coatings on the side shell, deck, bottom plating and framing all appeared to be in very good condition. No excessive damage was noted in the compartment.



***Starboard Stern Rake Compartment:***

The compartment was dry and clean, and the coatings on the side shell, deck, bottom plating and framing all appeared to be in very good condition. No excessive damage was noted in the compartment.

**COATINGS**

The black exterior hull coatings appeared to be in fair condition, with multiple areas of red primer paint showing through the black paint.

The gray coatings on the derrick superstructure appeared to be in fair condition and approximately 75% intact.

Coatings on the decks were in good condition and approximately 90% intact.

**SURVEYOR'S COMMENTS**

The derrick barge "B-6065" was utilized by the dredge "Oregon" crew to support dredging operations. In the opinion of the undersigned, the vessel appeared to be in good condition and was suitable for its current utilization.

No ultra-sonic gauging or other accurate measurements of hull plate thickness were made by the undersigned.

The above survey report is submitted by the undersigned independent marine surveyor without prejudice to the rights of all parties concerned.

NORTH AMERICAN MARINE CONSULTANTS, LLC

Capt. Steven J. Bahnsen, NAMS-CMS  
Independent Marine Surveyor





*Anchor winch*



*Bow deck, looking to starboard*





*Derrick machinery house*



*Deck, looking aft*





*Stern deck*



*Winch house*





*Main engine*



*Swing gear*





*Tool room*






*Draw works*



MACHINERY PLAN  
Scale: 1/4" = 1'-0"

CAPACITY - WEIGHTS & OPERATING DATA						
FUNCTION	CAPACITY	RADIUS	SPEED	MOTOR	CONTROL	REEVING
MAIN HOIST	135,400	82'-6" MIN. TO 75'-0" MAX.	200 FPM. APPROX.	3 DOWN MOTOR HOIST WITH 155 H.P. MOTOR	MAGNETIC & DYNAMIC BRAKING	4 ROPS OF 2 1/2" DIA. P.D. FIRST LAYER
DOWN LIFTING	135,400	82'-6" TO 75'-0"	15 MIN. APPROX.	155 H.P. MOTOR	IS CONTROLLED BY ELECTRIC 1 1/2" ROPS	00
AUX HOIST	33,500	81'-0" MIN. TO 100'-0" MAX.	60 FPM. APPROX.	33 H.P. MOTOR	ELECTRIC 1 1/2" ROPS	2 1/2" P.D. FIRST LAYER
ROTATE			ONE REVOLUTION IN 10 MIN.	15 H.P. MOTOR	MAGNETIC & DYNAMIC BRAKING	4 ROPS OF 2 1/2" DIA. P.D. FIRST LAYER
DECK WINCHES	5000 LBS. EACH		10 H.P. EACH	10 H.P. MOTOR	IS CONTROLLED BY ELECTRIC 1 1/2" ROPS	2 1/2" P.D. FIRST LAYER
ROLLER CIRCLE	28'-0" DIA.			150 K.W. GENERATOR	230 VOLT D.C.	
POWER				DIESEL ELECTRIC	150 K.W. GENERATOR	230 VOLT D.C.
TOTAL OPERATING WEIGHT OF CRANE ABOVE ROLLER CIRCLE	665,000					CRANE BASE - 80,000
COUNTERWEIGHT	280,000					CONCRETE @ 140# PER CU. FT.
LIGHTING GENERATOR				DIESEL ELECTRIC	5 K.W. GEN.	230 VOLT D.C.



DRAYO CORPORATION DR. PHILLIPS CHK. FOR MARK APP'D. E. WILLIAMS	60 TON FLOATING CRANE HULL 142'x58'x12'0" GENERAL ARRANGEMENT SCALE	DRAYO CORPORATION [E.W.D.] PITTSBURGH, PA. DRAWING NO. 3-122675 Y&D No 546351
--	--	--



March 18, 2022  
Project No. M0232.25.027

Erin Anderson  
Port of Portland  
7200 Northeast Airport Way  
Portland, Oregon 97218

Re: Navigation Base Float Crane—Pre-Renovation Hazardous Building Materials Survey

Dear Ms. Anderson:

On December 13 and 14, 2021, at the request of the Port of Portland (Port), Maul, Foster, & Alongi, Inc. (MFA) conducted a pre-renovation assessment of suspected asbestos-containing materials (ACM) and lead-based paint (LBP) of the float crane located at the Navigation Base at 6208 N Ensign Street (the Property). The assessment included below deck areas including the former crew quarters and the interior and exterior of the portable job trailer. The Port requested this assessment in support of proposed renovation activities at the Property.

The assessment was conducted consistent with federal standards, Oregon Department of Environmental Quality building survey requirements, and Oregon Administrative Rules pertaining to ACM. Sampling was conducted by Emily Curtis, Connor Anderson, and Ysabel Perez, Asbestos Hazard Emergency Response Act (AHERA) accredited asbestos building inspectors. The samplers AHERA building inspector certificates are included in Attachment A. Access to the Property was coordinated with the Port.

## **SAMPLING PROCEDURES**

### **Confined-Space Entry**

The below deck crew quarters is only accessible via a hatch and semi-vertical ladder and is a confined space subject to 29 Code of Federal Regulations 1915 Subpart B, Confined and Enclosed Spaces and Other Dangerous Atmospheres in Shipyard Employment. As part of this assessment, MFA completed a confined space evaluation and provided a mechanical retrieval tripod above the hatch while sampling for potential rescue purposes.

Both entrants to the space were equipped with a harness and MFA had one designated attendant present for each entrant during the sampling. Before entering the confined space, MFA evaluated the space using a combustible gas monitor. MFA prepared a safe work plan describing these procedures that was approved by the Port before completing the assessment.

## Asbestos-Containing Materials

The asbestos sampling procedure was consistent with the AHERA protocol outlined in 40 Code of Federal Regulations (CFR) 763. The survey consisted of a pre-renovation assessment of building materials that, as identified by the Port, might be disturbed during renovation.

MFA collected 30 samples of suspected ACM-containing materials and submitted them for laboratory analysis. The sampling procedures included appropriate work practices to minimize the release of asbestos fibers, such as using water to minimize dust generation.

Samples were sent to NVL Laboratories Inc., located in Seattle, Washington, for analysis by polarized light microscopy, consistent with U.S. Environmental Protection Agency (EPA) Method 600/R-93/116.

## Lead-Based Paint

At the request of the Port, MFA conducted a survey for interior and exterior paint coatings of the float crane, including X-ray fluorescence (XRF) readings of each color and/or layer identified. For quality assurance, MFA collected 4 paint chips samples from representative XRF sampling locations. Paint with a detectable amount of lead is considered “lead-containing.” EPA (40 CFR 745) and the Oregon Health Authority define LBP as paint containing lead concentrations of over 5,000 parts per million (higher than 0.5 percent).

The paint chip samples were placed in labeled sample bags and sent to NVL Laboratories, Inc., for analysis by EPA Method 3051/7000B.

## RESULTS AND DISCUSSION

Field sampling information, as well as photographs documented ACM and LBP are included in Attachment B. Certified laboratory reports for all samples collected are included in Attachment D. The attached Table 1 summarizes asbestos laboratory results, and the attached Table 2 summarizes the XRF and laboratory results for the lead paint samples.

Asbestos was detected above one percent in the following materials:

- White coating material on the roof of the job trailer (9-ROOF-JT-14)
- Silver roof penetration sealant on the job trailer (10-ROOF-JT-15 and 9-ROOF-JT-16)
- Brown floor tile with black mastic in the former crew quarters (1-FTM-BD6065-1 and 1-FTM-BD6065-2)

Many of the painted surfaces evaluated on the float crane are considered to be lead-containing. For the purposes of renovation or reuse, the lead-containing paint should be abated by a licensed abatement contractor or safely managed in place consistent with EPA’s Renovation,

Repair and Painting Rule, which, in Oregon, is administered by the Oregon Health Authority. Painted surfaces with lead content above the EPA-regulated definition of LBP include the following:

- Gray paint on the circuit breaker in the former crew quarters
- Red paint on the west wall support beam in the northwest room of the former crew quarters
- Black paint on the back of the stairs and stair railing in the former crew quarters
- Orange paint on the doorway between the south and northwest rooms of the former crew quarters
- White paint on the center support beam in the south room of the former crew quarters
- Red paint on the northeast portion of the float crane deck
- Yellow paint on the rope tie downs located on the northeast portion and the west end of the float crane deck
- Pale yellow paint on the float crane deck adjacent to foot of crane (on east end)
- Pale yellow/gray paint on the stripes on the bottom of the gray structure on the deck of the float crane

Prior to any disturbance activities at the Property, identified hazardous materials should be abated by a licensed abatement contractor or safely managed in place consistent with a written operations and maintenance plan. The Port should inform contractors that other hazardous materials or conditions may be discovered during the renovation and/or demolition activities, which may warrant remediation and/or corrective actions.

Sincerely,

Maul Foster & Alongi, Inc.



Emily Curtis  
Project Environmental, Health, and Safety  
Specialist

Attachments: Limitations  
Tables  
A—AHERA Certificates  
B—Field Sampling Data Report  
C—Laboratory Reports

## LIMITATIONS

---

The services undertaken in completing this report were performed consistent with generally accepted professional consulting principles and practices. No other warranty, express or implied, is made. These services were performed consistent with our agreement with our client. This report is solely for the use and information of our client unless otherwise noted. Any reliance on this report by a third party is at such party's sole risk.

Opinions and recommendations contained in this report apply to conditions existing when services were performed and are intended only for the client, purposes, locations, time frames, and project parameters indicated. We are not responsible for the impacts of any changes in environmental standards, practices, or regulations subsequent to performance of services. We do not warrant the accuracy of information supplied by others, or the use of segregated portions of this report.



# TABLES



**Table 1**  
**Summary of Asbestos Sample Results**  
**Navigation Base Float Crane - Pre-Renovation Survey**  
**Portland, Oregon**



Sample Name	Sample Date	Material Description	Location	Bulk Asbestos	Condition if Detected	Estimated Quantity if Detected
<b>Job Trailer</b>						
1-CM-JT-1	12/13/2021	Green carpet with mastic	Along west wall	ND	--	--
1-CM-JT-2	12/13/2021	Green carpet with mastic	Room on south end	ND	--	--
2-IN-JT-3	12/13/2021	Fibrous insulation	West wall of room on south end	ND	--	--
2-IN-JT-4	12/13/2021	Fibrous insulation	East wall of room on south end	ND	--	--
3-CP-JT-5	12/13/2021	Wood ceiling panel with white vinyl covering	Ceiling of south end room	ND	--	--
2-IN-JT-6	12/13/2021	Fibrous insulation	Ceiling of south end room	ND	--	--
3-CP-JT-7	12/13/2021	Wood ceiling panel with white vinyl covering	Ceiling above kitchen area	ND	--	--
4-VC-JT-8	12/13/2021	Brown vinyl covering with clear mastic	Shelves in south end room	ND	--	--
5-VFT-JT-9	12/13/2021	Brown/tan speckled vinyl floor tile with black/brown mastic	South end room	ND	--	--
5-VFT-JT-10	12/13/2021	Brown/tan speckled vinyl floor tile with black/brown mastic	West wall	ND	--	--
6-VC-JT-11	12/13/2021	Orange vinyl covering with yellow mastic	Kitchen counter	ND	--	--
7-SM-JT-12	12/13/2021	White sealant material	South exterior wall	ND	--	--
8-SM-JT-13	12/13/2021	Gray sealant material	South exterior wall	ND	--	--
9-ROOF-JT-14	12/13/2021	White coating material on metal roof	Roof on east side	4%	Poor	600 sq. ft.
10-ROOF-JT-15	12/13/2021	Silver penetration sealant	Roof on west side	7%	Poor	Less than 5 sq. ft.
9-ROOF-JT-16	12/13/2021	Silver penetration sealant	Roof on west side	4%	Poor	Less than 5 sq. ft.

**Table 1**  
**Summary of Asbestos Sample Results**  
**Navigation Base Float Crane - Pre-Renovation Survey**  
**Portland, Oregon**



Sample Name	Sample Date	Material Description	Location	Bulk Asbestos	Condition if Detected	Estimated Quantity if Detected
<b>Former Crew Quarters</b>						
1-FTM-BD6065-1	12/14/2021	9x9 inch brown floor tile with black mastic	South room, southeast corner	Vinyl floor tile: 2% Mastic: 3%	Poor	375 sq. ft.
1-FTM-BD6065-2	12/14/2021	9x9 inch brown floor tile with black mastic	South room, southwest corner	Vinyl floor tile: 3% Mastic: 4%	Poor	375 sq. ft.
2-WI-BD6065-3	12/14/2021	Yellow insulation with woven white fabric	South room, northeast corner	ND	--	--
3-MCT-BD6065-4	12/14/2021	Multicolored tile with green mastic	Northwest room, southwest corner	ND	--	--
3-MCT-BD6065-5	12/14/2021	Multicolored tile with green mastic	Northwest room, northeast corner	ND	--	--
2-WI-BD6065-6	12/14/2021	Yellow insulation with woven fabric	Northwest room, northeast corner	ND	--	--
4-WT-BD6065-7	12/14/2021	White 6x6 inch wall tile with gray mastic	Northeast room, northwest corner	ND	--	--
5-HFT-BD6065-8	12/14/2021	White hexagonal floor tile with white mastic	Northeast room, northwest corner	ND	--	--
6-SWT-BD6065-9	12/14/2021	White 4x4 inch wall tile with gray mastic	Northeast room, southeast corner	ND	--	--
7-WC-BD6065-10	12/14/2021	White wall coating	Northeast room, northeast ceiling	ND	--	--
8-ST-BD6065-11	12/14/2021	Gray metallic seam tape	Northwest room, east wall	ND	--	--
9-SFT-BD6065-12	12/14/2021	White 1x1 inch floor tile with white mastic	Central room, west floor	ND	--	--
10-WCF-BD6065-13	12/14/2021	White ceiling fabric with white coating	Central room, west ceiling	ND	--	--
11-BDG-BD6065-14	12/14/2021	Black door gasket	Door between south room and northwest room	ND	--	--
NOTES: Samples were analyzed consistent with polarized light microscopy U.S. Environmental Protection Agency Method 600/R-93-116. ND = none detected. PLM = polarized light microscopy. sq. ft. = square feet.						

**Table 2**  
**Summary of Lead-Based Paint Sample Results**  
**Navigation Base Float Crane—Pre-Renovation Survey**  
**Portland, Oregon**



Sample Name	Sample Date	Material Description	Location	XRF Lead Result (mg/cm <sup>2</sup> )	Laboratory Lead Result (%)	Estimated Quantity if LBP
<b>Job Trailer</b>						
1-PB-JT-1	12/13/2021	Off-white paint	West interior wall	0.032	--	--
1-PB-JT-2	12/13/2021	Off-white paint	West interior wall	0.036	--	--
2-PB-JT-3	12/13/2021	Brown paint	East interior wall	0.032	--	--
2-PB-JT-4	12/13/2021	Brown paint	East interior wall	0.039	--	--
3-PB-JT-5	12/13/2021	Gray paint	Lockers	ND	--	--
4-PB-JT-6	12/13/2021	Light brown paint	Exit door on east wall	0.017	--	--
4-PB-JT-7	12/13/2021	Light brown paint	Exit door on east wall	0.0036	--	--
5-PB-JT-8	12/13/2021	Blue paint	East exterior wall	ND	--	--
5-PB-JT-9	12/13/2021	Blue paint	West exterior wall	ND	--	--
6-PB-JT-10	12/13/2021	White paint	East exterior wall	ND	--	--
6-PB-JT-11	12/13/2021	White paint	East exterior wall	ND	<0.0050	--
<b>Former Crew Quarters and Below Deck Areas</b>						
1-PB-BD6065-1	12/14/2021	White paint	South room, east wall	0.086	--	--
1-PB-BD6065-2	12/14/2021	White paint	South room, west wall	0.043	--	--
2-PB-BD6065-3	12/14/2021	Dark green paint	South room, northwest bottom wall	0.855	--	--
2-PB-BD6065-4	12/14/2021	Dark green paint	Northwest room, bottom north wall	0.51	--	--
3-PB-BD6065-5	12/14/2021	Dark green paint	Door frame between northwest and northeast rooms	0.618	--	--
4-PB-BD6065-6	12/14/2021	Gray paint	Storage room	0.703	--	--
4-PB-BD6065-7	12/14/2021	Gray paint	Storage room wall	0.241	--	--
5-PB-BD6065-8	12/14/2021	Gray paint	Circuit breaker in northwest room	1.343	--	6 sq. ft.
5-PB-BD6065-9	12/14/2021	Gray paint	Circuit breaker in northwest room	0.991	--	--
6-PB-BD6065-10	12/14/2021	Red paint	Northwest room, west wall support beam	2.535	--	2 sq. ft.
7-PB-BD6065-11	12/14/2021	Black paint	Back of stairs	4.532	0.95	80 sq. ft.
7-PB-BD6065-12	12/14/2021	Black paint	Stair railing	5	--	80 sq. ft.
8-PB-BD6065-13	12/14/2021	White paint	Support beam in center of northwest room	0.581	--	--
9-PB-BD6065-14	12/14/2021	Orange paint	Doorway between south and northwest rooms	3.029	--	4 sq. ft.

**Table 2**  
**Summary of Lead-Based Paint Sample Results**  
**Navigation Base Float Crane—Pre-Renovation Survey**  
**Portland, Oregon**



Sample Name	Sample Date	Material Description	Location	XRF Lead Result (mg/cm <sup>2</sup> )	Laboratory Lead Result (%)	Estimated Quantity if LBP
9-PB-BD6065-15	12/14/2021	White paint	Center support beam in south room	5	0.44	450 sq. ft.
10-PB-BD6065-16	12/14/2021	Yellow paint	Interior south small hatch on deck	ND	--	--
10-PB-BD6065-17	12/14/2021	Yellow paint	Interior north small hatch on deck	ND	--	--
11-PB-BD6065-18	12/14/2021	Red paint	Northeast deck	1.1	--	1,750 sq. ft.
12-PB-BD6065-19	12/14/2021	Yellow paint	Tie down, northeast	5	--	200 sq. ft.
13-PB-BD6065-20	12/14/2021	Pale yellow paint	Adjacent to foot of crane, east end	1.631	0.077	400 sq. ft.
14-PB-BD6065-21	12/14/2021	Beige yellow paint	Crane beam, east end	0.089	--	--
15-PB-BD6065-22	12/14/2021	Blue paint	Blue building, southeast end	ND	--	--
16-PB-BD6065-23	12/14/2021	White paint	Blue building, southeast end, top	ND	--	--
17-PB-BD6065-24	12/14/2021	Bright yellow paint	East end, yellow horizontal beam	ND	--	--
18-PB-BD6065-25	12/14/2021	Gray paint	Gray structure, west end	0.279	--	--
19-PB-BD6065-26	12/14/2021	Black paint	Stripes on bottom of gray structure	0.003	--	--
20-PB-BD6065-27	12/14/2021	Pale red paint	Bottom of gray structure	0.007	--	--
21-PB-BD6065-28	12/14/2021	Dark blue/gray paint	Stairs on gray structure	ND	--	--
22-PB-BD6065-29	12/14/2021	Pale yellow paint	Southwest interior hatch	0.026	--	--
11-PB-BD6065-30	12/14/2021	Red paint	West end, deck	0.808	--	--

**Table 2**  
**Summary of Lead-Based Paint Sample Results**  
**Navigation Base Float Crane—Pre-Renovation Survey**  
**Portland, Oregon**



Sample Name	Sample Date	Material Description	Location	XRF Lead Result (mg/cm <sup>2</sup> )	Laboratory Lead Result (%)	Estimated Quantity if LBP
12-PB-BD6065-31	12/14/2021	Yellow paint	West end, rope tie	4.915	--	200 sq. ft.
13-PB-BD6065-32	12/14/2021	Pale gray/yellow	Stripes on bottom of gray structure	2.572	--	32 sq. ft.
18-PB-BD6065-33	12/14/2021	Gray paint	Gray structure, west end	0.028	--	--
<p>NOTES:</p> <p>Sample was analyzed consistent with U.S. Environmental Protection Agency Method 3050B/7000B.</p> <p>-- = not applicable.</p> <p>% = percent (milligrams per kilogram/10000)</p> <p>LBP = lead-based paint.</p> <p>ln. ft. = linear feet.</p> <p>mg/cm<sup>2</sup> = milligrams per square centimeter.</p> <p>ND = none detected.</p> <p>sq. ft. = square feet.</p> <p>XRF = X-ray fluorescence.</p>						

# ATTACHMENT A

AHERA CERTIFICATES





THIS IS TO CERTIFY THAT  
**CONNOR ANDERSON**  
HAS SUCCESSFULLY COMPLETED THE TRAINING COURSE  
for  
**ASBESTOS INSPECTOR INITIAL COURSE**

In accordance with TSCA Title II, Part 763, Subpart E, Appendix C of 40 CFR

Course Date: 8/16/2021 - 8/18/2021

Course Location: Portland, OR

Certificate: IN-21-9554B



**CCB #SRA0614 24-Hr Training**

24-Hour AHERA Inspector Training; AHERA is the Asbestos Hazard Emergency Response Act enacting Title II of Toxic Substance Control Act (TSCA)

**Expiration Date:** 08/18/2022

For verification of the authenticity of this certificate contact:  
PBS Engineering and Environmental Inc.  
4412 S Corbett Avenue  
Portland, Oregon 97239  
503.248.1939

A handwritten signature in black ink that reads "Andy Fridley".

Andy Fridley, Instructor



# Certificate of Completion

This is to certify that  
**Emily Curtis**  
has satisfactorily completed  
4 hours of refresher training as an  
**AHERA Building Inspector**

to comply with the training requirements of  
TSCA Title II, 40 CFR 763 (AHERA)

EPA Provider # 1085

183511  
Certificate Number



A handwritten signature in black ink, appearing to read "Ed Edinger", is written over a horizontal line.

Instructor: Ed Edinger

Jan 19, 2022

Expires in 1 year.

Date(s) of Training

Exam Score: N/A  
(if applicable)

ARGUS PACIFIC, INC / 21905 64th AVE W, SUITE 100 / MOUNTLAKE TERRACE, WASHINGTON 98043 / 206.285.3373 / ARGUSPACIFIC.COM



# Certificate of Completion

This is to certify that  
**Ysabel E. Perez**  
has satisfactorily completed  
24 hours of training as an  
**AHERA Building Inspector**

to comply with the training requirements of  
TSCA Title II, 40 CFR 763 (AHERA)

EPA Provider # 1085

182826  
Certificate Number



A blue ink signature of Ed Edinger, written in a cursive style.

Instructor: Ed Edinger

Nov 1 - 3, 2021

Expires in 1 year.

Date(s) of Training

Exam Score: **92%**  
(if applicable)

ARGUS PACIFIC, INC / 21905 64th AVE W, SUITE 100 / MOUNT LAKE TERRACE, WASHINGTON 98043 / 206.285.3373 / ARGUSPACIFIC.COM

# ATTACHMENT B

## FIELD SAMPLING DATA REPORT



# Field Sampling Data Report

## Summary of Identified Asbestos and Lead-Containing Materials

**Project: Navigation Base Float Crane**  
**Client Name: Port of Portland**

Field Personnel: Emily Curtis, Connor Anderson, and Ysabel Perez  
Survey Type: Asbestos and Lead Paint

### Sample Information

**Sample Name:** 9-ROOF-JT-14

**Sample Date:** 12/13/2021

**Sample Location:** Roof of job trailer on eastside

**Type of Sample:** White coating material

**Is it friable?:** Yes

**Assessment Category:** Asbestos-containing building material (ACBM) with potential for damage

**Quantity:** 600 square feet

**Sample Photo:**





**Sample Name:** 10-ROOF-JT-15

**Sample Date:** 12/13/2021

**Sample Location:** West side of job trailer roof

**Type of Sample:** Gray patching material

**Is it friable?:** No

**Assessment Category:** ACBM with potential for damage

**Quantity:** Less than 5 square feet

**Sample Photo:**



**Sample Name:** 9-ROOF-JT-16

**Sample Date:** 12/13/2021

**Sample Location:** West side of job trailer roof

**Type of Sample:** Gray patching material

**Is it friable?:** No

**Assessment Category:** ACBM with potential for damage

**Quantity:** Less than 5 square feet

**Sample Photo:**



**Sample Name:** 1-FTM-BD6065-1

**Sample Date:** 12/14/2021

**Sample Location:** South room, southeast corner of former crew quarters

**Type of Sample:** Brown floor tile with black mastic

**Is it friable?:** No

**Assessment Category:** ACBM with potential for damage

**Quantity:** 375 square feet

**Sample Photo:**



**Sample Name:** 1-FTM-BD6065-2

**Sample Date:** 12/14/2021

**Sample Location:** South room, southwest corner of former crew quarters

**Type of Sample:** Brown floor tile with black mastic

**Is it friable?:** No

**Assessment Category:** ACBM with potential for damage

**Quantity:** 375 square feet

**Sample Photo:**





**Sample Name:** 5-PB-BD6065-8

**Sample Date:** 12/14/2021

**Sample Location:** Circuit breaker in northwest room of former crew quarters

**Type of Sample:** Lead paint chip

**Sample Description:** Gray paint

**Quantity:** 6 square feet

**Sample Photo:**



**Sample Name:** 6-PB-BD6065-10

**Sample Date:** 12/14/2021

**Sample Location:** Northwest room, west wall support beam in former crew quarters

**Type of Sample:** Lead paint chip

**Sample Description:** Red paint

**Quantity:** 2 square feet

**Sample Photo:**



**Sample Name:** 7-PB-BD6065-11

**Sample Date:** 12/14/2021

**Sample Location:** Back of stairs in former crew quarters

**Type of Sample:** Lead paint chip

**Sample Description:** Black paint

**Quantity:** 80 square feet

**Sample Photo:**



**Sample Name:** 7-PB-BD6065-12

**Sample Date:** 12/14/2021

**Sample Location:** Stair railing in former crew quarters

**Type of Sample:** Lead paint chip

**Sample Description:** Black paint

**Quantity:** 80 square feet

**Sample Photo:**



**Sample Name:** 9-PB-BD6065-14

**Sample Date:** 12/14/2021

**Sample Location:** Doorway between south and northwest rooms of former crew quarters

**Type of Sample:** Lead paint chip

**Sample Description:** Orange paint

**Quantity:** 4 square feet

**Sample Photo:**





**Sample Name:** 9-PB-BD6065-15

**Sample Date:** 12/14/2021

**Sample Location:** Center support beam in south roof of former crew quarters

**Type of Sample:** Lead paint chip

**Sample Description:** White paint

**Quantity:** 450 square feet


**Sample Photo:**





**Sample Name:** 11-PB-BD6065-18  
**Sample Date:** 12/14/2021  
**Sample Location:** Northeast deck of float crane  
**Type of Sample:** Lead paint chip  
**Sample Description:** Red paint  
**Quantity:** 1,750 square feet

**Sample Photo:**



**Sample Name:** 12-PB-BD6065-19

**Sample Date:** 12/14/2021


**Sample Location:** Tie down on northeast portion of float crane deck

**Type of Sample:** Lead paint chip

**Sample Description:** Yellow paint

**Quantity:** 200 square feet

**Sample Photo:**



**Sample Name:** 13-PB-BD6065-20

**Sample Date:** 12/14/2021

**Sample Location:** Adjacent to foot of crane, east end of float crane deck

**Type of Sample:** Lead paint chip

**Sample Description:** Pale yellow paint

**Quantity:** 400 square feet

**Sample Photo:**



**Sample Name:** 12-PB-BD6065-31

**Sample Date:** 12/14/2021

**Sample Location:** Rope tie down on west end of float crane deck

**Type of Sample:** Lead paint chip

**Sample Description:** Yellow paint

**Quantity:** 200 square feet

**Sample Photo:**





**Sample Name:** 13-PB-BD6065-32

**Sample Date:** 12/14/2021

**Sample Location:** Stipes on bottom of gray structure on float crane deck

**Type of Sample:** Lead paint chip

**Sample Description:** Pale gray/yellow paint

**Quantity:** 32 square feet

**Sample Photo:**



# ATTACHMENT C

LABORATORY REPORTS



December 21, 2021



Emily Curtis  
Maul Foster & Alongi, Inc.  
109 E 13th St.  
Vancouver, WA 98660

**RE: Bulk Asbestos Fiber Analysis; NVL Batch # 2121928.00**

Client Project: 0232.25.27  
Location: Portland, OR

Dear Mrs. Curtis,

Enclosed please find test results for the 30 sample(s) submitted to our laboratory for analysis on 12/16/2021.

Examination of these samples was conducted for the presence of identifiable asbestos fibers using polarized light microscopy (PLM) with dispersion staining in accordance with **U. S. EPA 40 CFR Appendix E to Subpart E of Part 763**, Interim Method for the Determination of Asbestos in Bulk Insulation Samples and **EPA 600/R-93/116**, Method for the Determination of Asbestos in Bulk Building Materials.

For samples containing more than one separable layer of materials, the report will include findings for each layer (labeled Layer 1 and Layer 2, etc. for each individual layer). The asbestos concentration in the sample is determined by calibrated visual estimation.

For those samples with asbestos concentrations between 1 and 10 percent based on visual estimation, the EPA recommends a procedure known as point counting (NESHAPS, 40 CFR Part 61). Point counting is a statistically more accurate means of quantification for samples with low concentrations of asbestos.

The detection limit for the calibrated visual estimation is <1%, 400 point counts is 0.25% and 1000 point counts is 0.1%

Samples are archived for two weeks following analysis. Samples that are not retrieved by the client are discarded after two weeks.

Thank you for using our laboratory services. Please do not hesitate to call if there is anything further we can assist you with.

Sincerely,

A handwritten signature in black ink, appearing to read 'Nick Ly', written over a white background.

Nick Ly, Technical Director

The logo for NVLAP (National Voluntary Laboratory Accreditation Program). It consists of the letters 'NVLAP' in a large, stylized, outlined font. The 'V' and 'L' are particularly large and prominent.

Lab Code: 102063-0

Enc.: Sample Results

**Phone: 206 547.0100 | Fax: 206 634.1936 | Toll Free: 1.888.NVL.LABS (685.5227)**  
**4708 Aurora Avenue North | Seattle, WA 98103-6516**



# Bulk Asbestos Fibers Analysis

By Polarized Light Microscopy

Client: Maul Foster & Alongi, Inc.

Address: 109 E 13th St.

Vancouver, WA 98660

**Attention: Mrs. Emily Curtis**

Project Location: Portland, OR

**Batch #: 2121928.00**

Client Project #: 0232.25.27

Date Received: 12/16/2021

Samples Received: 30

Samples Analyzed: 30

Method: EPA/600/R-93/116

**Lab ID: 21145692**      **Client Sample #: 1-CM-JT-1**

Location: Portland, OR

Comments: Unsure of correct layer sequence.

**Layer 1 of 3**      **Description:** Tan woven fibrous material

Non-Fibrous Materials:

Binder/Filler, Fine particles

Other Fibrous Materials: %

Synthetic fibers 72%

**Asbestos Type: %**

**None Detected ND**

**Layer 2 of 3**      **Description:** Light brown woven fibrous mesh

Non-Fibrous Materials:

Binder/Filler, Fine particles

Other Fibrous Materials: %

Cellulose 70%

**Asbestos Type: %**

**None Detected ND**

**Layer 3 of 3**      **Description:** Tan fluffy fibrous material

Non-Fibrous Materials:

Binder/Filler, Fine particles

Other Fibrous Materials: %

Cellulose 59%

**Asbestos Type: %**

**None Detected ND**

Synthetic fibers 20%

**Lab ID: 21145693**      **Client Sample #: 1-CM-JT-2**

Location: Portland, OR

**Layer 1 of 3**      **Description:** Tan woven fibrous material with beige mastic

Non-Fibrous Materials:

Binder/Filler, Fine particles, Mastic/Binder

Other Fibrous Materials: %

Synthetic fibers 68%

**Asbestos Type: %**

**None Detected ND**

**Layer 2 of 3**      **Description:** Light brown woven fibrous mesh

Non-Fibrous Materials:

Binder/Filler, Fine particles

Other Fibrous Materials: %

Cellulose 72%

**Asbestos Type: %**

**None Detected ND**

**Layer 3 of 3**      **Description:** Tan fluffy fibrous material

Non-Fibrous Materials:

Binder/Filler, Fine particles

Other Fibrous Materials: %

Cellulose 43%

**Asbestos Type: %**

**None Detected ND**

Synthetic fibers 38%

**Sampled by:** Client

**Analyzed by:** Hilary Crumley

**Reviewed by:** Nick Ly

**Date:** 12/21/2021

**Date:** 12/21/2021

Nick Ly, Technical Director

Note: If samples are not homogeneous, then subsamples of the components were analyzed separately. All bulk samples are analyzed using both EPA 600/R-93/116 and 600/M4-82-020 Methods with the following measurement uncertainties for the reported % Asbestos (1%=0-3%, 5%=1-9%, 10%=5-15%, 20%=10-30%, 50%=40-60%). This report relates only to the items tested. If sample was not collected by NVL personnel, then the accuracy of the results is limited by the methodology and acuity of the sample collector. This report shall not be reproduced except in full, without written approval of NVL Laboratories, Inc. It shall not be used to claim product endorsement by NVLAP or any other agency of the US Government





# Bulk Asbestos Fibers Analysis

By Polarized Light Microscopy

Client: Maul Foster & Alongi, Inc.  
Address: 109 E 13th St.  
Vancouver, WA 98660

**Batch #: 2121928.00**

Client Project #: 0232.25.27

Date Received: 12/16/2021

Samples Received: 30

Samples Analyzed: 30

Method: EPA/600/R-93/116

**Attention: Mrs. Emily Curtis**

Project Location: Portland, OR

**Lab ID: 21145694 Client Sample #: 2-IN-JT-3**

Location: Portland, OR

**Layer 1 of 1 Description:** Yellow fluffy fibrous material with wood debris

Non-Fibrous Materials:	Other Fibrous Materials: %
Binder/Filler, Glass debris, Debris	Glass fibers 95%
Insect parts, Wood flakes	

**Asbestos Type: %  
None Detected ND**

**Lab ID: 21145695 Client Sample #: 2-IN-JT-4**

Location: Portland, OR

**Layer 1 of 1 Description:** Pink fluffy fibrous material with wood debris

Non-Fibrous Materials:	Other Fibrous Materials: %
Binder/Filler, Glass debris, Wood flakes	Glass fibers 97%
Debris	

**Asbestos Type: %  
None Detected ND**

**Lab ID: 21145696 Client Sample #: 3-CP-JT-5**

Location: Portland, OR

**Layer 1 of 1 Description:** Thin gray crumbly material with paint on wood with debris

Non-Fibrous Materials:	Other Fibrous Materials: %
Binder/Filler, Fine particles, Paint	Cellulose <1%
Wood, Debris	

**Asbestos Type: %  
None Detected ND**

**Lab ID: 21145697 Client Sample #: 2-IN-JT-6**

Location: Portland, OR

**Layer 1 of 1 Description:** Pink fluffy fibrous material with debris

Non-Fibrous Materials:	Other Fibrous Materials: %
Binder/Filler, Glass debris, Debris	Cellulose 96%

**Asbestos Type: %  
None Detected ND**

**Sampled by:** Client

**Analyzed by:** Hilary Crumley

**Reviewed by:** Nick Ly

**Date:** 12/21/2021

**Date:** 12/21/2021

Nick Ly, Technical Director

Note: If samples are not homogeneous, then subsamples of the components were analyzed separately. All bulk samples are analyzed using both EPA 600/R-93/116 and 600/M4-82-020 Methods with the following measurement uncertainties for the reported % Asbestos (1%=0-3%, 5%=1-9%, 10%=5-15%, 20%=10-30%, 50%=40-60%). This report relates only to the items tested. If sample was not collected by NVL personnel, then the accuracy of the results is limited by the methodology and acuity of the sample collector. This report shall not be reproduced except in full, without written approval of NVL Laboratories, Inc. It shall not be used to claim product endorsement by NVLAP or any other agency of the US Government



# Bulk Asbestos Fibers Analysis

By Polarized Light Microscopy

Client: Maul Foster & Alongi, Inc.  
Address: 109 E 13th St.  
Vancouver, WA 98660

**Batch #: 2121928.00**

Client Project #: 0232.25.27

Date Received: 12/16/2021

Samples Received: 30

Samples Analyzed: 30

Method: EPA/600/R-93/116

**Attention: Mrs. Emily Curtis**

Project Location: Portland, OR

**Lab ID: 21145698 Client Sample #: 3-CP-JT-7**

Location: Portland, OR

Comments: Small amount for analysis.

**Layer 1 of 1 Description:** Trace gray crumbly material with paint on wood with debris

Non-Fibrous Materials:	Other Fibrous Materials:%
Binder/Filler, Fine particles, Paint	Cellulose 1%
Debris, Wood	

**Asbestos Type: %**  
**None Detected ND**

**Lab ID: 21145699 Client Sample #: 4-VC-JT-8**

Location: Portland, OR

**Layer 1 of 2 Description:** Brown flat hard compressed fibrous material with brown patterned surface

Non-Fibrous Materials:	Other Fibrous Materials:%
Binder/Filler, Fine particles	Cellulose 54%

**Asbestos Type: %**  
**None Detected ND**

**Layer 2 of 2 Description:** Thin yellow mastic with wood debris

Non-Fibrous Materials:	Other Fibrous Materials:%
Mastic/Binder, Fine particles, Debris	Cellulose <1%

**Asbestos Type: %**  
**None Detected ND**

**Lab ID: 21145700 Client Sample #: 5-VFT-JT-9**

Location: Portland, OR

**Layer 1 of 2 Description:** Tan vinyl material

Non-Fibrous Materials:	Other Fibrous Materials:%
Vinyl/Binder, Fine grains, Fine particles	Cellulose 13%

**Asbestos Type: %**  
**None Detected ND**

**Layer 2 of 2 Description:** Black asphaltic fibrous backing with brown mastic

Non-Fibrous Materials:	Other Fibrous Materials:%
Adhesive/Binder, Fine particles, Mastic/Binder	Cellulose 55%

**Asbestos Type: %**  
**None Detected ND**

**Lab ID: 21145701 Client Sample #: 5-VFT-JT-10**

Location: Portland, OR

**Sampled by:** Client

**Analyzed by:** Hilary Crumley

**Reviewed by:** Nick Ly

**Date:** 12/21/2021

**Date:** 12/21/2021

Nick Ly, Technical Director

Note: If samples are not homogeneous, then subsamples of the components were analyzed separately. All bulk samples are analyzed using both EPA 600/R-93/116 and 600/M4-82-020 Methods with the following measurement uncertainties for the reported % Asbestos (1%=0-3%, 5%=1-9%, 10%=5-15%, 20%=10-30%, 50%=40-60%). This report relates only to the items tested. If sample was not collected by NVL personnel, then the accuracy of the results is limited by the methodology and acuity of the sample collector. This report shall not be reproduced except in full, without written approval of NVL Laboratories, Inc. It shall not be used to claim product endorsement by NVLAP or any other agency of the US Government



# Bulk Asbestos Fibers Analysis

By Polarized Light Microscopy

Client: Maul Foster & Alongi, Inc.  
Address: 109 E 13th St.  
Vancouver, WA 98660

**Attention: Mrs. Emily Curtis**  
Project Location: Portland, OR

**Batch #: 2121928.00**  
Client Project #: 0232.25.27  
Date Received: 12/16/2021  
Samples Received: 30  
Samples Analyzed: 30  
Method: EPA/600/R-93/116

<b>Layer 1 of 2</b>	<b>Description:</b> Tan vinyl material with debris Non-Fibrous Materials: Vinyl/Binder, Fine grains, Fine particles Debris	Other Fibrous Materials:% Cellulose 15%	<b>Asbestos Type: %</b> <b>None Detected ND</b>
<b>Layer 2 of 2</b>	<b>Description:</b> Black asphaltic fibrous backing with debris Non-Fibrous Materials: Asphalt/Binder, Fine particles, Debris	Other Fibrous Materials:% Cellulose 53%	<b>Asbestos Type: %</b> <b>None Detected ND</b>
<b>Lab ID: 21145702      Client Sample #: 6-VC-JT-11</b> Location: Portland, OR			
<b>Layer 1 of 2</b>	<b>Description:</b> Brown flat hard compressed fibrous material with orange surface Non-Fibrous Materials: Binder/Filler, Fine particles	Other Fibrous Materials:% Cellulose 54%	<b>Asbestos Type: %</b> <b>None Detected ND</b>
<b>Layer 2 of 2</b>	<b>Description:</b> Tan soft mastic with wood debris Non-Fibrous Materials: Mastic/Binder, Fine particles, Wood flakes	Other Fibrous Materials:% Cellulose <1%	<b>Asbestos Type: %</b> <b>None Detected ND</b>
<b>Lab ID: 21145703      Client Sample #: 7-SM-JT-12</b> Location: Portland, OR			
<b>Layer 1 of 1</b>	<b>Description:</b> White foamy material with debris Non-Fibrous Materials: Binder/Filler, Synthetic foam, Debris	Other Fibrous Materials:% None Detected ND	<b>Asbestos Type: %</b> <b>None Detected ND</b>
<b>Lab ID: 21145704      Client Sample #: 8-SM-JT-13</b> Location: Portland, OR			
<b>Layer 1 of 1</b>	<b>Description:</b> Clear rubbery material with thin paint and debris Non-Fibrous Materials: Binder/Filler, Fine particles, Paint	Other Fibrous Materials:% Cellulose <1%	<b>Asbestos Type: %</b> <b>None Detected ND</b>

**Sampled by:** Client

**Analyzed by:** Hilary Crumley

**Reviewed by:** Nick Ly

**Date:** 12/21/2021

**Date:** 12/21/2021

  
Nick Ly, Technical Director

Note: If samples are not homogeneous, then subsamples of the components were analyzed separately. All bulk samples are analyzed using both EPA 600/R-93/116 and 600/M4-82-020 Methods with the following measurement uncertainties for the reported % Asbestos (1%=0-3%, 5%=1-9%, 10%=5-15%, 20%=10-30%, 50%=40-60%). This report relates only to the items tested. If sample was not collected by NVL personnel, then the accuracy of the results is limited by the methodology and acuity of the sample collector. This report shall not be reproduced except in full, without written approval of NVL Laboratories, Inc. It shall not be used to claim product endorsement by NVLAP or any other agency of the US Government



# Bulk Asbestos Fibers Analysis

By Polarized Light Microscopy

Client: Maul Foster & Alongi, Inc.  
Address: 109 E 13th St.  
Vancouver, WA 98660

**Attention: Mrs. Emily Curtis**  
Project Location: Portland, OR

**Batch #: 2121928.00**  
Client Project #: 0232.25.27  
Date Received: 12/16/2021  
Samples Received: 30  
Samples Analyzed: 30  
Method: EPA/600/R-93/116

## Debris

**Lab ID: 21145705**      **Client Sample #: 9-ROOF-JT-14**

Location: Portland, OR

**Layer 1 of 2**      **Description:** White soft coating with debris

Non-Fibrous Materials:

Other Fibrous Materials:%

**Asbestos Type: %**

Binder/Filler, Fine particles, Debris

None Detected    ND

**None Detected ND**

**Layer 2 of 2**      **Description:** Silver paint with debris

Non-Fibrous Materials:

Other Fibrous Materials:%

**Asbestos Type: %**

Paint/Binder, Metallic paint, Debris

Cellulose <1%

**Chrysotile 4%**

**Lab ID: 21145706**      **Client Sample #: 10-ROOF-JT-15**

Location: Portland, OR

**Layer 1 of 1**      **Description:** Silver crumbly rubbery material

Non-Fibrous Materials:

Other Fibrous Materials:%

**Asbestos Type: %**

Binder/Filler, Fine grains, Fine particles

None Detected    ND

**Chrysotile 7%**

**Lab ID: 21145707**      **Client Sample #: 9-ROOF-JT-16**

Location: Portland, OR

Comments: Wet sample was dried prior to analysis. Unsure of correct layer sequence.

**Layer 1 of 4**      **Description:** White soft rubbery coating with debris

Non-Fibrous Materials:

Other Fibrous Materials:%

**Asbestos Type: %**

Binder/Filler, Fine particles, Debris

None Detected    ND

**None Detected ND**

**Layer 2 of 4**      **Description:** Silver paint

Non-Fibrous Materials:

Other Fibrous Materials:%

**Asbestos Type: %**

Paint/Binder, Metallic paint

None Detected    ND

**Chrysotile 4%**

**Sampled by:** Client

**Analyzed by:** Hilary Crumley

**Reviewed by:** Nick Ly

**Date:** 12/21/2021

**Date:** 12/21/2021

Nick Ly, Technical Director

Note: If samples are not homogeneous, then subsamples of the components were analyzed separately. All bulk samples are analyzed using both EPA 600/R-93/116 and 600/M4-82-020 Methods with the following measurement uncertainties for the reported % Asbestos (1%=0-3%, 5%=1-9%, 10%=5-15%, 20%=10-30%, 50%=40-60%). This report relates only to the items tested. If sample was not collected by NVL personnel, then the accuracy of the results is limited by the methodology and acuity of the sample collector. This report shall not be reproduced except in full, without written approval of NVL Laboratories, Inc. It shall not be used to claim product endorsement by NVLAP or any other agency of the US Government





# Bulk Asbestos Fibers Analysis

By Polarized Light Microscopy

Client: Maul Foster & Alongi, Inc.  
Address: 109 E 13th St.  
Vancouver, WA 98660

**Attention: Mrs. Emily Curtis**  
Project Location: Portland, OR

**Batch #: 2121928.00**  
Client Project #: 0232.25.27  
Date Received: 12/16/2021  
Samples Received: 30  
Samples Analyzed: 30  
Method: EPA/600/R-93/116

Layer 3 of 4	Description: Black asphaltic crumbly material	Non-Fibrous Materials:	Other Fibrous Materials:%	Asbestos Type: % None Detected ND
		Asphalt/Binder, Fine particles, Fine grains	Cellulose 12%	
Layer 4 of 4	Description: Thin silver paint	Non-Fibrous Materials:	Other Fibrous Materials:%	Asbestos Type: % Chrysotile 3%
		Paint/Binder, Metallic paint	Cellulose 1%	

**Lab ID: 21145708**      **Client Sample #: 1-FTM-BD6065-1**

Location: Portland, OR

Layer 1 of 2	Description: Green vinyl tile with debris	Non-Fibrous Materials:	Other Fibrous Materials:%	Asbestos Type: % Chrysotile 2%
		Vinyl/Binder, Fine grains, Fine particles	None Detected ND	
Layer 2 of 2	Description: Black asphaltic mastic with paint and debris	Non-Fibrous Materials:	Other Fibrous Materials:%	Asbestos Type: % Chrysotile 3%
		Asphalt/Binder, Fine particles, Paint	None Detected ND	

**Lab ID: 21145709**      **Client Sample #: 1-FTM-BD6065-2**

Location: Portland, OR

Comments: Unable to separate mastics for analysis, asbestos concentrated in black mastic.

Layer 1 of 2	Description: Green vinyl tile with debris	Non-Fibrous Materials:	Other Fibrous Materials:%	Asbestos Type: % Chrysotile 3%
		Vinyl/Binder, Fine grains, Fine particles	None Detected ND	

**Sampled by:** Client

**Analyzed by:** Hilary Crumley

**Reviewed by:** Nick Ly

**Date:** 12/21/2021

**Date:** 12/21/2021

Nick Ly, Technical Director

Note: If samples are not homogeneous, then subsamples of the components were analyzed separately. All bulk samples are analyzed using both EPA 600/R-93/116 and 600/M4-82-020 Methods with the following measurement uncertainties for the reported % Asbestos (1%=0-3%, 5%=1-9%, 10%=5-15%, 20%=10-30%, 50%=40-60%). This report relates only to the items tested. If sample was not collected by NVL personnel, then the accuracy of the results is limited by the methodology and acuity of the sample collector. This report shall not be reproduced except in full, without written approval of NVL Laboratories, Inc. It shall not be used to claim product endorsement by NVLAP or any other agency of the US Government



# Bulk Asbestos Fibers Analysis

By Polarized Light Microscopy

Client: Maul Foster & Alongi, Inc.  
Address: 109 E 13th St.  
Vancouver, WA 98660

**Attention: Mrs. Emily Curtis**  
Project Location: Portland, OR

**Batch #: 2121928.00**  
Client Project #: 0232.25.27  
Date Received: 12/16/2021  
Samples Received: 30  
Samples Analyzed: 30  
Method: EPA/600/R-93/116

---

<b>Layer 2 of 2</b>	<b>Description:</b> Black asphaltic mastic with thin yellow mastic and debris		
	Non-Fibrous Materials:	Other Fibrous Materials: %	<b>Asbestos Type: %</b>
	Asphalt/Binder, Fine particles, Mastic/Binder	Cellulose <1%	<b>Chrysotile 4%</b>
	Debris		

---

**Lab ID: 21145710**      **Client Sample #: 2-WI-BD6065-3**

Location: Portland, OR

<b>Layer 1 of 2</b>	<b>Description:</b> White woven fibrous material with paint and yellow soft mastic		
	Non-Fibrous Materials:	Other Fibrous Materials: %	<b>Asbestos Type: %</b>
	Binder/Filler, Glass debris, Paint	Glass fibers 75%	<b>None Detected ND</b>
	Mastic/Binder		

<b>Layer 2 of 2</b>	<b>Description:</b> Yellow fluffy fibrous material		
	Non-Fibrous Materials:	Other Fibrous Materials: %	<b>Asbestos Type: %</b>
	Binder/Filler, Glass debris	Glass fibers 96%	<b>None Detected ND</b>

---

**Lab ID: 21145711**      **Client Sample #: 3-MCT-BD6065-4**

Location: Portland, OR

<b>Layer 1 of 2</b>	<b>Description:</b> Tan ceramic material		
	Non-Fibrous Materials:	Other Fibrous Materials: %	<b>Asbestos Type: %</b>
	Ceramic/Binder, Fine particles	None Detected ND	<b>None Detected ND</b>

<b>Layer 2 of 2</b>	<b>Description:</b> Green crumbly mastic		
	Non-Fibrous Materials:	Other Fibrous Materials: %	<b>Asbestos Type: %</b>
	Mastic/Binder, Fine particles	None Detected ND	<b>None Detected ND</b>

---

**Lab ID: 21145712**      **Client Sample #: 3-MCT-BD6065-5**

Location: Portland, OR

**Sampled by:** Client

**Analyzed by:** Hilary Crumley

**Reviewed by:** Nick Ly

**Date:** 12/21/2021

**Date:** 12/21/2021

Nick Ly, Technical Director

Note: If samples are not homogeneous, then subsamples of the components were analyzed separately. All bulk samples are analyzed using both EPA 600/R-93/116 and 600/M4-82-020 Methods with the following measurement uncertainties for the reported % Asbestos (1%=0-3%, 5%=1-9%, 10%=5-15%, 20%=10-30%, 50%=40-60%). This report relates only to the items tested. If sample was not collected by NVL personnel, then the accuracy of the results is limited by the methodology and acuity of the sample collector. This report shall not be reproduced except in full, without written approval of NVL Laboratories, Inc. It shall not be used to claim product endorsement by NVLAP or any other agency of the US Government



# Bulk Asbestos Fibers Analysis

By Polarized Light Microscopy

Client: Maul Foster & Alongi, Inc.

Address: 109 E 13th St.

Vancouver, WA 98660

**Attention: Mrs. Emily Curtis**

Project Location: Portland, OR

**Batch #: 2121928.00**

Client Project #: 0232.25.27

Date Received: 12/16/2021

Samples Received: 30

Samples Analyzed: 30

Method: EPA/600/R-93/116

Layer 1 of 2	Description: Tan ceramic material	Non-Fibrous Materials:	Other Fibrous Materials:%	Asbestos Type: %
		Ceramic/Binder, Fine particles	None Detected ND	
Layer 2 of 2	Description: Green crumbly mastic with debris	Non-Fibrous Materials:	Other Fibrous Materials:%	Asbestos Type: %
		Mastic/Binder, Fine particles, Debris	Cellulose <1%	

**Lab ID: 21145713 Client Sample #: 2-WI-BD6065-6**

Location: Portland, OR

Layer 1 of 2	Description: White woven fibrous material with paint and yellow mastic	Non-Fibrous Materials:	Other Fibrous Materials:%	Asbestos Type: %
		Binder/Filler, Mastic/Binder, Paint	Glass fibers 77%	
Layer 2 of 2	Description: Yellow fluffy fibrous material	Non-Fibrous Materials:	Other Fibrous Materials:%	Asbestos Type: %
		Binder/Filler, Fine particles, Glass debris	Glass fibers 97%	

**Lab ID: 21145714 Client Sample #: 4-WT-BD6065-7**

Location: Portland, OR

Comments: Small amount of layer 2 for analysis.

Layer 1 of 2	Description: Off-white ceramic tile	Non-Fibrous Materials:	Other Fibrous Materials:%	Asbestos Type: %
		Ceramic/Binder, Fine particles, Fine grains	None Detected ND	
Layer 2 of 2	Description: Trace gray brittle material	Non-Fibrous Materials:	Other Fibrous Materials:%	Asbestos Type: %
		Binder/Filler, Fine grains, Fine particles	None Detected ND	

**Lab ID: 21145715 Client Sample #: 5-HFT-BD6065-8**

Location: Portland, OR

**Sampled by:** Client

**Analyzed by:** Hilary Crumley

**Reviewed by:** Nick Ly

**Date:** 12/21/2021

**Date:** 12/21/2021

Nick Ly, Technical Director

Note: If samples are not homogeneous, then subsamples of the components were analyzed separately. All bulk samples are analyzed using both EPA 600/R-93/116 and 600/M4-82-020 Methods with the following measurement uncertainties for the reported % Asbestos (1%=0-3%, 5%=1-9%, 10%=5-15%, 20%=10-30%, 50%=40-60%). This report relates only to the items tested. If sample was not collected by NVL personnel, then the accuracy of the results is limited by the methodology and acuity of the sample collector. This report shall not be reproduced except in full, without written approval of NVL Laboratories, Inc. It shall not be used to claim product endorsement by NVLAP or any other agency of the US Government



# Bulk Asbestos Fibers Analysis

By Polarized Light Microscopy

Client: Maul Foster & Alongi, Inc.  
Address: 109 E 13th St.  
Vancouver, WA 98660

**Attention: Mrs. Emily Curtis**  
Project Location: Portland, OR

**Batch #: 2121928.00**  
Client Project #: 0232.25.27  
Date Received: 12/16/2021  
Samples Received: 30  
Samples Analyzed: 30  
Method: EPA/600/R-93/116

Layer 1 of 2	Description: Off-white ceramic tile with tan surface	Non-Fibrous Materials:	Other Fibrous Materials:%	Asbestos Type: %
		Ceramic/Binder, Fine particles, Fine grains	None Detected ND	
Layer 2 of 2	Description: Thin white crumbly material	Non-Fibrous Materials:	Other Fibrous Materials:%	Asbestos Type: %
		Binder/Filler, Fine grains, Fine particles	None Detected ND	

**Lab ID: 21145716 Client Sample #: 6-SWT-BD6065-9**

Location: Portland, OR

Layer 1 of 2	Description: Off-white ceramic tile	Non-Fibrous Materials:	Other Fibrous Materials:%	Asbestos Type: %
		Ceramic/Binder, Fine particles, Fine grains	None Detected ND	
Layer 2 of 2	Description: Thin gray brittle material	Non-Fibrous Materials:	Other Fibrous Materials:%	Asbestos Type: %
		Binder/Filler, Fine grains, Fine particles	None Detected ND	

**Lab ID: 21145717 Client Sample #: 7-WC-BD6065-10**

Location: Portland, OR

Layer 1 of 1	Description: Off-white crumbly material with paint and debris	Non-Fibrous Materials:	Other Fibrous Materials:%	Asbestos Type: %
		Binder/Filler, Fine particles, Paint	None Detected ND	
		Debris		

**Lab ID: 21145718 Client Sample #: 8-ST-BD6065-11**

Location: Portland, OR

Layer 1 of 1	Description: Off-white woven fibrous mesh with off-white mastic and gray plastic coating	Non-Fibrous Materials:	Other Fibrous Materials:%	Asbestos Type: %
		Binder/Filler, Mastic/Binder, Plastic	Cellulose 65%	

**Sampled by:** Client

**Analyzed by:** Hilary Crumley

**Reviewed by:** Nick Ly

**Date:** 12/21/2021

**Date:** 12/21/2021

Nick Ly, Technical Director

Note: If samples are not homogeneous, then subsamples of the components were analyzed separately. All bulk samples are analyzed using both EPA 600/R-93/116 and 600/M4-82-020 Methods with the following measurement uncertainties for the reported % Asbestos (1%=0-3%, 5%=1-9%, 10%=5-15%, 20%=10-30%, 50%=40-60%). This report relates only to the items tested. If sample was not collected by NVL personnel, then the accuracy of the results is limited by the methodology and acuity of the sample collector. This report shall not be reproduced except in full, without written approval of NVL Laboratories, Inc. It shall not be used to claim product endorsement by NVLAP or any other agency of the US Government





# Bulk Asbestos Fibers Analysis

By Polarized Light Microscopy

Client: Maul Foster & Alongi, Inc.  
Address: 109 E 13th St.  
Vancouver, WA 98660

**Batch #: 2121928.00**

Client Project #: 0232.25.27

Date Received: 12/16/2021

Samples Received: 30

Samples Analyzed: 30

Method: EPA/600/R-93/116

**Attention: Mrs. Emily Curtis**

Project Location: Portland, OR

**Lab ID: 21145719 Client Sample #: 9-SFT-BD6065-12**

Location: Portland, OR

**Layer 1 of 2 Description:** Off-white ceramic tile with debris

Non-Fibrous Materials:

Other Fibrous Materials:%

**Asbestos Type: %**

Ceramic/Binder, Fine particles, Debris

None Detected ND

**None Detected ND**

**Layer 2 of 2 Description:** White fibrous material with off-white mastic and debris

Non-Fibrous Materials:

Other Fibrous Materials:%

**Asbestos Type: %**

Binder/Filler, Mastic/Binder, Fine particles

Cellulose 50%

**None Detected ND**

**Lab ID: 21145720 Client Sample #: 10-WCF-BD6065-13**

Location: Portland, OR

**Layer 1 of 1 Description:** Pale green fibrous material with layered paint and debris

Non-Fibrous Materials:

Other Fibrous Materials:%

**Asbestos Type: %**

Binder/Filler, Fine particles, Paint

Cellulose 76%

**None Detected ND**

Debris

**Lab ID: 21145721 Client Sample #: 11-BDG-BD6065-14**

Location: Portland, OR

**Layer 1 of 1 Description:** Black rubbery material with debris

Non-Fibrous Materials:

Other Fibrous Materials:%

**Asbestos Type: %**

Binder/Filler, Fine particles, Debris

Cellulose <1%

**None Detected ND**

**Sampled by:** Client

**Analyzed by:** Hilary Crumley

**Reviewed by:** Nick Ly

**Date:** 12/21/2021

**Date:** 12/21/2021

Nick Ly, Technical Director

Note: If samples are not homogeneous, then subsamples of the components were analyzed separately. All bulk samples are analyzed using both EPA 600/R-93/116 and 600/M4-82-020 Methods with the following measurement uncertainties for the reported % Asbestos (1%=0-3%, 5%=1-9%, 10%=5-15%, 20%=10-30%, 50%=40-60%). This report relates only to the items tested. If sample was not collected by NVL personnel, then the accuracy of the results is limited by the methodology and acuity of the sample collector. This report shall not be reproduced except in full, without written approval of NVL Laboratories, Inc. It shall not be used to claim product endorsement by NVLAP or any other agency of the US Government

# ASBESTOS LABORATORY SERVICES



**Company** Maul Foster & Alongi, Inc. **NVL Batch Number** 2121928.00  
**Address** 109 E 13th St. **TAT** 5 Days **AH** No  
 Vancouver, WA 98660 **Rush TAT**  
**Project Manager** Mrs. Emily Curtis **Due Date** 12/23/2021 **Time** 9:00 AM  
**Phone** (971) 544-2139 **Email** ecurtis@maulfoster.com  
**Fax**

**Project Name/Number:** 0232.25.27 **Project Location:** Portland, OR

**Subcategory** PLM Bulk

**Item Code** ASB-02 EPA 600/R-93-116 Asbestos by PLM <bulk>

**Total Number of Samples** 30

**Rush Samples**

	Lab ID	Sample ID	Description	A/R
1	21145692	1-CM-JT-1		A
2	21145693	1-CM-JT-2		A
3	21145694	2-IN-JT-3		A
4	21145695	2-IN-JT-4		A
5	21145696	3-CP-JT-5		A
6	21145697	2-IN-JT-6		A
7	21145698	3-CP-JT-7		A
8	21145699	4-VC-JT-8		A
9	21145700	5-VFT-JT-9		A
10	21145701	5-VFT-JT-10		A
11	21145702	6-VC-JT-11		A
12	21145703	7-SM-JT-12		A
13	21145704	8-SM-JT-13		A
14	21145705	9-ROOF-JT-14		A
15	21145706	10-ROOF-JT-15		A
16	21145707	9-ROOF-JT-16		A
17	21145708	1-FTM-BD6065-1		A
18	21145709	1-FTM-BD6065-2		A

	Print Name	Signature	Company	Date	Time
<b>Sampled by</b>	Client				
<b>Relinquished by</b>	Federal Express				

	Print Name	Signature	Company	Date	Time
<b>Received by</b>	Kelly AuVu		NVL	12/16/21	900
<b>Analyzed by</b>	Hilary Crumley		NVL	12/21/21	
<b>Results Called by</b>					
<input type="checkbox"/> <b>Faxed</b> <input type="checkbox"/> <b>Emailed</b>					

**Special Instructions:**

Date: 12/16/2021

Time: 9:22 AM

Entered By: Kelly AuVu

# ASBESTOS LABORATORY SERVICES



**Company** Maul Foster & Alongi, Inc. **NVL Batch Number** 2121928.00  
**Address** 109 E 13th St. **TAT** 5 Days **AH** No  
 Vancouver, WA 98660 **Rush TAT**  
**Project Manager** Mrs. Emily Curtis **Due Date** 12/23/2021 **Time** 9:00 AM  
**Phone** (971) 544-2139 **Email** ecurtis@maulfoster.com  
**Fax**

**Project Name/Number:** 0232.25.27 **Project Location:** Portland, OR

**Subcategory** PLM Bulk

**Item Code** ASB-02 EPA 600/R-93-116 Asbestos by PLM <bulk>

**Total Number of Samples** 30

**Rush Samples**

	Lab ID	Sample ID	Description	A/R
19	21145710	2-WI-BD6065-3		A
20	21145711	3-MCT-BD6065-4		A
21	21145712	3-MCT-BD6065-5		A
22	21145713	2-WI-BD6065-6		A
23	21145714	4-WT-BD6065-7		A
24	21145715	5-HFT-BD6065-8		A
25	21145716	6-SWT-BD6065-9		A
26	21145717	7-WC-BD6065-10		A
27	21145718	8-ST-BD6065-11		A
28	21145719	9-SFT-BD6065-12		A
29	21145720	10-WCF-BD6065-13		A
30	21145721	11-BDG-BD6065-14		A

	Print Name	Signature	Company	Date	Time
<b>Sampled by</b>	Client				
<b>Relinquished by</b>	Federal Express				

	Print Name	Signature	Company	Date	Time
<b>Received by</b>	Kelly AuVu		NVL	12/16/21	900
<b>Analyzed by</b>	Hilary Crumley		NVL	12/21/21	
<b>Results Called by</b>					
<input type="checkbox"/> Faxed <input type="checkbox"/> Emailed					

**Special Instructions:**

Date: 12/16/2021  
 Time: 9:22 AM  
 Entered By: Kelly AuVu

2121928



# ASBESTOS CHAIN OF CUSTODY

Turn Around Time

Standard TAT

☐ 1 Hour☐ 24 Hours☐ 4 Days☐ 2 Hours☐ 2 Days☐ 5 Days☐ 4 Hours☐ 3 Days☒ 10 Days

Please call for TAT less than 24 Hours

Company Maul Foster & Alongi  
 Address 3140 NE Broadway  
Portland, OR 97232  
 Phone 971-544-2139

Project Manager Emily Curtis  
 Cell (503) 501-5233  
 Email ecurtis@maulfoster.com  
 Fax ( )

Project Name/Number <u>0232.25.27</u>	Project Location <u>Portland, OR</u>
<input type="checkbox"/> PCM Air (NIOSH 7400) <input type="checkbox"/> TEM (NIOSH 7402) <input type="checkbox"/> TEM (AHERA) <input type="checkbox"/> TEM (EPA Level II Modified) <input checked="" type="checkbox"/> PLM (EPA 600/R-93-116) <input type="checkbox"/> EPA 400 Points (600/R-93-116) <input type="checkbox"/> EPA 1000 Points (600/R-93-116) <input type="checkbox"/> PLM Gravimetry (600/R-93-116) <input type="checkbox"/> Asbestos in Vermiculite (EPA 600/R-04/004) <input type="checkbox"/> Asbestos in Sediment (EPA 1900 Points) <input type="checkbox"/> Asbestos Friable/Non-Friable (EPA 600/R-93/116) <input type="checkbox"/> Other _____	

Reporting Instructions Report to Emily Curtis  
☐ Call ( ) ☐ Fax ( ) ☒ Email ecurtis@maulfoster.com

Total Number of Samples 30

Sample ID	Description	A/R
1-1-CM-JT-1	Green carpet with unidentifiable mastic	
2-1-CM-JT-2	Green carpet with unidentifiable mastic	
3-2-IN-JT-3	Insulation	
4-2-IN-JT-4	Insulation	
5-3-CP-JT-5	Wood ceiling panel with vinyl covering	
6-2-IN-JT-6	Insulation	
7-3-CP-JT-7	Wood ceiling panel with vinyl covering	
8-4-VC-JT-8	Brown Vinyl covering with clear mastic	
9-5-VFT-JT-9	Brown/tan speckled vinyl floor tile with black/brown mastic	
10-5-VFT-JT-10	Brown/tan speckled vinyl floor tile with Brown/black mastic	
11-6-VC-JT-11	Orange vinyl covering with yellow mastic	
12-7-SM-JT-12	White sealant material	
13-8-SM-JT-13	Gray sealant material	
14-9-ROOF-JT-14	White Coating material on metal roof	
15-10-ROOF-JT-15	Silver Penetration Sealant	

	Print Name	Signature	Company	Date	Time
Sampled by	Connor Anderson	<i>Connor Anderson</i>	MFA	12/14/21	1330
Relinquish by	Connor Anderson	<i>Connor Anderson</i>	MFA	12/15/21	1130

## Office Use Only

	Print Name	Signature	Company	Date	Time
Received by	<i>Kurtz</i>	<i>e</i>	<i>MFA</i>	12/16/21	900 AM
Analyzed by					
Called by					
Faxed/Email by					



2121928



# ASBESTOS CHAIN OF CUSTODY

Standard TAT

- ☐ 1 Hour    ☐ 24 Hours    ☐ 4 Days  
☐ 2 Hours    ☐ 2 Days    ☐ 5 Days  
☐ 4 Hours    ☐ 3 Days    ☒ 10 Days

Please call for TAT less than 24 Hours

Company Maul Foster & Alongi  
 Address 3140 NE Broadway  
Portland, OR 97232  
 Phone 971-544-2139

Project Manager Emily Curtis  
 Cell (503) 501-5233  
 Email ecurtis@maulfoster.com  
 Fax ( )

Project Name/Number 0232.25.27 Project Location Portland, OR

- ☐ PCM Air (NIOSH 7400)    ☐ TEM (NIOSH 7402)    ☐ TEM (AHERA)    ☐ TEM (EPA Level II Modified)  
☒ PLM (EPA 600/R-93-116)    ☐ EPA 400 Points (600/R-93-116)    ☐ EPA 1000 Points (600/R-93-116)  
☐ PLM Gravimetry (600/R-93-116)    ☐ Asbestos in Vermiculite (EPA 600/R-04/004)    ☐ Asbestos in Sediment (EPA 1900 Points)  
☐ Asbestos Friable/Non-Friable (EPA 600/R-93/116)    ☐ Other

Reporting Instructions Report to Emily Curtis  
☐ Call ( )    ☐ Fax ( )    ☒ Email ecurtis@maulfoster.com

Total Number of Samples 30

	Sample ID	Description	A/R
1	9-ROOF-JT-16	Silver Penetration Sealant	
2	1-FTM-BD6065-1	Floor tile with black mastic	
3	1-FTM-BD6065-2	Floor tile with black mastic	
4	2-WI-BD6065-3	Yellow insulation with woven white fabric	
5	3-MCT-BD6065-4	Multicolored tile with teal mastic	
6	3-MCT-BD6065-5	Multicolored tile with teal mastic	
7	2-WI-BD6065-6	Yellow insulation with woven fabric	
8	4-WT-BD6065-7	White 6"x6" wall tile with gray mastic	
9	5-HFT-BD6065-8	White hexagonal floor tile with white mastic	
10	6-SWT-BD6065-9	White 4"x4" wall tile with gray mastic	
11	7-WC-BD6065-10	White wall coating	
12	8-ST-BD6065-11	Gray metallic seal tape	
13	9-SFT-BD6065-12	White 1"x1" floor tile with white mastic	
14	10-WCF-BD6065-13	White ceiling fabric with white coating	
15	11-BDG-BD6065-14	Black door gasket	

	Print Name	Signature	Company	Date	Time
Sampled by	Connor Anderson	<i>Connor Anderson</i>	MFA	12/14/21	1330
Relinquish by	Connor Anderson	<i>Connor Anderson</i>	MFA	12/15/21	1130

## Office Use Only

	Print Name	Signature	Company	Date	Time
Received by	<i>Connor Anderson</i>	<i>Connor Anderson</i>	MFA	12/16/21	900 AM
Analyzed by					
Called by					
Faxed/Email by					

December 23, 2021

Emily Curtis

**Maul Foster & Alongi, Inc.**

109 E 13th St.

Vancouver, WA 98660



**NVL Batch # 2121932.00**

**RE: Total Metal Analysis**  
**Method: EPA 7000B Lead by FAA <paint>**  
**Item Code: FAA-02**

Client Project: 0232.25.27

Location: Portland, OR

Dear Mrs. Curtis,

NVL Labs received 4 sample(s) for the said project on 12/16/2021. Preparation of these samples was conducted following protocol outlined in EPA 3051/7000B , unless stated otherwise. Analysis of these samples was performed using analytical instruments in accordance with EPA 7000B Lead by FAA <paint>. The results are usually expressed in mg/Kg and percentage (%). Test results are not blank corrected.

For recent regulation updates pertaining to current regulatory levels or permissible exposure levels, please call your local regulatory agencies for more detail.

At NVL Labs all analyses are performed under strict guidelines of the Quality Assurance Program. This report is considered highly confidential and will not be released without your approval. Samples are archived after two weeks from the analysis date. Please feel free to contact us at 206-547-0100, in case you have any questions or concerns.

Sincerely,

A handwritten signature in black ink, appearing to read 'Nick Ly', written over a white background.

Nick Ly, Technical Director

Enc.: Sample results



Phone: 206 547.0100 | Fax: 206 634.1936 | Toll Free: 1.888.NVL.LABS (685.5227)  
4708 Aurora Avenue North | Seattle, WA 98103-6516

# Analysis Report

## Total Lead (Pb)



Client: Maul Foster & Alongi, Inc.  
Address: 109 E 13th St.  
Vancouver, WA 98660

**Batch #: 2121932.00**

Matrix: Paint  
Method: EPA 3051/7000B  
Client Project #: 0232.25.27  
Date Received: 12/16/2021  
Samples Received: 4  
Samples Analyzed: 4

**Attention: Mrs. Emily Curtis**

Project Location: Portland, OR

Lab ID	Client Sample #	Sample Weight (g)	RL in mg/Kg	Results in mg/Kg	Results in percent
21145736	6-PB-JT-11	0.2010	50	< 50	<0.0050
21145737	7-PB-BD6065-11	0.2239	45	9500	0.95
21145738	9-PB-BD6065-15	0.2018	50	4400	0.44
21145739	13-PB-BD6065-20	0.2070	48	770	0.077

Sampled by: Client

Analyzed by: Yasuyuki Hida

Reviewed by: Nick Ly

Date Analyzed: 12/22/2021

Date Issued: 12/23/2021

Nick Ly, Technical Director

mg/ Kg =Milligrams per kilogram

Percent = Milligrams per kilogram / 10000

Note : Method QC results are acceptable unless stated otherwise.

Unless otherwise indicated, the condition of all samples was acceptable at time of receipt.

RL = Reporting Limit

'<' = Below the reporting Limit

Bench Run No: 2021-1222-10

FAA-02

# LEAD LABORATORY SERVICES



**Company** Maul Foster & Alongi, Inc. **NVL Batch Number** 2121932.00  
**Address** 109 E 13th St. **TAT** 10 Days **AH** No  
 Vancouver, WA 98660 **Rush TAT** \_\_\_\_\_  
**Project Manager** Mrs. Emily Curtis **Due Date** 1/3/2022 **Time** 9:00 AM  
**Phone** (971) 544-2139 **Email** ecurtis@maulfoster.com  
**Fax** \_\_\_\_\_

**Project Name/Number:** 0232.25.27 **Project Location:** Portland, OR

**Subcategory** Flame AA (FAA)

**Item Code** FAA-02 EPA 7000B Lead by FAA <paint>

**Total Number of Samples** 4

**Rush Samples** \_\_\_\_\_

	Lab ID	Sample ID	Description	A/R
1	21145736	6-PB-JT-11		A
2	21145737	7-PB-BD6065-11		A
3	21145738	9-PB-BD6065-15		A
4	21145739	13-PB-BD6065-20		A

	Print Name	Signature	Company	Date	Time
<b>Sampled by</b>	Client				
<b>Relinquished by</b>	Federal Express				

Office Use Only	Print Name	Signature	Company	Date	Time
<b>Received by</b>	Kelly AuVu		NVL	12/16/21	900
<b>Analyzed by</b>	Yasuyuki Hida		NVL	12/22/21	
<b>Results Called by</b>					
<input type="checkbox"/> Faxed <input type="checkbox"/> Emailed					

**Special Instructions:** \_\_\_\_\_

Date: 12/16/2021  
 Time: 9:41 AM  
 Entered By: Kelly AuVu





# METALS CHAIN OF CUSTODY

# 2121932

Standard TAT

- ☐ 2 Hour    ☐ 4 Hours    ☐ 24 Hours  
☐ 2 Days    ☐ 3 Days    ☐ 4 Days  
☐ 5 Days    ☒ 6-10 Days  
Please call for TAT less than 24 Hours

Company Maul Foster & Alongi  
Address 3140 NE Broadway  
Portland, OR 97232  
Phone 971-544-2139

Project Manager Emily Curtis  
Cell (503) 501-5233  
Email ecurtis@maulfoster.com  
Fax ( ) -

Project Name/Number 0232.25.27 Project Location Portland, OR

<input checked="" type="checkbox"/> Total Metals	<input type="checkbox"/> FAA (ppm)	<input type="checkbox"/> Air Filter	<input checked="" type="checkbox"/> Paint Chips (%)	<input type="checkbox"/> Soil	RCRA 8	RCRA 11		
<input type="checkbox"/> TCLP	<input type="checkbox"/> ICP (PPM)	<input type="checkbox"/> Paint Chips (cm)	<input type="checkbox"/> Dust Wipes		<input type="checkbox"/> Barium	<input type="checkbox"/> Chromium	<input type="checkbox"/> Silver	<input type="checkbox"/> Copper
	<input type="checkbox"/> GFAA (ppb)	<input type="checkbox"/> Drinking Water	<input type="checkbox"/> Waste Water		<input type="checkbox"/> Arsenic	<input type="checkbox"/> Mercury	<input checked="" type="checkbox"/> Lead	<input type="checkbox"/> Zinc
	<input type="checkbox"/> CVAA (ppb)	<input type="checkbox"/> Other			<input type="checkbox"/> Selenium	<input type="checkbox"/> Cadmium		<input type="checkbox"/> Other

Reporting Instructions Report to Emily Curtis  
☐ Call ( ) - ☐ Fax ( ) - ☒ Email ecurtis@maulfoster.com

Total Number of Samples 4

	Sample ID	Description	A/R
1	<u>6-PB-JT-11</u>	<u>White paint</u>	
2	<u>7-PB-BD6065-11</u>	<u>Black paint</u>	
3	<u>9-PB-BD6065-15</u>	<u>White paint</u>	
4	<u>13-PB-BD6065-20</u>	<u>Pale yellow paint</u>	
5			
6			
7			
8			
9			
10			
11			
12			
13			
14			
15			

	Print Name	Signature	Company	Date	Time
Sampled by	<u>Connor Anderson</u>	<u>[Signature]</u>	<u>MFA</u>	<u>12/14/21</u>	<u>1330</u>
Relinquish by	<u>Connor Anderson</u>	<u>[Signature]</u>	<u>MFA</u>	<u>12/15/21</u>	<u>1130</u>

## Office Use Only

	Print Name	Signature	Company	Date	Time
Received by	<u>Kelly Allen</u>	<u>[Signature]</u>	<u>MFA</u>	<u>12/16/21</u>	<u>900 am</u>
Analyzed by					
Called by					
Faxed/Email by					



And Consultants

## CERTIFICATE OF INSPECTION

**NUMBER 23-03-81**

### **EQUIPMENT PARTICULARS**

Name of Equipment:	Dravo/Wellman
Type:	Barge Mounted Crane
Manufacturer:	Dravo
Model Number:	BD 6065
Serial Number:	NOY 24308
Owner:	Port of Portland
Date of Inspection:	14 March 2023
Inspection Due:	<b><i>No Later Than One Year from Inspection Date</i></b>

The above equipment was inspected under the purview of the regulations found in 29 CFR 1919 and ANSI B 30.8 (Standards for Floating Cranes & Floating Derricks.)

The unit was tested with an operational load of 16,000 pounds, at an 88 Foot Radius, 98 Feet of boom, as per mfg. Four-degree list load charts.

Charles Streeter  
Surveyor

Marine Surveyors and Consultants  
Accredited by USDL / OSHA

Marine Surveyors and Consultants  
P.O. Box 22123  
Milwaukie, OR 97269-2123

Portland 503-227-0287  
Fax 503-908-7796  
E-mail: [office@testyourcrane.com](mailto:office@testyourcrane.com)

# MARINE SURVEYORS AND CONSULTANTS

COMPREHENSIVE CRANE INSPECTION AND CERTIFICATION P.O. Box 22123, MILWAUKIE, OR 97269-2123  
 PHONE: (503) 227-0287 FAX: (503) 908-7796 EMAIL: office@testyourcrane.com

## REPORT OF EXAMINATION AND/OR TEST

JOB NO. **23-03-81** EQUIPMENT ID: **#28** LAST ANNUAL: **4/28/2022** LAST QUAD: **1/24/2019**  
 INSPECTION DATE: **14 MARCH 2023** ☒ THIRD PARTY ☐ WISHA #: \_\_\_\_\_ ☐ OSHA LAST #: \_\_\_\_\_ ☒ ANNUAL ☐ QUAD

### OWNER IDENTIFICATION:

OWNER: **PORT OF PORTLAND** CONTACT NAME: **MR. MARK WRIGHT**  
 ADDRESS: **6208 N. ENSIGN ST** CITY: **PORTLAND** STATE: **OR** ZIP: **97217** PHONE: **503-679-9794**  
 LEASED/RENTED ☐ YES ☒ NO LESSEE: ☐ LESSOR ☐ COMPANY NAME: \_\_\_\_\_

### EQUIPMENT DESCRIPTION:

TYPE: ☐ CRANE ☒ DERRICK DESCRIPTION: **BARGE MOUNTED**  
 MANUFACTURER: **DRAVO/WELLMAN** MODEL #: **BP-6065** SERIAL #: **NOY 24308**  
 TEST LOCATION: **6208 N. ENSIGN ST., PORTLAND, OREGON**  
 POWERED BY: ☐ SUPPLIED ELECTRIC ☐ ELECTRO-HYDRAULIC ☐ DIESEL-HYDRAULIC ☒ DIESEL OTHER: \_\_\_\_\_  
 SERVICE STATUS: ☒ LIFTING ☐ CLAMSHELL ☐ MAGNET ☐ OTHER: \_\_\_\_\_  
 BOOM TYPE: **LATTICE** CHORDS: **I BEAM** LACINGS: **ANGLE**  
 BOOM LENGTH: MAIN HOIST: **97'10"** WHIP: **XXX** JIB: **XXX**  
 MAX LIFT CAPACITY: **134,400** MAINTENANCE RECORDS SITED: ☒ YES ☐ NO HOURS: \_\_\_\_\_

NAVAL ARCHITECT/RPME: \_\_\_\_\_

### WIRE ROPE:

APPLICATION	PARTS	DIAM	CONSTRUCT	GRADE	RR	CORE	LAY	STRENGTH	WIRE ROPE CERTS
Main Hoist	8	1 1/8	6x26	EIPS	No	IWRC	RRL	130,000	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
Aux. Hoist	1	7/8	8x25	EIPS	No	IWRC	RRL	70,000	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
3 <sup>rd</sup> Drum									<input type="checkbox"/> YES <input type="checkbox"/> NO
Boom	19	1 1/8	6x26	EIPS	No	IWRC	RRL	130,000	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
Boom Pendants									<input type="checkbox"/> YES <input type="checkbox"/> NO

### TESTING: SEE 22-TMS-1060 FOR LOAD TEST WEIGHTS

	BOOM (ft)	RADIUS (ft)	ANGLE (°)	CHART(lbs)	DEDUCTS	NET CAPACITY	TEST WEIGHT
MAIN 360	98'	88'		82,000		11,000	16,000
WHIP							

OPERATIONAL TEST: ☒ FULL ☐ OTHER \_\_\_\_\_

LOAD APPLICATION: ☐ CERTIFIED ☒ OTHER \_\_\_\_\_

STEEL TEST WEIGHTS, CUSTOMER ONLY HAD ENOUGH WEIGHT ON SITE FOR A 16,000 LBS TEST PICK

LOAD DESCRIPTION: **(2023)**

BASIS FOR LOAD RATING: ☐ OWNER ☒ MANUFACTURER WINCH PULL: \_\_\_\_\_

# MARINE SURVEYORS AND CONSULTANTS

JOB NO: 23-03-81

## INSPECTION CHECK-LIST

EQUIPMENT ID: #28 DRAVO

	ITEM (AS PER 29CFR1919.71)	SAT.	N/A	DISCREPANCY / COMMENT:
A)	BOOM	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
B)	BOOM EXTENSIONS, JIB	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
C)	BOOM SHEAVES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
D)	FIRE EXTINGUISHER	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
E)	FLUID LEVELS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
F)	GUARDS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
G)	HOIST DRUM (s)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
H)	HOOK (s)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
I)	HOOK LATCH (s)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
J)	OUTRIGGERS, STABILIZERS, PADS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
K)	STRUCTURAL WELDS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
L)	ROTATION BEARINGS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
M)	WIRE ROPE, BECKETS, PINS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
N)	ANTI-TWO-BLOCK DEVICE(s)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
O)	BACKUP ALARM	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
P)	BRAKES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Q)	CONTROLS/FUNCTIONS LABELED	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> AIR LEAK IN CAB BEHIND CONTROLS
R)	ELECTRICAL EQUIPMENT	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
S)	LADDERS, HAND RAILS, WINDOWS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
T)	GAUGES WORKING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
U)	DATA PLATES, WARNING DECALS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
V)	HOUSEKEEPING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
W)	LIGHTS, SIGNALS, HORNS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
X)	LIMIT SWITCHES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> UPPER BM. LIMIT 70 DEG.
Y)	PENNANT BARS, CABLES, LINKS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Z)	LOAD CHART AND OP. MANUAL	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
AA)	OPERATIONAL AIDS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
BB)	HOOK AND LOAD ROLLERS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
CC)	CHASSIS, TIRES, STEERING	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
DD)	SWING LOCK AND BRAKES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

### Additional Remarks:

	NEED TO KEEP OPERATOR INSPECTIONS ON FILE 2023
	SMALL AIR LEAK IN CAB 2023

Date: 3/14/2023	Accredited Certifier's Name (please print) Charles Streeter / Marine Surveyors and Consultants	Signature of Accredited Certifier 
Certifier's Phone # 503-227-0287	Address P. O. Box 22123, Milwaukie, Oregon 97269-2123	

WW Quality Management Systems are registered to ISO9001:2015 &amp; API-Q1.



# Certificate

of

Examination and Test of Wire Rope  
Before Being Taken into Use

Reel No: 0241262



This Certificate when properly executed by a competent person, in accordance with 29CFR 1919.37, is accepted by the Government of the United States of America as being in accordance with the requirements of 29CFR 1918.12 and 1919.33.

**Name and address of maker or supplier:**

WIREROPE WORKS, INC.  
100 MAYNARD STREET  
WILLIAMSPORT, PA 17701

**Name and address of customer:**

WOODS LOGGING  
PO BOX K  
LONGVIEW, WA 98632  
PO: 1083134

**Date Tested:** March 25, 2020

**Actual Break Strength in Pounds:** 139,500

**Catalog Break Strength in Pounds:** 130,000

**Description:** 1 1/8 0626 BR EIP RR IW

**Size:** 1 1/8 (in inches, unless otherwise specified.)

**Number of Strands:** 06

**Number of Wires per Strand:** 26

**Finish:** Bright (Uncoated)

**Grade:** Extra Improved Plow

**Lay:** Right Regular Lay

**Core:** Wire Rope

Design load, subject to any stated qualifying conditions such as minimum pulley diameter, direct tensile load, etc. :  
"Using a design factor of 5, the design working load would be one-fifth of the rated catalog breaking strength."

Manufactured in accordance with RRW410-E, F, G or H; ASTM A1023; or API9A specification where applicable.

**Name and address of public service, association, company, or firm making the examination and test:**

Wirerope Works, Inc.  
100 Maynard Street  
Williamsport, PA 17701

**Position of signatory in public service, association, company, or firm making the examination and test:**

Quality Engineer

I certify that the above particulars are correct and that the examination and test were carried out by a competent person.

**Certificate No.** 025351

**Signature:**

**Date:** 12/08/2020

per authority of Roger Gilliland  
Director of Engineering  
and Technical Services