



11815 NE 99th Street, Suite 1294
Vancouver, WA 98662
Voice: 360-574-3058
Fax: 360-576-0925
Web: <https://www.swcleanair.gov>
Email: Tina@swcleanair.gov

Notice of Intent to Remove Asbestos

Case #: 24-265

Amendment: 0

Date Received: 4/23/2024

Date Paid: 4/23/2024

SWCAA Fee: \$735.00

Receipt #: 155026209

This notification MUST be present at all times at the asbestos project sit

Quantity to be removed: 8638 Square Feet 0 Linear Feet

Workshift days: M T W Th F

Project starting date: 5/13/2024 Project Completion date: 9/30/2024

Workshift hours: 8:00am-4:30pm &a

Site Name: The Oaks at Timberline Senior Nurse

Site address: 400 E 33rd St

Location of Asbestos: 5,6,7,15,16,17,19,20,21,22,23,24,25

City/State/Zip: Vancouver

WA 98663

☐ Demolition of Structure (Notification of Demolition required)

County: CLARK COUNTY

☒ Asbestos survey conducted?

No survey reason:

AHERA Inspector: Stephen Strickland

Certification #: ON-4644-11135-121222

Material to be Removed:

- ☐ Fireproofing ☐ Popcorn Ceiling ☐ CAB ☐ Sheet Vinyl ☐ Boiler Insulation ☐ Duct Tape
☐ Duct Paper ☐ Mag Pipe Insulation ☐ Air Cell ☐ CA Pipe ☒ VAT
☒ Other Mastic

Control Methods:

- ☒ N.P Enclosure ☐ Glove Bag ☐ Mini Enclosure ☐ Wrap and Cut ☒ Water ☒ HEPA Vac
☒ Other Regulate Area

Asbestos Contractor: Minority Abatement Contractors, Inc.

Phone: 360-750-1900

Mailing Address: 3200 NE 65th St, Vancouver, WA, 98663

Email: vwhitebird@minorityac.com

Certification ##: ABCN00001346

Supervisor: Jose Bahena

Phone: 503-780-6691

Property Owner: Kristina Mills

Phone: 360-696-2561

Mailing Address: 400 E 33rd St, Vancouver WA 98663

Asbestos Disposal Site: Wasco County Landfill: 2550 Steele Rd, The Dalles, OR, 97058-

**I DO HEREBY CERTIFY THAT THE INFORMATION CONTAINED IN THIS NOTIFICATION IS,
TO THE BEST OF MY KNOWLEDGE, ACCURATE AND COMPLETE.**

Submitter Name: Guillermo Plaza

Representing: Minority Abatement Contract

Submitter Title: Project Manager

Date Submitted: 4/23/2024

Reviewed by SWCAA: Mihai Voivod

☒ Approved



11815 NE 99th Street, Suite 1294
Vancouver, WA 98662
Voice: 360-574-3058
Fax: 360-576-0925
Web: <https://www.swcleanair.gov>
Email: Tina@swcleanair.gov

Notice of Intent to Remove Asbestos

Case #: 24-265

Amendment: 0

Date Received: 4/23/2024

Date Paid: 4/23/2024

SWCAA Fee: \$735.00

Receipt #: 155026209

This notification MUST be present at all times at the asbestos project sit



ADVANTAGE
Environmental INC.
www.Advantage-Enviro.com

Limited Asbestos Building Material Survey



Conducted for:
Elevated Restoration Services
11627 Airport Rd, Suite A
Everett, WA 98204

Prepared By:
Advantage Environmental Inc.
9317 NE Hwy 99, Suite D
Vancouver, WA 98665

Project Number
240005

Conducted at
400 E 33rd St.
Vancouver, WA

Inspection Date(s)
Thursday, January 4, 2024

EPA/AHERA Inspector(s)
Stephen Strickland



ADVANTAGE **Environmental INC.**

Clean your world.

January 8, 2024

Elevated Restoration Services
Brett Paterson
11627 Airport Rd, Suite A
Everett, WA 98204
Brett.p@ersconst.com
206-565-6744

Re: Limited Asbestos Building Material Survey: 400 E 33rd St. - Vancouver, WA

Dear Mr. Paterson,

Advantage Environmental, Inc., (AEI) was retained by Elevated Restoration Services to complete a limited asbestos building material survey of the commercial structure listed above. The results of the survey are provided in the accompanying report.

The purpose of this survey was to identify the location of asbestos containing materials prior to renovation and disposal of building material within the structure. The scope of work included a walk-through inspection, bulk sampling and analysis of specific suspect asbestos containing materials, and a written report documenting the results of the survey. This survey was limited to the material identified within the material summary tables section.

This is not a bidding document and all quantities of asbestos containing material should be verified by the abatement contractor prior to submitting their bid.

Thank you for choosing Advantage Environmental for this project. Please feel free to contact us at (360) 356-7628 if you have any questions.

Respectfully,
Advantage Environmental, Inc.

Chelsea Moore
Office Admin

- 1 -

Asbestos Regulatory Background

The National Emissions Standards for Hazardous Air Pollutants (40 CFR Part 61) defines the three categories.

RACMs are:

- *Friable asbestos materials*
- *Category 1 & 2 non-friable materials which have become friable*
- *Category 2 non-friable ACM that will or has been subjected to sanding grinding, cutting or abrading*
- *Category 2 non-friable ACM that has a high probability of becoming or has become friable by the forces expected to act upon them in the course of demolition or renovation*

Category 1 non-friable materials include gaskets, packings, resilient floor coverings and asphalt roofing products containing more than 1% asbestos.

Category 2 non-friable materials are all non-friable materials not included in Category 1.

Homogeneous materials are materials that are considered consistent throughout an area of the building based on the material's appearance, including texture size and color, manufacturers' labels and or construction era.

Asbestos Containing Building Materials (ACBMs) are placed into one of three general material categories which include surfacing materials, thermal system insulation, and miscellaneous materials. Surfacing materials are spray or trowel applied materials such as plasters, acoustical, or texturing products. Thermal system insulation materials are associated with HVAC systems and include pipe, boiler, tank insulation, duct insulation, seam tape, pipe insulation, and chimney or flue insulation. The final category is miscellaneous materials, which includes any material that does not fall into one of the two prior categories. These include, but are not limited to: floor finishes, adhesives, cement asbestos boards, gypsum wall board, ceiling tiles, and window glazing.

After the category of building material is assessed, the condition is determined. Materials are divided into two condition categories: friable and non-friable. This describes the materials potential to release asbestos fibers. 17.74.352 defines friable asbestos containing materials as any material containing more than 1% asbestos applied on ceilings, walls, structural members, piping, ducting, or any other part of a structure which when dry may be crumbled, pulverized, or reduced to powder by hand pressure. This also includes non-friable material that may become damaged through such actions as sawing, grinding, abrading or chipping and may become friable and release fibers.

"Asbestos" means the asbestiform varieties of serpentine (chrysotile), riebeckite (crocidolite), cummingtonite-grunerite (amosite), anthophyllite, actinolite, and tremolite.

"Asbestos containing material" means a material containing more than one-percent asbestos by weight.

In accordance with EPA regulations, any material which tests at less than 1% asbestos is not regulated by the EPA. However, the EPA requires that any material less than 1% asbestos be confirmed by EPA 600 Method 400 or 1000 Point Count. OSHA safety regulations still apply no matter the asbestos content.

Building Description

The structure is a commercial building currently occupied as a rehabilitation center. It is a single story ~30,648 sq. ft. brick-built building on concrete foundation. The floors were concrete with carpet or tile throughout sampled areas. Interior walls and ceilings were excluded from this survey.

Inaccessible Areas:

None noted.

Sampling Methodology

Asbestos

A walk-through of the area was conducted by an EPA/AHERA accredited building inspector to identify the location of suspect hazardous materials. The location, approximate quantity and condition of each material were recorded on field data sheets. Bulk samples of each suspect material were then collected and submitted to the laboratory under chain of custody documentation for analysis of asbestos content.

Samples were collected from selected homogeneous materials to evaluate the presence or absence of hazardous materials. Determination of homogeneous material included material type, texture, pattern, color, and size. A total of 16 suspect asbestos containing material samples were analyzed including sub-layers.

All asbestos samples collected by AEI were placed into pre-labeled airtight containers and brought to AEI's laboratory for analysis of asbestos content. AEI's laboratory analyzed the samples using Polarized Light Microscopy (PLM) with dispersion staining to identify asbestos constituents as required by EPA regulation 40 CFR, Part 763.

Advantage Environmental, Inc. participates in the American Industrial Hygiene Association (AIHA) Proficiency Analytical Testing's BAPAT program and is currently rated as proficient, Participant ID 163978.

Visual Assessment and Findings

Our survey activities began with visual observation of the property to identify homogeneous areas of suspect materials. Assessments were conducted throughout visually accessible areas of the property.

Building material identified as concrete, glass, wood, masonry, metal, or rubber were not considered suspect asbestos containing material.

Unidentified asbestos-containing material may be in place behind walls, ceilings, under floors, beneath carpeted areas, areas outside the scope of work at the time of inspection, and in other inaccessible areas.

A table indicating sample numbers, material description, material location, material condition and content of each material sampled is included in the material summary table below.

Laboratory analytical results, chain of custody documentation and notes are included in Appendix A. AHERA Building inspector credentials are included in Appendix B.

Limitations

The report is limited to the samples shown below in the material summary pages. Upon discovery of asbestos containing material found during demolition, renovation, or after an unexpected emergency, the property owner or operator of the demolition or renovation company is required to stop work immediately. All exposed suspect materials will need to be sampled by an AHERA accredited inspector and sent to an accredited laboratory for sample analysis. Although due diligence was taken during the inspection, unidentified asbestos-containing materials may be behind wall systems, above ceiling systems, or beneath concrete slabs.

Discussion & Recommendations

Asbestos

Based on the laboratory results the following asbestos containing materials were identified during this inspection. Locations include but may not be limited to the following:

Greater Than 1% Asbestos Containing Materials						
Sample Group Number	Material Type	Material Location	Condition	Quantity	Friable Or Non-Friable	Asbestos Concentration
1, 2, 3, 4, & 5	12" light tan floor tile & Black flooring mastic	Throughout remaining areas within the structure. Including but not limited to: ~30 rooms, 2 nurse's stations, and dining room. (Black flooring mastic is also present beneath the non-asbestos containing 12" white floor tile in Room 30).	Good	~8,600 Sq. Ft.	Friable	2% Chrysotile 5% Chrysotile
6	Black flooring mastic	Beneath the carpet in the reception area.	Good	~500 Sq. Ft.	Non-friable	5% Chrysotile

****Please note: All asbestos samples collected for this survey contain positive black flooring mastic. All flooring materials adhered to positive black flooring mastic are contaminated and should be treated and disposed of as asbestos containing material.**

Asbestos-containing material must be removed by a licensed asbestos abatement contractor prior to any renovation, demolition, or repair work that will impact those materials.

Any materials encountered that are not specifically mentioned in this report should be considered asbestos containing until sufficient sampling has been completed to determine that these materials are non-asbestos containing.

OSHA regulations

(29 CFR 1926.1101) states that if asbestos containing materials, containing <1% asbestos, are to be removed by construction personnel, the employer shall provide awareness training, a written respirator protection program, respirators, and a negative exposure assessment.

The Occupational Safety and Health Administration (OSHA) classifies the removal or disturbance of asbestos containing material as Class I and Class II asbestos abatement projects. The removal of asbestos containing material requires the use of appropriate engineering controls, by a contractor licensed by the State of Oregon. The work methods utilized must include the use of wet methods, negative pressure enclosure, and decontamination facility.

Additionally, OSHA regulations (29 CFR 1926.1101) require employers to meet standards regarding personal protection, labeling, signs, daily air monitoring, use of engineering controls, notification, and respiratory protection for all activities related to the removal or disturbance of asbestos containing building materials.

Discussion & Recommendations (Continued)

EPA

***EPA recommends that bulk material found negative for asbestos or less than one percent asbestos by polarized light microscopy be reanalyzed by an additional method such as transmission electron microscopy.*

Warranty

Advantage Environmental Inc. warrants that this report has been prepared in a manner consistent with that degree of care and skill ordinarily exercised by members of the same profession currently practicing under similar circumstances. No other warranties are implied or expressed.

Material Summary Table

Asbestos

Materials highlighted in red contain 1% asbestos content or greater as determined by laboratory analysis. These materials will need to be removed prior to disturbance, construction or demolition activities that may impact these materials.

Sample Number	Material Description	Sample Locations	Condition	Approximate Quantity	Friable Yes/No	Asbestos Content
1	12" Light tan floor tile	Room 36				Asbestos Not Present
	Black flooring mastic	Room 36	Good	~8,600 Sq. Ft.	No	5% Chrysotile
2	12" Light tan floor tile	Room 33	Good	~8,600 Sq. Ft.	Yes	2% Chrysotile
	Black flooring mastic	Room 33	Good	~8,600 Sq. Ft.	No	5% Chrysotile
3	12" White floor tile	Room 30				Asbestos Not Present
	Clear flooring mastic	Room 30				Asbestos Not Present
	Black flooring mastic	Room 30	Good	~8,600 Sq. Ft.	No	5% Chrysotile
	Gray leveling compound	Room 30				Asbestos Not Present
4	12" Light tan floor tile	Nurse Station 1				Asbestos Not Present
	Yellow flooring mastic	Nurse Station 1				Asbestos Not Present
	Black flooring mastic	Nurse Station 1	Good	~8,600 Sq. Ft.	No	5% Chrysotile
5	12" Light tan floor tile	Front reception-back room	Good	~8,600 Sq. Ft.	Yes	2% Chrysotile
	Black flooring mastic	Front reception-back room	Good	~8,600 Sq. Ft.	No	5% Chrysotile
6	Blue carpet	Reception area				Asbestos Not Present
	Yellow flooring mastic	Reception area				Asbestos Not Present
	Black flooring mastic	Reception area	Good	~500 Sq. Ft.	No	5% Chrysotile

APPENDIX A
Laboratory Analytical Results
Chain of Custody
Notes



9317 NE Hwy 99, Suite D, Vancouver, WA 98665 | 360-356-7628
Polarized Light Microscopy Results

Lab No 142017
Layers Analyzed 16

Date Received 1/4/2024
Received By Karla Jara
Date Analyzed 1/5/2024
Analyzed By Nathan Blondino

Property Address 400 E 33rd St
City, State, Zip Vancouver, WA
Job Number Flooring Removal
Client Name Elevated Restoration
Client Address _____
City, State, Zip _____
Phone & E-mail _____

AEI Sample ID	Client Sample ID	Composition	Color/ Description	Asbestos (%)	Non-Asbestos Fiber (%)	Non Fibrous
001	1	Layered	Light Tan Floor Tile	Asbestos Not Present	N/A	Vinyl-CaCO3
001A		Layered	Black Flooring Mastic	5% Chrysotile	N/A	Tar
002	2	Layered	Light Tan Floor Tile	2% Chrysotile	N/A	Vinyl-CaCO3
002A		Layered	Black Flooring Mastic	5% Chrysotile	N/A	Tar
003	3	Layered	White Floor Tile	Asbestos Not Present	N/A	Vinyl-CaCO3
003A		Layered	Clear Flooring Mastic	Asbestos Not Present	N/A	Silicone
003B		Layered	Black Flooring Mastic	5% Chrysotile	N/A	Tar
003C		Layered	Gray Leveling Compound	Asbestos Not Present	N/A	CaCO3-Sand
004	4	Layered	Light Tan Floor Tile	Asbestos Not Present	N/A	Vinyl-CaCO3
004A		Layered	Yellow Flooring Mastic	Asbestos Not Present	N/A	Silicone
004B		Layered	Black Flooring Mastic	5% Chrysotile	N/A	Tar
005	5	Layered	Light Tan Floor Tile	2% Chrysotile	N/A	Vinyl-CaCO3
005A		Layered	Black Flooring Mastic	5% Chrysotile	N/A	Tar
006	6	Layered	Blue Carpet	Asbestos Not Present	80% Synthetic Fibers	Binder
006A		Layered	Yellow Flooring Mastic	Asbestos Not Present	N/A	Glue
006B		Layered	Black Flooring Mastic	5% Chrysotile	N/A	Tar



Disclaimer

- EPA Method 600/M4-82-020 (1982) was used to determine the presence or absence of asbestos fibers in all materials referenced in the above report. PLM analysis is based on visual estimation, and due to limitations of PLM analysis NESHAP regulations recommend that any material determined to contain less than 10% asbestos by the above referenced method should either be assumed to contain greater than 1% asbestos by the owner/operator, or be verified by PLM Point Count or TEM analysis as containing less than 1% asbestos.
- We recommend that TEM analysis be conducted for confirmation of negative PLM analytical results of vinyl floor tiles and vermiculite. These materials may contain asbestos fibers that cannot be detected by PLM analysis due to their size (<0.25 microns in diameter)
- This report may not be used to represent any materials not analyzed and listed in the included report. Advantage Environmental Inc. cannot be held responsible for the interpretation of the results shown. This report may not be reproduced in part and may only be reproduced in full without prior written consent from Advantage Environmental Inc.



ADVANTAGE
Environmental INC.

ASBESTOS CHAIN OF CUSTODY
9317 NE Hwy 99, Suite D • (360) 356-7628
LEGAL DOCUMENT - PLEASE PRINT LEGIBLY

Page 1 of 1

Lab Use Only	
Survey <input checked="" type="checkbox"/>	Lab No. 142017
Walk-In <input type="checkbox"/>	Accept Reject

AHERA Inspector / Sampled By			Project Information		
Date:	1/4/2024		Company Name:	Elevated Restoration	
Name:	Stephen Strickland		Project Name:	Flooring Removal	
Phone:	360-356-7628		Project Location:	400 E 33rd St, Vancouver, WA	
Email:	Chelsea.Moore@advantage-enviro.com		P.O. Number:		
RELINQUISHED BY	DATE & TIME	VIA	RECEIVED BY	DATE & TIME	
Name Stephen Strickland	Date 1/4/2024	Drop-off	<i>Korcia</i>	1-4-24	
Sign	Time 8:00			9:23	

REQUESTED SERVICES

PLM			TURNAROUND TIME				
Bulk Analysis			<input type="checkbox"/> Verbal	<input type="checkbox"/> Rush	<input type="checkbox"/> Same Day	<input checked="" type="checkbox"/> 24-Hour	<input type="checkbox"/> 3-Days
No.	Sample ID	Color	Description	Volume/Area (as applicable)	Comments / Notes	Condition	Friable
1	1	Tan	12x12 Floor Tile	8600 Sqft	Room 36	G	Y
2	2	Tan	12x12 Floor Tile		Room 33	G	Y
3	3	White	12x12 Floor Tile		Room 30	G	Y
4	4	Tan	12x12 Floor Tile		Nurse Station 1	G	Y
5	5	Tan	12x12 Floor Tile		Front reception back room	G	Y
6	6	Blue	Carpet	500 Sqft	Reception area	G	N
7						G F P	Y N
8						G F P	Y N
9						G F P	Y N
10						G F P	Y N
11						G F P	Y N

Sample #	Additional Notes	Sample #	Additional Notes



ADVANTAGE Environmental INC.

Job Name:	Elevated Restoration	Inspector:	Steve
Jobsite Address:	400 E 33rd St Vancouver Wa 98663	Date:	1/4/2024
Contact:	Dan	Hours Worked:	5
Phone Number:	360-989-7827	Time:	8am
Lead:	No	Lab:	AEI
Asbestos:	Yes	Project Manager:	Ronnie
Property Type:	Commercial	Demo/Limited:	Limited
Info:	Flooring only		

Description of Building Commercial assisted living / hospice building
"The structure is a (# of stories, type of building, "equipped with, # of rooms" on a 'type of foundation)"

Total Floors:	1	Office #1 Sq Ft:		Women's RR Sq Ft:	
Building Sq Ft:		Office #2 Sq Ft:		Men's RR Sq Ft:	
Floor/Suite Sq Ft:		Office #3 Sq Ft:		Main Area Sq Ft:	
Total Offices:		Office #4 Sq Ft:		Break Room Sq Ft:	
Total Restrooms:		Office #5 Sq Ft:		Mech/Janitor Sq Ft:	

Walls: Drywall | Plaster | Wood Notes: _____

Floors: Wood | Concrete Finishes: Tile | Sheet Vinyl | Ceramic | Carpet | Wood

List Flooring Layers: _____

Ceilings: Popcorn | Brocade | Orange Peel | Panels | Tiles | Mastic Notes: _____

Roofing Material: N/A

Siding Material: N/A Stucco Siding Yes | No Minimum 3 samples

Window Type: Wood | Aluminum | Vinyl Glazing: Yes | No Aluminum Window Mastic: Yes | No

Heat Source/Type: N/A HVAC Ducting Present: Attic | Crawl Space | Basement

Duct Seam Tape or Wrap Present: Yes | No Pipe Insulation Type: _____

Insulation Type: N/A Areas Checked: Floors

Inspector's Name: Stephen Strickland

Notes, or different materials identified at the site, wood stove backing board, etc: Existing old

Flooring to be removed



Survey Check List

Advantage Environmental

Project Name: Elevated Restoration Inspector: Steve
Address: 400 E 33rd St Vancouver Wa 98663 Date: 1/4/2024

	Yes	No	N/A
1: Project info provided correctly?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2: Is the structure occupied?	<input checked="" type="checkbox"/> Occupied	<input type="checkbox"/> Unoccupied	<input type="checkbox"/>
3: Has the original scope of work changed?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
4: Is this a Limited Survey?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5: Is this a Demo Survey?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6: All areas accessible at time of inspection	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7: Concealed or inaccessible areas observed & noted?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8: Are all materials quantified on the COC including drywall systems?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9: Sampling from all homogeneous materials per AHERA protocol?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10: Attic space inspected?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
11: Crawl Space inspected?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
12: Ceiling texture systems inspected, tested and noted?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
13: Wall systems, textures, patches inspected, tested and noted?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
14: Ceiling tiles, panels, tile mastic inspected tested and noted?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
15: All floor coverings, mastics, leveling compounds inspected, tested, and noted?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16: Flooring vapor barrier located, inspected and noted?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17: Attic, wall, sprayed on insulations inspected, tested and noted?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
18: HVAC system, ducting, tape, cement, wrap inspected, tested and noted?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
19: Boiler system, block, tank, breaching, gaskets, piping inspected, tested, noted?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
20: CMU block inspected for insulation?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
21: Interior/exterior brick and mortar inspected, tested, noted?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
22: All sinks inspected, tested and noted?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
23: All electrical panels, wiring, cloth inspected, tested, noted?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
24: Fire blankets, doors, fireproofing, cement, inspected, tested and noted?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
25: Wood stove gasektes found?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
26: Pipe insulation or hard fittings inspected, tested, noted?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
27: Wall coverings, textured paints or coatings inspected, tested, noted?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
28: Incandescent light fixture backing inspected, tested, noted?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
29: Construction, mirror, flooring, wall mastic/adhesives inspected, tested, noted?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
30: All caulking and putty inspected, tested, noted?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
31: Stucco found on siding or foundation?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
32: Roofing type inspected, tested and noted?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
33: Transite (CAB) noted on siding or interior sections of structure?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
34: Window glazing inspected, tested, noted?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
35: Cement piping found?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>



Project Name:	Elevated Restoration	Inspector:	Steve
Address:	400 E 33rd St Vancouver Wa 98663	Date:	1/4/2024

This image shows a single sheet of white paper with horizontal ruling lines. The lines are evenly spaced and run across the width of the page. There are no margins, text, or other markings on the paper.

APPENDIX B
AHERA Building Inspector
Certification

THE ASBESTOS INSTITUTE

Certifies that

Stephen Strickland

has attended and received instruction in the EPA approved course

AHERA Building Inspector Refresher

on


December 07, 2023

and successfully completed and passed the competency exam.

Certificate:
ON-4644-11135-120723

Date of Examination:
7-Dec-2023

Date of Expiration:
07-Dec-2024


William T. Cavness
Director
Approved Instructor

THE ASBESTOS INSTITUTE

20033 N. 19th Ave, Building 6, Phoenix, AZ 85027
602-864-6564 – www.theasbestosinstitute.com

The person receiving this certificate has completed the requisite training for asbestos accreditation under TSCA Title II.