



11815 NE 99th Street, Suite 1294
Vancouver, WA 98662
Voice: 360-574-3058
Fax: 360-576-0925
Web: <https://www.swcleanair.gov>
Email: Tina@swcleanair.gov

Notice of Intent to Remove Asbestos

Case #: 24-056

Amendment: 0

Date Received: 1/25/2024

Date Paid: 1/25/2024

SWCAA Fee: \$738.00

Receipt #: 149993082

This notification MUST be present at all times at the asbestos project site

*** EMERGENCY NOTICE ***

Quantity to be removed: 400 Square Feet 0 Linear Feet

Workshift days: F

Project starting date: 1/26/2024 Project Completion date: 1/26/2024

Workshift hours: 08:00-04:00

Site Name: W281_PaulDavis_1206NeBirchSt_9

Site address: 1206 NE Birch St. Camas WA

Location of Asbestos: Prayer Station

City/State/Zip: Camas WA 98607

☐ Demolition of Structure (Notification of Demolition required)

County: CLARK COUNTY

☒ Asbestos survey conducted?

No survey reason:

AHERA Inspector: Jorge Camacho

Certification #: IRO-23-1175C

Material to be Removed:

- ☐ Fireproofing ☐ Popcorn Ceiling ☐ CAB ☐ Sheet Vinyl ☐ Boiler Insulation ☐ Duct Tape
☐ Duct Paper ☐ Mag Pipe Insulation ☐ Air Cell ☐ CA Pipe ☐ VAT
☐ Other Texture

Control Methods:

- ☐ N.P Enclosure ☐ Glove Bag ☐ Mini Enclosure ☐ Wrap and Cut ☐ Water ☐ HEPA Vac
☐ Other 6-mil Poly, Wet, Labeled

Asbestos Contractor: Alpine Abatement Associates Inc.

Phone: 541-388-2672

Mailing Address: PO Box 1557, Bend, OR, 97709

Email: annmarie@alpineabatement.com

Certification ##: ABCN00001215

Supervisor: Ari Ramirez

Phone: 541-388-2672

Property Owner: Saints Johns Church

Phone: 360-823-7847

Mailing Address:

Asbestos Disposal Site: Hillsboro Landfill: 3205 SE Minter Bridge Rd, Hillsboro, OR, 97123-

**I DO HEREBY CERTIFY THAT THE INFORMATION CONTAINED IN THIS NOTIFICATION IS,
TO THE BEST OF MY KNOWLEDGE, ACCURATE AND COMPLETE.**

Submitter Name: Bo Davidson

Representing: Alpine Abatement

Submitter Title: Senior Project Manager

Date Submitted: 1/25/2024 1:47:55 PM

Reviewed by SWCAA: Mihai Voivod

☒ Approved



11815 NE 99th Street, Suite 1294
Vancouver, WA 98662
Voice: 360-574-3058
Fax: 360-576-0925
Web: <https://www.swcleanair.gov>
Email: Tina@swcleanair.gov

Notice of Intent to Remove Asbestos

Case #: 24-056

Amendment: 0

Date Received: 1/25/2024

Date Paid: 1/25/2024

SWCAA Fee: \$738.00

Receipt #: 149993082

This notification MUST be present at all times at the asbestos project site

Limited Asbestos Survey Report

Owner/Operator Name:

Paul Davis Restoration of Vancouver/Portland

Owner/Operator Number:

360-823-7847

Limited Survey Date:

January 22, 2024

Survey Address:

1206 NE Birch St, Camas, WA 98607

Survey Location:

Interior of Prayer Station

What is the building's description?

Commercial/Church

What is this structure's current use?

Commercial/Church

What is this structure's past use?

Commercial/Church

Building Square Footage:

5,000

Number of Floors:

2

Area Surveyed:

Interior Prayer Station Walls & Ceiling

Approximate Build Date:

1970

Purpose of the Survey:

Remediation due to water damage

Survey Limitations: Samples are collected based on a visual inspection of the work area as defined in the analysis report. Samples were collected from accessible, representative construction materials, which were suspected to contain asbestos. If additional materials are found during the demolition process that were inaccessible at time of inspection that are not listed in this report please have materials tested before they are impacted. Survey is subject to direction from contractor, homeowner or owners agent.

Asbestos Containing Building Material Identified During Survey: **Please see the completed attached analysis report.*

Sample #	Location	Asbestos Containing Material	Description (Color, Texture & Pattern)	Asbestos % & Asbestiform	Approx. Sq. Footage	Friable Y/N	Condition
3-A Layer 2	Prayer Station Wall	Texture	Off White	3% Chrysotile	400'	Y	Good
3-A Layer 3	Prayer Station Wall	Joint Compound	Off White	2% Chrysotile	—	Y	Good
3-B Layer 2	Prayer Station Wall	Texture	Off White	3% Chrysotile	—	Y	Good
3-B Layer 3	Prayer Station Wall	Joint Compound	Off White	2% Chrysotile	—	Y	Good
3-C Layer 2	Prayer Station Wall	Texture	Off White	3% Chrysotile	—	Y	Good
3-C Layer 3	Prayer Station Wall	Joint Compound	Off White	2% Chrysotile	—	Y	Good

Recommended Response Action Plan:**Contact a Licenced Abatement Contractor or SW Clean Air Agency**

Sw Clean Air Agency regulates the handling, removal and disposal of asbestos-containing material to protect public health and the environment.

<https://www.lni.wa.gov/licensing-permits/other-licenses-permits/asbestos-certification#certified-contractors-list> . For more information on asbestos removal, please refer to [SWCAA 476](#), specifically SWCAA 476-050. If you have any questions, please contact us at 360-574-3058


A copy of this survey report must be kept onsite during any remediation, renovation or demolition activities, as required by Southwest Clean Air Agency.

Surveyed Performed By:

Jorge Camacho
Of
Atlas Labs Inc.
Environmental Testing Services
Jorge@atlaslabinc.com
(360) 953-0731
AHERA Cert #: IRO-23-1175C
CCB #: 231684



Atlas Laboratories Inc.
14795 SW 72nd Ave, STE B Portland, OR 97224
(503) 430-5290 www.atlaslabsinc.com
CCB #231684



Limited Survey Chain of Custody

Name / Company Name: Paul Davis Restoration of Vancouver/Portland		Phone: 360-823-7847
Contact Email: On File		
Project Name: St. John's Presbyterian Church 4696-E		Batch: 22-1080701
Job/Project Address: 1206 NE Birch St, Camas, WA 98607		
Inspector: Jorge Camacho Pichardo Ph: (360) 953-0731 AHERA Cert. # IRO-23-1175C Lead RRP Cert. #R-I-41R028-21-00048		
Survey Area Use: Commercial/Church	Approx. Year Built: 1970	Reason for Survey: Remediation

<input checked="" type="checkbox"/>	Rush
<input type="checkbox"/>	Next Day
<input type="checkbox"/>	2-Day
<input type="checkbox"/>	5-Day

<input checked="" type="checkbox"/>	Asbestos PLM
<input checked="" type="checkbox"/>	Lead Paint
<input type="checkbox"/>	Other

#	Material Description	Friable Y/N	Location	Condition	Approx. SQ FT.
1-A	Ceiling Tile	Y	Prayer Station 1st Layer Ceiling	Poor	
2-A	Drywall	Y	Prayer Station 2nd Layer Ceiling	Poor	
2-B	Drywall	Y	Prayer Station 2nd Layer Ceiling	Poor	
2-C	Drywall	Y	Prayer Station 2nd Layer Ceiling	Good	
3-A	Drywall	Y	Prayer Station Wall	Good	
3-B	Drywall	Y	Prayer Station Wall	Good	
3-C	Drywall	Y	Prayer Station Wall	Good	
Pb-1	Paint- Prayer Station Wall				

Notes:

Inspector Signature:	Date: 1-22-2024	Time: 4:23 PM
Accepted By:	Date: 1/22/2024	Time: 4:40pm
Lab Results Completed By:	Date Sent Out: 1/22/24	Email / Mail

Limitations of Inspection: Atlas Labs Inc. AHERA certified inspector performed a limited survey at the site, date, time and cause as stated above in this document along with lab analysis of possible asbestos and/or lead containing material. Atlas Labs Inc. survey is limited to areas defined on the Chain of Custody form.

General NESHAPS Bulk Sampling Guidelines: Material sampling areas were grouped based on homogenous materials. A homogeneous area is one which contains material that seems by texture, color and surface wear to be uniform and applied during the same general time period. Samples are collected based on a visual survey of the work area as defined in this report. Samples were collected from accessible, representative construction materials, which were suspected to contain asbestos. If additional materials are found during the demolition process that were inaccessible at time of inspection that are not listed in this report please test before you cut. Survey is subject to direction from contractor, homeowner or owners agent.



Batch # 2022 *

22-1080701

Name / Company *

Paul Davis Restoration of
Vancouver/Portland

Analysis Date *

01/22/2024

Project Name

St. John's Presbyterian
Church

Project #

4696-E

PO #

Analyst *

Crossland Kapaun

Project Location *

1206 NE Birch St, Camas,
WA 98607

Turnaround Time *

Rush

Asbestos Analysis of Bulk Material by Polarized Light Microscopy

Sample*	Layer*	Description*	Non Asbestos*	Asbestos Type*	Asbestos %*
1-A	1	Ceiling Tile (Grey) - Prayer Station 1st Layer Ceiling	Cellulose / Fiberglass	None Present	N/D
1-A	2	Mastic (Yellow) - Prayer Station 1st Layer Ceiling	Cellulose	None Present	N/D
2-A	1	Drywall (White) - Prayer Station 2nd Layer Ceiling	Cellulose / Fiberglass	None Present	N/D
2-A	2	Joint Compound (White) - Prayer Station 2nd Layer Ceiling	Fiberglass	None Present	N/D
2-B	1	Drywall (White) - Prayer Station 2nd Layer Ceiling	Cellulose / Fiberglass	None Present	N/D
2-B	2	Joint Compound (White) - Prayer Station 2nd Layer Ceiling	Fiberglass	None Present	N/D
2-C	1	Drywall (White) - Prayer Station 2nd Layer Ceiling	Cellulose / Fiberglass	None Present	N/D
2-C	2	Joint Compound (White) - Prayer Station 2nd Layer Ceiling	Fiberglass	None Present	N/D
3-A	1	Drywall (White) - Prayer Station Wall	Cellulose	None Present	N/D
3-A	2	Texture (Off White) - Prayer Station Wall	Cellulose	Chrysotile	3%

Sample*	Layer*	Description*	Non Asbestos*	Asbestos Type*	Asbestos %*
3-A	3	Joint Compound (Off White) - Prayer Station Wall	Cellulose	Chrysotile	2%
3-B	1	Drywall (White) - Prayer Station Wall	Cellulose	None Present	N/D
3-B	2	Texture (Off White) - Prayer Station Wall	Cellulose	Chrysotile	3%
3-B	3	Joint Compound (Off White) - Prayer Station Wall	Cellulose	Chrysotile	2%
3-C	1	Drywall (White) - Prayer Station Wall	Cellulose	None Present	N/D
3-C	2	Texture (Off White) - Prayer Station Wall	Cellulose	Chrysotile	3%
3-C	3	Joint Compound (Off White) - Prayer Station Wall	Cellulose	Chrysotile	2%

To Be Filled by the Technician

Technician *

Atlas Laboratories maintains liability to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full without written permission by Atlas. Atlas bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval or endorsement by NVLAP, NIST, NIOSH or any other agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore Atlas recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Transmission Electron Microscopy asbestos identification and lead paint analysis will be available and performed by laboratories by proxy. Original analysis documents are available upon request of the client.