

### **Notice of Intent to Remove Asbestos**

Case #: 24-060

Amendment: 0

11815 NE 99th Street, Suite 1294

Vancouver, WA 98662 Voice: 360-574-3058 Fax: 360-576-0925

Web: https://www.swcleanair.gov Email: Tina@swcleanair.gov

Date Received: 1/29/2024

Date Paid: 1/29/2024

Receipt #:

SWCAA Fee: \$738.00

150183295

### This notification MUST be present at all times at the asbestos project site

Quantity to be removed:	: 166 Square Feet	0 Linear Feet	Work	shift days: T
Project starting date: 1/	/30/2024 Project C	Completion date: 1/30/2	024 Works	hift hours: 10am-3pm
Site Name: JeauAnne St	tephens	Site addr	ess: 19913 NW Ceda	r Acres Dr
Location of Asbestos:	Laundry, Bathroom, and E	Bedroom City/State/	Zip: Ridgefield	WA 98642
☐ Demolition of Structu	ire (Notification of Demo	lition required)	County: CLA	RK COUNTY
✓ Asbestos survey cond	lucted? N	lo survey reason:		
AHERA Inspector: Blake	: Marshall		Certificatio	n #: IRO-23-0280C
	Popcorn Ceiling ☐ CAB	S Sheet V ☐ Air Cell	nyl ∐ Boiler In □ CA Pipe	
Control Methods:	Glove Bag 🔲 Mini E	Enclosure   Wrap ar	nd Cut 🗹 Water	✓ HEPA Vac
Asbestos Contractor: Ab	patement Services of Was	hington	Phone: 503-8	357-7175
Mailing Address: PO Certification ##: AB	Box 747, Beavercreek, C BCN00001610	DR, 97004	Email: trista	n@abateservices.com
Supervisor: Jac	cob Mcvey		Phone: 971-429-5	140
Property Owner: JeauAr	nne Stephens		Phone: 503-852-4	345
Mailing Address:				

# TO THE BEST OF MY KNOWLEDGE, ACCURATE AND COMPLETE.

Submitter Name:	Mckenzie Bates		Representing:	ASI
Submitter Title:	Secretary		Date Submitted:	1/29/2024 2:35:07 PM
Reviewed by SWC	AA: Danielle Kreps	Danle	Keps	✓ Approved



11815 NE 99th Street, Suite 1294

Web: https://www.swcleanair.gov Email: Tina@swcleanair.gov

Vancouver, WA 98662 Voice: 360-574-3058

Fax: 360-576-0925

### **Notice of Intent to Remove Asbestos**

Case #: 24-060

Amendment: 0

Date Received: 1/29/2024

> Date Paid: 1/29/2024

SWCAA Fee: \$738.00

Receipt #:

This notification MUST be present at all times at the asbestos project site

150183295



Date of survey: 1/5/23

Site address:19913 Nw Cedar Acres Year Built: 1974 Square

Dr

Ridgefield, WA 98642

Footage & Floors:

Type of structure: Residential

Property owner/phone number: JeauAnne Stephens

Inspector name/phone number: Blake Marshall

Rooms affected/surveyed: Basement

Objective: renovation / repair of damaged building materials within the room affected

Type of survey conducted: Destructive sampling was performed within the scope of work

### **LIMITATIONS**

The purpose of this survey was to identify the location, of asbestos containing material prior to renovation/disposal of building material within the structure/area. Any material encountered that are not specifically mentioned in this report should be considered asbestos containing until sufficient sampling has been completed to determine that these materials are non-asbestos containing.

### **PURPOSE OF SURVEY**

The purpose of this survey was to identify the location, of asbestos containing material prior to renovation/disposal of building material within the structure/area. The scope of work included a walk-through inspection, bulk sampling, and analysis of specific suspect asbestos-containing material, and a written report documenting the results of the survey. This survey was limited to the material identified in the report.

### **METHODOLOGY**

Bulk samples of suspect <u>ACM (Asbestos Containing Material)</u> were analyzed by Polarized Light Microscopy (PLM) with dispersion staining, as described in 40 CFR Part 763 and the National Emissions Standard for Hazardous Air Pollutants (NESHAP). Advantage Environmental, Inc. was responsible for the analysis of all bulk samples within this report. Advantage Environmental is an accredited laboratory through the AIHI.

### **CONCLUSIONS AND RECOMMENDATIONS:**

Asbestos-containing materials may have been positively identified in one or more locations throughout the structure. If any of the identified ACM is to be disturbed by the proposed demolition/renovation work, proper asbestos abatement procedures must be implemented prior to the commencement of such work. All asbestos abatement work shall be performed in accordance with all applicable Federal, State and Local rules and regulations. The abatement project shall be filed with all agencies having jurisdiction over this project. A licensed abatement contractor must perform the removal of all friable and non-friable ACM.

Areas of non-asbestos containing building material were examined during this survey. This survey is does not include areas that are outside the scope of work for DryTime Restoration and may not adequately cover all materials for other contractor, trades or client to perform work. All contractors and the client are responsible to perform their own survey and to ensure compliance with state and federal regulations. This survey does not include lead-based paint testing. This survey is for DryTime Restoration's use only and is not to be used by any other person, business, or project at any time.

DryTime Restoration warrants that this report has been prepared in a manner consistent with that degree of care and skill ordinarily exercised by members of the same profession currently practicing under similar circumstances. No other warranties are implied or expressed. DryTime has made every effort to survey and randomly sample all suspect building materials associated with the scope of the project. However, in some cases hidden or unforeseen materials may be present which are outside the scope of work or were not readily observed.



### **Disclaimer**

- EPA Method 600/M4-82-020 (1982) was used to determine the presence or absence of asbestos fibers in all materials referenced in the above report. PLM analysis is based on visual estimation, and due to limitations of PLM analysis NESHAP regulations recommend that any material determined to contain less than 10% asbestos by the above referenced method should either be assumed to contain greater than 1% asbestos by the owner/operator or be verified by PLM Point Count or TEM analysis as containing less than 1% asbestos.
- We recommend that TEM analysis be conducted for confirmation of negative PLM analytical results of vinyl floor tiles and vermiculite. These materials may contain asbestos fibers that cannot be detected by PLM analysis due to their size (<0.25 microns in diameter)
- This report may not be used to represent any materials not analyzed and listed in the included report. DryTime Restoration cannot be held responsible for the interpretation of the results shown. This report may not be reproduced in part and may only be reproduced in full without prior written consent from DryTime Restoration.



### Clean your world.

9317 NE Hwy 99, Suite D, Vancouver, WA 98665 | 360-356-7628 Polarized Light Microscopy Results

Lab No 142087
Layers Analyzed 13

 Date Received
 1/10/2024

 Received By
 Karla Jara

 Date Analyzed
 1/11/2024

 Analyzed By
 Nathan Blondino

Property Address 19913 NW Cedar Acres Dr
City, State, Zip
Job Number
Client Name
DryTime Restoration, LLC

Client Address 11927 NE 113th Ave Suite 104
City, State, Zip Vancouver, WA 98662

Phone & E-mail a.mcmurty@drytimerestoration.com

Sample ID Sample ID Description Fiber (%)  001 1A Layered White Texture 3% Chrysotile N/A CaCO3  001A Layered White Drywall Asbestos Not Present 20% Cellulose Gypsur  002 1B Layered White Texture 3% Chrysotile N/A CaCO3  002A Layered White Drywall Asbestos Not Present 20% Cellulose Gypsur  003 1C Layered White Texture 3% Chrysotile N/A CaCO3  003A Layered White Drywall Asbestos Not Present 20% Cellulose Gypsur  004 2A Homogeneous White Orange Peel Ceiling Texture 2% Chrysotile N/A (White) Paint Sand  005 2B Homogeneous White Orange Peel Ceiling Texture 2% Chrysotile N/A (White) Paint Sand  006 2C Homogeneous White Orange Peel Ceiling Texture 2% Chrysotile N/A (White) Paint Sand			Nathan Bionamo	•	ono & E man	a.memarty@dryamerestoration.com		
DO1A   Layered   White Drywall   Asbestos Not Present   20% Cellulose   Gypsur			Composition	•	Asbestos (%)		Non Fibrous	
DO2	001	1A	Layered	White Texture	3% Chrysotile	N/A	CaCO3	
Layered   White Drywall   Asbestos Not Present   20% Cellulose   Gypsur	001A		Layered	White Drywall	Asbestos Not Present	20% Cellulose	Gypsum	
003     1C     Layered     White Texture     3% Chrysotile     N/A     CaCO3       003A     Layered     White Drywall     Asbestos Not Present     20% Cellulose     Gypsur       004     2A     Homogeneous     White Orange Peel Ceiling Texture     2% Chrysotile     N/A     (White) Paint Sand       005     2B     Homogeneous     White Orange Peel Ceiling Texture     2% Chrysotile     N/A     (White) Paint Sand       006     2C     Homogeneous     White Orange Peel Ceiling Texture     2% Chrysotile     N/A     (White) Paint Sand       007     3     Layered     Off-White Sheet Flooring     Ashestos Not Present     25% Cellulose     Vinyl-CaC	002	002 1B Layered White Texture		3% Chrysotile	N/A	CaCO3		
DO3A Layered White Drywall Asbestos Not Present 20% Cellulose Gypsur  White Orange Peel Ceiling Texture 2% Chrysotile N/A (White) Paints Sand  White Orange Peel Ceiling Texture 2% Chrysotile N/A (White) Paints Sand  White Orange Peel Ceiling Texture 2% Chrysotile N/A (White) Paints Sand  White Orange Peel Ceiling Texture 2% Chrysotile N/A (White) Paints Sand  ONA 2C Homogeneous White Orange Peel Ceiling Texture 2% Chrysotile N/A (White) Paints Sand  ONA 25% Cellulose Vipul-CaC	002A	002A Layered White Drywall		Asbestos Not Present	20% Cellulose	Gypsum		
OO4   2A   Homogeneous   White Orange Peel Ceiling   2% Chrysotile   N/A   (White) Paints Sand	003	1C	Layered	White Texture	3% Chrysotile	N/A	CaCO3	
OO4	003A	.,		White Drywall	Asbestos Not Present	20% Cellulose	Gypsum	
005 2B Homogeneous Texture 2% Chrysotile N/A Sand  006 2C Homogeneous White Orange Peel Ceiling Texture 2% Chrysotile N/A Sand  007 3 Layered Off-White Sheet Flooring Ashestos Not Present 25% Cellulose Vinyl-CaC	004	2A	Homogeneous		2% Chrysotile	N/A	(White) Paint-CaCO3- Sand	
006 2C Homogeneous Texture 2% Chrysotile N/A Sand  O07 3 Layered Off-White Sheet Flooring Ashestos Not Present 25% Cellulose Vinyl-CaC	005	2B	Homogeneous	•	2% Chrysotile	N/A	(White) Paint-CaCO3- Sand	
1 NN7 I 3 I Lavered I Ott-White Sheet Flooring I Ashestos Not Present I I Vinyl-CaC	006	2C	Homogeneous		2% Chrysotile	N/A	(White) Paint-CaCO3- Sand	
15% Synthetic Fibers   15% Synthetic Fibers	007	3	Layered	Off-White Sheet Flooring	Asbestos Not Present	25% Cellulose 15% Synthetic Fibers	Vinyl-CaCO3	
007A Layered White Flooring Mastic Asbestos Not Present N/A Glue	007A		Layered	White Flooring Mastic	Asbestos Not Present	N/A	Glue	
007B Layered White Sheet Flooring Asbestos Not Present N/A Vinyl-CaCO3	007B		Layered	White Sheet Flooring	Asbestos Not Present	N/A	Vinyl-CaCO3-Foam	
007C Layered Clear Flooring Mastic Asbestos Not Present N/A Silicone	007C		Layered	Clear Flooring Mastic	Asbestos Not Present	N/A	Silicone	



### Clean your world.

### Disclaimer

- EPA Method 600/M4-82-020 (1982) was used to determine the presence or absence of asbestos fibers in all materials referenced in the above report. PLM analysis is based on visual estimation, and due to limitations of PLM analysis NESHAP regulations recommend that any material determined to contain less than 10% asbestos by the above referenced method should either be assumed to contain greater than 1% asbestos by the owner/operator, or be verified by PLM Point Count or TEM analysis as containing less than 1% asbestos.
- We recommend that TEM analysis be conducted for confirmation of negative PLM analytical results of vinyl floor tiles and vermiculite. These materials may contain asbestos fibers that cannot be detected by PLM analysis due to their size (<0.25 microns in diameter)
- This report may not be used to represent any materials not analyzed and listed in the included report. Advantage Environmental Inc. cannot be held responsible for the interpretation of the results shown. This report may not be reproduced in part and may only be reproduced in full without prior written consent from Advantage Environmental Inc.

# **ADVANTAGE Environmental** INC.

### **ASBESTOS CHAIN OF CUSTODY**

9317 NE Hwy 99. Suite D • {360) 356-7628

### **LEGAL DOCUMENT- PLEASE PRINT LEGIBLY**

		Paee 1 of 1
	Lab Use Only	
Survey	Lab 140. 110: ()	,-1-
Walk-In	Accept	Reject

AHERA Inspector/ Sampled By				Project Information			
Date:	ate: 1/10/2024			Company Name: Dry Time			
Name:	Name: Nick Phillips			Project Name: Stephens			
Phone:	ne: 360-931-8433		Project Location: 19913 NW Cedar Acres Dr, Ridgefield, WA				
Email:	Nick.PhilliQs@advantage-enviro.com			P.O. Number:			
RE	LINQUISHED BY	DATE&TIME	VIA	,	RECEIVED BY	DATE & TIME	
Name	Nick Phillips	Date 1/10/2024	Drop-off	V£1	'(ft1 VJ{C(	\ . / f"J· <i>r;</i>	
Sign	1	Time 4:00 PM		'	V	= *	

### REQUESTED SERVICES

		PLM		TURNAROUND TIME						
	Вι	ılk Analysis	0 '	Verbal 0	0 Rush 0 Same Day 0 24-Hour 0 3		0 3-Days	3		
No.	Sample ID	Color		Description		Volume/Area (as applicable) Comments/ Notes		Condition	Friable	
1	IA	White	Dry	wall & Joint Compound		200 SF	North wall	of the upstairs hallway bathroom	Poor	Yes
2	18	White	Dry	wall & Joint Compound		.J,	North wall	of the upstairs hallway bathroom	Poor	Yes
3	IC	White	Dry	wall & Joint Compound		.J,	North wall	of the upstairs hallway bathroom	Poor	Yes
4	2A	White	Ora	nge Peel Ceiling Texture		100 SF	Center	of the basement laundry room	Good	Yes
5	28	White	Ora	nge Peel Ceiling Texture		.J,	Center	of the basement laundry room	Good	Yes
6	2C	White	Ora	nge Peel Ceiling Texture		.J,	Center	of the basement laundry room	Good	Yes
7	3	Tan	L	ayered Sheet Flooring		120 SF	North side	of the upstairs hallway bathroom	Good	No
8									GIFIP	YIN
9									GIFIP	YIN
10									GIFIp	YIN
11								P8xl	GIFIP	YIN

Sample# Sample# Additional Notes

### THIS IS TO CERTIFY THAT

### **BLAKE MARSHALL**

# HAS SUCCESSFULLY COMPLETED THE TRAINING COURSE

### for

## **ASBESTOS INSPECTOR INITIAL COURSE**

In accordance with TSCA Title II, Part 763, Subpart E, Appendix C of 40 CFR

Course Date: <u>5/9/2022 - 5/11/2022</u>

Course Location: Portland, OR

Certificate: IN-22-0280C

For verification of the authenticity of this certificate contact:
PBS Engineering and Environmental Inc.



### CCB #SRA0614 24-Hr Training

24-Hour AHERA Inspector Training; AHERA is the Asbestos Hazard Emergency Response Act enacting Title II of Toxic Substance Control Act (TSCA)

**Expiration Date:** 05/11/2023

Andy Fridley, Instructor

ander Fielly