

11815 NE 99th Street, Suite 1294

Web: https://www.swcleanair.gov Email: Tina@swcleanair.gov

Vancouver, WA 98662 Voice: 360-574-3058 Fax: 360-576-0925

#### **Notification of Demolition**

Case #: 24-110

Date Received: 2/21/2024

Date Paid: 2/21/2024

SWCAA Fee: \$74.00

Amendment: 0

10 day waiting period from date submitted

Receipt #: 151568814

Type of Notification: Original
 Type of Operation: Demolition

3. Facility Description: same as above

Commercial Name or Description: mobile home

Address: 11316 NE 28TH ST #4

City/State/Zip/County: Vancouver, WA 98682 CLARK COUNTY

Present Use: Residence Previous Use: Residence

4. Facility Information

Property Owner: David Hoggatt

Mailing Address:

Contact: Phone:

5. Name and AHERA Certification Number of Asbestos Inspector:

Name: Don Young Certification #: 181914

6. Asbestos Removal Contractor (if applicable):

Name: Minority Abatement Contractors, Inc.

Mailing Address: 3200 NE 65th St, Vancouver, 98663

Contact: Valerie Whitebird Phone: 360-750-1900

7. Dates Asbestos Removal Occurred:

Start: 3/1/2024 Complete: 3/1/2024 Asbestos Case No.: -

8. Dates Demolition Will Occur:

Start: 3/2/2024 Complete: 3/2/2024

9. Demolition Contractor:

Name: Integrity Excavation and Construction, LLC Jason Hog

Mailing Address:

Contact: Phone:

10. Asbestos Disposal Site: N/A

<ol><li>Description of planned demolition work, method(s) to</li></ol>	be used:
Demo of existing old mobile home	
12. Fugitive Emssions/dust from Demolition Activites MUS	ST BE Controlled/Prevented during all phases of the project
water mist	
13. If unexpected Asbestos containing Material (ACM) is for Consult/Hire a Certified Asbestos Abatement Contractor	ound during demolition, Stop Work, Notify SWCAA and
abatement contractor to do abatement prior to demo	
14. If demolition is ordered by a Government Agent:	
Name:	Title:
Agency:	
Date of Order:	Date Ordered to Begin:
15. For Emergency Demolitions (Contact SWCAA prior to v	vork): Emergency Demolition
Date and Time of Emergency:	
Description of Sudden, Unexpected Event:	
Description of Sauden, Onexpected Events	
Explanation of how the event caused unsafe condition burden:	s or would cause equipment damage or an unreasonable
16. I Certify that the above information is correct:	
Submitter Name: DAVID HOGGATT	Representing: Integrity Excavation and Cons
Submitter Title: Emploee	Date Submitted: 2/21/2024

**Email Address:** dhoggatt1@gmail.com

**Reviewed by SWCAA:** Brian Fallon

✓ Approved

The Washington State Dangerous Waste Regulations (WAC 173-303) require that demolition debris be evaluated to determine if it is dangerous. The evaluation should be completed before demolition to ensure that hazardous constituents are not released to the environment and do not present a risk to human health during or after demolition. These requirements apply to all buildings being demolished and are the responsibility of the property owner. The Washington Department of Ecology's website, https://ecology.was.gov/Regulations-Permits/Guidance-technical-assistance/Dangerous-waste-guidance/Common-dangerouswaste/Construction-and-demolition, provides more information about the requirements and about sampling and testing construction materials to detemine if they present a risk. For more information please contact a Hazardous Waste Inspector at the Washington Department of Ecology Southwest Regional Office: (360) 407-6300.

#### **ASBESTOS SURVEY**

For the mobile home and sheds located at:

#### 11316 NE 28<sup>TH</sup> STREET #4 VANCOUVER, WASHINGTON

Prepared for: EG Ventures, LLC

CERTIFIED ENVIRONMENTAL CONSULTING, LLC 615 SE CHKALOV DRIVE SUITE 12 VANCOUVER, WASHINGTON 98683-5280

> Prepared by: Don Young Eric S. Viken

#### **EXECUTIVE SUMMARY**

Dear Mr. Hoggatt:

Enclosed are the results of the asbestos survey report conducted by C.E.C., LLC, for the mobile home and sheds located at, 11316 NE 28<sup>th</sup> Street, in Vancouver, Washington for demolition purposes. This survey was coordinated with you and conducted on January 30, 2024, by Eric S. Viken, and Don Young, AHERA certified inspectors. Please note that this these structures have some materials in damaged condition and/or disturbed.

All samples were taken in a random manner as required by EPA AHERA rules and analyzed using polarized light microscopy with dispersion staining according to EPA and OR-OSHA Methodology. The samples were analyzed in C.E.C., LLC's laboratory at, 615 SE Chkalov Drive Suite #12, in Vancouver, Washington. As the asbestos samples were analyzed in our laboratory, the analytical data enclosed is the analysis report.

Asbestos was identified in the silver roof paint/coating (See sample data sheet attached). Please note: the quantities and/or amounts listed within (Summary Data, Assessment of Materials sections) are estimates only and are not to be relied upon for estimating the removal costs. All quantities and/or amounts should be field verified by the responsible parties for the true amounts and removal costs.

The following survey is divided into the following sections:

- Summary sheet details the type and construction of the building with approximate amounts of asbestos in the building.
- Sample result sheet contains sample numbers and results, description of materials and homogeneous areas of material.
- Assessment of materials contains an assessment of asbestos materials.
- A Response actions recommended contains the response actions we recommend.
- ♦ Laboratory analysis sheet contains the results of our laboratory analysis.
- ◊ Inspector's certifications.
- ♦ Photographic log.
- Asbestos chain of custody form (survey report form).

C.E.C. has investigated accessible and inaccessible areas of this facility in locating suspect ACM using destructive sampling including the interior and exterior. The current extent and condition of the ACM was detected through on-site observation and physical determination.

NOTE: This asbestos survey report is available to EG Ventures, LLC, and not to be reproduced in total or part without written consent of EG Ventures, LLC.

We appreciate the opportunity to have worked with you. If you have any questions or if we can be of any further service, please contact our office.

Sincerely,

Don Young Principal

#### SUMMARY SHEET

Owner or Representative: David Hoggatt

Address: Mobile Home and Sheds at, 11316 NE 28th Street #4

City: Vancouver State: Washington

Owner's Representative: EG Ventures, LLC

Mr. David Hoggatt 14060 NW Harvest Lane Portland, Oregon 97229

Owner/Rep. Telephone Number: (360) 600-4159

Surveyed by: Eric S. Viken-Accreditation Number: 192140

Don Young-Accreditation Number: 190124

#### **CONSTRUCTION DATA:**

Year Built: Approx.: 1973-Mobile Home and Sheds

Size: Approx. 720 SQ FT-Mobile Home, 80 SQ FT-Rectangular Shed, 100 SQ FT-Barn Style Shed

Construction Type: Wood, Metal, Concrete-All Structures

Number of Floors: 1-All Structures

Current/Past Use: Residential/Residential

Roof Construction: Metal with Asbestos Containing Silver Paint-Mobile Home, Metal-Barn Style

Shed, Asphalt Roofing Material-Rectangular Shed

Heating System: Forced Air-Mobile Home, No Heating Systems Present-Sheds

Attic Insulation: Fiberglass-Mobile Home & Barn Style Shed, No Attic Space Present-Rectangular

Shed

Pipe Insulation: Non-Insulated-Mobile Home, No Pipes Present-Sheds

#### **SUMMARY DATA**

## MOBILE HOME AND SHEDS AT, 11316 NE 28<sup>TH</sup> STREET #4, VANCOUVER, WASHINGTON

PRODUCT	FUNCTIONAL SPACE	AMOUNT	FRIABLE	CONDITION	SAMPLE #	RESULTS
SILVER ROOF PAINT/COATING	ON METAL ROOF MOBILE HOME, THROUGHOUT ON METAL ROOF MOBILE HOME	APPROX. 720 SQ FT	YES	GOOD	7, 8, 9	5% CHRYSOTILE

Please note: the quantities and/or amounts listed within (Summary Data, Assessment of Materials sections) are estimates only and are not to be relied upon for estimating the removal costs. All quantities and/or amounts should be field verified by the responsible parties for the true amounts and removal costs.

Certified Environmental Consulting, LLC, warrants that the findings contained herein have been prepared in general accordance with accepted professional practices as applied by similar professionals in the community at the time of this report preparation. Changes in the state of the art or in applicable regulations cannot be anticipated and have not been addressed in this report. The field and laboratory results reported herein are considered sufficient in detail and scope to determine presence of asbestos containing materials in or around the area(s) requested at the time of the inspection. Test results are valid only for the materials tested.

There is a distinct possibility that conditions may exist that could not be identified within the scope of the inspection or that were not apparent during the site visit. This inspection covered only those areas that were exposed or physically accessible to the inspector. The inspection is limited to the information available from the client at the time of the inspection was conducted.



#### SAMPLE RESULTS

# MOBILE HOME AND SHEDS AT, 11316 NE 28<sup>TH</sup> STREET #4, VANCOUVER, WASHINGTON

	WASHINGTON					
SAMPLE #	SAMPLE DESCRIPTION	SAMPLE LOCATION	HOMOGENEOUS AREA	ASBESTOS CONTENT		
1	PINK/YELLOW INSULATION	EXTERIOR WALL MOBILE HOME	CRAWLSPACE AND ATTIC MOBILE HOME	NONE DETECTED		
2	WHITE FLOOR TILE AND MASTIC	HALLWAY BATHROOM		NONE DETECTED		
3	YELLOW/CREAM SHOWER SURROUND AND MASTIC	HALLWAY BATHROOM		NONE DETECTED		
4	WHITE COUNTERTOP MATERIAL AND MASTIC	HALLWAY BATHROOM	KITCHEN	NONE DETECTED		
5	BLACK/CREAM FLOOR TILE AND MASTIC	UNDER PERGO FLOORING BATHROOM	UNDER PERGO FLOORING KITCHEN	NONE DETECTED		
6	GREEN/WHITE SHEET VINYL	UNDER CARPET BACK BEDROOM	HALLWAY BATHROOM CLOSET, UNDER CARPET LIVING ROOM	NONE DETECTED		
7	SILVER ROOF PAINT/COATING	ON METAL ROOF MOBILE HOME	THROUGHOUT ON METAL ROOF MOBILE HOME	5% CHRYSOTILE		
8	SILVER ROOF PAINT/COATING	ON METAL ROOF MOBILE HOME	THROUGHOUT ON METAL ROOF MOBILE HOME	5% CHRYSOTILE		
9	SILVER ROOF PAINT/COATING	ON METAL ROOF MOBILE HOME	THROUGHOUT ON METAL ROOF MOBILE HOME	5% CHRYSOTILE		
10	WHITE/PINK SHEET VINYL	ON EXTERIOR WINDOWSILLS MOBILE HOME		NONE DETECTED		
11	BLACK ASPHALT ROOFING MATERIAL	TOP LA YER RECTANGULAR SHED ROOF	THROUGHOUT	NONE DETECTED		
12	BLACK TAR PAPER	BOTTOM LAYER RECTANGULAR SHED ROOF	THROUGHOUT	NONE DETECTED		
13	PINK/YELLOW INSULATION	BARN STYLE SHED		NONE DETECTED		

#### ASSESSMENT OF MATERIALS

## Building: MOBILE HOME AND SHEDS AT, 11316 NE 28<sup>TH</sup> STREET #4, VANCOUVER, WASHINGTON

Sample #'s	Functional Space	Asbestos Type	%	Material And Condition	Comments	Sq. Ft. And/or Linear Footage
7, 8, 9	ON METAL ROOF MOBILE HOME, THROUGHOUT ON METAL ROOF MOBILE HOME	CHRYSOTILE	5%	SILVER ROOF PAINT/COATING	SEE RESPONSE ACTIONS	APPROX. 720 SQ FT

Please note: the quantities and/or amounts listed within (Summary Data, Assessment of Materials sections) are estimates only and are not to be relied upon for estimating the removal costs. All quantities and/or amounts should be field verified by the responsible parties for the true amounts and removal costs.

Inspector: Eric S. Viken- Accreditation Number: 192140

ignature: Date: February 7, 2024

#### RESPONSE ACTIONS RECOMMENDED

Building: MOBILE HOME AND SHEDS AT, 11316 NE 28<sup>TH</sup> STREET #4, VANCOUVER, WASHINGTON

MATERIAL	LOCATION	RECOMMENDED RESPONSE ACTIONS
SILVER ROOF PAINT/COATING	ON METAL ROOF MOBILE HOME, THROUGHOUT ON METAL ROOF MOBILE HOME	Silver roof paint/coating a friable material currently in good condition and poses no health hazards in its present state. Must be maintained in an intact condition. Must be removed prior to renovation or demolition.

Management Planner: Don Young - Accreditation Number: 190128

Signature:

Date February 7, 2024

#### SAMPLE ANALYSIS REPORT

**CLIENT:** EG VENTURES, LLC

SOURCE: MOBILE HOME AND SHEDS AT,

11316 NE 28TH STREET #4, VANCOUVER,

WASHINGTON

MR. DAVID HOGGATT

14060 NW HARVEST LANE

PORTLAND, OREGON 97229 ANALY

**SAMPLED BY:** ERIC S. VIKEN LAB/JOB #: JJ-169/24-23

ANALYZED BY: ERIC S. VIKEN

DATE SAMPLED: 01-30-24 DATE RECEIVED: 01-30-24 DATE COMPLETED: 01-31-24

ANALYTICAL METHOD: EPA 600/R-93/116, 40 CFR Part 763, Subpart E, Appendix E, Section 1,

PLM/Dispersion Staining

SAMPLE ID #	SAMPLE DESCRIPTION	SAMPLE LOCATION	ASBESTOS CONTENT	OTHER MATERIAL
1	PINK/YELLOW INSULATION	EXTERIOR WALL MOBILE HOME	NONE DETECTED	80% FIBERGLASS, DEBRIS
2	WHITE FLOOR TILE AND MASTIC	HALLWAY BATHROOM	NONE DETECTED	2% CELLULOSE, CALCIUM CARBONATE, VINYL, BINDER, ADHESIVE
3	YELLOW/CREAM SHOWER SURROUND AND MASTIC	HALLWAY BATHROOM	NONE DETECTED	60% CELLULOSE, VINYL, ADHESIVE
4	WHITE COUNTERTOP MATERIAL AND MASTIC	HALLWAY BATHROOM	NONE DETECTED	55% CELLULOSE, FORMICA, EPOXY, ADHESIVE
5	BLACK/CREAM FLOOR TILE AND MASTIC	UNDER PERGO FLOORING BATHROOM	NONE DETECTED	CALCIUM CARBONATE, VINYL, BIDER, ADHESIVE
6	GREEN/WHITE SHEET VINYL	UNDER CARPET BACK BEDROOM	NONE DETECTED	65% CELLULOSE, VINYL, BINDER
7	SILVER ROOF PAINT/COATING	ON METAL ROOF MOBILE HOME	5% CHRYSOTILE	10% FIBERGLASS, TAR, PAINT, ADHESIVE

ANALYST:

DEVIATION FROM METHOD: NONE. PERCENTAGES ARE ESTIMATES.

TEST RESULTS PERTAIN ONLY TO ITEMS TESTED.

\* DETECTION LIMIT IS LESS THAN 1% ASBESTOS.

NON-ASBESTOS MATERIALS ARE NOT NECESSARILY LISTED.

REVIEWED BY:

#### SAMPLE ANALYSIS REPORT

CLIENT: EG VENTURES, LLC SOURCE: MOBILE HOME AND SHEDS AT,

11316 NE 28<sup>TH</sup> STREET #4, VANCOUVER,

WASHINGTON

MR. DAVID HOGGATT SAMPLED BY: ERIC S. VIKEN

14060 NW HARVEST LANE
PORTLAND, OREGON 97229

LAB/JOB #: JJ-169/24-23
ANALYZED BY: ERIC S. VIKEN

DATE SAMPLED: 01-30-24 DATE RECEIVED: 01-30-24 DATE COMPLETED: 01-31-24

ANALYTICAL METHOD: EPA 600/R-93/116, 40 CFR Part 763, Subpart E, Appendix E, Section 1,

PLM/Dispersion Staining

SAMPLE ID #	SAMPLE DESCRIPTION	SAMPLE LOCATION	ASBESTOS CONTENT	OTHER MATERIAL		
8	SILVER ROOF PAINT/COATING	ON METAL ROOF MOBILE HOME	5% CHRYSOTILE	10% FIBERGLASS, TAR, PAINT, ADHESIVE		
9	SILVER ROOF PAINT/COATING	ON METAL ROOF MOBILE HOME	5% CHRYSOTILE	10% FIBERGLASS, TAR, PAINT, ADHESIVE		
10	WHITE/PINK SHEET VINYL	ON EXTERIOR WINDOW SILLS MOBILE HOME	NONE DETECTED	20% CELLULOSE, 3% FIBERGLASS, VINYL, CALCITE, ADHESIVE		
11	BLACK ASPHALT ROOFING MATERIAL	TOP LAYER RECTANGULAR SHED ROOF	NONE DETECTED	20% FIBERGLASS, TAR, AGGREGATE		
12	BLACK TAR PAPER	BOTTOM LAYER RECTANGULAR SHED ROOF	NONE DETECTED	65% CELLULOSE, TAR		
13	PINK/YELLOW INSULATION	BARN STYLE SHED	NONE DETECTED	80% FIBERGLASS, DEBRIS		

ANALYST:

DEVIATION FROM METHOD: NONE.

PERCENTAGES ARE ESTIMATES.

TEST RESULTS PERTAIN ONLY TO ITEMS TESTED.

\* DETECTION LIMIT IS LESS THAN 1% ASBESTOS.

NON-ASBESTOS MATERIALS ARE NOT NECESSARILY LISTED.

## **Certificate of Completion**

This is to certify that

Eric S. Viken

has satisfactorily completed 4 hours of online refresher training as an

AHERA Building Inspector

to comply with the training requirements of TSCA Title II, 40 CFR 763 (AHERA)

EPA Provider # 1085

192140 Certificate Number

Instructor: Tracy Bockla

Dec 27, 2023

Expires in 1 year.

Date(s) of Training Exam Score: N/A (f applicable)



\* Facilities \* Environmental \* Geotechnical \* Materials

TEPPACON TRAINING FORMERLY ARGUS FACTITO / 21905 64TH AVE W. SUITE 100/ MOUNTLAKE TERRACE, WASHINGTON 98043 / 206.285.3373 / ARGUSPACTITO.COM

### **Certificate of Completion**

This is to certify that

#### Don E. Young

has satisfactorily completed 4 hours of online refresher training as an

AHERA Building Inspector

to comply with the training requirements of

TSCA TILLE II, 40 CFR 763 (AHERA)

EPA Provider # 1085

190124 Certificate Number

Instructor: David Welch





Jul 13, 2023

Expires in 1 year.

TER AL IN TRAINING - POPERTY ANAUS PACIFIC / 23 MM, NATH AND IN, SULTE 100 / HOUNTLAKE TERRACE, WASHINGTON 980 43 / 206 255 1373 / APGUSPACIFIC.COM

### **Certificate of Completion**

This is to certify that

Don E. Young

has satisfactorily completed 4 hours of refresher training as an

AHERA Management Planner

to comply with the training requirements of TSCA Title II, 40 CFR 763 (AHERA)

EPA Provider # 1085

190128 Certificate Number



Jul 13, 2023 Expires in 1 year. Date(s) of Training

Exam Score: N/A (# applicable)


TERRACEN TRAINING TORNERS ARABS FACIFIC (2595 64TH 6/E W. SUITE 1007 HOUNTLAKE TERRACE, WASHINGTON 98043 / 206 285 3373 / ARGUSPACIFIC COM



















































DATE:	630-64 SAMPLED BY: _8	COST/QUOTE \$	LAB#_ <u>\(\frac{1}{2}\)</u> PO#/JOB#&	169				
CLIENT: E6 Ventures LLC CONTACT: David Hoggett								
BILLING ADDRESS: CITY/STATE: ZIP:  Mobile Home o Shed 3 out								
PHONE:		1						
PROJECT YEAR B	t address: <u>      3   6   nc</u> uilt: <u>    9   73  </u> totai	28257 #4 Val 720 Sa FF Millie HM 100 SF: 00547 CONSTRUCTI	on type wood, mera	1, wacret c				
HOW M MATON ROOFIN	HOW MANY FLOORS: 1 - All Styletures BASEMENT PRESENT: NO MICHAL WHOM CONTINUE HOME ROOFING TYPE: Alm recipies the sheet Building use previous/current: Res.  HEATING SYSTEM: Forced acj. Howinsulation: ATTIC: F. G Burg PIPES: Mobile Home  NO High My Surfam word Shed NO Attic Space Ref and No Pipes present Shed S							
AMPLE #	DESCRIPTION OF MATERIAL	SAMPLE LOCATION	HOMOGENEOUS AREA	SQ FOOTAGE				
1	Insulation Pinklyeller	Mobile Home	Craw13Pacc Attic Space	14000				
٤	Floor till white	Bathroom						
>	shows some	Hall Bothman		50				
4	white im	Hall Bathwoon	15.76hen	25°				
5	Flourtike Bluck Cream	Hall Bathrow	Withen	lvv				
6	Green white	Back bedom under Carpet	Hall BAN Closet. LURM under Corpet	1000				
7	Silver Point / Cong	Root metal momble Alm	ROOFMOBIL HM	7200				
8	Silver paint Louting	Roof metal Mobile none	RODE Mobiletim	720°				
9	siver Paini/ Coating	n motal mobile	n.on Meta	7200				

615 SE CHKALOV DRIVE SUITE 12, VANCOUVER, WASHINGTON 98683-5280 (503) 221-7904 PHONE (360) 254-9385 AND FAX-(360) 891-9633

#### **SURVEY SAMPLE FORM**

LAB# 1169

SAMPLE #	DESCRIPTION OF MATERIAL	SAMPLE LOCATION	HOMOGENEOUS AREA	SQ FOOTAGE
10	SHU White/PINK	Sill's Molail Home		100
11	ARM BIOUK	Root top langer	$\mathcal{R}_{o}$	50"
12	Tor Paper Block	Bottom layer Rectangular poor	Ru	50"
13	Insumolon Pink/Yellow	Born Style Shed	*	300
	м			
			307	
	2 V			
	ন্			
			1	

615 SE CHKALOV DRIVE SUITE #12 • VANCOUVER, WASHINGTON 98683-5280 • (503) 221-7904 • (360) 254-9385 • FAX (360) 891-9633

#### INVOICE ACCOUNT: **INVOICE NO: 55624 INCLUDE THIS NUMBER** ON YOUR PAYMENT EG VENTURES, LLC ATTN: ACCOUNTS PAYALE DATE: FEBRUARY 8, 2024 14060 NW HARVEST LANE **PURCHASE ORDER #** PORTLAND, OREGON 97229 C.E.C. PROJECT #JJ-169 **TERMS** VISIT US ON THE WEB NET 20/ACCOUNTS OVER 66 DAYS MAY BE REFERRED TO www.certified-environmental-consulting.com OCL # 197023/FED TAX ID #45-4104910 A COLLECTION AGENCY **PRICE PER AMOUNT** ASBESTOS SURVEY AND LEAD PAINT REPORT AT MOBILE HOME AND SHEDS AT, 11316 NE 28TH STREET #4, VANCOUVER, WA ON 01-30-24 AS REQUESTED BY DAVID HOGGATT 1 ASBESTOS SURVEY AND LEAD PAINT REPORT 1.100.00 EACH 1.100.00

PLEASE FORWARD INVOICE TO YOUR ACCOUNTING DEPARTMENT		
PLEASE REFER TO OUR INVOICE NO 55624 ON YOUR REMITTANCE,		
THANK YOU! CEC NOW ACCEPTS MOST MAJOR CREDIT CARDS		
TOTAL DUE		\$1,10

February 7, 2024

EG Ventures, LLC Mr. David Hoggatt 14060 NW Harvest Lane Portland, Oregon 97229

Dear Mr. Hoggatt:

On January 30, 2024, three lead paint samples were collected from the mobile south exterior metal siding, barn style shed south side on wood, rectangular shed on wood south side. The samples were collected at the mobile home and sheds at, 11316 NE 28<sup>th</sup> Street #4, in Vancouver, Washington. The samples were collected by Don Young; A State of Washington Department of Commerce Lead Paint Program Certified Lead Risk Assessor (Certification #6219) and analyzed by EMSL Analytical, Inc., in San Leandro, California (NLLAP Certificate #LAP-101748). Please note that this sampling is for demolition purposes.

The samples were analyzed by flame Atomic Absorption spectrophotometry with sample results of 93 ppm (parts per million), and <80 ppm (parts per million). The current regulatory guidelines issued by HUD and EPA specify that paint containing more than 5000 ppm be considered lead paint.

OSHA's standard makes it absolutely clear that paint containing any lead falls into OSHA's guideline, 29 CFR 1926.62 "Lead For The Construction Industry" and Washington Code WAC 296-155-176, where an employee may become occupationally exposed to lead. All construction work excluded in the general industry standard for lead is now covered by this standard. It includes the demolition or salvage of structures where lead or materials of lead are present.

If lead is present in your workplace in any quantity, the employer and/or owners' representative is required to make an initial determination of whether any employee's exposure to lead exceeds the action level of 30 micrograms per cubic meter of air averaged over an 8-hour day. Employee exposure is that exposure which would occur if the employee were not using a respirator.

There are requirements for employee protection during the assessment for each specific task(s). For these tasks, employees must be protected as if exposed above the PEL (permissible exposure limit, greater than 50 micrograms per cubic meter of air, averaged over an eight-hour period).

When applicable, disposal requirements call for a Toxic Characteristic Leaching Procedure (TCLP) test to be done to profile the debris, as per 40 CFR 148, before any disposal can occur to determine if it is a hazardous waste as defined by the EPA.

We appreciate the opportunity to have worked with you on this project and look forward to serving you needs in the future. Please contact our offices, if you have any questions or if we can be of further assistance.

Sincerely,

Principal

#### LEAD PAINT ANALYSIS REPORT

#### CLIENT:

EG VENTURES, LLC

SOURCE:

MOBILE HOME AND SHEDS AT, 11316 NE

28TH STREET #4, VANCOUVER,

WASHINGTON

MR. DAVID HOGGATT

SAMPLED BY:

DON YOUNG

14060 NW HARVEST LANE

LAB#:

JJ-169

PORTLAND, OREGON 97229

ANALYZED BY:

EMSL ANALYTICAL, INC.

(NLLAP CERTIFICATE #LAP-101748)

**DATE SAMPLED:** 01-30-24 **DATE RECEIVED:** 01-30-24 **DATE (COMP):** 02-01-24

LEAD IN PAINT CHIPS BY FLAME ATOMIC ABSORPTION (SW 846 305B/7000B)\*

SAMPLE #	SAMPLE DESCRIPTION	SAMPLE LOCATION	WEIGHT	LEAD CONCENTRATION PPM
1	TAN PAINT	MOBILE HOME SOUTH EXTERIOR METAL SIDING	0.2522 g	93
2	WHITE PAINT	BARN STYLE SHED SOUTH SIDE ON WOOD	0.2594 g	<80
3	WHITE PAINT	RECTANGULAR SHED SOUTH SIDE ON WOOD	0.2528 g	<80

REVIEWED BY:

DON YOUNG

12000

The current regulatory guidelines issued by HUD and EPA specify that paint containing more than 5000 ppm be considered lead paint.

<sup>\*</sup> Analysis following lead in paint by EMSL SOP/Determination of Environmental lead by FLAA. Reporting limit is 0.010% wt. based on the minimum sample weight per our SOP. Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above. Samples received in good condition unless otherwise noted. "<" (less than) result signifies that the analyte was not detected at or above the reporting limit.

#### STATE OF WASHINGTON

Department of Commerce Lead-Based Paint Abatement Program

Donald Eugene Young, Jr.

Has fulfilled the certification requirements of WAC 365-230 and has been certified to conduct lead-based paint activities as a Risk Assessor

Certification #

Issuance Date

Expiration Date

06/13/2022

07/11/2025



#### STATE OF WASHINGTON

Department of Commerce Lead-Based Paint Abatement Firm

Certified Environmental Consulting, LLC

Has fulfilled the certification requirements of WAC 365-230 and has been certified to conduct lead-based paint activities.

Certification #

Issuance Date

Expiration Date 05/10/2025

144

06/13/2022

Department of Labor and Industries

PO Box 44450

Olympia, WA 98504-4450

CERTIFIED ENVIRNMTL CNSLTG LLC

Reg: CC CERTIEC881K2

UBI: 603-172-593

Registered as provided by Law as: Construction Contractor

(CCXX) - Asbestos and Lead

CERTIFIED ENVIRNMTL CNSLTG LLC

615 SE CHKALOV DRIVE

SUITE 12

VANCOUVER WA 98683

Effective Date: 5/22/2012 Expiration Date: 5/22/2024





#### AIHA Laboratory Accreditation Programs, LLC SCOPE OF ACCREDITATION

EMS L Analytical, Inc. 484 McComick Street, Sen Leendro, CA 94577 Leboratory ID: LAP-101748 leave Date: 06/01/2022

The laboratory is approved for those specific field(e) of testing/methods lieted in the table below. Clients are urged to verify the laboratory's current accreditation status for the particular field(e) of testing/Methods, since these can change due to proficiency status, suspension and/or withdrawal of accreditation.

The EPA recognizes the AIHA LAP, LLC ELLAP program as meeting the requirements of the National Lead Leboratory Accreditation Program (NLLAP) setablished under Title X of the Residential Lead-Based Paint Hazard Reduction Act of 1992 and includes paint, soil and dust wipe analysis. Air and composited wipes analyses are not included as part of the NLLAP.

#### Environmental Lead Laboratory Accreditation Program (ELLAP)

#### Initial Accreditation Date: 02/01/2020

Coreponent, paremoter or characteristic bated	Teelvral oggreste-type/Detector	Method	noitgresed beertplion (for etodem iganetaina)
Airtome Duet	AA	NBQ594 778-2:	
Point		EPA \$94 845 TODOH	
		EPA 5 94-848 3060回	
Markey Print by Mine		EPA SW \$45 TODOS	
Selled Dust by Wilpe		EPA \$ 14-040 \$0000	
		EPA 5W 545 Y000B	
2504		EPA 5 W-845 30508	

A complete listing of currently accredited ELLAP leboratories is available on the AIHA LAP, LLC website at: <a href="http://www.eiheecoreditediabs.org">http://www.eiheecoreditediabs.org</a>

Effective: 07/29/2021 Revision: 9.1 Page 1 of 1




### **PHOTOGRAPHIC LOG**





























#### **EMSL Analytical, Inc**

464 McCormick Street, San Leandro, CA 94577 Phone/Fax (510) 895-3675 / (510) 895-3680

http://www.EMSL.com

sanleandrolab@emsl.com

EMSL Order:

092402145

CustomerID: CustomerPO: CECI50 JJ-163

ProjectID:

**Annie Hamilton** 

Certified Environmental Consulting, Inc. 615 S.E. Chkalov Drive Suite 12

Vançouver, WA 98683-5280

JJ-18 EG Ventures, 11C

JJ-163 VERG RESTORATION

(503) 221-7904 Phone:

Fax:

Received:

2/1/2024 09:00 AM

Collected:

1/29/2024

#### Test Report: Lead in Paint Chips by Flame AAS (SW 846 3050B/7000B)\*

Client Sample Description	Lab ID	Collected	Analyzed	Weight	Lead Concentration
1	092402145-0001	1/29/2024	2/1/2024	0.2522 g	93 ppm
	Site: SOUTH EX WOOD SOUTH		TAL SIDING BARN STYLE SHED ON		
2	092402145-0002	1/29/2024	2/1/2024	0.2594 g	<80 ppm
	Site: BARN STY	LE SHED O	N WOOD SOUTH SIDE		
3	092402145-0003	1/29/2024	2/1/2024	_ 0.2528 g	<80 ppm
	Site: RESTANG	ULAR SHEE	ON WOOD SOUTH SIDE		

Oscar Merino, Laboratory Manager or other approved signatory

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in ful, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted.

\*Analysis following Lead in Paint by EMSL SOP/Determination of Environmental Lead by FLAA. Reporting limit is 0.008% wt based on the minimum sample weight per our SOP. "<" (less than) result signifies the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. Definitions of modifications are available upon request.

Samples analyzed by EMSL Analytical, Inc San Leandro, CA AlHA LAP, LLC-ELLAP Accredited #101748

Initial report from 02/01/2024 13:33:37

OrderID: 092402145



# Lead Chain of Custody EMSL Order Number / Lab Use Only

092402145

EMSL Analytical, Inc. 464 McCormick Street

San Leandro, CA 94577 PHONE: (510) 895-3675

EMAIL: sanleandrolab@emsi.com

Customer ID:		Billing ID:	Billing ID:					
Company Name: Certified Enviro	onmental Consulting, Inc	Company N	g Company Name: Certified Environmental Consulting, Inc					
Company Name: Certified Environment Contact Name: Annie Hamilton		Billing Cont	Billing Contact: Annie Hamilton					
Street Address: 615 C E Chke	alov Drive Suite 12	Street Addr	Street Address: 615 S.E. Chkalov Drive Suite 12					
b OTO S.E. CIIKA	WA 98683-(Country: US	E	E 015 S.E. Clikalov Dilve Suite 12					
Valicouvel	VVA 98063-1 US	City, State,	vance		A 90003			
8 303-221-1904		Email(s) for		21-7904				
Emell(s) for Report: annieh_cec(			anvoice.					
Project 11 100 TO 16	P	roject Information		Purchase				
Project Name/No: JJ-169 EG Ventures			Order:					
EMSL LIMS Project ID: (if applicable, EMSL will provide)		US State where samples collecte	S State where Imples collected: WA State of Connecticut (CT) must select project location:    Commercial (Taxable)   Residential (Non-Taxat)					
Sampled By Name: Don Young	Sampled By Signature:				No. of Samples 3			
	Turr	n-Around-Time (TAT)	_					
3 Hour 6 Hour	24 Hour 32 Hour sall shoot for large projects and/or tumoround times 6 Hours	46 Hour	72 Hour	96 Hour	1 Week 2 Week			
MATRIX	METHOD	INSTRUM		REPORTING LIMIT				
CHIPS TO STATE OF THE STATE OF	SW 846-7000B	Flame Atomic A	osorption	0.008% (80ppm)				
*Reporting Limit based on a minimum 0.25g sample weight	SW 846-6010D*	ICP-OE	3	0.0004% (4ppm)				
	NIOSH 7082	Flame Atomic A	bsorption	4µg/filter				
AIR	NIOSH 7300M / NIOSH 7303M	ICP-OE	3	0.5µg/filter				
	NIOSH 7300M / NIOSH 7303M	ICP-MS		0.05µg/filter	3			
WIPE ASTM NON-ASTM	SW 846-70008	Flame Atomic Absorption		10µg/wipe				
*If no box is checked, non-ASTM Wipe is assumed	SW 846-6010D°	ICP-OE	ICP-OES					
TCLP	SW 846-1311 / 7000B / SM 3111B	Flame Atomic A		0.4 mg/L (ppm)				
	SW 846-1311 / SW 846-6010D* SW 846-1312 / 7000B / SM 3111B	ICP-OES Flame Atomic Absorption		0.1 mg/L (ppm) 0.4 mg/L (ppm)				
SPLP	SW 846-1312 / SW 846-6010D*	ICP-OES		0.1 mg/L (ppm)				
71.0	22 CCR App. II, 7000B	Flame Atomic Absorption		40mg/kg (ppm)				
TTLC	22 CCR App. II, SW 846-6010D*	ICP-OE	S	2mg/kg (ppm)				
STLC	22 CCR App. II. 7000B	Flame Atomic Absorption		0,4 mg/L (ppm)				
	22 CCR App. II, SW 846-6010D* SW 846-7000B	ICP-OES Flame Atomic Absorption		0.1 mg/L (ppm) 40mg/kg (ppm)				
Soll	SW 846-6010D*	ICP-OES		2mg/kg (ppm)				
Wastewater	SM 3111B / SW 846-7000B	Flame Atomic Absorption		0.4 mg/L (ppm)	8			
Unpreserved Preserved with HNO3 PH<2	EPA 200.7	ICP-OE	5	0.020 mg/L (ppm)				
Drinking Water	EPA 200.5	ICP-OE	S	0.003 mg/L (ppm)				
Unpreserved Preserved with HNO3 PH<2	EPA 200.8	ICP-MS		0.001 mg/L (ppm)				
TSP/SPM Filter	40 CFR Part 50	ICP-OE	S	12 µg/filter				
Other:								
Sample Number	Sample Location		Vol	ume / Area	Date / Time Sampled			
1	South Exterior Metal Si	Siding			1/30/24			
2	Barn Style Shed on Wood S	South Side	Side		1/30/24			
3	Rectangualr Shed on Wood	South Side	1/30/24		1/30/24			
Method of Shipment:		Sample Co	ndition Upon Recei	pt:				
Relinquished by: Annie Hami	Iton Data/Time: 1/31/24	10.49 Received	y NO E	FX3	Date/Time 0 11/24 Q LIA			
Relinquished by:	Date/Time:	Received			2/1/24 9 AM			
Controlled Document - COC-25 Leed R16 4/19/2021	SENSO Available							

\*6010C Available Upon Request AGREE TO ELECTRONIC SIGNATURE (By checking, I consent to signing this Chain of Custody do

Page 1 of 2