



11815 NE 99th Street, Suite 1294
Vancouver, WA 98662
Voice: 360-574-3058
Fax: 360-576-0925
Web: <https://www.swcleanair.gov>
Email: Tina@swcleanair.gov

Notice of Intent to Remove Asbestos

Case #: 24-131

Amendment: 0

Date Received: 3/1/2024

Date Paid: 3/1/2024

SWCAA Fee: \$738.00

Receipt #: 152146088

This notification MUST be present at all times at the asbestos project sit

*** EMERGENCY NOTICE ***

Quantity to be removed: 196 Square Feet 0 Linear Feet

Workshift days: M

Project starting date: 3/4/2024 Project Completion date: 3/4/2024

Workshift hours: 10am-3pm

Site Name: Randy Forest

Site address: 229 Louise St

Location of Asbestos: kitchen

City/State/Zip: Kelso WA 98626

☐ Demolition of Structure (Notification of Demolition required)

County: COWLITZ COUNTY

☒ Asbestos survey conducted?

No survey reason:

AHERA Inspector: Delfino Montes

Certification #: IN-23-9487B

Material to be Removed:

- | | | | | | |
|---|--|------------------------------|---|--|------------------------------------|
| <input type="checkbox"/> Fireproofing | <input type="checkbox"/> Popcorn Ceiling | <input type="checkbox"/> CAB | <input checked="" type="checkbox"/> Sheet Vinyl | <input type="checkbox"/> Boiler Insulation | <input type="checkbox"/> Duct Tape |
| <input type="checkbox"/> Duct Paper | <input type="checkbox"/> Mag Pipe Insulation | | <input type="checkbox"/> Air Cell | <input type="checkbox"/> CA Pipe | <input type="checkbox"/> VAT |
| <input checked="" type="checkbox"/> Other Drywall | | | | | |

Control Methods:

- | | | | | | |
|---|------------------------------------|---|---------------------------------------|---|--|
| <input checked="" type="checkbox"/> N.P Enclosure | <input type="checkbox"/> Glove Bag | <input type="checkbox"/> Mini Enclosure | <input type="checkbox"/> Wrap and Cut | <input checked="" type="checkbox"/> Water | <input checked="" type="checkbox"/> HEPA Vac |
| <input type="checkbox"/> Other | | | | | |

Asbestos Contractor: Abatement Services of Washington

Phone: 503-857-7175

Mailing Address: PO Box 747, Beavercreek, OR, 97004

Email: tristan@abateservices.com

Certification ##: ABCN00001610

Supervisor: Torell Ireton

Phone: 971-412-1906

Property Owner: Randy Forest

Phone: 360-270-1836

Mailing Address: 229 Louise St, Kelso WA 98626

Asbestos Disposal Site: Hillsboro Landfill: 3205 SE Minter Bridge Rd, Hillsboro, OR, 97123-

**I DO HEREBY CERTIFY THAT THE INFORMATION CONTAINED IN THIS NOTIFICATION IS,
TO THE BEST OF MY KNOWLEDGE, ACCURATE AND COMPLETE.**

Submitter Name: Verna Munoz

Representing: Abatement Services Inc

Submitter Title: Secretary

Date Submitted: 3/1/2024

Reviewed by SWCAA: Brian Fallon

☒ Approved



11815 NE 99th Street, Suite 1294
Vancouver, WA 98662
Voice: 360-574-3058
Fax: 360-576-0925
Web: <https://www.swcleanair.gov>
Email: Tina@swcleanair.gov

Notice of Intent to Remove Asbestos

Case #: 24-131

Amendment: 0

Date Received: 3/1/2024

Date Paid: 3/1/2024

SWCAA Fee: \$738.00

Receipt #: 152146088


This notification MUST be present at all times at the asbestos project sit

Randy Forest

(360) 270-1836

229 Louise St Kelso

wa 98626



- * Lower cabinets 10 LF
- * Sink
- * Dishwasher
- * viny floor 10 X 3
- * Back splash 10 LF
- * Counter top 10 LF
- * particle Board
- * Marked floor with Blue tape
- * Cause of loss (cat 3)
Drain pipe under Sink



Polarized Light Microscopy Results

Lab No 143039
Layers Analyzed 7

Date Received 2/12/2024
Received By Chelsea Moore
Date Analyzed 2/12/2024
Analyzed By Ronnie Carter

Property Address 229 Louise St
City, State, Zip Kelso, WA
Job Number Randy Forest
Client Name Robinson Restoration
Client Address 5900 NE 152nd Ave
City, State, Zip Vancouver, WA
Phone & E-mail 360-947-2738 info@robinsonrestore.com

AEI Sample ID	Client Sample ID	Composition	Color/Description	Asbestos (%)	Non-Asbestos Fiber (%)	Non Fibrous
001	1	Homogenous	White Drywall	Asbestos Not Present	10% Cellulose	Gypsum
002	2	Layered	Brown/Tan Sheet Flooring	Asbestos Not Present	20% Cellulose 5% Glass Fiber	Vinyl-CaCO3
002A		Layered	Off-White Sheet Flooring Backing	40% Chrysotile	N/A	CaCO3
002B		Layered	Tan Sheet Flooring	Asbestos Not Present	20% Cellulose 5% Synthetic Fiber	Vinyl-CaCO3
003	3	Layered	White Joint Compound	2% Chrysotile	N/A	Paint-CaCO3
003A		Layered	White Drywall	Asbestos Not Present	10% Cellulose	Gypsum
003B		Composite	White Joint Compound / White Drywall	<1% Chrysotile	10% Cellulose	Paint-CaCO3-Gypsum

Disclaimer

- EPA Method 600/M4-82-020 (1982) was used to determine the presence or absence of asbestos fibers in all materials referenced in the above report. PLM analysis is based on visual estimation, and due to limitations of PLM analysis NESHAP regulations recommend that any material determined to contain less than 10% asbestos by the above referenced method should either be assumed to contain greater than 1% asbestos by the owner/operator, or be verified by PLM Point Count or TEM analysis as containing less than 1% asbestos.
- We recommend that TEM analysis be conducted for confirmation of negative PLM analytical results of vinyl floor tiles and vermiculite. These materials may contain asbestos fibers that cannot be detected by PLM analysis due to their size (<0.25 microns in diameter)
- This report may not be used to represent any materials not analyzed and listed in the included report. Advantage Environmental Inc. cannot be held responsible for the interpretation of the results shown. This report may not be reproduced in part and may only be reproduced in full without prior written consent from Advantage Environmental Inc.



ASBESTOS CHAIN OF CUSTODY
9317 NE Hwy 99, Suite D • (360) 356-7628
LEGAL DOCUMENT - PLEASE PRINT LEGIBLY

Lab Use Only	
Survey <input type="checkbox"/>	Lab No 143039
Walk-In <input checked="" type="checkbox"/>	Accept <input checked="" type="checkbox"/> Reject <input type="checkbox"/>

Sampled By - Please fill out yellow highlighted areas		Project Information - Please fill out yellow highlighted areas	
Date: 2/12/2021	Project Name: Randy Forest		
Company Name OR Name: Robinson Restoration	Address (where material was pulled from): 729 Louise St		
Phone: (360) 947-2738	City, State, Zip: Kelso WA 98626		
Email:	P.O. #:		

RELINQUISHED BY		DATE & TIME	VIA	RECEIVED BY	DATE & TIME
Name: Deanna Montoya		Date: 2/12	Drop Box/Drop Off	Deanna Montoya	2/12/21
Sign: [Signature]		Time: 12:00			12:00pm

REQUESTED SERVICES	
PLM	
TURNAROUND TIME - Please choose a turnaround time	
<input type="checkbox"/> Verbal <input checked="" type="checkbox"/> Rush <input type="checkbox"/> Same Day <input type="checkbox"/> 24-Hour <input type="checkbox"/> 3-Days	

No.	Sample ID	Color	Description	Volume / Area (as applicable)	Comments / Notes
1	①	white	Drum wall (kitchen)		
2	②	Brown	vinyl floor (kitchen)		
3	③	white	Drum wall (kitchen)		
4					
5					
6					
7					
8					
9					
10					
11					



ROBINSON
RESTORATION

PO BOX 822366
Vancouver WA. 98682

Limited Asbestos Survey Report

Owner/Operator Name:

Robinson Restoration

Owner/Operator Number:

360-947-2738

Limited Survey Date:

february/12/2024

Survey Address:

229 louise st kelso wa 98626

Survey Location:

Kitchen room

What is the building's description?

Residential home

What is this structure's current use?

Residential home

What is the structure's past use?

Residential home

Building Square Footage:

1,512

Number of Floors: 1



ROBINSON
RESTORATION

PO BOX 822366
Vancouver WA. 98682

Area Surveyed:

Kitchen room

Approximate Build Date:

1967

Purpose of the Survey:

Test for asbestos

Survey Limitations: Samples are collected based on a visual inspection of the work area as defined in the analysis report. Samples were collected from accessible, representative construction materials, which were suspected to contain asbestos. If additional materials are found during the demolition process that were inaccessible at the time of inspection that are not listed in this report, please have materials tested before they are impacted. Survey is subject to direction from contractor, homeowner or owners agent.



ROBINSON
RESTORATION

PO BOX 822366
Vancouver WA, 98682

The Oregon Department of Environmental Quality regulates the handling, removal and disposal of asbestos-containing material to protect public health and the environment.

<https://www.oregon.gov/deq/Hazards-and-cleanup/pages/asbestos-information.aspx>

A copy of this survey report must be kept onsite during any remediation, renovation or demolition activities, as required by Oregon DEQ OAR 340-248-027(2).

Survey Performed By:

----- Delfino montes angeles -----

Of

Robinson Restoration, LLC.

AHERA Cert# IRO-23-9487B_____

CCB#:____SRA0615_____

THIS IS TO CERTIFY THAT

DELFINO MONTES ANGELES

HAS SUCCESSFULLY COMPLETED THE TRAINING COURSE

for

ASBESTOS INSPECTOR REFRESHER

In accordance with TSCA Title II, Part 763, Subpart E, Appendix C of 40 CFR

CCB #SRA0615 4-Hr Training



4-Hour AHERA Inspector Refresher
Training: AHERA is the Asbestos Hazard
Emergency Response Act enacting Title II
of Toxic Substance Control Act (TSCA)

Expiration Date: 08/18/2024

Course Date: 08/18/2023

Course Location: Online

Certificate: IR-23-9487B

For verification of the authenticity of this
certificate contact:
PBS Engineering and Environmental Inc.
4412 S Corbett Avenue
Portland, OR 97239

Andy Fridley
Andy Fridley, Instructor