



11815 NE 99th Street, Suite 1294  
Vancouver, WA 98662  
Voice: 360-574-3058  
Fax: 360-576-0925  
Web: <https://www.swcleanair.gov>  
Email: [Tina@swcleanair.gov](mailto:Tina@swcleanair.gov)

## Notice of Intent to Remove Asbestos

Case #: 24-140

Amendment: 0

Date Received: 3/8/2024

Date Paid: 3/8/2024

SWCAA Fee: \$735.00

Receipt #: 152478219

**This notification MUST be present at all times at the asbestos project sit**

Quantity to be removed: 0 Square Feet 8285 Linear Feet

Workshift days: M T W Th F

Project starting date: 4/1/2024 Project Completion date: 4/5/2024

Workshift hours: 8-4

Site Name: W281\_PaulDavis\_1206NeBirchSt\_9

Site address: 1206 NE Birch St. Camas WA 98607

Location of Asbestos: Pray room, Nursery, bathroom, fello

City/State/Zip: Camas

WA

98607

☐ Demolition of Structure (Notification of Demolition required)

County: CLARK COUNTY

☒ Asbestos survey conducted?

No survey reason:

AHERA Inspector: Jorge Camacho

Certification #: IRO-23-1175C

### Material to be Removed:

☐ Fireproofing

☐ Popcorn Ceiling

☐ CAB

☐ Sheet Vinyl

☐ Boiler Insulation

☐ Duct Tape

☐ Duct Paper

☐ Mag Pipe Insulation

☐ Air Cell

☐ CA Pipe

☐ VAT

☒ Other Wall texture, Joint Compound

### Control Methods:

☒ N.P Enclosure

☐ Glove Bag

☐ Mini Enclosure

☐ Wrap and Cut

☒ Water

☒ HEPA Vac

☒ Other 6-Mil Poly, Wet, Labeled

Asbestos Contractor: Alpine Abatement Associates Inc.

Phone: 541-388-2672

Mailing Address: PO Box 1557, Bend, OR, 97709

Email: [annmarie@alpineabatement.com](mailto:annmarie@alpineabatement.com)

Certification ##: ABCN00001215

Supervisor: Manuel Lopez

Phone: 541-388-2672

Property Owner: Saint John&#39;s Presbyterian Church

Phone: 360-823-7847

Mailing Address: 1206 NE Birch St., Camas WA 98607

Asbestos Disposal Site: Hillsboro Landfill: 3205 SE Minter Bridge Rd, Hillsboro, OR, 97123-

**I DO HEREBY CERTIFY THAT THE INFORMATION CONTAINED IN THIS NOTIFICATION IS,  
TO THE BEST OF MY KNOWLEDGE, ACCURATE AND COMPLETE.**

Submitter Name: Bo Davidson

Representing: Alpine Abatement

Submitter Title: Senior Project Manager

Date Submitted: 3/8/2024

Reviewed by SWCAA: Brian Fallon

☒ Approved



11815 NE 99th Street, Suite 1294  
Vancouver, WA 98662  
Voice: 360-574-3058  
Fax: 360-576-0925  
Web: <https://www.swcleanair.gov>  
Email: [Tina@swcleanair.gov](mailto:Tina@swcleanair.gov)

## Notice of Intent to Remove Asbestos

Case #: 24-140

Amendment: 0

Date Received: 3/8/2024

Date Paid: 3/8/2024

SWCAA Fee: \$735.00

Receipt #: 152478219

**This notification MUST be present at all times at the asbestos project sit**

# Limited Asbestos Survey Report

**Owner/Operator Name:**

Paul Davis Restoration of Vancouver/Portland

**Owner/Operator Number:**

360-823-7847

**Limited Survey Date:**

January 22, 2024

**Survey Address:**

1206 NE Birch St, Camas, WA 98607

**Survey Location:**

Interior of Prayer Station

**What is the building's description?**

Commercial/Church

**What is this structure's current use?**

Commercial/Church

**What is this structure's past use?**

Commercial/Church

**Building Square Footage:**

5,000

**Number of Floors:**

2

**Area Surveyed:**

Interior Prayer Station Walls &amp; Ceiling

**Approximate Build Date:**

1970

**Purpose of the Survey:**

Remediation due to water damage

**Survey Limitations:** Samples are collected based on a visual inspection of the work area as defined in the analysis report. Samples were collected from accessible, representative construction materials, which were suspected to contain asbestos. If additional materials are found during the demolition process that were inaccessible at time of inspection that are not listed in this report please have materials tested before they are impacted. Survey is subject to direction from contractor, homeowner or owners agent.

**Asbestos Containing Building Material Identified During Survey: *\*Please see the completed attached analysis report.***

Sample #	Location	Asbestos Containing Material	Description (Color, Texture & Pattern)	Asbestos % & Asbestiform	Approx. Sq. Footage	Friable Y/N	Condition
3-A Layer 2	Prayer Station Wall	Texture	Off White	3% Chrysotile	400'	Y	Good
3-A Layer 3	Prayer Station Wall	Joint Compound	Off White	2% Chrysotile	—	Y	Good
3-B Layer 2	Prayer Station Wall	Texture	Off White	3% Chrysotile	—	Y	Good
3-B Layer 3	Prayer Station Wall	Joint Compound	Off White	2% Chrysotile	—	Y	Good
3-C Layer 2	Prayer Station Wall	Texture	Off White	3% Chrysotile	—	Y	Good
3-C Layer 3	Prayer Station Wall	Joint Compound	Off White	2% Chrysotile	—	Y	Good

**Recommended Response Action Plan:****Contact a Licenced Abatement Contractor or SW Clean Air Agency**

Sw Clean Air Agency regulates the handling, removal and disposal of asbestos-containing material to protect public health and the environment.

<https://www.lni.wa.gov/licensing-permits/other-licenses-permits/asbestos-certification#certified-contractors-list> . For more information on asbestos removal, please refer to [SWCAA 476](#), specifically SWCAA 476-050. If you have any questions, please contact us at 360-574-3058

A copy of this survey report must be kept onsite during any remediation, renovation or demolition activities, as required by Southwest Clean Air Agency.


**Surveyed Performed By:**

**Jorge Camacho**  
**Of**  
**Atlas Labs Inc.**  
**Environmental Testing Services**  
[Jorge@atlaslabinc.com](mailto:Jorge@atlaslabinc.com)  
**(360) 953-0731**  
**AHERA Cert #: IRO-23-1175C**  
**CCB #: 231684**





Atlas Laboratories Inc.  
14795 SW 72nd Ave, STE B Portland, OR 97224  
(503) 430-5290 www.atlaslabsinc.com  
CCB #231684



### Limited Survey Chain of Custody

Name / Company Name: Paul Davis Restoration of Vancouver/Portland		Phone: 360-823-7847
Contact Email: On File		
Project Name: St. John's Presbyterian Church 4696-E		Batch: 22-1080701
Job/Project Address: 1206 NE Birch St, Camas, WA 98607		
Inspector: Jorge Camacho Pichardo Ph: (360) 953-0731 AHERA Cert. # IRO-23-1175C Lead RRP Cert. #R-I-41R028-21-00048		
Survey Area Use: Commercial/Church	Approx. Year Built: 1970	Reason for Survey: Remediation

<input checked="" type="checkbox"/>	Rush
<input type="checkbox"/>	Next Day
<input type="checkbox"/>	2-Day
<input type="checkbox"/>	5-Day

<input checked="" type="checkbox"/>	Asbestos PLM
<input checked="" type="checkbox"/>	Lead Paint
<input type="checkbox"/>	Other

#	Material Description	Friable Y/N	Location	Condition	Approx. SQ FT.
1-A	Ceiling Tile	Y	Prayer Station 1st Layer Ceiling	Poor	
2-A	Drywall	Y	Prayer Station 2nd Layer Ceiling	Poor	
2-B	Drywall	Y	Prayer Station 2nd Layer Ceiling	Poor	
2-C	Drywall	Y	Prayer Station 2nd Layer Ceiling	Good	
3-A	Drywall	Y	Prayer Station Wall	Good	
3-B	Drywall	Y	Prayer Station Wall	Good	
3-C	Drywall	Y	Prayer Station Wall	Good	
Pb-1	Paint- Prayer Station Wall				

Notes:

Inspector Signature:

Date: 1-22-2024

Time: 4:23 PM

Accepted By:

Date: 1/22/2024

Time: 4:40 pm

Lab Results Completed By:

Date Sent Out: 1/22/24

Email / Mail

**Limitations of Inspection:** Atlas Labs Inc. AHERA certified inspector performed a limited survey at the site, date, time and cause as stated above in this document along with lab analysis of possible asbestos and/or lead containing material. Atlas Labs Inc. survey is limited to areas defined on the Chain of Custody form.

**General NESHAPS Bulk Sampling Guidelines:** Material sampling areas were grouped based on homogenous materials. A homogeneous area is one which contains material that seems by texture, color and surface wear to be uniform and applied during the same general time period. Samples are collected based on a visual survey of the work area as defined in this report. Samples were collected from accessible, representative construction materials, which were suspected to contain asbestos. If additional materials are found during the demolition process that were inaccessible at time of inspection that are not listed in this report please test before you cut. Survey is subject to direction from contractor, homeowner or owners agent.



Batch # 2022 \*

22-1080701

Name / Company \*

Paul Davis Restoration of  
Vancouver/Portland

Analysis Date \*

01/22/2024

Project Name

St. John's Presbyterian  
Church

Project #

4696-E

PO #

Analyst \*

Crossland Kapaun

Project Location \*

1206 NE Birch St, Camas,  
WA 98607

Turnaround Time \*

Rush

#### Asbestos Analysis of Bulk Material by Polarized Light Microscopy

Sample*	Layer*	Description*	Non Asbestos*	Asbestos Type*	Asbestos %*
1-A	1	Ceiling Tile (Grey) - Prayer Station 1st Layer Ceiling	Cellulose / Fiberglass	None Present	N/D
1-A	2	Mastic (Yellow) - Prayer Station 1st Layer Ceiling	Cellulose	None Present	N/D
2-A	1	Drywall (White) - Prayer Station 2nd Layer Ceiling	Cellulose / Fiberglass	None Present	N/D
2-A	2	Joint Compound (White) - Prayer Station 2nd Layer Ceiling	Fiberglass	None Present	N/D
2-B	1	Drywall (White) - Prayer Station 2nd Layer Ceiling	Cellulose / Fiberglass	None Present	N/D
2-B	2	Joint Compound (White) - Prayer Station 2nd Layer Ceiling	Fiberglass	None Present	N/D
2-C	1	Drywall (White) - Prayer Station 2nd Layer Ceiling	Cellulose / Fiberglass	None Present	N/D
2-C	2	Joint Compound (White) - Prayer Station 2nd Layer Ceiling	Fiberglass	None Present	N/D
3-A	1	Drywall (White) - Prayer Station Wall	Cellulose	None Present	N/D
3-A	2	Texture (Off White) - Prayer Station Wall	Cellulose	Chrysotile	3%



Sample*	Layer*	Description*	Non Asbestos*	Asbestos Type*	Asbestos %*
3-A	3	Joint Compound (Off White) - Prayer Station Wall	Cellulose	Chrysotile	2%
3-B	1	Drywall (White) - Prayer Station Wall	Cellulose	None Present	N/D
3-B	2	Texture (Off White) - Prayer Station Wall	Cellulose	Chrysotile	3%
3-B	3	Joint Compound (Off White) - Prayer Station Wall	Cellulose	Chrysotile	2%
3-C	1	Drywall (White) - Prayer Station Wall	Cellulose	None Present	N/D
3-C	2	Texture (Off White) - Prayer Station Wall	Cellulose	Chrysotile	3%
3-C	3	Joint Compound (Off White) - Prayer Station Wall	Cellulose	Chrysotile	2%

**To Be Filled by the Technician**

Technician \*



Atlas Laboratories maintains liability to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full without written permission by Atlas. Atlas bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval or endorsement by NVLAP, NIST, NIOSH or any other agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore Atlas recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Transmission Electron Microscopy asbestos identification and lead paint analysis will be available and performed by laboratories by proxy. Original analysis documents are available upon request of the client.