



11815 NE 99th Street, Suite 1294
Vancouver, WA 98662
Voice: 360-574-3058
Fax: 360-576-0925
Web: <https://www.swcleanair.gov>
Email: Tina@swcleanair.gov

Notice of Intent to Remove Asbestos

Case #: 24-141

Amendment: 0

Date Received: 3/8/2024

Date Paid: 3/8/2024

SWCAA Fee: \$738.00

Receipt #: 152486182

This notification MUST be present at all times at the asbestos project sit

*** EMERGENCY NOTICE ***

Quantity to be removed: 0 Square Feet 365 Linear Feet

Workshift days: W

Project starting date: 3/13/2024 Project Completion date: 3/13/2024

Workshift hours: 8-4

Site Name: W293_PaulDavis_3469IndianCreek

Site address: 3469 Indian Creek Dr.

Location of Asbestos: Kitchen/Dining Room/Entry

City/State/Zip: Longview WA 98632

☐ Demolition of Structure (Notification of Demolition required)

County: COWLITZ COUNTY

☒ Asbestos survey conducted?

No survey reason:

AHERA Inspector: Joel Dillard

Certification #: IN-231415-C

Material to be Removed:

- | | | | | | |
|---------------------------------------|--|------------------------------|---|--|------------------------------------|
| <input type="checkbox"/> Fireproofing | <input type="checkbox"/> Popcorn Ceiling | <input type="checkbox"/> CAB | <input checked="" type="checkbox"/> Sheet Vinyl | <input type="checkbox"/> Boiler Insulation | <input type="checkbox"/> Duct Tape |
| <input type="checkbox"/> Duct Paper | <input type="checkbox"/> Mag Pipe Insulation | | <input type="checkbox"/> Air Cell | <input type="checkbox"/> CA Pipe | <input type="checkbox"/> VAT |
| <input type="checkbox"/> Other | | | | | |

Control Methods:

- | | | | | | |
|--|------------------------------------|---|---------------------------------------|---|--|
| <input checked="" type="checkbox"/> N.P Enclosure | <input type="checkbox"/> Glove Bag | <input type="checkbox"/> Mini Enclosure | <input type="checkbox"/> Wrap and Cut | <input checked="" type="checkbox"/> Water | <input checked="" type="checkbox"/> HEPA Vac |
| <input checked="" type="checkbox"/> Other 6-Mil Poly, Wet, Labeled | | | | | |

Asbestos Contractor: Alpine Abatement Associates Inc.

Phone: 541-388-2672

Mailing Address: PO Box 1557, Bend, OR, 97709

Email: annmarie@alpineabatement.com

Certification ##: ABCN00001215

Supervisor: Ari Rameriz

Phone: 541-388-2672

Property Owner: TAYLOR DANIAL/VICKY ANN

Phone: 360-869-3347

Mailing Address: 3469 Indian Creek Dr. WA, Longview WA 98632

Asbestos Disposal Site: Hillsboro Landfill: 3205 SE Minter Bridge Rd, Hillsboro, OR, 97123-

**I DO HEREBY CERTIFY THAT THE INFORMATION CONTAINED IN THIS NOTIFICATION IS,
TO THE BEST OF MY KNOWLEDGE, ACCURATE AND COMPLETE.**

Submitter Name: Bo Davidson

Representing: Alpine Abatement

Submitter Title: Senior Project Manager

Date Submitted: 3/8/2024

Reviewed by SWCAA: Brian Fallon

☒ Approved



11815 NE 99th Street, Suite 1294
Vancouver, WA 98662
Voice: 360-574-3058
Fax: 360-576-0925
Web: <https://www.swcleanair.gov>
Email: Tina@swcleanair.gov

Notice of Intent to Remove Asbestos

Case #: 24-141

Amendment: 0

Date Received: 3/8/2024

Date Paid: 3/8/2024

SWCAA Fee: \$738.00

Receipt #: 152486182

This notification MUST be present at all times at the asbestos project sit

Limited Asbestos Survey Report

Owner/Operator Name:

Paul Davis Restoration of Vancouver/Portland

Owner/Operator Number:

253-249-4489

Limited Survey Date:

February 29, 2024

Survey Address:

3469 Indian Creek Dr, Longview, WA 98632

Survey Location:

Interior Attic, Kitchen, and Laundry Room. Exterior Roof.

What is the building's description?

Residence

What is this structure's current use?

Residential Home

What is this structure's past use?

Residential Home

Building Square Footage:

1,548'

Number of Floors:

1

Area Surveyed:

Kitchen and Laundry Room Ceiling, Wall(s), and Floor. Attic Insulation. Exterior Roofing.

Approximate Build Date:

1959

Purpose of the Survey:

Remediation due to damages.

Survey Limitations: Samples are collected based on a visual inspection of the work area as defined in the analysis report. Samples were collected from accessible, representative construction materials, which were suspected to contain asbestos. If additional materials are found during the demolition process that were inaccessible at time of inspection that are not listed in this report please have materials tested before they are impacted. Survey is subject to direction from contractor, homeowner or owners agent.

Asbestos Containing Building Material Identified During Survey: **Please see the completed attached analysis report.*

Sample #	Location	Asbestos Containing Material	Description (Color, Texture & Pattern)	Asbestos % & Asbestiform	Approx. Sq. Footage	Friable Y/N	Condition
3-A Layer 5	Kitchen Floor	Vinyl	Yellow	25% Chrysotile	85'	Y	Good
3-A Layer 6	Kitchen Floor	Mastic	Tan	2% Chrysotile	-	Y	-

Recommended Response Action Plan:**Contact a Licenced Abatement Contractor or SW Clean Air Agency**


Sw Clean Air Agency regulates the handling, removal and disposal of asbestos-containing material to protect public health and the environment.

<https://www.lni.wa.gov/licensing-permits/other-licenses-permits/asbestos-certification#certified-contractors-list> . For more information on asbestos removal, please refer to [SWCAA 476](#), specifically SWCAA 476-050. If you have any questions, please contact us at 360-574-3058

A copy of this survey report must be kept onsite during any remediation, renovation or demolition activities, as required by Southwest Clean Air Agency.

Surveyed Performed By:

**Joel Dillard
Of
Atlas Labs Inc.
Environmental Testing Services
AHERA Cert #: IN-231415-C
CCB #: 231684**



Atlas Laboratories Inc.
 14795 SW 72nd Ave, STE B Portland, OR 97224
 (503) 430-5290 www.atlaslabsinc.com
 CCB #231684



Limited Survey Chain of Custody

Name / Company Name: Paul Davis Restoration of Vancouver/Portland		Phone: 253-249-4489
Contact Email: On File		
Project Name: Daniel Taylor Job #: GVWA-24-5350-E		Batch: 22-1206601
Job/Project Address: 3469 Indian Creek Dr, Longview, WA 98632		
Inspector: Joel Dillard Ph: (360) 949-2984 AHERA Cert. # IN-231415-C Lead RRP Cert. # R-I-41R036-23-00588		
Survey Area Use: Residential	Approx. Year Built: 1959	Reason for Survey: Remediation

<input checked="" type="checkbox"/>	Rush
<input type="checkbox"/>	Next Day
<input type="checkbox"/>	2-Day
<input type="checkbox"/>	5-Day

<input checked="" type="checkbox"/>	Asbestos PLM
<input checked="" type="checkbox"/>	Lead Paint
<input type="checkbox"/>	Other

#	Material Description	Friable Y/N	Location	Condition	Approx. SQ FT.
1-A	Drywall	Y	Kitchen Ceiling	Good	100'
1-B	Drywall	Y	Kitchen Ceiling	Good	-
1-C	Drywall	Y	Kitchen Ceiling	Good	-
2-A	Drywall	Y	Kitchen Wall	Good	100'
2-B	Drywall	Y	Laundry Room Wall	Good	-
2-C	Drywall	Y	Laundry Room Ceiling	Good	-
3-A	Laminate	N	Kitchen Floor	Good	85'
3-B	Laminate	N	Laundry Room Floor	Good	-
4-A	Insulation	Y	Attic	Good	Unk
5-A	Shingle	N	Roof	Good	1700'

Notes:

Inspector Signature:	Date: 2/29/2024	Time: 2:32 pm
Accepted By: Will Sokolowsky	Date: 2/29/24	Time: 2:34 pm
Lab Results Completed By:	Date Sent Out: 2/29/24	Email / Mail

Limitations of Inspection: Atlas Labs Inc. AHERA certified inspector performed a limited survey at the site, date, time and cause as stated above in this document along with lab analysis of possible asbestos and/or lead containing material. Atlas Labs Inc. survey is limited to areas defined on the Chain of Custody form.

General NESHAPS Bulk Sampling Guidelines: Material sampling areas were grouped based on homogeneous materials. A homogeneous area is one which contains material that seems by texture, color and surface wear to be uniform and applied during the same general time period. Samples are collected based on a visual survey of the work area as defined in this report. Samples were collected from accessible, representative construction materials, which were suspected to contain asbestos. If additional materials are found during the demolition process that were inaccessible at time of inspection that are not listed in this report please test before you cut. Survey is subject to direction from contractor, homeowner or owners agent.



Atlas Labs

**Approx. SQ
FT.**

[illegible]

Special Instructions:



Batch # 2022 *

22-1206601

Name / Company *

Paul Davis Restoration of
Vancouver/Portland

Analysis Date *

02/29/2024

Project Name

Daniel Taylor

Project #

GVWA-24-5350-E

PO #

Analyst *

Crossland Kapaun

Project Location *

3469 Indian Creek Dr.,
Longview, WA 98632

Turnaround Time *

Rush

Asbestos Analysis of Bulk Material by Polarized Light Microscopy

Sample*	Layer*	Description*	Non Asbestos*	Asbestos Type*	Asbestos %*
1-A	1	Drywall (White) - Kitchen Ceiling	Cellulose / Fiberglass	None Present	N/D
1-A	2	Texture (White) - Kitchen Ceiling	Cellulose	None Present	N/D
1-A	3	Joint Compound (White) - Kitchen Ceiling	Cellulose	None Present	N/D
1-B	1	Drywall (White) - Kitchen Ceiling	Cellulose / Fiberglass	None Present	N/D
1-B	2	Texture (White) - Kitchen Ceiling	Cellulose	None Present	N/D
1-B	3	Joint Compound (White) - Kitchen Ceiling	Cellulose	None Present	N/D
1-C	1	Drywall (White) - Kitchen Ceiling	Cellulose / Fiberglass	None Present	N/D
1-C	2	Texture (White) - Kitchen Ceiling	Cellulose	None Present	N/D
1-C	3	Joint Compound (White) - Kitchen Ceiling	Cellulose	None Present	N/D
2-A	1	Drywall (White) - Kitchen Wall	Cellulose / Fiberglass	None Present	N/D
2-A	2	Texture (White) - Kitchen Wall	Cellulose	None Present	N/D
2-A	3	Joint Compound (White) - Kitchen Wall	Cellulose	None Present	N/D

Sample*	Layer*	Description*	Non Asbestos*	Asbestos Type*	Asbestos %*
2-B	1	Drywall (White) - Laundry Room Wall	Cellulose / Fiberglass	None Present	N/D
2-B	2	Texture (White) - Laundry Room Wall	Cellulose	None Present	N/D
2-B	3	Joint Compound (White) - Laundry Room Wall	Cellulose	None Present	N/D
2-C	1	Drywall (White) - Laundry Room Ceiling	Cellulose / Fiberglass	None Present	N/D
2-C	2	Texture (White) - Laundry Room Ceiling	Cellulose	None Present	N/D
2-C	3	Joint Compound (White) - Laundry Room Ceiling	Cellulose	None Present	N/D
3-A	1	Laminate (Brown Wood Tone) - Kitchen Floor	Cellulose	None Present	N/D
3-A	2	Foam Layer (Black) - Kitchen Floor	Synthetic	None Present	N/D
3-A	3	Mastic (White) - Kitchen Floor	Cellulose	None Present	N/D
3-A	4	Leveling Compound (Grey) - Kitchen Floor	Cellulose	None Present	N/D
3-A	5	Vinyl (Yellow) - Kitchen Floor	Cellulose	Chrysotile	25%
3-A	6	Mastic (Tan) - Kitchen Floor	Cellulose	Chrysotile	2%
3-A	7	Vinyl (Cream) - Kitchen Floor	Synthetic	None Present	N/D
3-A	8	Mastic (Brown) - Kitchen Floor	Cellulose	None Present	N/D
3-B	1	Laminate (Brown Wood Tone) - Laundry Room Floor	Cellulose	None Present	N/D
3-B	2	Foam Layer (Black) - Laundry Room Floor	Synthetic	None Present	N/D
3-B	3	Leveling Compound (Grey) - Laundry Room Floor	Cellulose	None Present	N/D
4-A	1	Insulation (Brown) - Attic	Cellulose	None Present	N/D
5-A	1	Shingle (Black) - Roof	Fiberglass	None Present	N/D
5-A	2	Underlayment (Grey) - Roof	Synthetic	None Present	N/D

To Be Filled by the Technician
Technician *

Atlas Laboratories maintains liability to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full without written permission by Atlas. Atlas bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval or endorsement by NVLAP, NIST, NIOSH or any other agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore Atlas recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Transmission Electron Microscopy asbestos identification and lead paint analysis will be available and performed by laboratories by proxy. Original analysis documents are available upon request of the client.



SanAir ID Number
24012283
FINAL REPORT
3/4/2024 5:03:28 PM

Name: Atlas Labs, Inc.
Address: 14795 SW 72nd Ave. Suite B
Portland, OR 97224
Phone: 360-852-8936

Project Number: 3469 Indian Creek Dr
P.O. Number: GVWA-24-5350-E
Project Name: Paul Davis Creek Restoration-Danile Taylor
Collected Date: 2/29/2024
Received Date: 3/1/2024 10:20:00 AM

Analyst: Baird, Marti
Test Method: SW846/M3050B/7000B

Lead Paint Analysis

PAINT Sample	Description	µg Pb In Sample	Sample Size (grams)	Calculated RL	Sample Results	Sample Results
24012283 - 1	Pb-1 Paint-Interior Base Kitchen Ceiling	< 10	0.1203	83.1	<83.1 µg/g (ppm)	<0.008 % By Weight
24012283 - 2	Pb-2 Paint-Interior Base Kitchen Wall	< 10	0.1011	98.9	<98.9 µg/g (ppm)	<0.010 % By Weight
24012283 - 3	Pb-3 Paint-Exterior Base Overhang Siding	1834	0.1235	81	14850 µg/g (ppm)	1.485 % By Weight

Method Reporting Limit <10 µg/0.1 g paint

Signature:

Date: 3/4/2024

Reviewed:

Date: 3/4/2024



LEAD
CLASSES.COM

EPA HUD & STATE RRP LEAD PAINT CERTIFICATION

10350 N Vancouver Way, 1021
Portland OR 97217
Info@LeadClasses.com

1-888-840-8388

Certificate of Attendance and Successful Completion Renovator Initial - English

Issued per OAC 333-070 and 40 CFR Part 745.225

Joel M Dillard
8256 NE Snowberry Loop
Vancouver, WA 98664
Certificate # R-I-41R036-23-00588

Course Date: 06/08/2023
Exam Date: 06/08/2023
Expiration Date: 06/08/2028

6/08/2023

Steven Hoff Training Manager
Crosswall Training / LeadClasses.com

Date

