

Notice of Intent to Remove Asbestos

Case #: 24-176

3/22/2024

11815 NE 99th Street, Suite 1294

Vancouver, WA 98662 Voice: 360-574-3058 Fax: 360-576-0925

Web: https://www.swcleanair.gov Email: Tina@swcleanair.gov

Date Received: 3/22/2024

Amendment: 0

Date Paid:

\$294.00 SWCAA Fee:

This notification MUST be present at all times at the	aspestos project sit	Receipt #:	15322135
*** EMERGENCY NOTICE ***			
Quantity to be removed: 139 Square Feet 0 L	inear Feet	Workshift days: T	
Project starting date: 3/26/2024 Project Completion of	date: 3/26/2024	Workshift hours: 10	AM-4PM
ite Name: Laura Pike	Site address: 7525 Car	olina Ln	
ocation of Asbestos: bedroom 1	City/State/Zip: Vancouve	er WA	98664
Demolition of Structure (Notification of Demolition require	d) Count	cy: CLARK COUNTY	
Asbestos survey conducted? No survey rea	son:		
AHERA Inspector: Jorge Camacho	Cert	ification #: IRO-23-11	.75C
Material to be Removed: ☐ Fireproofing ☐ Popcorn Ceiling ☐ CAB ☐ Duct Paper ☐ Mag Pipe Insulation ☐ Other			Duct Tape VAT
Control Methods: ✓ N.P Enclosure ☐ Glove Bag ✓ Mini Enclosure ☐ Other	☐ Wrap and Cut ✓ W	/ater ✓	HEPA Vac
sbestos Contractor: Abatement Services of Washington	Phone	: 503-857-7175	
Mailing Address: PO Box 747, Beavercreek, OR, 97004 Certification ##: ABCN00001610		: tristan@abateservio	ces.com
Supervisor: Tion Mozee	Phone: 503	-435-7365	
roperty Owner: Laura Pike	Phone: 415	-395-6410	
Mailing Address: 7525 Carolina Ln, Vancouver WA 98664			
sbestos Disposal Site: Hillsboro Landfill: 3205 SE Minter Brid	dge Rd, Hillsboro, OR, 971	23-	

Submitter Name:	Ashley Morales	Representing:	Asi
Submitter Title:	Secretary	Date Submitted:	3/22/2024

✓ Approved Reviewed by SWCAA: Brian Fallon



Notice of Intent to Remove Asbestos

Case #: 24-176

11815 NE 99th Street, Suite 1294 Vancouver, WA 98662

Voice: 360-574-3058 Fax: 360-576-0925

Web: https://www.swcleanair.gov Email: Tina@swcleanair.gov Date Received: 3/22/2024

Amendment: 0

, ,

Date Paid: 3/22/2024

SWCAA Fee: \$294.00

This notification MUST be present at all times at the asbestos project sit

Receipt #:

153221351



Limited Asbestos Survey Report

Owner/Operator Name: 1-800 Water Damage of Vancouver **Owner/Operator Number:** 360-909-1207 **Limited Survey Date:** 2/20/2024 Survey Address: 7525 Carolina Ln, Vancouver, WA 98664 **Survey Location:** Interior Bedroom and Bathroom. What is the building's description? Residence What is this structure's current use? Residential Home What is this structure's past use? Residential Home **Building Square Footage:** 1,066' **Number of Floors:**



Area Surveyed:

Interior Bedroom Wall(s) and Floor, and Bathroom Floor.

Approximate Build Date:

1958

Purpose of the Survey:

Remediation Due to Damages.

Survey Limitations: Samples are collected based on a visual inspection of the work area as defined in the analysis report. Samples were collected from accessible, representative construction materials, which were suspected to contain asbestos. If additional materials are found during the demolition process that were inaccessible at time of inspection that are not listed in this report please have materials tested before they are impacted. Survey is subject to direction from contractor, homeowner or owners agent.

Asbestos Containing Building Material Identified During Survey: *Please see the completed attached analysis report.

Sample #	Location	Asbestos Containing Material	Description (Color, Texture & Pattern)	Asbestos % & Asbestiform	Sq.	Friable Y/N	Condition
2-A Layer 1	Bedroom Floor	VCT	Brown / Tan	3% Chrysotile	130'	N	Good

Recommended Response Action Plan:

Contact a Licenced Abatement Contractor or SW Clean Air Agency

Sw Clean Air Agency regulates the handling, removal and disposal of asbestos-containing material to protect public health and the environment. https://www.lni.wa.gov/licensing-permits/other-licenses-permits/asbestos-certification#ce https://www.lni.wa.gov/licensing-permits/asbestos-certification#ce https://www.lni.wa.gov/licensing-permits/asbestos-certification#ce <a href="https://www.lni.wa.gov/licensing-permits/asbes

A copy of this survey report must be kept onsite during any remediation, renovation or demolition activities, as required by Southwest Clean Air Agency.



Surveyed Performed By:

Jorge Camacho
Of
Atlas Labs Inc.
Environmental Testing Services
Jorge@atlaslabinc.com
(360) 953-0731

AHERA Cert #: IRO-23-1175C CCB #: 231684



Atlas Laboratories Inc.

14795 SW 72nd Ave, STE B Portland, OR 97224
(503) 430-5290 www.atlaslabsinc.com

CCB #231684



Limited Survey Chain of Custody

Name / Company Name: 1-800 Water Damage of Vancouver					Phone: 360-909-1207		
Contact Email: On File							
Project Name: Laura Pike				Batch: 22-	118240	1	
Job/Project Address: 7525 Carolin	a Ln, Vancouver, V	VA 98664					
Inspector: Jorge Camacho Pichardo	Ph: (360) 953-0731	1 AHERA Cert.	# IRO-23-1175C L	ead RRP Cert. #	#R-I-41R028-2	1-00048	
Survey Area Use: Residential Approx. Year Built: 1958 Reason for				r Survey: Rem	ediation		
Rush X Next Day 2-Day 5-Day			X Asbestos I X Lead Paint Other				
# Material Descrip	otion	Friable Y/N	Loca	tion	Condition	Approx. SQ FT.	
1-A Drywall		Υ	Bedroo	m Wall	Fair	90'	
1-B Drywall		Y	Bedroom Wall		Fair	•	
1-C Drywall		Υ	Bedroom Wall		Fair		
2-A VCT		N	Bedroom Floor		Good	130'	
3-A Vinyl		Y	Bathroo	m Floor	Good	40'	
Pb-1 Paint - Bedroom Wall							
Notes:	1						
Inspector Signature:	And of		Date: 2-20-202	24	Time: 11:13	AM	
Accepted By:	/		Date: 2-20	-24	Time: 11:	22am	
Lab Results Completed By:	1		Date Sent Out:	2-20-2024	Email	Mail	
Limitations of Inspection: Atlas Labs	Inc. AHERA certified	inspector perfor	rmed a limited surv	ev at the site da	te time and ca	ause as	

Limitations of Inspection: Atlas Labs Inc. AHERA certified inspector performed a limited survey at the site, date, time and cause as stated above in this document along with lab analysis of possible asbestos and/or lead containing material. Atlas Labs Inc. survey is limited to areas defined on the Chain of Custody form.

General NESHAPS Bulk Sampling Guidelines: Material sampling areas were grouped based on homogenous materials. A homogeneous area is one which contains material that seems by texture, color and surface wear to be uniform and applied during the same general time period. Samples are collected based on a visual survey of the work area as defined in this report. Samples were collected from accessible, representative construction materials, which were suspected to contain asbestos. If additional materials are found during the demolition process that were inaccessible at time of inspection that are not listed in this report please test before you cut. Survey is subject to direction from contractor, homeowner or owners agent.

Atlas Labs

Batch # 2022 *

22-1182401

Analysis Date *

02/20/2024

Project #

Analyst *

Dillon Lafever

Turnaround Time *

1-Day

Name / Company *

1-800 Water Damage of

Vancouver

Project Name

Laura Pike

PO#

Project Location *

7525 Carolina Ln., Vancouver, WA 98664

Asbestos Analysis of Bulk Material by Polarized Light Microscopy

Sample*	Layer*	Description*	Non Asbestos*	Asbestos Type*	Asbestos %*
1-A	1	Drywall (White) - Bedroom Wall	Cellulose / Fiberglass	None Present	N/D
1-A	2	Texture (White) - Bedroom Wall	Cellulose	None Present	N/D
1-A	3	Joint Compound (White) - Bedroom Wall	Fiberglass / Cellulose	None Present	N/D
1-B	1	Drywall (White) - Bedroom Wall	Cellulose / Fiberglass	None Present	N/D
1-B	2	Texture (White) - Bedroom Wall	Cellulose	None Present	N/D
1-B	3	Joint Compound (White) - Bedroom Wall	Fiberglass / Cellulose	None Present	N/D
1-B	4	Plaster (Grey) - Bedroom Wall	Cellulose	None Present	N/D
1-B	5	Skim Coat (Brown) - Bedroom Wall	Cellulose	None Present	N/D
1-C	1	Drywall (White) - Bedroom Wall	Cellulose / Fiberglass	None Present	N/D
1-C	2	Texture (White) - Bedroom Wall	Cellulose	None Present	N/D
1-C	3	Joint Compound (White) - Bedroom Wall	Fiberglass / Cellulose	None Present	N/D
2-A	1	VCT (Brown / Tan) - Bedroom Floor	Cellulose	Chrysotile	3%

Sample*	Layer*	Description*	Non Asbestos*	Asbestos Type*	Asbestos %*
2-A	2	Mastic (Black) - Bedroom Floor	Cellulose	None Present	N/D
3-A	1	Vinyl (White / Beige) - Bathroom Floor	Cellulose / Fiberglass	None Present	N/D
3-A	2	Mastic (Tan / Brown) - Bathroom Floor	Cellulose	None Present	N/D

To Be Filled by the Technician

Technician *



Atlas Laboratories maintains liability to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full without written permission by Atlas. Atlas bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval or endorsement by NVLAP, NIST, NIOSH or any other agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore Atlas recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Transmission Electron Microscopy asbestos identification and lead paint analysis will be available and performed by laboratories by proxy. Original analysis documents are available upon request of the client.



SanAir ID Number
24010319
FINAL REPORT
2/21/2024 3:31:59 PM

Name: Atlas Labs, Inc.

Address: 14795 SW 72nd Ave. Suite B

Portland, OR 97224

Phone: 360-852-8936

Project Number: 7525 Carolina Ln

P.O. Number: Laura Pike

Project Name: 1-800 Water Damage Of Vancouver

Collected Date: 2/20/2024

Received Date: 2/21/2024 10:40:00 AM

Analyst: Rivera, Shirley

Test Method: SW846/M3050B/7000B

Lead Paint Analysis

PAINT		μg Pb	Sample Size	Calculated	Sample	Sample
Sample	Description	In Sample	(grams)	RL	Results	Results
24010319 - 1	Pb-1	< 10	0.1201	83.3	<83.3	<0.008 %
	Paint - Bedroom Wall				μg/g (ppm)	By Weight

Method Reporting Limit <10 μg/0.1 g paint

Signature: Reviewed:

Date: 2/21/2024 Date: 2/21/2024



1066 Oldstone Road Allentown, PA 18103 (888) 779-8404 <u>rrptraining@enviroed.net</u> <u>www.enviroed.net</u>

Certificate of Attendance and Successful Completion Renovator Initial – English

Issued in accordance with OAR 333-070 and 40 CFR 745.225

Jorge Camacho Pichardo 5620 NE Gher Rd Suite M Vancouver, WA 98682

Certificate Number: R-I-41R028-21-00048

Date of Course: 4/15/2021

Date of Successful Test Completion: 4/15/2021 Date of Certificate Expiration: 4/15/2026

George L. Lucas

Jessica L. Lucas RS, HHS

Date

EnviroEd, LLC, Training Manager

