



11815 NE 99th Street, Suite 1294
Vancouver, WA 98662
Voice: 360-574-3058
Fax: 360-576-0925
Web: <https://www.swcleanair.gov>
Email: Tina@swcleanair.gov

Notice of Intent to Remove Asbestos

Case #: 24-203

Amendment: 0

Date Received: 4/1/2024

Date Paid: 4/1/2024

SWCAA Fee: \$147.00

Receipt #: 153706835

This notification MUST be present at all times at the asbestos project sit

Quantity to be removed: 0 Square Feet 40 Linear Feet

Workshift days: M T W Th F

Project starting date: 4/10/2024 Project Completion date: 4/17/2024

Workshift hours: 7:00 Am - 3:30 PM

Site Name: USPS Longview

Site address: 1603 Larch Street

Location of Asbestos: Basement Boiler Room

City/State/Zip: Longview WA 98635

☐ Demolition of Structure (Notification of Demolition required)

County: COWLITZ COUNTY

☐ Asbestos survey conducted?

No survey reason: It is a very old inspection. We are assuming the material i

AHERA Inspector:

Certification #:

Material to be Removed:

- | | | | | | |
|---------------------------------------|---|------------------------------|--|--|------------------------------------|
| <input type="checkbox"/> Fireproofing | <input type="checkbox"/> Popcorn Ceiling | <input type="checkbox"/> CAB | <input type="checkbox"/> Sheet Vinyl | <input type="checkbox"/> Boiler Insulation | <input type="checkbox"/> Duct Tape |
| <input type="checkbox"/> Duct Paper | <input checked="" type="checkbox"/> Mag Pipe Insulation | | <input checked="" type="checkbox"/> Air Cell | <input type="checkbox"/> CA Pipe | <input type="checkbox"/> VAT |
| <input type="checkbox"/> Other | | | | | |

Control Methods:

- | | | | | | |
|---|------------------------------------|---|---------------------------------------|---|--|
| <input checked="" type="checkbox"/> N.P Enclosure | <input type="checkbox"/> Glove Bag | <input type="checkbox"/> Mini Enclosure | <input type="checkbox"/> Wrap and Cut | <input checked="" type="checkbox"/> Water | <input checked="" type="checkbox"/> HEPA Vac |
| <input type="checkbox"/> Other | | | | | |

Asbestos Contractor: Kanway Abatement & Demolition LLC.

Phone: 253-442-6999

Mailing Address: 3021 69th Ave W, University Place, WA, 98466

Email: brandon@kanwayllc.com

Certification ##: ABCN00001720

Supervisor: Luciano Valdovinos

Phone: 206-359-0215

Property Owner: USPS

Phone: 360-523-3174

Mailing Address: 1603 Larch Street, Longview WA 98635

Asbestos Disposal Site: Chemical Waste Managment of the NW - Arl: 17629 Cedar Springs Ln, Arlington, OR, 97812

**I DO HEREBY CERTIFY THAT THE INFORMATION CONTAINED IN THIS NOTIFICATION IS,
TO THE BEST OF MY KNOWLEDGE, ACCURATE AND COMPLETE.**

Submitter Name: Jason Kanar

Representing: Kanway Abatement & De

Submitter Title: VP

Date Submitted: 4/1/2024

Reviewed by SWCAA: Brian Fallon

☒ Approved



11815 NE 99th Street, Suite 1294
Vancouver, WA 98662
Voice: 360-574-3058
Fax: 360-576-0925
Web: <https://www.swcleanair.gov>
Email: Tina@swcleanair.gov

Notice of Intent to Remove Asbestos

Case #: 24-203

Amendment: 0

Date Received: 4/1/2024

Date Paid: 4/1/2024

SWCAA Fee: \$147.00

Receipt #: 153706835

This notification MUST be present at all times at the asbestos project sit



9317 NE Hwy 99, Suite D, Vancouver, WA 98665 | 360-356-7628

Polarized Light Microscopy Results

Lab No 143800
Layers Analyzed 3
Date Received 3/27/2024
Received By Talia Carroll
Date Analyzed 3/27/2024
Analyzed By Nathan Blondino

Property Address 1038 Cloverdale Rd
City, State, Zip Kalama, WA
Job Number Garage
Client Name John Davis
Client Address
City, State, Zip
Phone & E-mail (916) 216-1297

AEI Sample ID	Client Sample ID	Composition	Color/ Description	Asbestos (%)	Non-Asbestos Fiber (%)	Non Fibrous
001	1	Layered	Black Roofing	Asbestos Not Present	25% Glass Fibers	Sand-Tar
001A		Layered	Black Felt Paper	Asbestos Not Present	60% Cellulose	Tar
002	2	Homogeneous	Brown Vapor Barrier	Asbestos Not Present	99% Cellulose	Debris

Disclaimer


- EPA Method 600/M4-82-020 (1982) was used to determine the presence or absence of asbestos fibers in all materials referenced in the above report. PLM analysis is based on visual estimation, and due to limitations of PLM analysis NESHAP regulations recommend that any material determined to contain less than 10% asbestos by the above referenced method should either be assumed to contain greater than 1% asbestos by the owner/operator, or be verified by PLM Point Count or TEM analysis as containing less than 1% asbestos.
- We recommend that TEM analysis be conducted for confirmation of negative PLM analytical results of vinyl floor tiles and vermiculite. These materials may contain asbestos fibers that cannot be detected by PLM analysis due to their size (<0.25 microns in diameter)
- This report may not be used to represent any materials not analyzed and listed in the included report. Advantage Environmental Inc. cannot be held responsible for the interpretation of the results shown. This report may not be reproduced in part and may only be reproduced in full without prior written consent from Advantage Environmental Inc.



ADVANTAGE
Environmental INC.

ASBESTOS CHAIN OF CUSTODY
9317 NE Hwy 99, Suite D • (360) 356-7628
LEGAL DOCUMENT - PLEASE PRINT LEGIBLY

Lab Use Only	
Survey <input type="checkbox"/>	Lab No. <u>143800</u>
Walk-In <input checked="" type="checkbox"/>	<u>Accept</u> Reject

Sampled By - Please fill out yellow highlighted areas				Project Information - Please fill out yellow highlighted areas					
Date: <u>3/27/2024</u>		Project Name: <u>GARAGE</u>		Address (where material was pulled from): <u>1038 Cloverdale Road</u>		City, State, Zip: <u>Kolama, WA 98025</u>			
Company Name OR Name: <u>John Davis</u>		P.O. #:							
Phone: <u>916 216 1297</u>									
Email: <u>budsterr10@yahoo.com</u>									
RELINQUISHED BY		DATE & TIME		VIA		RECEIVED BY		DATE & TIME	
Name		Date		Drop Box/Drop Off				<u>3-27-24</u>	
Sign		Time						<u>9:23</u>	
REQUESTED SERVICES									
PLM				TURNAROUND TIME - Please choose a turnaround time					
Bulk Analysis				<input type="checkbox"/> Verbal		<input type="checkbox"/> Rush		<input checked="" type="checkbox"/> Same Day <input type="checkbox"/> 24-Hour <input type="checkbox"/> 3-Days	
No.	Sample ID	Color	Description		Volume / Area (as applicable)	Comments / Notes			
1	<u>1</u>	<u>Black</u>	<u>Roofing Shingle w/ Tar paper</u>						
2									
3	<u>2</u>	<u>Tan</u>	<u>Vapor Barrier</u>						
4									
5									
6									
7									
8									
9									
10									
11									

March 28, 2024

John Davis
1038 Cloverdale Road
Kalama, WA 98625

Re: Demolition of Detached Garage

Mr. Davis:

Based on the information and photos provided by Nelson & Son Contracting of the **detached garage at 1038 Cloverdale Road Ave in Kalama, Washington**, I find no evidence of asbestos containing materials that would require further action prior to the demolition / deconstruction of this structure (residential and other buildings excluded).

These conclusions are based on the information Nelson & Son Contracting provided and the attached pictures sent to me. SWCAA is not responsible for any asbestos-containing material that might be behind walls, under floors, underground or in any area not depicted in the referenced photographs. If suspect asbestos containing material is discovered during demolition, the project must stop and an AHERA certified building inspector should be consulted. An AHERA inspection must also be performed prior to the demolition of any residential structure or other building not depicted in the attached photos.

A Notification of Demolition for the detached garage is required to be submitted to SWCAA prior commencement of demolition activity. A copy of this letter must be kept onsite during the demolition.

If you have any questions regarding this matter, please call me at 360-574-3058 x115.

Sincerely,



Danielle Kreps
Air Quality Specialist

AHERA Certification No. IN-22-0301C



Photographs of
1038 Cloverdale Road, Kalama, WA 98625
Detached Garage Only (Residence/Other Buildings Excluded)



Photographs of
1038 Cloverdale Road, Kalama, WA 98625
Detached Garage Only (Residence/Other Buildings Excluded)

