



11815 NE 99th Street, Suite 1294  
Vancouver, WA 98662  
Voice: 360-574-3058  
Fax: 360-576-0925  
Web: <https://www.swcleanair.gov>  
Email: [Tina@swcleanair.gov](mailto:Tina@swcleanair.gov)

## Notice of Intent to Remove Asbestos

Case #: 24-218

Amendment: 0

Date Received: 4/8/2024

Date Paid: 4/8/2024

SWCAA Fee: \$294.00

Receipt #: 154082513

**This notification MUST be present at all times at the asbestos project sit**

### \*\*\* EMERGENCY NOTICE \*\*\*

Quantity to be removed: 90 Square Feet 0 Linear Feet

Workshift days: M

Project starting date: 4/9/2024 Project Completion date: 4/9/2024

Workshift hours: 12PM - 6PM

Site Name: 24879

Site address: 3326 NE 160th Street

Location of Asbestos: Bathroom, Closet, and Bedroom

City/State/Zip: Ridgefield

WA 98642

☐ Demolition of Structure (Notification of Demolition required)

County: CLARK COUNTY

☒ Asbestos survey conducted?

No survey reason:

AHERA Inspector: Jake Rodgers

Certification #: IN-22-0802c

#### Material to be Removed:

- |   |  |                              |                                      |  |                                    |
|---|--|------------------------------|--------------------------------------|--|------------------------------------|
| <input type="checkbox"/> Fireproofing             | <input type="checkbox"/> Popcorn Ceiling     | <input type="checkbox"/> CAB | <input type="checkbox"/> Sheet Vinyl | <input type="checkbox"/> Boiler Insulation | <input type="checkbox"/> Duct Tape |
| <input type="checkbox"/> Duct Paper               | <input type="checkbox"/> Mag Pipe Insulation |                              | <input type="checkbox"/> Air Cell    | <input type="checkbox"/> CA Pipe           | <input type="checkbox"/> VAT       |
| <input checked="" type="checkbox"/> Other Drywall |  |                              |                                      |  |                                    |

#### Control Methods:

- |   |                                    |   |                                       |   |  |
|---|------------------------------------|---|---------------------------------------|---|--|
| <input checked="" type="checkbox"/> N.P Enclosure | <input type="checkbox"/> Glove Bag | <input type="checkbox"/> Mini Enclosure | <input type="checkbox"/> Wrap and Cut | <input checked="" type="checkbox"/> Water | <input checked="" type="checkbox"/> HEPA Vac |
| <input type="checkbox"/> Other                    |                                    |   |                                       |   |  |

Asbestos Contractor: Rose City Contracting, Inc

Phone: 503-376-8646

Mailing Address: 29791 SW Kinsman Rd, Wilsonville, OR, 97070

Email: [DEChaff@rosecitycontracting.com](mailto:DEChaff@rosecitycontracting.com)

Certification ##: ABCN00001219

Supervisor: Antolin Lopez

Phone: 503-724-0245

Property Owner: Cindy Martinez

Phone: 360-909-0015

Mailing Address: 3326 NE 160th Street, Ridgefield WA 98642

Asbestos Disposal Site: Hillsboro Landfill: 3205 SE Minter Bridge Rd, Hillsboro, OR, 97123-

**I DO HEREBY CERTIFY THAT THE INFORMATION CONTAINED IN THIS NOTIFICATION IS,  
TO THE BEST OF MY KNOWLEDGE, ACCURATE AND COMPLETE.**

Submitter Name: David Chaff

Representing: Rose City Contracting

Submitter Title:

Date Submitted: 4/8/2024

Reviewed by SWCAA: Danielle Kreps

*Danielle Kreps*

☒ Approved



11815 NE 99th Street, Suite 1294  
Vancouver, WA 98662  
Voice: 360-574-3058  
Fax: 360-576-0925  
Web: <https://www.swcleanair.gov>  
Email: [Tina@swcleanair.gov](mailto:Tina@swcleanair.gov)

## Notice of Intent to Remove Asbestos

Case #: 24-218

Amendment: 0

Date Received: 4/8/2024

Date Paid: 4/8/2024

SWCAA Fee: \$294.00

Receipt #: 154082513

**This notification MUST be present at all times at the asbestos project sit**

---



**ROBINSON**  
R E S T O R A T I O N

PO BOX 822366  
Vancouver WA. 98682

## **Limited Asbestos Survey Report**

**Owner/Operator Name:**

Robinson Restoration

**Owner/Operator Number:**

360-987-2738

**Limited Survey Date:**

**03/25/23**

**Survey Address:**

3326 NE 160th St  
Ridgefield , WA , 98642

**Survey Location:**

**Basement bedroom**  
**Basement bathroom**

**What is the building's description?**

**Residential home**

**What is this structure's current use?**

**Residential**

**What is the structure's past use?**

**Residential**



**ROBINSON**  
R E S T O R A T I O N

PO BOX 822366  
Vancouver WA. 98682

**Building Square Footage:**

1,900

**Number of Floors:**

2

**Area Surveyed:**

Basement bedroom

Basement bathroom

**Approximate Build Date:**

1978

**Purpose of the Survey:**

**Test for asbestos**

**Survey Limitations:** Samples are collected based on a visual inspection of the work area as defined in the analysis report. Samples were collected from accessible, representative construction materials, which were suspected to contain asbestos. If additional materials are found during the demolition process that were inaccessible at the time of inspection that are not listed in this report, please have materials tested before they are impacted. Survey is subject to direction from contractor, homeowner or owners agent.



# ROBINSON RESTORATION

PO BOX 822366  
Vancouver WA. 98682

Robinson Restoration's asbestos survey was performed following the sampling protocol for the renovation/demolition areas as outlined under AHERA, 40 CFR 763, the Southwest Clean Air Agency (SWCAA) and the State of WASHINGTON Department of Labor and Industries WAC 296-62-007.

<https://doh.wa.gov/community-and-environment/contaminants/asbestos>

**A copy of this survey report must be kept onsite during any remediation, renovation or demolition activities, as required by Oregon DEQ OAR 340-248-027(2).**

**Survey Performed By:**

\_\_\_\_\_ Jake Rogers \_\_\_\_\_

**Of**

**Robinson Restoration, LLC.**

**AHERA Cert#:** \_\_\_\_\_IN-22-0802c\_\_\_\_\_

**CCB#:** \_\_\_\_\_SRA0614\_\_\_\_\_





# ADVANTAGE Environmental INC.

Clean your world.

9317 NE Hwy 99, Suite D, Vancouver, WA 98665 | 360-356-7628  
Polarized Light Microscopy Results

Lab No 143784  
Layers Analyzed 15  
  
Date Received 3/26/2024  
Received By Talia Carroll  
Date Analyzed 3/26/2024  
Analyzed By Nathan Blondino

Property Address 3326 NE 160th St  
City, State, Zip Ridgefield, WA  
Job Number Cindy Martinez  
Client Name Robinson Restoration  
Client Address 5900 NE 152nd Ave  
City, State, Zip Vancouver, WA  
Phone & E-mail 360-947-2738 info@robinsonrestore.com

AEI Sample ID	Client Sample ID	Composition	Color/Description	Asbestos (%)	Non-Asbestos Fiber (%)	Non Fibrous
001	1	Layered	White Texture	2% Chrysotile	N/A	(Gray) Paint-CaCO <sub>3</sub>
001A		Layered	White Joint Compound	2% Chrysotile	N/A	CaCO <sub>3</sub>
001B		Layered	White Drywall	Asbestos Not Present	15% Cellulose	Gypsum
002	2	Layered	White Texture	2% Chrysotile	N/A	(Gray) Paint-CaCO <sub>3</sub>
002A		Layered	White Joint Compound	2% Chrysotile	N/A	CaCO <sub>3</sub>
002B		Layered	White Drywall	Asbestos Not Present	15% Cellulose	Gypsum
003	3	Layered	White Texture	2% Chrysotile	N/A	(Gray) Paint-CaCO <sub>3</sub>
003A		Layered	White Joint Compound	2% Chrysotile	N/A	CaCO <sub>3</sub>
003B		Layered	White Drywall	Asbestos Not Present	15% Cellulose	Gypsum
004	4	Layered	White Joint Compound	Asbestos Not Present	N/A	(Light Blue) Paint-CaCO <sub>3</sub>
004A		Layered	White Drywall	Asbestos Not Present	15% Cellulose	Gypsum
005	5	Layered	White Joint Compound	Asbestos Not Present	N/A	(Light Blue) Paint-CaCO <sub>3</sub>
005A		Layered	White Drywall	Asbestos Not Present	15% Cellulose	Gypsum
006	6	Layered	White Joint Compound	Asbestos Not Present	N/A	(Light Blue) Paint-CaCO <sub>3</sub>
006A		Layered	White Drywall	Asbestos Not Present	15% Cellulose	Gypsum



## Disclaimer

- EPA Method 600/M4-82-020 (1982) was used to determine the presence or absence of asbestos fibers in all materials referenced in the above report. PLM analysis is based on visual estimation, and due to limitations of PLM analysis NESHAP regulations recommend that any material determined to contain less than 10% asbestos by the above referenced method should either be assumed to contain greater than 1% asbestos by the owner/operator, or be verified by PLM Point Count or TEM analysis as containing less than 1% asbestos.
- We recommend that TEM analysis be conducted for confirmation of negative PLM analytical results of vinyl floor tiles and vermiculite. These materials may contain asbestos fibers that cannot be detected by PLM analysis due to their size (<0.25 microns in diameter)
- This report may not be used to represent any materials not analyzed and listed in the included report. Advantage Environmental Inc. cannot be held responsible for the interpretation of the results shown. This report may not be reproduced in part and may only be reproduced in full without prior written consent from Advantage Environmental Inc.



**ADVANTAGE**  
Environmental INC.

## ASBESTOS CHAIN OF CUSTODY

9317 NE Hwy 99, Suite D • (360) 356-7628

LEGAL DOCUMENT - PLEASE PRINT LEGIBLY

Lab Use Only	
Survey	Lab No. 143784
Walk-In	Accept Reject

Sampled By - Please fill out yellow highlighted areas			Project Information - Please fill out yellow highlighted areas		
Date: 3/23/24			Project Name: Cindy Martinez		
Name/Company Name: Robinson Restoration			Address (where material was pulled from): 3326 NE 160th St		
Phone: 000 000 0000			City, State, Zip: Ridgefield WA 98642		
Email: 000 000 0000			P.O. #:		
RELINQUISHED BY		DATE & TIME	VIA	RECEIVED BY	DATE & TIME
Name: Jake Rogers		Date: 3/25/24	Drop Box		3-26-24
Sign:		Time: 3:30			10:27
REQUESTED SERVICES					
PLM			TURNAROUND TIME - Please choose a turnaround time		
Bulk Analysis			Verbal	<input checked="" type="checkbox"/> Rush	Same Day 24-Hour 3-Days
No.	Sample ID	Color	Description	Volume / Area (as applicable)	Comments / Notes
1	01	Grey	Bedroom drywall		
2	02				
3	03				
4	04	Blue	Bathroom drywall		
5	05				
6	06				
7					
8					
9					
10					
11					



THIS IS TO CERTIFY THAT  
**JAKE ROGERS**  
HAS SUCCESSFULLY COMPLETED THE TRAINING COURSE  
for  
**ASBESTOS INSPECTOR INITIAL COURSE**

In accordance with TSCA Title II, Part 763, Subpart E, Appendix C of 40 CFR

CCB #SRA0614 24-Hr Training

24-Hour AHERA Inspector Training: AHERA  
is the Asbestos Hazard Emergency  
Response Act enacting Title II of Toxic  
Substance Control Act (TSCA)

Course Date: 11/14/2022 - 11/16/2022


Course Location: Portland, OR

Certificate: IN-22-0802C



Expiration Date: 11/16/2023

For verification of the authenticity of this  
certificate contact:  
PBS Engineering and Environmental Inc.  
4412 S Corbett Avenue  
Portland, OR 97239  
503.248.1939

  
Andy Fridley, Instructor