| $\sim$ SM/CAA   |   | Case #: 24-229  |
|---|---|-----------------|
| Southwest Clean Air Agency Notice of Intent to Remove Asl   | bestos Ame                                | ndment: 0       |
| 1815 NE 99th Street, Suite 1294<br>/ancouver, WA 98662  | Date Receiv                               | ed: 4/12/202    |
| /oice: 360-574-3058<br>ax: 360-576-0925   | Date Pa                                   | aid: 4/12/202   |
| Veb: https://www.swcleanair.gov<br>Email: Tina@swcleanair.gov   | SWCAA F                                   | ee: \$294.00    |
| This notification MUST be present at all times at the asbestos project  | sit Receip                                | t #: 15437435   |
| *** EMERGENCY NOTICE ***  |   |                 |
| Quantity to be removed: 120 Square Feet 0 Linear Feet   | Workshift days:                           | Μ               |
| Project starting date: 4/15/2024 Project Completion date: 4/15/2024   | Workshift hours:                          | 8-4             |
| Site Name:W299_EagleRestoration_13803SeASite address:3803   | SE 28th Ave                               |                 |
| Location of Asbestos: Kitchen City/State/Zip: Vance   | ouver                                     | WA 98683        |
| Demolition of Structure (Notification of Demolition required)   | ounty: CLARK COUNT                        | Y               |
| Asbestos survey conducted? No survey reason:  |   |                 |
|   | Certification #:                          |                 |
|   |   |                 |
| Material to be Removed:         □ Fireproofing       □ Popcorn Ceiling       □ CAB       ☑ Sheet Vinyl  | Boiler Insulation                         | Duct Tape       |
| □ Duct Paper □ Mag Pipe Insulation □ Air Cell □   | CA Pipe                                   |                 |
| ✓ Other Mastic  |   |                 |
| Control Methods:  |   |                 |
| ✓ N.P Enclosure   | ✔ Water                                   | 🖌 HEPA Vac      |
| ✓ Other 6-Mil Poly, Wet, Labeled  |   |                 |
|   |   |                 |
| Asbestos Contractor: Alpine Abatement Associates Inc.   | one: 541-388-2672                         |                 |
|   | one: 541-388-2672<br>mail: annmarie@alpir | neabatement.com |
|   |   | neabatement.com |
| Mailing Address:PO Box 1557, Bend, OR, 97709EnCertification ##:ABCN00001215   |   | neabatement.com |
| Mailing Address:PO Box 1557, Bend, OR, 97709EndCertification ##:ABCN00001215Supervisor:Jose VeraPhone:  | mail: annmarie@alpir                      | neabatement.com |
| Mailing Address:       PO Box 1557, Bend, OR, 97709       En         Certification ##:       ABCN00001215       En         Supervisor:       Jose Vera       Phone: | mail: annmarie@alpir<br>541-388-2672      | neabatement.com |

#### TO THE BEST OF MY KNOWLEDGE, ACCURATE AND COMPLETE.

| Submitter Name:  | Bo Davidson            | Representing:   | Alpine Abatement |
|------------------|------------------------|-----------------|------------------|
| Submitter Title: | Senior Project Manager | Date Submitted: | 4/12/2024        |
|                  |                        |                 |                  |

Reviewed by SWCAA: Brian Fallon



#### Notice of Intent to Remove Asbestos

Case #: 24-229
Amendment: 0

| 11815 NE 99th Street, Suite 1294<br>Vancouver, WA 98662                     | Date Received: | 4/12/2024 |
|---|----------------|-----------|
| Voice: 360-574-3058<br>Fax: 360-576-0925<br>Web: https://www.swcleanair.gov | Date Paid:     | 4/12/2024 |
| Email: Tina@swcleanair.gov  | SWCAA Fee:     | \$294.00  |
| This notification MUST be present at all times at the asbestos project sit  | Receipt #:     | 154374351 |

Eagle Restoration P.O. Box 549 Redmond, OR 97756 (503) 785-9824 www.eaglerestorationpdx.com CCB #223734

### Atlas Labs

|                                      | Limited Survey Chai            | in of Custody                         |                             |
|--------------------------------------|--------------------------------|---------------------------------------|-----------------------------|
| Client Name: Eagle Restoration       | and the state                  | Client Phone: 503-785-9824            |                             |
| Client Email: accounting@eagle       | erestorationpdx.com            |                                       |                             |
| Job/Project Address: A nani          | KUFFN85-13803                  | SE 78th ave, van                      | ower, wa 9868               |
| Inspector Name: Austin Hensey        |                                | Inspector Phone Number: (             | 503) 785-9824               |
| Inspector Email Address: accou       | inting@eaglerestorationpdx.com | Inspector AHERA Cert.: IRC            | 0-22-9353B                  |
| Survey Area Use: Approx. Year Built: |                                | Reason for Survey: MT                 | t                           |
| X Rush<br>Next Day<br>2-Day<br>5-Day |                                | X Asbestos PLM<br>Lead Paint<br>Other |                             |
| # Material Desc                      | ription Friable Y/M            | Location                              | Approx.<br>Condition SQ FT. |
| Ol White texture                     | d, Jurywall 7                  | Kitchen Wall                          |                             |
| Inspector Signature:                 | n Henry                        | Date: 4-11-24                         | Time: 8:35am                |
| Accepted By: V 1111                  | Vatoria                        | Date: 4.11. 2024                      | Time: 10:54                 |

Limitations of Inspection: Eagle Restoration's AHERA certified inspector performed a limited survey at the site, date, time and cause as stated above in this document along with lab analysis of possible asbestos and/or lead containing material. Eagle Restoration's survey is limited to areas defined on the Chain of Custody form.

General NESHAPS Bulk Sampling Guidelines: Material sampling areas were grouped based on homogeneous materials. A homogeneous area is one which contains material that seems by texture, color and surface wear to be uniform and applied during the same general time period. Samples are collected based on a visual survey of the work area as defined in this report. Samples were collected from accessible, representative construction materials, which were suspected to contain asbestos. If additional materials are found during the demolition process that were inaccessible at time of inspection that are not listed in this report please test before you cut. Survey is subject to direction from contractor, homeowner or owners agent.

# Atlas Labs

| Batch # 2022 *   | Name / Company *                           |
|------------------|--|
| 22-1277201       | Eagle Restoration                          |
| Analysis Date *  | Project Name                               |
| 04/11/2024       | Anani Kuffner                              |
| Project #        | PO #                                       |
|                  |  |
| Analyst *        | Project Location *                         |
| Crossland Kapaun | 13803 SE 28th Ave.,<br>Vancouver, WA 98683 |

Turnaround Time \*

Rush

#### Asbestos Analysis of Bulk Material by Polarized Light Microscopy

| Sample* | Layer* | Description*                    | Non Asbestos* | Asbestos Type* | Asbestos %* |
|---------|--------|---------------------------------|---------------|----------------|-------------|
| 01      | 1      | Drywall (White) - Kitchen Wall  | Cellulose     | None Present   | N/D         |
| 01      | 2      | Texture (White) - Kitchen Wall  | Cellulose     | None Present   | N/D         |
| 02      | 1      | Vinyl (Brown) - Kitchen Floor   | Cellulose     | Chrysotile     | 25%         |
| 02      | 2      | Mastic (Yellow) - Kitchen Floor | Cellulose     | Chrysotile     | 2%          |

**To Be Filled by the Technician** Technician \*

rK

Atlas Laboratories maintains liability to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full without written permission by Atlas. Atlas bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client.

This report must not be used by the client to claim product certification, approval or endorsement by NVLAP, NIST, NIOSH or any other agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore Atlas recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Transmission Electron Microscopy asbestos identification and lead paint analysis will be available and performed by laboratories by proxy. Original analysis documents are available upon request of the client.

## THIS IS TO CERTIFY THAT **AUSTIN HENSEY**

## HAS SUCCESSFULLY COMPLETED THE TRAINING COURSE for ASBESTOS INSPECTOR INITIAL COURSE

In accordance with TSCA Title II, Part 763, Subpart E, Appendix C of 40 CFR

Course Date:

Certificate:

7/10/2023 - 7/12/2023

Course Location:

Portland, OR

IN-23-1357C

For verification of the authenticity of this certificate contact: PBS Engineering and Environmental Inc. 4412 S Corbett Avenue Portland, OR 97239 503.248.1939



CCB #SRA0614 24-Hr Training

24-Hour AHERA Inspector Training; AHERA is the Asbestos Hazard Emergency Response Act enacting Title II of Toxic Substance Control Act (TSCA)

Expiration Date:

07/12/2024

ander fieldy

Andy Fridley, Instructor

# THIS IS TO CERTIFY THAT WYATT JONES

## HAS SUCCESSFULLY COMPLETED THE TRAINING COURSE for ASBESTOS INSPECTOR INITIAL COURSE

In accordance with TSCA Title II, Part 763, Subpart E, Appendix C of 40 CFR

Course Date:

7/10/2023 - 7/12/2023

Course Location:

Portland, OR

Certificate:

IN-23-1358C

For verification of the authenticity of this certificate contact: PBS Engineering and Environmental Inc. 4412 S Corbett Avenue Portland, OR 97239 503.248.1939



#### CCB #SRA0614 24-Hr Training

24-Hour AHERA Inspector Training; AHERA is the Asbestos Hazard Emergency Response Act enacting Title II of Toxic Substance Control Act (TSCA)

Expiration Date:

07/12/2024

ander Fridley

Andy Fridley, Instructor