



11815 NE 99th Street, Suite 1294
Vancouver, WA 98662
Voice: 360-574-3058
Fax: 360-576-0925
Web: <https://www.swcleanair.gov>
Email: Tina@swcleanair.gov

Notification of Demolition

Case #: 24-240

Amendment: 0

Date Received: 4/16/2024

Date Paid: 4/16/2024

SWCAA Fee: \$74.00

Receipt #: 154629144

10 day waiting period from date submitted

1. Type of Notification: Original

2. Type of Operation: Demolition

3. Facility Description: structure demo

Commercial Name or Description: O Street Demo

Address: 3202 O Street

City/State/Zip/County: Vancouver, WA 98663 CLARK COUNTY

Present Use: Vacant

Previous Use: Residence

4. Facility Information

Property Owner:

Property Owner: Linda Rainwater

5. Name and AHERA Certification Number of Asbestos Inspector:

Name: Jason Hawks

Certification #: BI/R-NES-12-19-22-09

6. Asbestos Removal Contractor (if applicable):

Name: 3 Kings Environmental Inc.

Mailing Address: PO Box 280, Battle Ground, WA, 98604

Contact: Jason Hawks

Phone: Jason Hawks

7. Dates Asbestos Removal Occurred:

Start: 4/22/2024

Complete: 4/22/2024

Asbestos Case No.: 24-226-0

8. Dates Demolition Will Occur:

Start: 4/29/2024

Complete: 5/10/2024

9. Demolition Contractor:

Name: 3 Kings Environmental Inc.

Mailing Address: PO Box 280, Battle Ground, WA, 98604

Contact: Jason Hawks

Phone: 253-750-4143

10. Asbestos Disposal Site: N/A

11. Description of planned demolition work, method(s) to be used:

Mechanical means

12. Fugitive Emissions/dust from Demolition Activities MUST BE Controlled/Prevented during all phases of the project

Wet methods

13. If unexpected Asbestos containing Material (ACM) is found during demolition, Stop Work, Notify SWCAA and Consult/Hire a Certified Asbestos Abatement Contractor

Asbestos will be removed prior to demo.

14. If demolition is ordered by a Government Agent:

15. For Emergency Demolitions (Contact SWCAA prior to work): ☐ Emergency Demolition

Date and Time of Emergency:

Description of Sudden, Unexpected Event:

Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable burden:

16. I Certify that the above information is correct:

Submitter Name: Adrianna Yugovich

Representing: 3 Kings Environmental, Inc.

Submitter Title: Project Engineer

Date Submitted: 4/16/2024

Email Address: ayugovich@3kingsinc.com

Reviewed by SWCAA: Brian Fallon

☒ Approved

The Washington State Dangerous Waste Regulations (WAC 173-303) require that demolition debris be evaluated to determine if it is dangerous. The evaluation should be completed before demolition to ensure that hazardous constituents are not released to the environment and do not present a risk to human health during or after demolition. These requirements apply to all buildings being demolished and are the responsibility of the property owner. The Washington Department of Ecology's website, <https://ecology.was.gov/Regulations-Permits/Guidance-technical-assistance/Dangerous-waste-guidance/Common-dangerous-waste/Construction-and-demolition>, provides more information about the requirements and about sampling and testing construction materials to determine if they present a risk. For more information please contact a Hazardous Waste Inspector at the Washington Department of Ecology Southwest Regional Office: (360) 407-6300.



3 Kings Environmental, Inc.

Asbestos Containing Materials Inspection

Good Faith Inspection

April 3, 2024

Prepared For: Linda Rainwater
PO Box 54
Owasso, OK 74055

Project: 3203 O Street
Vancouver, WA 98663

RE: Pre-Demolition Good Faith Asbestos Survey

FRONT OF STRUCTURE



INSPECTION REPORT

BACKGROUND

On April 1, 2024 3 Kings Environmental, Inc. performed a Pre-Demolition Good Faith Asbestos Inspection of the above mentioned project to determine the presence of asbestos containing materials (ACMs). The intent of this inspection is to ensure that the property owner is in compliance with the regulatory requirements for the identification of ACMs prior to any demolition or renovation activities.

BUILDING DESCRIPTION

The structure was a wood framed single family residence. The home was on a concrete foundation with a attached lower level bonus room that is slab on grade.

Year Built: 1940

Approximate Dimensions: 912 Sf

Interior Finishes:

The interior of home was primarily plaster or drywall walls and ceiling. Floors were primarily bare wood or sheet vinyl.

Exterior Finishes:

The exterior of home consisted of one vinyl window, one aluminum framed window, wood siding was already 99% removed, wood trim and asphalt type roofing shingles were already removed.

SAMPLING PROCESS

All accessible areas of the specific work area were sampled during the inspection. Inaccessible areas are those defined as requiring select demolition, fall protection, repair to the structure i.e. weather protection or water proofing or are considered a confined space entry. If during the course of asbestos abatement or demolition suspect materials are discovered that are not identified on this report stop work immediately. These materials need to be treated as asbestos containing until the material can be tested by an AHERA Building Inspector and determined otherwise.

Suspect materials were collected by an AHERA certified building inspector. Samples are then given a unique identification number. Sample information such as type of material and its locations are then placed on the chain of custody that accompany the samples to the testing laboratory. Once the samples are delivered to an asbestos laboratory for analysis. Samples are analyzed by polarized light microscopy (PLM) with dispersion staining in accordance with USEPA 600/M-82/020, which has a reliable limit of quantification of one percent asbestos by volume.

Samples were collected following EPA guidelines. The suspect materials are broken down into three categories: Surfacing Materials, Thermal System Insulation, and Miscellaneous Materials. Each of these categories have a set of guidelines that were followed that include the number of samples required for that particular category based on the quantity of the material, how the material was applied and what was the intent of the material. All these factors are accounted for during the time of inspection.

AHERA Certified Building Inspector



Certified AHERA Building Inspector was Jason Hawks

Certification # BI/R-NES-12-01-23-07, Expiration December 1, 2024

SURVEY FINDINGS

Materials found to contain asbestos in concentrations greater than one percent (>1%) as part of this investigation and estimated quantities for removal:

Sample #	Material Description	Sample Location	Friability / Condition / Category	Lab Result	Quantity
04	Black Mastic Glue Dots	Living Room, Walls	NF / Good	5% Chrysotile	177 SF
24	Brown Sheet Vinyl	Center of Lower Bonus Room Floor, Remnants Found Throughout Room	NF / Fair	15% Chrysotile	160 SF

	<p>04 – In the living room area contained Black Mastic Glue Dots which contained 5% Chrysotile. The Glue Dots were seen in good condition.</p>
	<p>24 – Brown Sheet Vinyl Flooring at the center of the floor in the lower bonus room contained 15% Chrysotile. The condition of this flooring was fair.</p>

The following is a summary of all the suspect bulk asbestos sampled during the inspection.

Sample #	Material Description & Location	Friability & Condition	Material Category	Lab Result
01	Popcorn Ceiling Texture / Living Room	F / Good	S	NAD
02	Popcorn Ceiling Texture / Living Room	F / Good	S	NAD

03	Popcorn Ceiling Texture / Living Room	F / Good	S	NAD
04	Black Mastic Glue Dots / Living Room	NF / Good	M	5% Chrysotile
05	Black Mastic Glue Dots / Living Room	NF / Good	M	PACM
06	Plaster Wall / Living Room	F / Good	S	NAD
07	Plaster Wall / Living Room	F / Good	S	NAD
08	Plaster Wall / Bedroom 1	F / Good	S	NAD
09	Plaster Wall / Bedroom 2	F / Good	S	NAD
10	Orange Peel Texture on Drywall / Kitchen Ceiling	NF / Good	S	NAD
11	Orange Peel Texture on Drywall / Kitchen Ceiling	NF / Good	S	NAD
12	Orange Peel Texture on Drywall / Bathroom Wall	NF / Good	S	NAD
13	Orange Peel Texture on Drywall / Bathroom Wall	NF / Good	S	NAD
14	Backsplash Mastic Over Plaster on Wall / Kitchen	NF / Good	M	NAD
15	Backsplash Mastic Over Plaster on Wall / Kitchen	NF / Good	M	NAD
16	Brown Cove base Mastic / Kitchen	NF / Good	M	NAD
17	Brown Cove base Mastic / Kitchen	NF / Good	M	NAD
18	Tar Paper Under Hardwood Floor / Living Room	NF / Good	M	NAD
19	Tar Paper Under Hardwood Floor / Bedroom 1	NF / Good	M	NAD
20	Cream Sheet Vinyl / Base of Stairs	NF / Good	M	NAD
21	Cream Sheet Vinyl / Base of Stairs	NF / Good	M	NAD
22	Cream Tile Under Washer and Dryer / Base of Stairs	NF / Good	M	NAD
23	Cream Tile Under Washer and Dryer / Base of Stairs	NF / Good	M	NAD
24	Brown Sheet Vinyl / Center of Lower Bonus Room	NF / Fair	M	15%Chrysotile
25	Brown Sheet Vinyl / Center of Lower Bonus Room	NF / Fair	M	PACM
26	Tar Paper Under Siding / Exterior Front	NF / Good	M	NAD
27	Tar Paper Under Siding / Exterior Front	NF / Good	M	NAD
28	Caulking Exterior Door / Front	NF / Good	M	NAD
29	Caulking Exterior Door / Front	NF / Good	M	NAD

Legend: NAD – No Asbestos Detected	Category: S – Surfacing Material
--	--

F – Friable (can be pulverized by hand pressure)	TSI – Thermal System Insulation
NF – Non-Friable	M – Miscellaneous Material
PACM – Presumed Asbestos Containing Material	

ADDITIONAL OBSERVATIONS

Lead Paint and Other Metals

Lead-based paint was not sampled as part of this survey. Based on the age of the structure lead based paints should be assumed.

Lead safe work practices and appropriate precautions should be utilized during all work impacting painted surfaces.

Microbial Growth

Water damage and potential microbial growth were not observed as part of this sampling. Appropriate precautions should be utilized during work.

PCBs, Mercury Bulbs and Mercury Thermostats

PCBs, Mercury Bulbs and Mercury Thermostats were not tested or examined as part of this survey. Appropriate precautions should be utilized during work.

Inaccessible Components

No inaccessible components spaces were observed at the time of the inspection.

RESULTS AND RECOMMENDATIONS

Of the twenty-nine (29) suspect bulk materials sampled two (2) tested positive for asbestos with a concentration greater than 1%. Two additional samples are noted as presumed asbestos containing materials (PACM) as they were designated for positive stop.

3 Kings Environmental, Inc. recommends that any ACM or PACM to be impacted during the course of the renovation or demolition be removed by a licensed, bonded, and insured asbestos abatement firm. Removal and disposal of asbestos containing materials should only be performed by certified firms following all local, state, and federal guidelines. Should materials not noted in this report be discovered during the course of the work, stop all demolition and have the newly discovered materials tested for asbestos or treat the materials as an asbestos containing material. Be sure to notify the governing authorities and clean-air agencies prior to disturbing materials over the recordable limits.

The conclusions/ recommendations of the report are professional opinions based solely on visual observations and interpretation of sample results from our third-party laboratory. Re-use of this document for other than its intended purpose is at the sole risk of said user. 3 Kings Environmental, Inc. cannot be held responsible for the interpretation by others of the data contained in this report as site conditions or



regulations may have changed. 3 Kings Environmental makes no warranty, expressed or implied for information found in this report.

If you have any questions regarding this asbestos survey/inspection report, please contact me at (360) 949-5822, or email: jhawks@3kingsinc.com

Respectfully submitted,
3 Kings Environmental, Inc.

Jason Hawks
Certified AHERA Building Inspector

LAB RESULTS



The Identification Specialists

Analysis Report
prepared for
3 Kings Environmental Inc.

Report Date: 4/2/2024

Project Name: Linda Rainwater

Project #: 224046

SanAir ID#: 24018603



NVLAP LAB CODE 200870-0

10501 Trade Court | North Chesterfield, Virginia 23236
888.895.1177 | 804.897.1177 | fax: 804.897.0070 | IAQ@SanAir.com | SanAir.com



SanAir ID Number

24018603

FINAL REPORT

4/2/2024 5:36:58 PM

Name: 3 Kings Environmental Inc.
Address: PO Box 280
Battle Ground, WA 98604
Phone: 360-666-5464

Project Number: 224046
P.O. Number: 12024-109
Project Name: Linda Rainwater
Collected Date: 4/1/2024
Received Date: 4/2/2024 10:15:00 AM

Dear Jason Hawks,

We at SanAir would like to thank you for the work you recently submitted. The 29 sample(s) were received on Tuesday, April 02, 2024 via UPS. The final report(s) is enclosed for the following sample(s): 01, 02, 03, 04, 05, 06, 07, 08, 09, 10, 11, 12, 13, 14, 15, 16, 17, 18, 19, 20, 21, 22, 23, 24, 25, 26, 27, 28, 29.

These results only pertain to this job and should not be used in the interpretation of any other job. This report is only complete in its entirety. Refer to the listing below of the pages included in a complete final report.

Sincerely,

A handwritten signature in black ink that reads "Sandra Sobrino".

Sandra Sobrino
Asbestos & Materials Laboratory Manager
SanAir Technologies Laboratory

Final Report Includes:

- Cover Letter
- Analysis Pages
- Disclaimers and Additional Information

Sample conditions:

- 29 samples in Good condition.



SanAir ID Number

24018603

FINAL REPORT

4/2/2024 5:36:58 PM

Name: 3 Kings Environmental Inc.
Address: PO Box 280
Battle Ground, WA 98604
Phone: 360-666-5464

Project Number: 224046
P.O. Number: 12024-109
Project Name: Linda Rainwater
Collected Date: 4/1/2024
Received Date: 4/2/2024 10:15:00 AM

Analyst: Mayes, Jean

Asbestos Bulk PLM EPA 600/R-93/116

SanAir ID / Description	Stereoscopic	Components		Asbestos Fibers
	Appearance	% Fibrous	% Non-fibrous	
01 / 24018603-001 Popcorn Ceiling Texture / Living Room	Off-White Non-Fibrous Heterogeneous		100% Other	None Detected
02 / 24018603-002 Popcorn Ceiling Texture / Living Room	Off-White Non-Fibrous Heterogeneous		100% Other	None Detected
03 / 24018603-003 Popcorn Ceiling Texture / Living Room	Off-White Non-Fibrous Heterogeneous		100% Other	None Detected
04 / 24018603-004 Mastic Glue Dots / Living Room	Black Non-Fibrous Homogeneous		95% Other	5% Chrysotile
05 / 24018603-005 Mastic Glue Dots / Living Room				Not Analyzed
06 / 24018603-006 Plaster Wall / Living Room, Plaster	Grey Non-Fibrous Heterogeneous	1% Hair	99% Other	None Detected
06 / 24018603-006 Plaster Wall / Living Room, Skim Coat	White Non-Fibrous Homogeneous		100% Other	None Detected
07 / 24018603-007 Plaster Wall / Living Room, Plaster	Grey Non-Fibrous Heterogeneous	1% Hair	99% Other	None Detected
07 / 24018603-007 Plaster Wall / Living Room, Skim Coat	White Non-Fibrous Homogeneous		100% Other	None Detected
08 / 24018603-008 Plaster Wall / Bedroom 1, Plaster	Grey Non-Fibrous Heterogeneous	1% Hair	99% Other	None Detected

Analyst: 

Analysis Date: 4/2/2024

Approved Signatory: 

Date: 4/2/2024



SanAir ID Number
24018603
FINAL REPORT
4/2/2024 5:36:58 PM


Name: 3 Kings Environmental Inc.
Address: PO Box 280
Battle Ground, WA 98604
Phone: 360-666-5464


Project Number: 224046
P.O. Number: 12024-109
Project Name: Linda Rainwater
Collected Date: 4/1/2024
Received Date: 4/2/2024 10:15:00 AM

Analyst: Mayes, Jean

Asbestos Bulk PLM EPA 600/R-93/116

SanAir ID / Description	Stereoscopic	Components		Asbestos Fibers
	Appearance	% Fibrous	% Non-fibrous	
08 / 24018603-008 Plaster Wall / Bedroom 1, Skim Coat	White Non-Fibrous Homogeneous		100% Other	None Detected
09 / 24018603-009 Plaster Wall / Bedroom 2, Plaster	Grey Non-Fibrous Heterogeneous	1% Hair	99% Other	None Detected
09 / 24018603-009 Plaster Wall / Bedroom 2, Skim Coat	White Non-Fibrous Homogeneous		100% Other	None Detected
10 / 24018603-010 Orange Peel Drywall Texture / Kitchen Ceiling, Drywall	Various Non-Fibrous Heterogeneous	10% Cellulose	90% Other	None Detected
10 / 24018603-010 Orange Peel Drywall Texture / Kitchen Ceiling, Texture	White Non-Fibrous Homogeneous		100% Other	None Detected
11 / 24018603-011 Orange Peel Drywall Texture / Kitchen Ceiling, Drywall	Various Non-Fibrous Heterogeneous	10% Cellulose	90% Other	None Detected
11 / 24018603-011 Orange Peel Drywall Texture / Kitchen Ceiling, Texture	White Non-Fibrous Homogeneous		100% Other	None Detected
12 / 24018603-012 Orange Peel Drywall Texture Drywall / Bathroom Wall, Drywall	Various Non-Fibrous Heterogeneous	10% Cellulose	90% Other	None Detected
12 / 24018603-012 Orange Peel Drywall Texture Drywall / Bathroom Wall, Texture	White Non-Fibrous Homogeneous		100% Other	None Detected
13 / 24018603-013 Orange Peel Drywall Texture Drywall / Bathroom Wall, Drywall	Various Non-Fibrous Heterogeneous	10% Cellulose	90% Other	None Detected

Analyst: 
Analysis Date: 4/2/2024

Approved Signatory: 
Date: 4/2/2024



SanAir ID Number
24018603
FINAL REPORT
4/2/2024 5:36:58 PM


Name: 3 Kings Environmental Inc.
Address: PO Box 280
Battle Ground, WA 98604
Phone: 360-666-5464


Project Number: 224046
P.O. Number: 12024-109
Project Name: Linda Rainwater
Collected Date: 4/1/2024
Received Date: 4/2/2024 10:15:00 AM

Analyst: Mayes, Jean

Asbestos Bulk PLM EPA 600/R-93/116

SanAir ID / Description	Stereoscopic	Components		Asbestos Fibers
	Appearance	% Fibrous	% Non-fibrous	
13 / 24018603-013 Orange Peel Drywall Texture Drywall / Bathroom Wall, Texture	White Non-Fibrous Homogeneous		100% Other	None Detected
14 / 24018603-014 Mastic Over Plaster On Wall / Kitchen	Yellow Non-Fibrous Homogeneous		100% Other	None Detected
15 / 24018603-015 Mastic Over Plaster On Wall / Kitchen	Yellow Non-Fibrous Homogeneous		100% Other	None Detected
16 / 24018603-016 Covebase Mastic / Kitchen	Brown Non-Fibrous Homogeneous		100% Other	None Detected
17 / 24018603-017 Covebase Mastic / Kitchen	Brown Non-Fibrous Homogeneous		100% Other	None Detected
18 / 24018603-018 Tar Paper Under Hardwood Floor / Living Room	Black Fibrous Heterogeneous	70% Cellulose	30% Other	None Detected
19 / 24018603-019 Tar Paper Under Hardwood Floor / Bedroom 1	Black Fibrous Heterogeneous	70% Cellulose	30% Other	None Detected
20 / 24018603-020 Sheet Vinyl / Base Of Stairs, Flooring	Cream Non-Fibrous Heterogeneous	5% Glass	95% Other	None Detected
20 / 24018603-020 Sheet Vinyl / Base Of Stairs, Mastic	Cream Non-Fibrous Homogeneous		100% Other	None Detected
21 / 24018603-021 Sheet Vinyl / Base Of Stairs, Flooring	Cream Non-Fibrous Heterogeneous	5% Glass	95% Other	None Detected

Analyst: 
Analysis Date: 4/2/2024

Approved Signatory: 
Date: 4/2/2024



SanAir ID Number

24018603

FINAL REPORT

4/2/2024 5:36:58 PM

Name: 3 Kings Environmental Inc.
Address: PO Box 280
Battle Ground, WA 98604
Phone: 360-666-5464

Project Number: 224046
P.O. Number: 12024-109
Project Name: Linda Rainwater
Collected Date: 4/1/2024
Received Date: 4/2/2024 10:15:00 AM

Analyst: Mayes, Jean

Asbestos Bulk PLM EPA 600/R-93/116

SanAir ID / Description	Stereoscopic	Components		Asbestos Fibers
	Appearance	% Fibrous	% Non-fibrous	
21 / 24018603-021 Sheet Vinyl / Base Of Stairs, Mastic	Cream Non-Fibrous Homogeneous		100% Other	None Detected
22 / 24018603-022 Tile Under Washer And Dryer / Base Of Stairs, Floor Tile	Cream Non-Fibrous Homogeneous		100% Other	None Detected
22 / 24018603-022 Tile Under Washer And Dryer / Base Of Stairs, Mastic	Yellow Non-Fibrous Homogeneous		100% Other	None Detected
23 / 24018603-023 Tile Under Washer And Dryer / Base Of Stairs, Floor Tile	Cream Non-Fibrous Homogeneous		100% Other	None Detected
23 / 24018603-023 Tile Under Washer And Dryer / Base Of Stairs, Mastic	Yellow Non-Fibrous Homogeneous		100% Other	None Detected
24 / 24018603-024 Sheet Vinyl / Base Of Stairs	Brown Non-Fibrous Heterogeneous		85% Other	15% Chrysotile
25 / 24018603-025 Sheet Vinyl / Base Of Stairs				Not Analyzed
26 / 24018603-026 Tar Paper Under Siding / Exterior Front	Black Fibrous Heterogeneous	80% Cellulose	20% Other	None Detected
27 / 24018603-027 Tar Paper Under Siding / Exterior Front	Black Fibrous Heterogeneous	80% Cellulose	20% Other	None Detected
28 / 24018603-028 Caulking At Exterior Door / Front	Brown Non-Fibrous Homogeneous		100% Other	None Detected

Analyst: Approved Signatory: 

Analysis Date: 4/2/2024

Date: 4/2/2024



SanAir ID Number
24018603
FINAL REPORT
4/2/2024 5:36:58 PM

Name: 3 Kings Environmental Inc.
Address: PO Box 280
Battle Ground, WA 98604
Phone: 360-666-5464

Project Number: 224046
P.O. Number: 12024-109
Project Name: Linda Rainwater
Collected Date: 4/1/2024
Received Date: 4/2/2024 10:15:00 AM

Analyst: Mayes, Jean

Asbestos Bulk PLM EPA 600/R-93/116

SanAir ID / Description	Stereoscopic	Components		Asbestos Fibers
	Appearance	% Fibrous	% Non-fibrous	
29 / 24018603-029 Caulking At Exterior Door / Front	Brown Non-Fibrous Homogeneous		100% Other	None Detected

Analyst:

Approved Signatory:

Analysis Date: 4/2/2024

Date: 4/2/2024

Disclaimer

This report is the sole property of the client named on the SanAir Technologies Laboratory chain-of-custody (COC). Results in the report are confidential information intended only for the use by the customer listed on the COC. Neither results nor reports will be discussed with or released to any third party without our client's written permission. The final report shall not be reproduced except in full without written approval of the laboratory to assure that parts of the report are not taken out of context. This report and any information contained within shall not be edited, altered, or modified in any way by any persons or agencies receiving, viewing, distributing, or otherwise possessing a copy of this final report. The laboratory reserves the right to perform amendments to any finalized report, of which shall supersede and make obsolete any previous editions. Such changes, modifications, additions, or deletions shall be effective immediately upon notice thereof, which may be given by means including but not limited to posting on the SanAir client portal website, electronic or conventional mail, or by any other means. The information provided in this report applies only to the samples submitted and is relevant only for the date, time, and location of sampling. The accuracy of the results is dependent upon the client's sampling procedure and information provided to the laboratory by the client on the COC. SanAir assumes no responsibility for the sampling procedure and will provide evaluation reports based solely on the sample(s) in the condition in which they arrived at the laboratory and information provided by the client on the COC, such as: project number, project name, collection dates, po number, special instructions, samples collected by, sample numbers, sample identifications, sample type, selected analysis type, flow rate, total volume or area, and start stop times that may affect the validity of the results in this report. Samples were received in good condition unless otherwise noted on the report. SanAir assumes no responsibility or liability for the manner in which the results are used or interpreted. This report does not constitute nor shall not be used by the client to claim product, process, system, or person certification, approval, or endorsement by NVLAP, NIST, NELAC, AIHA LAP, LLC or any other U.S. governmental agencies and may not be accredited by every local, state, and federal regulatory agencies. Samples are held for a period of 60 days. Fibers smaller than 5 microns cannot be seen with this method due to scope limitations. For NY state samples, method EPA 600/M4-82-020 is performed.

NYELAP Disclaimer:

Polarized- light microscopy is not consistently reliable in detecting asbestos in floor covering and similar non-friable organically bound materials. Quantitative transmission electron microscopy is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos containing.

Asbestos Accreditations

National Voluntary Laboratory Accreditation Program (NVLAP) Lab Code 200870-0
City of Philadelphia Department of Public Health Air Management Services, Certification#ALL-460
Commonwealth of Pennsylvania Department of Environmental Protection Number 68-05397
California State Environmental Laboratory Accreditation Program Certificate Number 2915
Colorado Department of Public Health and Environment Registration Number AL-23143
Connecticut Department of Public Health Environmental Laboratory Registration Number PH-0105
Massachusetts Department of Labor Standards Asbestos Analytical Services License Number: AA000222
State of Maine Department of Environmental Protection License Number: LB-0075, LA-0084
New York State Department of Health Laboratory ID: 11983
State of Rhode Island Department of Health Certification No.: PCM00126, PLM00126, TEM00126
Texas Department of State Health Services License Number: 300440
Commonwealth of Virginia Department of Professional and Occupational Regulation Number: 3333000323
State of Washington Department of Ecology Laboratory ID: C989
State of West Virginia Bureau for Public Health Analytical Laboratory Number: LT000616
Vermont Department of Health License Number: Asb-Co-An-000006
Louisiana Department of Environmental Quality AI Number 212253, Certificate #05088



10501 Trade Ct., Suite 100
N. Chesterfield, VA 23236
804.897.1177 / 888.895.1177
Fax 804.897.0070
sanair.com

Asbestos
Chain of Custody
Form 140, Rev 7, 10/20/2022

SanAir ID Number

24018603

Company: 3 Kings Environmental, Inc.		Project #: 224046	Collected by: J. Hawks
Address: PO Box 280		Project Name: Linda Rainwater	Phone #: 360-666-5464
City, St., Zip: Battle Ground, WA 98604		Date Collected: 04/01/2024	Fax #: 360-666-8202
State of Collection: WA	Account#: 2344	P.O. Number: 12024-109	Email: jhawks@3kingsinc.com

Bulk			Air			Soil		
ABB	PLM EPA 600/R-93/116	<input checked="" type="checkbox"/>	ABA	PCM NIOSH 7400	<input type="checkbox"/>	ABSE	PLM EPA 600/R-93/116 (Qual.)	<input type="checkbox"/>
	Positive Stop	<input checked="" type="checkbox"/>	ABA-2	OSHA w/ TWA*	<input type="checkbox"/>	Vermiculite		
ABEPA	PLM EPA 400 Point Count	<input type="checkbox"/>	ABTEM	TEM AHERA	<input type="checkbox"/>	ABB	PLM EPA 600/R-93/116	<input type="checkbox"/>
ABB1K	PLM EPA 1000 Point Count	<input type="checkbox"/>	ABATN	TEM NIOSH 7402	<input type="checkbox"/>	ABEPA3	PLM EPA 400 Point Count	<input type="checkbox"/>
ABBN	PLM EPA NOB**	<input type="checkbox"/>	ABT2	TEM Level II	<input type="checkbox"/>	ABCM	Cincinnati Method	<input type="checkbox"/>
ABBCH	TEM Chatfield**	<input type="checkbox"/>	Other:		<input type="checkbox"/>	Dust		
ABBTM	TEM EPA NOB**	<input type="checkbox"/>	New York ELAP			ABWA	TEM Wipe ASTM D-6480	<input type="checkbox"/>
ABQ	PLM Qualitative	<input type="checkbox"/>	ABEPA2	NY ELAP 198.1	<input type="checkbox"/>	ABDMV	TEM Microvac ASTM D-5755	<input type="checkbox"/>
			ABENY	NY ELAP 198.6 PLM NOB	<input type="checkbox"/>			
			ABBNY	NY ELAP 198.4 TEM NOB	<input type="checkbox"/>			
			Positive Stop			Matrix	Other	<input type="checkbox"/>

** Available on 24-hr. to 5-day TAT

Water	
ABHE	EPA 100.2 <input type="checkbox"/>

Turn Around Times	3 HR (4 HR TEM) <input type="checkbox"/>	6 HR (8HR TEM) <input type="checkbox"/>	12 HR <input type="checkbox"/>	1 Day <input checked="" type="checkbox"/>
	<input type="checkbox"/> 2 Days	<input type="checkbox"/> 3 Days	<input type="checkbox"/> 4 Days	<input type="checkbox"/> 5 Days

Special Instructions	
-----------------------------	--

Sample #	Sample Identification/Location	Volume or Area	Sample Date	Flow Rate*	Start - Stop Time*
01	Popcorn Ceiling Texture / Living Room				
02	Popcorn Ceiling Texture / Living Room				
03	Popcorn Ceiling Texture / Living Room				
04	Black Mastic Glue Dots / Living Room				
05	Black Mastic Glue Dots / Living Room				
06	Plaster Wall / Living Room				
07	Plaster Wall / Living Room				
08	Plaster Wall / Bedroom 1				
09	Plaster Wall / Bedroom 2				
10	Orange Peel Drywall Texture / Kitchen Ceiling				
11	Orange Peel Drywall Texture / Kitchen Ceiling				
12	Orange Peel Drywall Texture drywall / Bathroom Wall				

Relinquished by	Date	Time	Received by	Date	Time
jHawks	04/01/24	9:19am	EDR	4/2/24	10:15 a.m.

If no technician is provided, then the primary contact for your account will be selected. Unless scheduled, the turnaround time for all samples received after 3 pm EST will be logged in the next business day. Weekend or holiday work must be scheduled ahead of time and is charged at 150% of the 3hr TAT or a minimum charge of \$150. A courier charge will be applied for same day and one-day turnaround times for offsite work. SanAir covers Ground and Next Day Air shipping. Shipments billed to SanAir with a faster shipping rate will result in additional charges.

[illegible]

Special Instructions	
-----------------------------	--

Relinquished by	Date	Time	Received by	Date	Time
JHawks	4/1/824	9:19am	EDR	4/2/24	10:15 a.m.

If no technician is provided, then the primary contact for your account will be selected. Unless scheduled, the turnaround time for all samples received after 3 pm EST will be logged in the next business day. Weekend or holiday work must be scheduled ahead of time and is charged at 150% of the 3hr TAT or a minimum charge of \$150. A courier charge will be applied for same day and one-day turnaround times for offsite work. SanAir covers Ground and Next Day Air shipping. Shipments billed to SanAir with a faster shipping rate will result in additional charges.

Page of 2

CERTIFICATION

AHERA

CERTIFICATE

This is to certify that

Jason Hawks

has attended and satisfactorily completed all requirements to maintain accreditation as an AHERA Building Inspector in accordance with the Toxic Substance Control Act Title (Section 206) and 40 CFR 763.

Accreditation No. BI/R-NES-12-01-23-07

Course Date: December 1st, 2023

Valid through: December 1st 2024



NOW Environmental Services, Inc.
34004 – 9th Avenue South, Suite # 12
Federal Way, Washington 98003
(253) 927-5233