

11915 NE 00th Street Suite 1204

# Notice of Intent to Remove Asbestos

Case #: 24-248

Amendment: 0

This notification MUST be present at all times at the asbestos project sit	Receipt #:	154741822
Email: Tina@swcleanair.gov	SWCAA Fee:	\$369.00
Fax: 360-576-0925 Web: https://www.swcleanair.gov	Date Paid:	4/18/2024
Voice: 360-574-3058		
Vancouver, WA 98662	Date Received:	4/18/2024

Quantity to be remove	ed: 3200 Squar	e Feet 0 I	Linear Feet	Workshift days	: M T W Th F
Project starting date:	4/29/2024	Project Completion	date: 5/6/2024	Workshift hours	: 7am to 330pm
Site Name: Fircrest N	leadows		Site address: 12	2301 SE 18th Street	
Location of Asbestos:	basement family	room, bedroom, la	City/State/Zip: V	ancouver	WA 98684
Demolition of Strue	cture (Notification o	of Demolition require	ed)	County: CLARK COUNT	Υ
Asbestos survey co	onducted?	No survey rea	ason:		
AHERA Inspector: Ke	vin Crouse			Certification #: IR-23	-1030B
	Popcorn Ceiling Mag Pipe Insulatio		□ Sheet Vinyl □ Air Cell	<ul><li>Boiler Insulation</li><li>CA Pipe</li></ul>	<ul> <li>□ Duct Tape</li> <li>✓ VAT</li> </ul>
Control Methods: ✓ N.P Enclosure	Glove Bag	☐ Mini Enclosure	✓ Wrap and Cut	☑ Water	✓ HEPA Vac
Certification ##:	PO Box 2759, Vanco		Phor	Phone: 360-772-6402 Email: KEVIN@GLOBA ne: 360-909-9947	LPACIFIC.INFO
Property Owner: Gini	n Group LLC.		Phor	ne: 360-608-6026	
Mailing Address:	502 NE 72nd Street	,Vancouver WA 986	65		
Asbestos Disposal Site	: Wasco County La	andfill: 2550 Steele F	Rd, The Dalles, OR,	97058-	

# I DO HEREBY CERTIFY THAT THE INFORMATION CONTAINED IN THIS NOTIFICATION IS, TO THE BEST OF MY KNOWLEDGE, ACCURATE AND COMPLETE.

Submitter Name: Kevin D Crouse

Representing:Global Pacific Environmental IDate Submitted:4/18/2024

<b>Reviewed b</b>	y SWCAA:	Danielle	Kreps
-------------------	----------	----------	-------

Submitter Title:

VP operations

Danlle Kaps



# Notice of Intent to Remove Asbestos

Case #: 24-248

Amendment: 0

This notification MUST be present at all times at the asbestos project sit	Receipt #:	154741822
Email: Tina@swcleanair.gov	SWCAA Fee:	\$369.00
Fax: 360-576-0925 Web: https://www.swcleanair.gov	Date Paid:	4/18/2024
Voice: 360-574-3058		.,,
11815 NE 99th Street, Suite 1294 Vancouver, WA 98662	Date Received:	4/18/2024

# 1.) INTRODUCTION

Global Pacific Environmental (GPE) was retained by Ginn Group LLC. to perform an asbestos demolition survey of the above-mentioned property. The on-site inspection was performed by an EPA/AHERA accredited building inspector Kevin Crouse on 4/12/2024.

Suspect asbestos-containing materials were sampled and analyzed including various floor coverings, sheetrock wall systems, sheetrock ceilings, tar paper underneath the exterior siding, window glazing, and construction adhesives.

The residential structure is constructed of wood walls, ceilings, roof and floor. A total of 26 samples were collected.

For an easy reference guide to the samples see the attached lab data sheets.

Asbestos was detected in the following materials.

- 1.) Ceiling brocade was found to contain 2% Chrysotile asbestos in the bedrooms, basement spare room, hallways, living room on the main floor and the kitchen and small dining area. 1350 Sqft
- 2.) Sheetrock joint compound was also detected in various quantities throughout the house. 1080 Sqft
- 3.) 9x9 VAT and mastic was detected in the basement family room, spare room, and laundry/restroom areas. 460 Sqft
- 4.) The kitchen sink has asbestos undercoating.6 Sqft
- 5.) Sheetrock J/C in the garage also tested positive for asbestos. 400Sqft

A map of the property is included for reference.

A table indicating sample numbers, material description, material location, material condition and content of each material sampled is included in the attached lab reports. Laboratory analytical results and chain of custody documentation are included in Appendix B. Building inspector credentials are included in Appendix C.

# 2. PURPOSE AND SCOPE

The purpose of the survey was to determine the presence of asbestos containing building materials prior to demolition of the structure. All asbestos containing materials containing more than 1% asbestos will be removed prior to demolition.

# 3. SAMPLING METHODOLOGY

A walk through the residence was conducted by an EPA/AHERA accredited building inspector to identify the location of suspect asbestos-containing materials where feasible. The location, approximate quantity and condition of each material were recorded on field data sheets. Bulk samples of each suspect material were then collected and submitted to



April 17th, 2024

Ginn Group 7223 NE Hazeldell ave. Vancouver WA 98685 Attn. Chad Stewart / JB Schnelle

Phone (360)-608-6026

Email: chad@ginngrp.com

# RE: Asbestos Survey for Demolition at 12301 SE 18th Street Avenue (Fircrest Meadows).

Chad,

Per your request, Global Pacific Environmental AHERA Inspector Kevin Crouse (Certification #IR-23-1030B) has conducted a full asbestos demolition survey of the singlefamily residential building at the above listed address.

The results of the survey are provided in the accompanying report.

The purpose of the survey was to determine if asbestos containing materials (ACM) are present. The there is a single-family residence with a daylight basement and attached garage.

Thank you

Kevin Crouse

Vice-President Operations Global Pacific Environmental Inc. (360) 772-6402

1919 W. 39th Street Vancouver, WA 98660 Environmental Services & **Construction Management**  Phone (360) 993-4479 (503) 223-4401 Fax (360) 993-4684

# 1.) INTRODUCTION

Global Pacific Environmental (GPE) was retained by Ginn Group LLC. to perform an asbestos demolition survey of the above-mentioned property. The on-site inspection was performed by an EPA/AHERA accredited building inspector Kevin Crouse on 4/12/2024.

Suspect asbestos-containing materials were sampled and analyzed including various floor coverings, sheetrock wall systems, sheetrock ceilings, tar paper underneath the exterior siding, window glazing, and construction adhesives.

The residential structure is constructed of wood walls, ceilings, roof and floor. A total of 26 samples were collected.

For an easy reference guide to the samples see the attached lab data sheets.

Asbestos was detected in the following materials.

- 1.) Ceiling brocade was found to contain 2% Chrysotile asbestos in the bedrooms, basement spare room, hallways, living room on the main floor and the kitchen and small dining area.
- 2.) Sheetrock joint compound was also detected in various quantities throughout the house.
- 3.) 9x9 VAT and mastic was detected in the basement family room, spare room, and laundry/restroom areas.
- 4.) The kitchen sink has asbestos undercoating.
- 5.) Sheetrock J/C in the garage also tested positive for asbestos.

A map of the property is included for reference.

A table indicating sample numbers, material description, material location, material condition and content of each material sampled is included in the attached lab reports. Laboratory analytical results and chain of custody documentation are included in Appendix B. Building inspector credentials are included in Appendix C.

### 2. PURPOSE AND SCOPE

The purpose of the survey was to determine the presence of asbestos containing building materials prior to demolition of the structure. All asbestos containing materials containing more than 1% asbestos will be removed prior to demolition.

### 3. SAMPLING METHODOLOGY

A walk through the residence was conducted by an EPA/AHERA accredited building inspector to identify the location of suspect asbestos-containing materials where feasible. The location, approximate quantity and condition of each material were recorded on field data sheets. Bulk samples of each suspect material were then collected and submitted to

the laboratory under chain of custody documentation for analysis of asbestos content. Samples were collected from areas that were believed to be representative of homogeneous materials throughout the building.

Samples were collected from selected homogeneous materials in order to evaluate the presence or absence of asbestos in each material. Determination of homogeneous materials included material type, texture, pattern, color, and size.

All samples collected were placed into pre-labeled airtight containers and shipped to SanAir Technologies Laboratory, Inc. for analysis of asbestos content. Environmental Hazards Services analyzed the samples using Polarized Light Microscopy (PLM) with dispersion staining to identify asbestos constituents as required by EPA regulation 40 CFR, Part 763.

### 4. DISCUSSION & RECOMMENDATIONS

Any materials encountered that are not specifically mentioned in this report should be considered asbestos containing until sufficient sampling has been completed to determine that these materials are non-asbestos.

Unidentified asbestos-containing materials may be in place behind walls, under floors and in other inaccessible areas of the structure. If additional suspect asbestos-containing materials are identified during demolition of the building, these materials should be considered asbestos containing until sufficient sampling and analysis has been conducted to determine that these materials are non-asbestos.

### 5. WARRANTY

Global Pacific Environmental warrants that this report has been prepared in a manner consistent with that degree of care and skill ordinarily exercised by members of the same profession currently practicing under similar circumstances. No other warranties are implied or expressed.

Thank You

Kevin Crouse Global Pacific Environmental Inc. (360) 993-4479



# **The Identification Specialists**

# Analysis Report prepared for Global Pacific Environmental Inc

Report Date: 4/17/2024 Project Name: Fircrest Meadows Project #: 48-2329-A SanAir ID#: 24021477



NVLAP LAB CODE 200870-0

10501 Trade Court | North Chesterfield, Virginia 23236 888.895.1177 | 804.897.1177 | fax: 804.897.0070 | IAQ@SanAir.com | SanAir.com



24021477 FINAL REPORT 4/17/2024 4:22:33 PM

SanAir ID Number

Name: Global Pacific Environmental Inc Address: PO Box 2759

Vancouver, WA 98668 Phone: 360-993-4479 Project Number: 48-2329-A P.O. Number: 12301 NE 18th St Project Name: Fircrest Meadows Collected Date: 4/12/2024 Received Date: 4/17/2024 10:25:00 AM

Dear K Crouse,

We at SanAir would like to thank you for the work you recently submitted. The 26 sample(s) were received on Wednesday, April 17, 2024 via UPS. The final report(s) is enclosed for the following sample(s): 1, 2, 3, 4, 5, 6, 7, 8, 9, 10, 11, 12, 13, 14, 15, 16, 17, 18, 19, 20, 21, 22, 23, 24, 25, 26.

These results only pertain to this job and should not be used in the interpretation of any other job. This report is only complete in its entirety. Refer to the listing below of the pages included in a complete final report.

Sincerely,

andra Sobiint.

Sandra Sobrino Asbestos & Materials Laboratory Manager SanAir Technologies Laboratory

Final Report Includes:

- Cover Letter
- Analysis Pages
- Disclaimers and Additional Information

Sample conditions: - 26 samples in Good condition.



SanAir ID Number 24021477 FINAL REPORT 4/17/2024 4:22:33 PM

Name: Global Pacific Environmental Inc Address: PO Box 2759 Vancouver, WA 98668

Phone: 360-993-4479

Project Number: 48-2329-A P.O. Number: 12301 NE 18th St Project Name: Fircrest Meadows Collected Date: 4/12/2024 Received Date: 4/17/2024 10:25:00 AM

Analyst: Drakes, Renaldo | Tallert, Jonathan

# Asbestos Bulk PLM EPA 600/R-93/116

	Stereoscopic	Com	oonents	
SanAir ID / Description	Appearance	% Fibrous	% Non-fibrous	Asbestos Fibers
1 / 24021477-001 Basement SW Bedroom Ceiling Brocade	White Non-Fibrous Homogeneous		98% Other	2% Chrysotile
2 / 24021477-002 Basement SW Bedroom Overspray On Framing	White Non-Fibrous Homogeneous		100% Other	< 1% Chrysotile
3 / 24021477-003 9x9 Tile And Mastic Basement SW Bedroom, Tile	White Non-Fibrous Homogeneous		98% Other	2% Chrysotile
3 / 24021477-003 9x9 Tile And Mastic Basement SW Bedroom, Mastic	Black Non-Fibrous Homogeneous		92% Other	8% Chrysotile
4 / 24021477-004 Downstairs Family Room 9x9 Tile And Mastic, Tile	White Non-Fibrous Homogeneous		98% Other	2% Chrysotile
4 / 24021477-004 Downstairs Family Room 9x9 Tile And Mastic, Mastic	Black Non-Fibrous Homogeneous		92% Other	8% Chrysotile
5 / 24021477-005 Downstairs Family Room Popcorn	White Non-Fibrous Homogeneous		100% Other	< 1% Chrysotile
6 / 24021477-006 Downstairs Wall Texture And J/C, Texture	Beige Non-Fibrous Homogeneous		100% Other	None Detected
6 / 24021477-006 Downstairs Wall Texture And J/C, Joint Compound	White Non-Fibrous Homogeneous		100% Other	< 1% Chrysotile
7 / 24021477-007 Downstairs Wall Paneling Mastic	Yellow Non-Fibrous Homogeneous	3% Cellulose	97% Other	None Detected

Analyst:

les. J. PL

Approved Signatory:

3/atte

4/17/2024 Date:

Analysis Date:



SanAir ID Number 24021477 **FINAL REPORT** 4/17/2024 4:22:33 PM

Name: Global Pacific Environmental Inc Address: PO Box 2759 Vancouver, WA 98668 Phone: 360-993-4479

Project Number: 48-2329-A P.O. Number: 12301 NE 18th St Project Name: Fircrest Meadows Collected Date: 4/12/2024 Received Date: 4/17/2024 10:25:00 AM

Analyst: Drakes, Renaldo | Tallert, Jonathan

# Asbestos Bulk PLM EPA 600/R-93/116

	Stereoscopic	Comp		
anAir ID / Description	Appearance	% Fibrous	% Non-fibrous	Asbestos Fibers
3 / 24021477-008 Downstairs Ceiling Overspray On Framing	White Non-Fibrous Homogeneous		100% Other	< 1% Chrysotile
9 / 24021477-009 Downstairs Restroom J/C	White Non-Fibrous Homogeneous		98% Other	2% Chrysotile
10 / 24021477-010 Downstairs Laundry Room 9x9 Tile And Mastic, Tile	Brown Non-Fibrous Homogeneous		95% Other	5% Chrysotile
10 / 24021477-010 Downstairs Laundry Room 9x9 Tile And Mastic, Mastic	Black Non-Fibrous Homogeneous		92% Other	8% Chrysotile
11 / 24021477-011 Dining Room Ceiling Brocade	White Non-Fibrous Homogeneous		100% Other	< 1% Chrysotile
12 / 24021477-012 Living Room J/C	White Non-Fibrous Homogeneous		98% Other	2% Chrysotile
13 / 24021477-013 Living Room Fireplace Mortar	Grey Non-Fibrous Homogeneous		100% Other	None Detected
14 / 24021477-014 Living Room Ceiling Brocade	White Non-Fibrous Homogeneous		98% Other	2% Chrysotile
15 / 24021477-015 Kitchen Sink Undercoating	Black Non-Fibrous Homogeneous		98% Other	2% Chrysotile
16 / 24021477-016 Kitchen VSL	Brown Non-Fibrous Homogeneous	8% Cellulose	92% Other	None Detected

Analysis Date:

4/17/2024

Date: 4/17/2024



Name: Global Pacific Environmental Inc Address: PO Box 2759 Vancouver, WA 98668 Phone: 360-993-4479 SanAir ID Number 24021477 FINAL REPORT 4/17/2024 4:22:33 PM

Project Number: 48-2329-A P.O. Number: 12301 NE 18th St Project Name: Fircrest Meadows Collected Date: 4/12/2024 Received Date: 4/17/2024 10:25:00 AM

Analyst: Drakes, Renaldo | Tallert, Jonathan

# Asbestos Bulk PLM EPA 600/R-93/116

	Stereoscopic	Com		
SanAir ID / Description	Appearance	% Fibrous	% Non-fibrous	Asbestos Fibers
17 / 24021477-017 Kitchen Wall Texture	White Non-Fibrous Homogeneous		100% Other	None Detected
18 / 24021477-018 Kitchen Ceiling Texture And J/C, Texture	Green Non-Fibrous Homogeneous		100% Other	None Detected
18 / 24021477-018 Kitchen Ceiling Texture And J/C, Joint Compound	White Non-Fibrous Homogeneous		98% Other	2% Chrysotile
19 / 24021477-019 Garage Wall Texture And J/C, Textured Paint	Green Non-Fibrous Homogeneous		100% Other	< 1% Chrysotile
19 / 24021477-019 Garage Wall Texture And J/C, Joint Compound	White Non-Fibrous Homogeneous		98% Other	2% Chrysotile
20 / 24021477-020 Upstairs Bedroom NE Ceiling Brocade, Joint Compound	White Non-Fibrous Homogeneous		98% Other	2% Chrysotile
20 / 24021477-020 Upstairs Bedroom NE Ceiling Brocade, Texture	Off-White Non-Fibrous Homogeneous		97% Other	3% Chrysotile
21 / 24021477-021 Upstairs Landing Ceiling Texture	White Non-Fibrous Homogeneous		97% Other	3% Chrysotile
22 / 24021477-022 Upstairs Landing Wall Texture, Joint Compound	White Non-Fibrous Homogeneous		98% Other	2% Chrysotile
22 / 24021477-022 Upstairs Landing Wall Texture, Texture	White Non-Fibrous Homogeneous		98% Other	2% Chrysotile
	1			;/
Analyst: Remels	1. PL	Approve	d Signatory:	de la companya de la comp

Analysis Date:

4/17/2024

Date: 4/17/2024



Name: Global Pacific Environmental Inc Address: PO Box 2759 Vancouver, WA 98668

Phone: 360-993-4479

SanAir ID Number 24021477 FINAL REPORT 4/17/2024 4:22:33 PM

Project Number: 48-2329-A P.O. Number: 12301 NE 18th St Project Name: Fircrest Meadows Collected Date: 4/12/2024 Received Date: 4/17/2024 10:25:00 AM

Analyst: Drakes, Renaldo | Tallert, Jonathan

# Asbestos Bulk PLM EPA 600/R-93/116

	Stereoscopic	Com	oonents	
SanAir ID / Description	Appearance	% Fibrous	% Non-fibrous	Asbestos Fibers
23 / 24021477-023 Upstairs SW Bedroom Wall, Drywall	White Non-Fibrous Homogeneous	5% Cellulose	95% Other	None Detected
23 / 24021477-023 White Jpstairs SW Bedroom Wall, Non-Fibrous Fexture Homogeneous			98% Other	2% Chrysotile
24 / 24021477-024 Upstairs SW Bedroom Restroom VSL, Linoleum	Off-White Non-Fibrous Homogeneous	15% Cellulose	85% Other	None Detected
24 / 24021477-024 Upstairs SW Bedroom Restroom VSL, Adhesive	Brown Non-Fibrous Homogeneous		100% Other	None Detected
25 / 24021477-025 Upstairs SW Bedroom Ceiling Brocade	Off-White Non-Fibrous Homogeneous		97% Other	3% Chrysotile
26 / 24021477-026 Upstairs NE Bedroom Wall, Drywall	White Non-Fibrous Homogeneous	5% Cellulose	95% Other	None Detected
26 / 24021477-026 Upstairs NE Bedroom Wall,	White Non-Fibrous Homogeneous		98% Other	2% Chrysotile

Analyst:

Analysis Date:

ends. A. R.L 4/17/2024

Approved Signatory:

Date: 4/17/2024

### **Disclaimer**

This report is the sole property of the client named on the SanAir Technologies Laboratory chainof-custody (COC). Results in the report are confidential information intended only for the use by the customer listed on the COC. Neither results nor reports will be discussed with or released to any third party without our client's written permission. The final report shall not be reproduced except in full without written approval of the laboratory to assure that parts of the report are not taken out of context. This report and any information contained within shall not be edited, altered, or modified in any way by any persons or agencies receiving, viewing, distributing, or otherwise possessing a copy of this final report. The laboratory reserves the right to perform amendments to any finalized report, of which shall supersede and make obsolete any previous editions. Such changes, modifications, additions, or deletions shall be effective immediately upon notice thereof. which may be given by means including but not limited to posting on the SanAir client portal website, electronic or conventional mail, or by any other means. The information provided in this report applies only to the samples submitted and is relevant only for the date, time, and location of sampling. The accuracy of the results is dependent upon the client's sampling procedure and information provided to the laboratory by the client on the COC. SanAir assumes no responsibility for the sampling procedure and will provide evaluation reports based solely on the sample(s) in the condition in which they arrived at the laboratory and information provided by the client on the COC, such as: project number, project name, collection dates, po number, special instructions, samples collected by, sample numbers, sample identifications, sample type, selected analysis type, flow rate, total volume or area, and start stop times that may affect the validity of the results in this report. Samples were received in good condition unless otherwise noted on the report. SanAir assumes no responsibility or liability for the manner in which the results are used or interpreted. This report does not constitute nor shall not be used by the client to claim product, process, system, or person certification, approval, or endorsement by NVLAP, NIST, NELAC, AIHA LAP, LLC or any other U.S. governmental agencies and may not be accredited by every local, state, and federal regulatory agencies. Samples are held for a period of 60 days. Fibers smaller than 5 microns cannot be seen with this method due to scope limitations. For NY state samples, method EPA 600/M4-82-020 is performed.

#### NYELAP Disclaimer:

Polarized- light microscopy is not consistently reliable in detecting asbestos in floor covering and similar non-friable organically bound materials. Quantitative transmission electron microscopy is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos containing.

#### Asbestos Accreditations

National Voluntary Laboratory Accreditation Program (NVLAP) Lab Code 200870-0 City of Philadelphia Department of Public Health Air Management Services, Certification#ALL-460 Commonwealth of Pennsylvania Department of Environmental Protection Number 68-05397 California State Environmental Laboratory Accreditation Program Certificate Number 2915 Colorado Department of Public Health and Environment Registration Number AL-23143 Connecticut Department of Public Health Environmental Laboratory Registration Number PH-0105 Massachusetts Department of Labor Standards Asbestos Analytical Services License Number: AA000222

State of Maine Department of Environmental Protection License Number: LB-0075, LA-0084 New York State Department of Health Laboratory ID: 11983

State of Rhode Island Department of Health Certification No.: PCM00126, PLM00126, TEM00126 Texas Department of State Health Services License Number: 300440

Commonwealth of Virginia Department of Professional and Occupational Regulation Number: 3333000323

State of Washington Department of Ecology Laboratory ID: C989

State of West Virginia Bureau for Public Health Analytical Laboratory Number: LT000616 Vermont Department of Health License Number: Asb-Co-An-000006

Louisiana Department of Environmental Quality Al Number 212253, Certificate #05088



State of Collection; WA

Address: 1919 W 39th Street

Bulk

City, St., Zip: Vancouver WA 98660

Company: Global Pacific Environmental Inc.

Account#:

10501 Trade Ct., Suite 100 N. Chesterfield, VA 23236 804.897.1177 / 888.895.1177 Fax 804.897.0070 sanair.com

nite 100 23236 895.1177	Asbestos Chain of Custody Form 140, Rev 7, 10/20/2022	SanAir ID Number スインコー
l Inc.	Project #: 48-2329-A	Collected by.K Crouse
Project Name:	Fircrest Meadows	Phone #: 360-993-4479
	4/12/2024	Fax #: 360-993-4684
	12301 NE 18th St.	Email: kevin@globalpacific.info
Air		Soil
PCM N	OSH 7400 ABS	E PLM EPA 600/R-93/116 (Qual.)

ADD	PLIVI EPA 000/R-5	/110	~	ABA	PCM NIOSH 7400	ABSE	PLM EPA 0	00/R-93/116 (Qual.)	
	Positive Stop			ABA-2	OSHA w/ TWA*		Vern	niculite	
ABEPA	PLM EPA 400 Poi	nt Count		ABTEM	TEM AHERA	ABB	PLM EPA 6	00/R-93/116	
ABB1K	PLM EPA 1000 Pc	oint Count		ABATN	TEM NIOSH 7402	ABEPA3	PLM EPA 4	00 Point Count	
ABBEN	PLM EPA NOB**			ABT2	TEM Level II	ABCM	Cincinnati M	lethod	
ABBCH	TEM Chatfield**			Other:		-	Dust	t	
ABBTM	TEM EPA NOB**				New York ELAP	ABWA	TEM Wipe A	ASTM D-6480	
ABQ	PLM Qualitative			ABEPA2	NY ELAP 198.1	ABDMV	TEM Microv	vac ASTM D-5755	
**	Available on 24-hr. 1	to 5-day TAT		ABENY	NY ELAP 198.6 PLM NOB				1
	Water			ABBNY	NY ELAP 198.4 TEM NOB	Matrix	Othe	r	
ABHE	EPA 100.2				Positive Stop				
Tì	urn Around	3 HR (4	HR TE	M) 🗆	6 HR (8HR TEM)	12 HR		1 Day 🛛	
	Times		2 Day	S	D 3 Days	 <b>1</b> 4 D	avs	D 5 Days	

ial Instructions					
Sample #	Sample Identification/Location	Volume or Area	Sample Date	Flow Rate*	Start – Stoj Time*
1	basement SW bedroom ceiling brocade				
2	basement SW bedroom overspray on frameing				
3	9x9 tile and mastic basement SW bedroom white				
4	downstairs family room 9x9 tile and mastic white				
5	downstairs family room popcorn				
6	downstairs wall texture and j/c				
7	downstairs wall paneling mastic				
8	downstairs ceiling overspray on frameing				
9	downstairs restroom J/C				
10	downstairs laundry room 9x9 tile and mastic brown				
11	Dining room ceiling brocade				
12	livingroom j/c				

Relinquished by	Date	Time	Received by	Date	Time
			SAL	4/17/24	10257tm

If no technician is provided, then the primary contact for your account will be selected. Unless scheduled, the turnaround time for all samples received after 3 pm EST will be logged in the next business day. Weekend or holiday work must be scheduled ahead of time and is charged at 150% of the 3hr TAT or a minimum charge of \$150. A courier charge will be applied for same day and one-day turnaround times for offsite work. SanAir covers Ground and Next Day Air shipping. Shipments billed to SanAir with a faster shipping rate will result in additional charges.

# 2402 1477

Form 140, Revision 1, 1/20/2017

Sample #	Sample Identification/Location	Volume or Area	Sample Date	Flow Rate*	Start – Stop Time*	
13	living room fireplace mortar					
14	living room ceiling brocade					
15	kitchen sink undercoating					
16	kitchen vsl					
17	kitchen wall texture					
18	kitchen ceiling texture and J/C					
19	garage wall texture and j/c					
20	upstairs bedroom NE ceiling brocade					
21	upstairs landing celoing texture					
22	upstairs landing wall texture					
23	upstairs SW bedroom wall					
24	upstairs SW bedroom restroom vsl					
25	upstairs SW bedroom ceiling brocade					
26	upstairs NE bedroom wall					

Special Instructions					
Relinguished by	Date	Time	Received by	Date	Time
Kenneu by	Date		Snc	4/17/24	102577-

If no technician is provided, then the primary contact for your account will be selected. Unless scheduled, the turnaround time for all samples received after 3 pm EST will be logged in the next business day. Weekend or holiday work must be scheduled ahead of time and is charged at 150% of the 3hr TAT or a minimum charge of \$150. A courier charge will be applied for same day and one-day turnaround times for offsite work. SanAir covers Ground and Next Day Air shipping. Shipments billed to SanAir with a faster shipping rate will result in additional charges. Page of \_\_\_\_\_\_

Certificate: Course Location: 4412 S Corbett Avenue certificate contact: For verification of the authenticity of this Course Date: Portland, OR 97239 PBS Engineering and Environmental Inc. HAS SUCCESSFULLY COMPLETED THE TRAINING COURSE Online Training, IR-23-1030B 05/18/2023 In accordance with TSCA Title II, Part 763, Subpart E, Appendix C of 40 CFR ASBESTOS INSPECTOR REFRESHER THIS IS TO CERTIFY THAT **KEVIN CROUSE PBS** for Andy Fridley, Instructor **Expiration Date:** of Toxic Substance Control Act (TSCA) Emergency Response Act enacting Title II Training; AHERA is the Asbestos Hazard 4-Hour AHERA Inspector Refresher CCB #SRA0615 4-Hr Training Luder Fridey 05/18/2024

### PROPERTY INFORMATION CENTER

Account Summary

# Property Identification Number: 164912000 MapsOnline 🕅 Fact Sheet 🗐 Property Type: Real Property Status: Active Site Address: 12301 NE 18TH ST, VANCOUVER, WA 98684 (Situs Addresses) Abbreviated Description: #2 SEC 27 T2N R2EWM 7.58A (E)

Tax Status: Regular

Property Owner GINN GROUP LLC Administrative Data		502 NE 72ND ST		Property Site Address 12301 NE 18TH ST, VANCOUVER, WA 98684 Google Maps Street View Assessment Data Info	
Jurisdiction Vancouver		Councilors District		Market Value as of January 1, 2023	
Land Use Planning		Camas Council Ward n/a			
Comprehensive		CPU Commissioner	2		
Plan	UL	District	Carl Incompany	Land Value	\$2,350,374.00
Designation	S. Southers	Election Precinct	683	Building Value	\$0.00
Comprehensive	none	Legislative District	49	Total Property	\$2,350,374.00
Plan Overlay(s)	120763-226752	Library District	Fort Vancouver		
Urban Growth	Vancouver		Regional Library	Taxable Value Info	<u>.</u>
Area	Law Davaita	Port District	Vancouver Port	Total	\$2,350,374.00
Zoning Designation -	Low Density Residential-		District 3		
Codes	6du/ac (R-6)	School District Board Director District	irector District 5	2022 Values for 2023 Taxes	
Zoning Overlay(s)	none	Sewer Board District	Vancouver	Market Value as of	January 1,
Miscellaneous		State Weed Board District	2	2022	
Census Tract	413.17	District		Land Value	\$2,035,028.00
Drainage	- 1-	Land Data		Building Value	\$0.00
District	n/a	Land Data		Total Property	\$2,035,028.00
Neighborhood	Fircrest	Approximate Area Info	429,066 sq. ft. 9.85 acres		
Park District	С	Claule County Dood Atlan		Taxable Value Info	<u>.</u>
<b>Public Safety</b>		Clark County Road Atlas	<u> Page 10</u>	Total	\$2,035,028.00
Burning Allowed	No	DOR Land Use Code Info	11		
EMS Response		Section-Township-Range	NE		
Area	AMR		1/4,S27,T2N,R2E	General	
Fire District	Vancouver		DF	Assessor Neighborhood	d 71
Increased		Subdivision	no data	Re-valuation Cycle	6
Wildfire Danger	No	Survey	No Records		
Area				Notice of Value	<u>2023</u> 2022
Police	VPD East	Sales History			2022
Jurisdiction	District 4	Date of Sale	04/15/2024		2020
Schools					2019
School District	E	Document Type	D-PREP		2018
Name	Evergreen	Document Number	6176850		<u>2017</u>
Elementary		Excise Number	892367	Property assessment value i	s valid as of the date
School Attendance Area	Fircrest	Sale Amount	\$3,000,000.00	printed on the linked notice of value will not reflect any i value that occurred after the Please contact the Assessor	of value. The notice updates to property notice mail date.
Middle School Attendance	Cascade	Date of Sale	01/01/1900	question about your assesse	

Area		Document Type	DEATH
High School		Document Number	6062088
Attendance Area	Evergreen	Excise Number	0
Transportation		Sale Amount	\$0.00
C-TRAN Public Transportation Benefit Area	Yes		
Traffic Impact Fee (TIF) District	Cascade		
Transportation Analysis Zone	1674		
Utilities			
CPU Lighting Utility District	n/a		
Last Street Sweeping	n/a		
Sewer District	Vancouver		
Waste Collection Provider	n/a		
Waste Collection Day	No Data		
Water District	Vancouver The water service provider may be different from the indicated water district. Please contact the parcel's jurisdiction if you need to know the water service provider.		

If you have questions concerning the data on this page, please contact the Clark County Assessor's Office. Main Phone: (564) 397-2391, Email: <u>assessor@clark.wa.gov</u>

**Disclaimer:** Clark County does not warrant the accuracy, reliability or timeliness of any information in this system, and shall not be held liable for losses caused by using this information. Portions of this information may not be current or accurate. Any person or entity who relies on any information obtained from this system, does so at their own risk. <u>RCW 42.56.070(8)</u> prohibits releasing and/or using lists of individuals gathered from this site for commercial purposes. <u>[Full Disclaimer]</u>

### PROPERTY INFORMATION CENTER

Land & Building Details

Property Identification Number: 164912000 MapsOnline Fact Sheet Property Type: Real Property Status: Active Site Address: 12301 NE 18TH ST, VANCOUVER, WA 98684 (Situs Addresses) Abbreviated Description: #2 SEC 27 T2N R2EWM 7.58A (E)

Tax Status: Regular

Photos & Imagery	Building 1	
Property Photo	Summary Information	
Photo Date: 03/05/2002	Building Style	SPLIT
The second s	Number of Bedrooms	3
	Number of Bedrooms Approved for Septic System	3
	FULL BATH	1
	3/4 BATH	1
	1/2 BATH	1
	HEAT TYPE	HP
	Fireplace	FIRE2-DBL 1.00
	Details 1	
a state of the sta	MAIN	801 sq. ft.
and the second	Effective Year Built	1963
	Actual Year Built	1963
Click photo for printable image	Building Type	CONVENTIONAL
Puilding Cleatch	Construction Quality	AVERAGE
	Condition	AVERAGE
Instrume         (4/37/1-(2))         Kane         Instrume         (1%)           Instrume         (1/37/1-(2))         Kane         (1/37/1-(2))         (1/37/1-(2))           Instrume         (1/37/1-(2))         Kane         (1/37/1-(2))         (1/37/1-(2))           Verse         (1/37/1-(2))         (1/37/1-(2))         (1/37/1-(2))         (1/37/1-(2))           Kane         (1/37/1-(2))         (1/37/1-(2))         (1/37/1-(2))         (1/37/1-(2))           Kane         (1/37/1-(2))         (1/37/1-(2))         (1/37/1-(2))         (1/37/1-(2))	Details 2	
БР <u>и</u> «Т. сед. »	SECOND	726 sq. ft.
rearrier r	Effective Year Built	1963
2 Lance 2	Actual Year Built	1963
* * * * * * * * * * * * * * * * * * *	Building Type	CONVENTIONAL
	Construction Quality	AVERAGE
R MIDNOT R	Condition	AVERAGE
	Details 3	
MITROCH 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	DAY FINISHED BASEMENT	704 sq. ft.
Addal BC 0 er at 1 a 1 a 1 a 1 a 1 a 1 a 1 a 1 a 1 a	Effective Year Built	1963
The state of the s	Actual Year Built	1963
	Building Type	RESIDENTIAL
	Construction Quality	AVERAGE
	Condition	AVERAGE
	Details 4	
	ATTACHED GARAGE	420 sq. ft.
	Effective Year Built	1963
	Actual Year Built	1963
	Building Type	RESIDENTIAL
	Construction Quality	AVERAGE
	Condition	AVERAGE

If you have questions concerning the data on this page, please contact the Clark County Assessor's Office. Main Phone: (564) 397-2391, Email: <u>assessor@clark.wa.gov</u>

**Disclaimer:** Clark County does not warrant the accuracy, reliability or timeliness of any information in this system, and shall not be held liable for losses caused by using this information. Portions of this information may not be current or accurate. Any person or entity who relies on any information obtained from this system, does so at their own risk. <u>RCW 42.56.070(8)</u> prohibits releasing and/or using lists of individuals gathered from this site for commercial purposes. <u>[Full Disclaimer]</u>