



11815 NE 99th Street, Suite 1294  
Vancouver, WA 98662  
Voice: 360-574-3058  
Fax: 360-576-0925  
Web: <https://www.swcleanair.gov>  
Email: [Tina@swcleanair.gov](mailto:Tina@swcleanair.gov)

## Notice of Intent to Remove Asbestos

Case #: 24-267

Amendment: 0

Date Received: 4/24/2024

Date Paid: 4/24/2024

SWCAA Fee: \$37.00

Receipt #: 155071178

**This notification MUST be present at all times at the asbestos project sit**

### OWNER OCCUPIED PERFORMED

Quantity to be removed: 140 Square Feet 0 Linear Feet

Workshift days: Su M

Project starting date: 5/5/2024 Project Completion date: 5/6/2024

Workshift hours: 8-5

Site Name: Denise Brooks Residence

Site address: 414 Central Ave, Pe Ell WA

Location of Asbestos: kitchen floor mastic

City/State/Zip: Pe Ell WA 98539

☐ Demolition of Structure (Notification of Demolition required)

County: LEWIS COUNTY

☒ Asbestos survey conducted?

No survey reason: Owner took samples

AHERA Inspector: Dan Shoultz

Certification #: 110853

#### Material to be Removed:

- |                                       |  |                              |   |  |                                    |
|---------------------------------------|--|------------------------------|---|--|------------------------------------|
| <input type="checkbox"/> Fireproofing | <input type="checkbox"/> Popcorn Ceiling     | <input type="checkbox"/> CAB | <input checked="" type="checkbox"/> Sheet Vinyl | <input type="checkbox"/> Boiler Insulation | <input type="checkbox"/> Duct Tape |
| <input type="checkbox"/> Duct Paper   | <input type="checkbox"/> Mag Pipe Insulation |                              | <input type="checkbox"/> Air Cell               | <input type="checkbox"/> CA Pipe           | <input type="checkbox"/> VAT       |
| <input type="checkbox"/> Other        |  |                              |   |  |                                    |

#### Control Methods:

- |  |                                    |   |  |                                |                                   |
|--|------------------------------------|---|--|--------------------------------|-----------------------------------|
| <input type="checkbox"/> N.P Enclosure | <input type="checkbox"/> Glove Bag | <input type="checkbox"/> Mini Enclosure | <input checked="" type="checkbox"/> Wrap and Cut | <input type="checkbox"/> Water | <input type="checkbox"/> HEPA Vac |
| <input type="checkbox"/> Other         |                                    |   |  |                                |                                   |

Asbestos Contractor: Owner Occupant

Phone:

Mailing Address:

Email:

Certification ##:

Supervisor: Denise Brooks

Phone: 360-669-3079

Property Owner: Denise Brooks

Phone: 360-669-3079

Mailing Address: Po Box 111, Doty WA 985

Asbestos Disposal Site: Lewis County Central Transfer Station: 1411 S Tower Ave, Centralia, WA, 98532

**I DO HEREBY CERTIFY THAT THE INFORMATION CONTAINED IN THIS NOTIFICATION IS,  
TO THE BEST OF MY KNOWLEDGE, ACCURATE AND COMPLETE.**

Submitter Name: Rebecca R Meister

Representing: Denise Brooks

Submitter Title: Agent

Date Submitted: 4/24/2024

Reviewed by SWCAA: Danielle Kreps

*Danielle Kreps*

☒ Approved



11815 NE 99th Street, Suite 1294  
Vancouver, WA 98662  
Voice: 360-574-3058  
Fax: 360-576-0925  
Web: <https://www.swcleanair.gov>  
Email: [Tina@swcleanair.gov](mailto:Tina@swcleanair.gov)

## Notice of Intent to Remove Asbestos

Case #: 24-267

Amendment: 0

Date Received: 4/24/2024

Date Paid: 4/24/2024

SWCAA Fee: \$37.00

Receipt #: 155071178

**This notification MUST be present at all times at the asbestos project sit**

## AHERA ASBESTOS INSPECTION SURVEY

Inspector: Dan Shoultz  
1810 Taylor St. Centralia, WA. 98531  
360-669-3712

Upon the request of a member of Northwest Green Homes I did an inspection of a house located at 414 Central Ave. in Pe Ell Washington. The inspection was done on April 16, 2024 at 11 AM. It is a single story house that had a sever fire. The house was built in 1920 and is 936 square feet interior.


The exterior has cedar shingle siding, aluminum windows and 3 tab roofing. So I took a sample of the window caulking and the roofing to have them tested.

The interior has two bedrooms, a living room with an open dining area, a kitchen, one bathroom, and a small laundry room. All the rooms have wood walls and ceilings covered with wallpaper except for the kitchen. The kitchen has drywall. So I took 2 samples of the drywall with joint compound to have them tested. The bathroom and kitchen have vinyl flooring that are different from each other. So I took a sample of both floorings to have them tested. The bedrooms have laminate flooring installed over the original hard wood flooring. The living room with the dining area have the original hard wood flooring.

The 6 samples from the property were sent to Asbestos Northwest in Federal Way Washington on 4/16/2024 to have them tested. (See chain of custody) The results came back on 4/22/2024 and the lab report says that there was no asbestos in most of the samples, but the mastic (glue) in the kitchen floor has 65% Chrysotile asbestos in it.

If anyone has any questions call me at the above number.

Sincerely,



Dan Shoultz AHERA Certification Number 110853

## ASBESTOS NORTHWEST



30620 Pacific Hwy S, #103,  
Federal Way, WA 98003  
(253) 941-4343



Enclosed please find the analytical report for one or more samples submitted for analysis by Polarized Light Microscopy.

**The six types of asbestos fibers are chrysotile, amosite, crocidolite, tremolite, anthophyllite and actinolite. A sample which contains more than 1% asbestos is considered positive and is defined by the EPA as an Asbestos Containing Material (ACM).**

The samples were analyzed in accordance with EPA method 600/R-93/116 and 600/M4-82-020 which has a detection limit of approximately 1%. The analyst used a stereomicroscope to visually inspect the sample to determine homogeneity and material descriptions. The sample was then viewed under a polarized light microscope to determine the presence and percentage of asbestos and non-asbestos fibers.

After analysis is complete, all paperwork is filed together, and kept in a secure locked filing cabinet. Asbestos Northwest ensures that the files will not be tampered with at any time and will only be removed if the client requests reanalysis or a modification to the report. If you have any concerns or comments, contact us at [feedback@asbestosnw.com](mailto:feedback@asbestosnw.com) or fill out our survey at [asbestosnw.com/survey](http://asbestosnw.com/survey)

Thank you,

*Cathy Butler*

-These results are only applicable to the **samples enclosed** with information provided by the client. This report may not be reproduced, except in full, without the approval of the laboratory. This report may not be used to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the U.S. Government.-

202411625  
CHAIN OF CUSTODY

Client: AHERA Inspector  
1810 Taylor St.  
Centralia, WA. 98531  
Phone: 360-669-3712

Date: 4/16/2024  
NW Green Homes  
Location: 414 Centralia Ave.  
Pe Ell, WA.  
Collector: Daniel Shoultz

E-mail: dwshoultz@gmail.com

Date of collection: 4/16/2024  
11 Am

Sample	Type	Container	Type of test
#1 Kitchen wall #1	Gypsum	Ziploc	Asbestos
#2 Kitchen wall #2	Gypsum	Ziploc	Asbestos
#3 Bathroom floor	Vinyl	Ziploc	Asbestos
#4 Kitchen floor	Vinyl	Ziploc	Asbestos
#5 Window caulking	Fiber	Ziploc	Asbestos
#6 Roofing	Fiber	Ziploc	Asbestos

Relinquished By: Dan Shoultz Date 4/16/2024

Received by

Date

Total Number of Containers: 6 3 day turn around

Analyzed by: Crystal Andrzejewicz

4:20pm  
Crystal Andrzejewicz 4/18/24



Asbestos Northwest, LLC  
30620 Pacific Hwy S, #103, Federal Way, WA 98003  
Ph: (253) 941-4343



**Batch Number: 202411625**

**PLM Analysis by EPA Method 600/M4-82-020 and 600/R-93/116**

This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the U.S. Government.

**Attn: Dan Shoultz**  
**AHERA Inspector**  
**1810 Taylor St Centralia WA 98531**

**Date Received: 4/17/2024**  
**Date Analyzed: 4/17/2024**  
**Samples Received: 6**  
**Samples Analyzed: 6**

**Project: NW Green Homes**  
**Location: 414 Centralia Ave Pe Ell WA**

Client Sample ID	Lab Sample ID	Layer	Description	Matrix	% Non-Asbestos Fibers	% Asbestos Fibers and Type
1	1	1	Gray chalky material	Filler/binder, Gypsum	25% Cellulose, Glass fibers	None Detected
2	2	1	Gray chalky material	Filler/binder, Gypsum	25% Cellulose, Glass fibers	None Detected
3	3	1	Charred black soft/elastic material	Binder/filler	2% Cellulose	None Detected
4	4	1	Brown sheet vinyl	Vinyl/binder	None Detected	None Detected
		2	Beige fibrous material with mastic and charred black material	Filler, Mastic/binder	5% Cellulose	65% Chrysotile
5	5	1	Gray and brown soft/elastic material with wood	Binder/filler	3% Cellulose	None Detected
6	6	1	Black asphaltic material with sand	Asphalt/binder, Sand	5% Cellulose, Glass fibers	None Detected
		2	Black asphaltic fibrous material	Asphalt/binder	50% Cellulose, Glass Fibers	None Detected



# AHERA

## CERTIFICATE

This is to certify that


*Dan Shultz*

has attended and satisfactorily completed all requirements to maintain accreditation as an AHERA Building Inspector in accordance with the Toxic Substance Control Act Title (Section 206) and 40 CFR 763.

**Accreditation No. BI/R-NES-02-08-24-1**

Course Date: February 8<sup>th</sup>, 2024

**Valid through: February 8<sup>th</sup> 2025**



NOW Environmental Services, Inc.  
34004 – 9<sup>th</sup> Avenue South, Suite # 12  
Federal Way, Washington 98003  
(253) 927-5233

## AHERA ASBESTOS INSPECTION SURVEY

Inspector: Dan Shoultz  
1810 Taylor St. Centralia, WA. 98531  
360-669-3712

Upon the request of a member of Northwest Green Homes I did an inspection of a house located at 414 Central Ave. in Pe Ell Washington. The inspection was done on April 16, 2024 at 11 AM. It is a single story house that had a sever fire. The house was built in 1920 and is 936 square feet interior.


The exterior has cedar shingle siding, aluminum windows and 3 tab roofing. So I took a sample of the window caulking and the roofing to have them tested.

The interior has two bedrooms, a living room with an open dining area, a kitchen, one bathroom, and a small laundry room. All the rooms have wood walls and ceilings covered with wallpaper except for the kitchen. The kitchen floor is 10 feet by 7 feet. So the square footage is 70 square footage. It is brown vinyl flooring with with mastic (glue) attached to it. The kitchen has drywall. So I took 2 samples of the drywall with joint compound to have them tested. The bathroom and kitchen have vinyl flooring that are different from each other. So I took a sample of both corers to have them tested. The bedrooms have laminate flooring installed over the original hard wood flooring. The living room with the dining area have the original hard wood flooring.

The 6 samples from the property were sent to Asbestos Northwest in Federal Way Washington on 4/16/2024 to have them tested. (See chain of custody) The results came back on 4/22/2024 and the lab report says that there was no asbestos in most of the samples, but the mastic (glue) in the kitchen floor has 65% Chrysotile asbestos in it.

If anyone has any questions call me at the above number.

Sincerely,



Dan Shoultz AHERA Certification Number 110853