



11815 NE 99th Street, Suite 1294
Vancouver, WA 98662
Voice: 360-574-3058
Fax: 360-576-0925
Web: <https://www.swcleanair.gov>
Email: Tina@swcleanair.gov

Notice of Intent to Remove Asbestos

Case #: 24-631

Amendment: 0

Date Received: 9/11/2024

Date Paid: 9/11/2024

SWCAA Fee: \$369.00

Receipt #: 162508502

This notification MUST be present at all times at the asbestos project sit

Quantity to be removed: 2739 Square Feet 0 Linear Feet

Workshift days: M T W Th F

Project starting date: 9/23/2024 Project Completion date: 10/4/2024

Workshift hours: 7:00 am - 3:30pm

Site Name: Port of Kalama Hotel ACM

Site address: 602 E Frontage Rd

Location of Asbestos: Ceiling, Walls, Flooring, Sink

City/State/Zip: Kalama

WA

98625

☐ Demolition of Structure (Notification of Demolition required)

County: COWLITZ COUNTY

☒ Asbestos survey conducted?

No survey reason:

AHERA Inspector: Jason Hawks

Certification #: BI/R-NES-12-19-22-09

Material to be Removed:

☐ Fireproofing

☐ Popcorn Ceiling

☐ CAB

☒ Sheet Vinyl

☐ Boiler Insulation

☐ Duct Tape

☐ Duct Paper

☐ Mag Pipe Insulation

☐ Air Cell

☐ CA Pipe

☐ VAT

☒ Other Floor Tile with Mastic, Ceiling Texture, Sink Coating, Joint Compound

Control Methods:

☒ N.P Enclosure

☐ Glove Bag

☐ Mini Enclosure

☐ Wrap and Cut

☒ Water

☒ HEPA Vac

☒ Other Manual Methods, Critical Barriers

Asbestos Contractor: 3 Kings Environmental Inc.

Phone: 253-750-4143

Mailing Address: PO Box 280, Battle Ground, WA, 98604

Email: jhawks@3kingsinc.com

Certification ##: ABCN00001318

Supervisor: Emily Weiss

Phone: 253-750-4143

Property Owner: Port of Kalama

Phone: 360-673-2325

Mailing Address: 110 West Marine Dr, Kalama WA 98625

Asbestos Disposal Site: Wasco County Landfill: 2550 Steele Rd, The Dalles, OR, 97058-

**I DO HEREBY CERTIFY THAT THE INFORMATION CONTAINED IN THIS NOTIFICATION IS,
TO THE BEST OF MY KNOWLEDGE, ACCURATE AND COMPLETE.**

Submitter Name: Kristine Bantz

Representing: 3 Kings Environmental

Submitter Title: Asbestos Notice Payment Conf

Date Submitted: 9/11/2024

Reviewed by SWCAA: Brian Fallon

☒ Approved



11815 NE 99th Street, Suite 1294
Vancouver, WA 98662
Voice: 360-574-3058
Fax: 360-576-0925
Web: <https://www.swcleanair.gov>
Email: Tina@swcleanair.gov

Notice of Intent to Remove Asbestos

Case #: 24-631

Amendment: 0

Date Received: 9/11/2024

Date Paid: 9/11/2024

SWCAA Fee: \$369.00

Receipt #: 162508502

This notification MUST be present at all times at the asbestos project sit



3 Kings Environmental, Inc.

Asbestos Containing Materials Inspection

Good Faith Inspection

September 5, 2024

Prepared For: Port of Kalama
110 West Marine Dr.
Kalama, WA 98625

Project: Former OYO Hotel
602 E Frontage Rd.
Kalama, WA 98625

RE: Pre-Demolition Good Faith Asbestos Survey

FRONT OF STRUCTURE



INSPECTION REPORT

BACKGROUND

On August 14th and 28th, 2024, 3 Kings Environmental, Inc. performed a Pre-Demolition Good Faith Asbestos Inspection of the above mentioned project to determine the presence of asbestos containing materials (ACMs). The intent of this inspection is to ensure that the property owner is in compliance with the regulatory requirements for the identification of ACMs prior to any demolition or renovation activities.

BUILDING DESCRIPTION

The structure was a wood framed two story hotel built on a concrete foundation with a crawlspace. The floor systems were all built with a 2x6 tongue and groove sub floor. Roof system was a low slope roof with a plywood substrate.

Year Built: 1962

Approximate Size: Approximately 14,000 square feet

Interior Finishes:

The interior of building was drywall on the walls and ceilings, Floors were vinyl plank over wood or sheet vinyl. Maintenance or housekeeping areas were tile and mastic on wood. The front lobby was ceramic tile over concrete.

Exterior Finishes:

The exterior of the building consisted of vinyl windows, wood siding, brick façade of front of the main floor, wood trim and asphaltic built-up roofing.

SAMPLING PROCESS

All accessible areas of the specific work area were sampled during the inspection. Inaccessible areas are those defined as requiring select demolition, fall protection, repair to the structure i.e. weather protection or water proofing or are considered a confined space entry. If during the course of asbestos abatement or demolition suspect materials are discovered that are not identified in this report stop work immediately. These materials need to be treated as asbestos containing until the material can be tested by an AHERA Building Inspector and determined otherwise.

Suspect materials were collected by an AHERA certified building inspector. Samples are then given a unique identification number. Sample information such as type of material and its locations are then placed on the chain of custody that accompany the samples to the testing laboratory. Once the samples are delivered to an asbestos laboratory for analysis. Samples are analyzed by polarized light microscopy (PLM) with dispersion staining in accordance with USEPA 600/M-82/020, which has a reliable limit of quantification of one percent asbestos by volume.

Samples were collected following EPA guidelines. The suspect materials are broken down into three categories: Surfacing Materials, Thermal System Insulation, and Miscellaneous Materials. Each of these categories have a set of guidelines that were followed that include the number of samples required for that particular category based on the quantity of the material, how the material was applied and what was the intent of the material. All these factors are accounted for during the time of inspection.

AHERA Certified Building Inspector

Certified AHERA Building Inspector was Jason Hawks
 Certification # BI/R-NES-12-01-23-07, Expiration December 1, 2024



SURVEY FINDINGS






Materials found to contain asbestos in concentrations greater than one percent (>1%) as part of this investigation and estimated quantities for removal:






Sample #	Material Description	Sample Location	Friability / Condition / Category	Lab Result	Quantity
01	Drywall with Joint Compound and Orange Peel Texture	Unit 101 Ceiling and Walls	F / Good	2% Chrysotile in the Orange Peel Texture	293 SF of ceilings 872 SF of walls Total SF = 1,165 SF
24, 25	Orange Sheet Vinyl on wood counter	Housekeeping Room / Area – First Floor	NF / Good	20% Chrysotile-Sheet Vinyl	32 SF
26, 27	Beige Tile with Black Mastic – Under Wood Pattern Flooring. Half on Wood, Half on Concrete	Housekeeping Area – First Floor	NF / Good	5 % Chrysotile in the Tile and 3% Chrysotile in the Mastic	230 SF
34, 35	Beige Tile 9x9 with Black Mastic	Second Floor Housekeeping	NF / Good	4% Chrysotile-Tile/ 2% Chrysotile-Mastic	170 SF
36	Sheet Vinyl Backing with Brown Mastic	Unit 218 Bathroom	NF / Good	20% Chrysotile	See Note Below Regarding Sheet Vinyl Quantities and Locations
38, 39	Tan Sheet Vinyl Small Square Pattern	Unit 217 Bathroom Sink Area	NF / Good	20% Chrysotile / PACM	See Note Below Regarding Sheet Vinyl Quantities and Locations
40, 41	Cream Sheet Vinyl 4” Square Pattern	Unit 216 Bathroom	NF / Good	20% Chrysotile / PACM	See Note Below Regarding Sheet Vinyl Quantities and Locations
46	Ceramic Tile and Mortar with Joint	Unit 211 Bathroom Behind FRP	NF / Good	2% Chrysotile-	Not Quantified – Joint Compound

	Compound, Joint Compound Came back 2% Chrysotile			Joint Compound/ Composite of the Drywall System is <1%	was composited Per WRD 23.30
47	Sheet Vinyl Backing	Unit 209 Bathroom Floor	NF / Good	20% Chrysotile	See Note Below Regarding Sheet Vinyl Quantities and Locations
MO – 01, 02	Drywall with Joint Compound and Heavy Knockdown ceiling Texture	Managers Office (MO)	F / Good	2% Chrysotile- Joint Compound/ Composite of the Drywall System is <1%	Not Quantified – Joint Compound was composited Per WRD 23.30
MO – 04, 05	Drywall with Joint Compound and Orange Peel Texture	Managers Office (MO)	F / Good	2% Chrysotile- Joint Compound/ Composite of the Drywall System is <1%	Not Quantified – Joint Compound was composited Per WRD 23.30
201 – 01, 02	Wood Pattern Sheet Vinyl over Pebble Pattern Sheet Vinyl	Kitchen	NF / Good	10 % Chrysotile / PACM	100 SF
PACM	Kitchen Sinks	Managers Office Sink and Kitchen in Unit 201	NF / Good	PACM	2 EA
Misc. Sample Numbers	Sheet Vinyl Flooring or Remnant Sheet Vinyl Backing	Single Rooms – SV in Bathrooms and Separate Sink Areas, Double Rooms – SV in Bathrooms Only. <u>25 SF areas are double unit bathrooms</u> <u>33 SF areas are single unit bathrooms and sink areas</u>	NF / Good	20% Chrysotile	<u>SF by Unit</u> 101 – 25 SF 102 – 33 SF 103 – 33 SF 104 – 18 SF 105 – 18 SF 106 – 18 SF 107 – 33 SF 108 – 18 SF 109 – 33 SF 115 – 18 SF 116 – 33 SF 117 – 33 SF 119 – 33 SF

		<u>18 SF areas are single unit sink areas only</u>			120 – 33 SF 121 – 18 SF 123 – 25 SF MO – 25 SF 201 – 35 SF 202 – 18 SF 203 – 33 SF 204 – 33 SF 205 – 33 SF 206 – 18 SF 207 – 18 SF 208 – 33 SF 209 – 33 SF 210 – 25 SF 211 – 25 SF 212 – 25 SF 215 – 33 SF 216 – 33 SF 217 – 33 SF 218 – 33 SF 219 – 33 SF 220 – 33 SF 221 – 33 SF 222 – 25 SF
--	--	--	--	--	---

		01 - Drywall with Joint Compound and Orange Peel Texture located in Unit 101 on the Ceiling in good condition.
		24, 25 – Orange Sheet Vinyl located in the housekeeping area in good condition.

	<p>26, 27 – Beige Tile with Black Mastic located in the Housekeeping area in good condition.</p>
	<p>34, 35 – Beige 9x9 Tile with Black Mastic located in the 2nd Floor Housekeeping area in good condition.</p>
	<p>36 – Sheet Vinyl Backing with Brown Mastic located in Unit 218 Bathroom in good condition.</p> <p>**Picture is of single bed unit and may not be of the actual room stated.</p>
	<p>38, 39 – Tan Sheet Vinyl with Small Square Pattern located in Unit 217 Bathroom Sink area in good condition.</p> <p>**Picture is of single bed unit and may not be of the actual room stated.</p>
	<p>40, 41 – Cream Sheet Vinyl 4" Square Pattern located in Unit 216 Bathroom in good condition.</p> <p>**Picture is of single bed unit and may not be of the actual room stated.</p>

		<p>47 – Sheet Vinyl Backing located in Unit 209 Bathroom Floor in good condition.</p> <p>**Picture is of single bed unit and may not be of the actual room stated.</p>
		<p>MO – 01, 02 - Drywall with Joint Compound and Heavy Knockdown Ceiling Texture located in the Managers Office in good condition.</p>
		<p>MO – 04, 05 - Drywall with Joint Compound and Orange Peel Texture located in the Managers Office in good condition.</p>
		<p>201 – 01, 02 - Wood Pattern Sheet Vinyl over Pebble Pattern Sheet Vinyl located in the Kitchen in good condition.</p>
		<p>PACM – Kitchen sinks in the managers unit and unit 201</p>

The following is a summary of all the suspect bulk asbestos sampled during the inspection.

Sample #	Material Description & Location	Friability & Condition	Material Category	Lab Result
01	Drywall with Joint Compound and Orange Peel Texture / Unit 101 Ceiling	F / Good	S	2% Chrysotile
02	Beige Sheet Vinyl / Unit 101 Bathroom Floor	NF / Good	M	NAD
03	Beige Sheet Vinyl / Unit 101 Bathroom Floor	NF / Good	M	NAD
04	Yellow Carpet Adhesive / Unit 101 Entry	NF / Good	M	NAD
05	Sheet Vinyl Backing / Unit 102 Bathroom	NF / Good	M	NAD
06	Sheet Vinyl Backing / Unit 102 Bathroom	NF / Good	M	NAD
07	Tan Rubber Cove base with Tan Mastic / Unit 102 Bathroom	NF / Good	M	NAD
08	Tan Rubber Cove base with Tan Mastic / Unit 102 by Bed	NF / Good	M	NAD
09	Blue Grey 12x12 Tile with Yellow Mastic / First Floor Storeroom	NF / Good	M	NAD
10	Blue Grey 12x12 Tile with Yellow Mastic / First Floor Storeroom	NF / Good	M	NAD
11	Sheet Vinyl Backing / Unit 103 Bathroom	NF / Good	M	NAD
12	Sheet Vinyl Backing / Unit 103 Bathroom	NF / Good	M	NAD
13	Drywall with Joint Compound / Unit 103	NF / Good	M	<1% Chrysotile
14	White Laminate with Brown Mastic / Unit 103 Sink Surround	NF / Good	M	NAD
15	White Laminate with Tan Mastic / Unit 106 Sink Surround	NF / Good	M	NAD
16	Cementitious Leveling Compound / Unit 106 Bathroom	NF / Good	M	NAD
17	Cementitious Leveling Compound / Unit 106 Bathroom	NF / Good	M	NAD
18	Sheet Vinyl Backing / Unit 109 Bathroom	NF / Good	M	NAD
19	Slate Pattern Sheet Vinyl / Unit 110 Bathroom	NF / Good	M	NAD
20	Slate Pattern Sheet Vinyl / Unit 110 Bathroom	NF / Good	M	NAD
21	Sheet Vinyl Backing / Unit 117 Bathroom	NF / Good	M	NAD
22	Brown Mastic-Sink Surround / Unit 118 Bathroom	NF / Good	M	<1% Chrysotile

23	Drywall with Joint Compound and Orange Peel Texture / Unit 118 Living Area Wall	F / Good	S	NAD
24	Orange Sheet Vinyl / Counter Housekeeping Room	NF / Good	M	20% Chrysotile-Sheet Vinyl
25	Orange Sheet Vinyl / Counter Housekeeping Area	NF / Good	M	PACM
26	Beige Tile with Black Mastic / Housekeeping Area	NF / Good	M	3 % Chrysotile
27	Beige Tile with Black Mastic / Housekeeping Area	NF / Good	M	PACM
28	Brown Wood Pattern Sheet Vinyl / Housekeeping Area	NF / Good	M	NAD
29	Brown Wood Pattern Sheet Vinyl / Housekeeping Area	NF / Good	M	NAD
30	White Tile Mortar / Lobby Floor	NF / Good	M	NAD
31	White Tile Mortar / Lobby Floor	NF / Good	M	NAD
32	Drywall with Joint Compound / Unit 222	NF / Good	M	<1% Chrysotile
33	Ceramic Tile with White Mortar / Unit 219 Shower Surround	NF / Good	M	NAD
34	Beige 9x9 with Black Mastic / Second Floor Housekeeping	NF / Good	M	4% Chrysotile-Tile/ 2% Chrysotile-Mastic
35	Beige 9x9 with Black Mastic / Second Floor Housekeeping	NF / Good	M	PACM
36	Sheet Vinyl Backing with Brown Mastic / Unit 218 Bathroom	NF / Good	M	20% Chrysotile
37	Tan Cove Base with Tan and Brown Mastic / Unit 218 Bathroom	NF / Good	M	NAD
38	Tan Sheet Vinyl Small Square Pattern / Unit 217 Bathroom Sink Area	NF / Good	M	20% Chrysotile
39	Tan Sheet Vinyl Small Square Pattern / Unit 217 Bathroom Sink Area	NF / Good	M	PACM
40	Cream Sheet Vinyl 4" Square Pattern / Unit 216 Bathroom	NF / Good	M	20% Chrysotile
41	Cream Sheet Vinyl 4" Square Pattern / Unit 216 Bathroom	NF / Good	M	PACM
42	Dark Brown Sheet Vinyl / Unit 215 Bathroom	NF / Good	M	NAD
43	Dark Brown Sheet Vinyl / Unit 215 Bathroom	NF / Good	M	NAD
44	Drywall with Joint Compound / Unit 215 Ceiling	NF / Good	M	<1% Chrysotile

45	Sheet Vinyl Backing Over Grey Leveling Compound / Unit 212 Bathroom	NF / Good	M	NAD
46	Ceramic Tile and Mortar / Unit 211 Bathroom Behind FRP with Joint Compound, Joint Compound Came back 2% however, all the joint compound together equaled to <1%	NF / Good	M	2% Chrysotile-Joint Compound/ Composite of the drywall system is <1%
47	Sheet Vinyl Backing / Unit 209 Bathroom Floor	NF / Good	M	20% Chrysotile
48	Drywall with Joint Compound / Unit 205 Closet	NF / Good	M	<1% Chrysotile
49	Drywall with Joint Compound / Unit 203 by Nightstand	NF / Good	M	<1% Chrysotile
50	Wood Fiber Board Behind Drywall / Unit 203	NF / Good	M	NAD
51	Wood Fiber Board Behind Drywall / Unit 206	NF / Good	M	NAD
52	Brown Paper Uneven Vinyl Siding / Unit 204	NF / Good	M	NAD
53	Brown Paper Uneven Vinyl Siding / Unit 219	NF / Good	M	NAD
54	White Window Caulk / Unit 204	NF / Good	M	NAD
55	White Window Caulk / Unit 219	NF / Good	M	NAD
56	Built Up Roof System 1 ½" to 2" Thick / Lower Roof	NF / Good	M	NAD
57	Built Up Roof System ¼" Thick / Upper Roof	NF / Good	M	NAD
58	Exterior Brick / Outside Unit 120	NF / Good	M	NAD
59	Exterior Brick / Outside Unit 112	NF / Good	M	NAD
60	Exterior Mortar / Outside Unit 120	NF / Good	M	NAD
61	Exterior Mortar / Outside Unit 112	NF / Good	M	NAD
62	Black Felt Paper Under Wood Siding / First Floor Housekeeping	NF / Good	M	NAD
63	Black Felt Paper Under Wood Siding / First Floor Housekeeping	NF / Good	M	NAD
MO - 01	Drywall with Joint Compound and Heavy Knockdown Ceiling Texture / Managers Office	F / Good	S	2% Chrysotile-Joint Compound/ Composite of the drywall system is <1%
MO - 02	Drywall with Joint Compound and Heavy Knockdown Ceiling Texture / Managers Office	F / Good	S	PACM

MO – 03	Heavy Knockdown Ceiling Texture / Managers Office	F / Good	S	NAD
MO – 04	Drywall with Joint Compound and Orange Peel Texture / Managers Office	F / Good	S	2% Chrysotile-Joint Compound/ Composite of the drywall system is <1%
MO – 05	Drywall with Joint Compound and Orange Peel Texture / Managers Office	F / Good	S	PACM
MO – 06	Orange peel Texture / Managers Office	F / Good	S	NAD
MO – 07	Cream Sheet Vinyl / Secondary Bathroom	NF / Good	M	NAD
MO – 08	Cream Sheet Vinyl / Secondary Bathroom	NF / Good	M	NAD
201 – 01	Wood Pattern Sheet Vinyl over Pebble Pattern Sheet Vinyl / Kitchen	NF / Good	M	10% Chrysotile-beige Sheet Vinyl
201 – 02	Wood Pattern Sheet Vinyl over Pebble Pattern Sheet Vinyl / Kitchen	NF / Good	M	PACM

Legend:

NAD – No Asbestos Detected
F – Friable (can be pulverized by hand pressure)
NF – Non-Friable
PACM – Presumed Asbestos Containing Material

Category:

S – Surfacing Material
TSI – Thermal System Insulation
M – Miscellaneous Material

ADDITIONAL OBSERVATIONS

Lead Paint and Other Metals

Lead-based paint was not sampled as part of this survey. Based on the age of the structure lead based paints should be assumed.

Lead safe work practices and appropriate precautions should be utilized during all work impacting painted surfaces.

Microbial Growth

Water damage and potential microbial growth were not observed as part of this sampling. Appropriate precautions should be utilized during work.

PCBs, Mercury Bulbs and Mercury Thermostats



PCBs, Mercury Bulbs and Mercury Thermostats were not tested or examined as part of this survey. Appropriate precautions should be utilized during work.

Inaccessible Components

No inaccessible components spaces were observed at the time of the inspection.

RESULTS AND RECOMMENDATIONS

Of the seventy-three (73) suspect bulk materials sampled twelve (12) tested positive for asbestos with a concentration greater than 1%. Eight additional samples are noted as presumed asbestos containing materials (PACM) as they were designated for positive stop. Positive Joint Compound samples were reanalyzed per WRD 23.30 standard and the composite results were less than 1% asbestos.

3 Kings Environmental, Inc. recommends that any ACM or PACM to be impacted during the course of the renovation or demolition be removed by a licensed, bonded, and insured asbestos abatement firm. Removal and disposal of asbestos containing materials should only be performed by certified firms following all local, state, and federal guidelines. Should materials not noted in this report be discovered during the course of the work, stop all demolition and have the newly discovered materials tested for asbestos or treat the materials as an asbestos containing material. Be sure to notify the governing authorities and clean-air agencies prior to disturbing materials over the recordable limits.

The conclusions/ recommendations of the report are professional opinions based solely on visual observations and interpretation of sample results from our third-party laboratory. Re-use of this document for other than its intended purpose is at the sole risk of said user. 3 Kings Environmental, Inc. cannot be held responsible for the interpretation by others of the data contained in this report as site conditions or regulations may have changed. 3 Kings Environmental makes no warranty, expressed or implied for information found in this report.

If you have any questions regarding this asbestos survey/inspection report, please contact me at (360) 949-5822, or email: jhawks@3kingsinc.com

Respectfully submitted,
3 Kings Environmental, Inc.

Jason Hawks
Certified AHERA Building Inspector

LAB RESULTS



The Identification Specialists

Analysis Report
prepared for
3 Kings Environmental Inc.

Report Date: 8/22/2024

Project Name: Port Of Kalama Hotel-Amended Report JT 8.22.24

Project #: 224137

SanAir ID#: 24047195



NVLAP LAB CODE 200870-0

10501 Trade Court | North Chesterfield, Virginia 23236
888.895.1177 | 804.897.1177 | fax: 804.897.0070 | IAQ@SanAir.com | SanAir.com



SanAir ID Number

24047195

FINAL REPORT

8/22/2024 2:44:47 PM

Name: 3 Kings Environmental Inc.
Address: PO Box 280
Battle Ground, WA 98604
Phone: 360-666-5464

Project Number: 224137
P.O. Number: 12024-318
Project Name: Port Of Kalama Hotel-Amended Report JT
8.22.24
Collected Date: 8/14/2024
Received Date: 8/21/2024 10:25:00 AM

Dear Jason Hawks,

We at SanAir would like to thank you for the work you recently submitted. The 63 sample(s) were received on Wednesday, August 21, 2024 via UPS. The final report(s) is enclosed for the following sample(s): 01, 02, 03, 04, 05, 06, 07, 08, 09, 10, 11, 12, 13, 14, 15, 16, 17, 18, 19, 20, 21, 22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63.

These results only pertain to this job and should not be used in the interpretation of any other job. This report is only complete in its entirety. Refer to the listing below of the pages included in a complete final report.

Sincerely,

A handwritten signature in black ink that reads "Sandra Sobrino".

Sandra Sobrino
Asbestos & Materials Laboratory Manager
SanAir Technologies Laboratory

Final Report Includes:

- Cover Letter
- Analysis Pages
- Disclaimers and Additional Information

Sample conditions:

- 63 samples in Good condition.



SanAir ID Number

24047195

FINAL REPORT

8/22/2024 2:44:47 PM

Name: 3 Kings Environmental Inc.
Address: PO Box 280
Battle Ground, WA 98604
Phone: 360-666-5464

Project Number: 224137
P.O. Number: 12024-318
Project Name: Port Of Kalama Hotel-Amended Report JT 8.22.24
Collected Date: 8/14/2024
Received Date: 8/21/2024 10:25:00 AM

Analyst: Childress, Susan

Asbestos Bulk PLM EPA 600/R-93/116

SanAir ID / Description	Stereoscopic	Components		Asbestos Fibers
	Appearance	% Fibrous	% Non-fibrous	
01 / 24047195-001 Drywall W. Joint Compound & Orange Peel Texture/Unit 101-, Drywall	White Non-Fibrous Homogeneous	5% Cellulose	95% Other	None Detected
01 / 24047195-001 Drywall W. Joint Compound & Orange Peel Texture/Unit 101-, Joint Compound	White Non-Fibrous Homogeneous		98% Other	2% Chrysotile
01 / 24047195-001 Drywall W. Joint Compound & Orange Peel Texture/Unit 101-, Texture	White Non-Fibrous Homogeneous		98% Other	2% Chrysotile
02 / 24047195-002 Sheet Vinyl/Unit 101 Bathroom Floor, Sheet Vinyl	Beige Non-Fibrous Homogeneous		100% Other	None Detected
02 / 24047195-002 Sheet Vinyl/Unit 101 Bathroom Floor, Mastic	Clear Non-Fibrous Homogeneous	< 1% Cellulose	100% Other	None Detected
03 / 24047195-003 Sheet Vinyl/Unit 101 Bathroom Floor, Sheet Vinyl	Beige Non-Fibrous Homogeneous		100% Other	None Detected
03 / 24047195-003 Sheet Vinyl/Unit 101 Bathroom Floor, Mastic	Clear Non-Fibrous Homogeneous	< 1% Cellulose	100% Other	None Detected
04 / 24047195-004 Carpet Adhesive-Unit 101 Entry	Yellow Non-Fibrous Homogeneous		100% Other	None Detected
05 / 24047195-005 Sheet Vinyl Backing/Unit 102 Bathroom, Sheet Vinyl Backing	Grey Fibrous Homogeneous	80% Cellulose	20% Other	None Detected

Amended: Additional analysis; Samples 13, 23, 32, 44, 48, & 49 added as a composite. JT 8.22.24

Analyst: *Susan P. Childress*

Approved Signatory:

[Signature]

Analysis Date: 8/22/2024

Date: 8/22/2024



SanAir ID Number

24047195

FINAL REPORT

8/22/2024 2:44:47 PM

Name: 3 Kings Environmental Inc.
Address: PO Box 280
Battle Ground, WA 98604
Phone: 360-666-5464

Project Number: 224137
P.O. Number: 12024-318
Project Name: Port Of Kalama Hotel-Amended Report JT 8.22.24
Collected Date: 8/14/2024
Received Date: 8/21/2024 10:25:00 AM

Analyst: Childress, Susan

Asbestos Bulk PLM EPA 600/R-93/116

SanAir ID / Description	Stereoscopic	Components		Asbestos Fibers
	Appearance	% Fibrous	% Non-fibrous	
05 / 24047195-005 Sheet Vinyl Backing/Unit 102 Bathroom, Mastic	Grey Non-Fibrous Homogeneous		100% Other	None Detected
06 / 24047195-006 Sheet Vinyl Backing/Unit 102 Bathroom, Sheet Vinyl Backing	Grey Fibrous Homogeneous	80% Cellulose	20% Other	None Detected
06 / 24047195-006 Sheet Vinyl Backing/Unit 102 Bathroom, Mastic	Grey Non-Fibrous Homogeneous		100% Other	None Detected
07 / 24047195-007 Rubber Covebase W/ Mastic/Unit 102 Bathroom, Cove Base	Tan Non-Fibrous Homogeneous		100% Other	None Detected
07 / 24047195-007 Rubber Covebase W/ Mastic/Unit 102 Bathroom, Mastic	Tan Non-Fibrous Homogeneous		100% Other	None Detected
08 / 24047195-008 Rubber Covebase W/ Mastic/Unit 102 By Bed, Cove Base	Tan Non-Fibrous Homogeneous		100% Other	None Detected
08 / 24047195-008 Rubber Covebase W/ Mastic/Unit 102 By Bed, Mastic	Tan Non-Fibrous Homogeneous		100% Other	None Detected
09 / 24047195-009 12x12 Tile W/ Mastic/1st Floor Store Room, Floor Tile	Blue Non-Fibrous Homogeneous		100% Other	None Detected
09 / 24047195-009 12x12 Tile W/ Mastic/1st Floor Store Room, Mastic	Yellow Non-Fibrous Homogeneous		100% Other	None Detected
10 / 24047195-010 12x12 Tile W/ Mastic/1st Floor Store Room, Floor Tile	Blue Non-Fibrous Homogeneous		100% Other	None Detected

Amended: Additional analysis; Samples 13, 23, 32, 44, 48, & 49 added as a composite. JT 8.22.24

Analyst: *Susan P. Childress*

Approved Signatory:

[Signature]

Analysis Date: 8/22/2024

Date: 8/22/2024



SanAir ID Number

24047195

FINAL REPORT

8/22/2024 2:44:47 PM

Name: 3 Kings Environmental Inc.
Address: PO Box 280
Battle Ground, WA 98604
Phone: 360-666-5464

Project Number: 224137
P.O. Number: 12024-318
Project Name: Port Of Kalama Hotel-Amended Report JT 8.22.24
Collected Date: 8/14/2024
Received Date: 8/21/2024 10:25:00 AM

Analyst: Childress, Susan

Asbestos Bulk PLM EPA 600/R-93/116

SanAir ID / Description	Stereoscopic	Components		Asbestos Fibers
	Appearance	% Fibrous	% Non-fibrous	
10 / 24047195-010 12x12 Tile W/ Mastic/1st Floor Store Room, Mastic	Yellow Non-Fibrous Homogeneous		100% Other	None Detected
11 / 24047195-011 Sheet Vinyl Backing/Unit 103 Bathroom	Grey Fibrous Homogeneous	80% Cellulose	20% Other	None Detected
12 / 24047195-012 Sheet Vinyl Backing/Unit 103 Bathroom, Sheet Vinyl Backing	Grey Fibrous Homogeneous	80% Cellulose	20% Other	None Detected
12 / 24047195-012 Sheet Vinyl Backing/Unit 103 Bathroom, Mastic	Grey Non-Fibrous Homogeneous		100% Other	None Detected
13 / 24047195-013 Drywall W/ Joint Compound/Unit 103, Drywall	White Non-Fibrous Homogeneous	5% Cellulose	95% Other	None Detected
13 / 24047195-013 Drywall W/ Joint Compound/Unit 103, Joint Compound	White Non-Fibrous Homogeneous		98% Other	2% Chrysotile
13 / 24047195-013 Drywall W/ Joint Compound/Unit 103, Composite	Various Non-Fibrous Heterogeneous	< 1% Cellulose	100% Other	< 1% Chrysotile
14 / 24047195-014 Laminate W/ Mastic/Unit 103 Sink Surround, Laminate	White Non-Fibrous Homogeneous		100% Other	None Detected
14 / 24047195-014 Laminate W/ Mastic/Unit 103 Sink Surround, Mastic	Brown Non-Fibrous Homogeneous		100% Other	None Detected
15 / 24047195-015 Laminate W/ Mastic/Unit 106 Sink Surround, Laminate	White Non-Fibrous Homogeneous		100% Other	None Detected

Amended: Additional analysis; Samples 13, 23, 32, 44, 48, & 49 added as a composite. JT 8.22.24

Analyst: *Susan P. Childress*

Approved Signatory:

[Signature]

Analysis Date: 8/22/2024

Date: 8/22/2024



SanAir ID Number

24047195

FINAL REPORT

8/22/2024 2:44:47 PM

Name: 3 Kings Environmental Inc.
Address: PO Box 280
Battle Ground, WA 98604
Phone: 360-666-5464

Project Number: 224137
P.O. Number: 12024-318
Project Name: Port Of Kalama Hotel-Amended Report JT 8.22.24
Collected Date: 8/14/2024
Received Date: 8/21/2024 10:25:00 AM

Analyst: Childress, Susan

Asbestos Bulk PLM EPA 600/R-93/116

SanAir ID / Description	Stereoscopic	Components		Asbestos Fibers
	Appearance	% Fibrous	% Non-fibrous	
15 / 24047195-015 Laminate W/ Mastic/Unit 106 Sink Surround, Mastic	Brown Non-Fibrous Homogeneous		100% Other	None Detected
16 / 24047195-016 Cementitious Leveling Compound/Unit 106 Bathroom, Leveling Compound	Grey Non-Fibrous Homogeneous		100% Other	None Detected
16 / 24047195-016 Cementitious Leveling Compound/Unit 106 Bathroom, Skim Coat	White Non-Fibrous Homogeneous		100% Other	None Detected
17 / 24047195-017 Cementitious Leveling Compound/Unit 106 Bathroom, Leveling Compound	Grey Non-Fibrous Homogeneous		100% Other	None Detected
17 / 24047195-017 Cementitious Leveling Compound/Unit 106 Bathroom, Skim Coat	White Non-Fibrous Homogeneous		100% Other	None Detected
18 / 24047195-018 Sheet Vinyl Backing/Unit 109 Bathroom, Sheet Vinyl Backing	Grey Fibrous Homogeneous	80% Cellulose	20% Other	None Detected
18 / 24047195-018 Sheet Vinyl Backing/Unit 109 Bathroom, Mastic	Yellow Non-Fibrous Homogeneous		100% Other	None Detected
19 / 24047195-019 Slate Pattern Sheet Vinyl/Unit 110 Bathroom, Sheet Vinyl	Grey Non-Fibrous Homogeneous		100% Other	None Detected
19 / 24047195-019 Slate Pattern Sheet Vinyl/Unit 110 Bathroom, Mastic	Yellow Non-Fibrous Homogeneous		100% Other	None Detected

Amended: Additional analysis; Samples 13, 23, 32, 44, 48, & 49 added as a composite. JT 8.22.24

Analyst:

Approved Signatory:

Analysis Date: 8/22/2024

Date: 8/22/2024



SanAir ID Number

24047195

FINAL REPORT

8/22/2024 2:44:47 PM

Name: 3 Kings Environmental Inc.
Address: PO Box 280
Battle Ground, WA 98604
Phone: 360-666-5464

Project Number: 224137
P.O. Number: 12024-318
Project Name: Port Of Kalama Hotel-Amended Report JT 8.22.24
Collected Date: 8/14/2024
Received Date: 8/21/2024 10:25:00 AM

Analyst: Childress, Susan

Asbestos Bulk PLM EPA 600/R-93/116

SanAir ID / Description	Stereoscopic	Components		Asbestos Fibers
	Appearance	% Fibrous	% Non-fibrous	
20 / 24047195-020 Slate Pattern Sheet Vinyl/Unit 110 Bathroom, Sheet Vinyl	Grey Non-Fibrous Homogeneous		100% Other	None Detected
20 / 24047195-020 Slate Pattern Sheet Vinyl/Unit 110 Bathroom, Mastic	Yellow Non-Fibrous Homogeneous		100% Other	None Detected
21 / 24047195-021 Sheet Vinyl Backing/Unit 117 Bathroom, Sheet Vinyl Backing	Grey Fibrous Homogeneous	80% Cellulose	20% Other	None Detected
21 / 24047195-021 Sheet Vinyl Backing/Unit 117 Bathroom, Mastic	Yellow Non-Fibrous Homogeneous		100% Other	None Detected
22 / 24047195-022 Mastic-Sink Surround/Unit 118 Bathroom	Brown Non-Fibrous Homogeneous		100% Other	None Detected
23 / 24047195-023 Drywall W/ Joint Compound & Orange Peel Texture/Unit 118, Drywall	White Non-Fibrous Homogeneous	6% Cellulose	94% Other	None Detected
23 / 24047195-023 Drywall W/ Joint Compound & Orange Peel Texture/Unit 118, Joint Compound	White Non-Fibrous Homogeneous		98% Other	2% Chrysotile
23 / 24047195-023 Drywall W/ Joint Compound & Orange Peel Texture/Unit 118, Texture	White Non-Fibrous Homogeneous		100% Other	None Detected
23 / 24047195-023 Drywall W/ Joint Compound & Orange Peel Texture/Unit 118, Composite	Various Non-Fibrous Heterogeneous	< 1% Cellulose	100% Other	< 1% Chrysotile

Amended: Additional analysis; Samples 13, 23, 32, 44, 48, & 49 added as a composite. JT 8.22.24

Analyst:

Approved Signatory:

Analysis Date: 8/22/2024

Date: 8/22/2024



SanAir ID Number

24047195

FINAL REPORT

8/22/2024 2:44:47 PM

Name: 3 Kings Environmental Inc.
Address: PO Box 280
Battle Ground, WA 98604
Phone: 360-666-5464

Project Number: 224137
P.O. Number: 12024-318
Project Name: Port Of Kalama Hotel-Amended Report JT 8.22.24
Collected Date: 8/14/2024
Received Date: 8/21/2024 10:25:00 AM

Analyst: Childress, Susan

Asbestos Bulk PLM EPA 600/R-93/116

SanAir ID / Description	Stereoscopic	Components		Asbestos Fibers
	Appearance	% Fibrous	% Non-fibrous	
24 / 24047195-024 Sheet Vinyl/Counter- Housekeeping Room, Sheet Vinyl	Orange Non-Fibrous Heterogeneous	20% Cellulose	60% Other	20% Chrysotile
24 / 24047195-024 Sheet Vinyl/Counter- Housekeeping Room, Mastic	Yellow Non-Fibrous Homogeneous		100% Other	None Detected
25 / 24047195-025 Sheet Vinyl/Counter- Housekeeping Area, Sheet Vinyl				Not Analyzed
25 / 24047195-025 Sheet Vinyl/Counter- Housekeeping Area, Mastic	Yellow Non-Fibrous Homogeneous		100% Other	None Detected
26 / 24047195-026 Tile W/ Mastic/Counter- Housekeeping Area, Floor Tile	Beige Non-Fibrous Homogeneous		95% Other	5% Chrysotile
26 / 24047195-026 Tile W/ Mastic/Counter- Housekeeping Area, Mastic	Black Non-Fibrous Homogeneous		97% Other	3% Chrysotile
27 / 24047195-027 Tile W/ Mastic/Counter- Housekeeping Area, Floor Tile				Not Analyzed
27 / 24047195-027 Tile W/ Mastic/Counter- Housekeeping Area, Mastic				Not Analyzed
28 / 24047195-028 Wood Pattern Sheet Vinyl/Housekeeping Area, Sheet Vinyl	Brown Non-Fibrous Heterogeneous	15% Cellulose	85% Other	None Detected
28 / 24047195-028 Wood Pattern Sheet Vinyl/Housekeeping Area, Mastic	Yellow Non-Fibrous Homogeneous		100% Other	None Detected

Amended: Additional analysis; Samples 13, 23, 32, 44, 48, & 49 added as a composite. JT 8.22.24

Analyst: *Susan Childress*

Approved Signatory:

[Signature]

Analysis Date: 8/22/2024

Date: 8/22/2024



SanAir ID Number

24047195

FINAL REPORT

8/22/2024 2:44:47 PM

Name: 3 Kings Environmental Inc.
Address: PO Box 280
Battle Ground, WA 98604
Phone: 360-666-5464

Project Number: 224137
P.O. Number: 12024-318
Project Name: Port Of Kalama Hotel-Amended Report JT 8.22.24
Collected Date: 8/14/2024
Received Date: 8/21/2024 10:25:00 AM

Analyst: Childress, Susan

Asbestos Bulk PLM EPA 600/R-93/116

SanAir ID / Description	Stereoscopic	Components		Asbestos Fibers
	Appearance	% Fibrous	% Non-fibrous	
29 / 24047195-029 Wood Pattern Sheet Vinyl/Housekeeping Area, Sheet Vinyl	Brown Non-Fibrous Heterogeneous	15% Cellulose	85% Other	None Detected
29 / 24047195-029 Wood Pattern Sheet Vinyl/Housekeeping Area, Mastic	Yellow Non-Fibrous Homogeneous		100% Other	None Detected
30 / 24047195-030 Tile Mortar/Lobby Floor	White Non-Fibrous Homogeneous		100% Other	None Detected
31 / 24047195-031 Tile Mortar/Lobby Floor	White Non-Fibrous Homogeneous		100% Other	None Detected
32 / 24047195-032 Drywall W/ Joint Compound/Unit 222, Drywall	White Non-Fibrous Homogeneous	6% Cellulose	94% Other	None Detected
32 / 24047195-032 Drywall W/ Joint Compound/Unit 222, Joint Compound	White Non-Fibrous Homogeneous		98% Other	2% Chrysotile
32 / 24047195-032 Drywall W/ Joint Compound/Unit 222, Composite	Various Non-Fibrous Heterogeneous	< 1% Cellulose	100% Other	< 1% Chrysotile
33 / 24047195-033 Ceramic Tile W/ Mortar/Unit 219 Shower Surround, Ceramic Tile	Yellow Non-Fibrous Homogeneous		100% Other	None Detected
33 / 24047195-033 Ceramic Tile W/ Mortar/Unit 219 Shower Surround, Grout	White Non-Fibrous Homogeneous		100% Other	None Detected
33 / 24047195-033 Ceramic Tile W/ Mortar/Unit 219 Shower Surround, Mortar	White Non-Fibrous Homogeneous		100% Other	None Detected

Amended: Additional analysis; Samples 13, 23, 32, 44, 48, & 49 added as a composite. JT 8.22.24

Analyst: *Susan Childress* Approved Signatory: *[Signature]*

Analysis Date: 8/22/2024

Date: 8/22/2024



SanAir ID Number

24047195

FINAL REPORT

8/22/2024 2:44:47 PM

Name: 3 Kings Environmental Inc.**Address:** PO Box 280

Battle Ground, WA 98604

Phone: 360-666-5464**Project Number:** 224137**P.O. Number:** 12024-318**Project Name:** Port Of Kalama Hotel-Amended Report JT 8.22.24**Collected Date:** 8/14/2024**Received Date:** 8/21/2024 10:25:00 AM

Analyst: Childress, Susan

Asbestos Bulk PLM EPA 600/R-93/116

SanAir ID / Description	Stereoscopic	Components		Asbestos Fibers
	Appearance	% Fibrous	% Non-fibrous	
33 / 24047195-033 Ceramic Tile W/ Mortar/Unit 219 Shower Surround, Mastic	Yellow Non-Fibrous Homogeneous		100% Other	None Detected
34 / 24047195-034 9x9 W/ Mastic/2nd Floor Housekeeping, Floor Tile	Beige Non-Fibrous Homogeneous		96% Other	4% Chrysotile
34 / 24047195-034 9x9 W/ Mastic/2nd Floor Housekeeping, Mastic	Black Non-Fibrous Homogeneous		98% Other	2% Chrysotile
35 / 24047195-035 9x9 W/ Mastic/2nd Floor Housekeeping, Floor Tile				Not Analyzed
35 / 24047195-035 9x9 W/ Mastic/2nd Floor Housekeeping, Mastic				Not Analyzed
36 / 24047195-036 Sheet Vinyl Backing W/ Mastic/Unit 218 Bathroom, Sheet Vinyl Backing	Grey Fibrous Homogeneous	25% Cellulose	55% Other	20% Chrysotile
36 / 24047195-036 Sheet Vinyl Backing W/ Mastic/Unit 218 Bathroom, Mastic	Brown Non-Fibrous Homogeneous		100% Other	None Detected
37 / 24047195-037 Covebase W/ Mastic/Unit 218 Bathroom, Cove Base	Tan Non-Fibrous Homogeneous		100% Other	None Detected
37 / 24047195-037 Covebase W/ Mastic/Unit 218 Bathroom, Mastic	Tan Non-Fibrous Homogeneous		100% Other	None Detected
37 / 24047195-037 Covebase W/ Mastic/Unit 218 Bathroom, Mastic	Brown Non-Fibrous Homogeneous		100% Other	None Detected

Amended: Additional analysis; Samples 13, 23, 32, 44, 48, & 49 added as a composite. JT 8.22.24

Analyst: *Susan Childress* Approved Signatory: *J. Stettin*

Analysis Date: 8/22/2024

Date: 8/22/2024



SanAir ID Number

24047195

FINAL REPORT

8/22/2024 2:44:47 PM

Name: 3 Kings Environmental Inc.
Address: PO Box 280
Battle Ground, WA 98604
Phone: 360-666-5464

Project Number: 224137
P.O. Number: 12024-318
Project Name: Port Of Kalama Hotel-Amended Report JT 8.22.24
Collected Date: 8/14/2024
Received Date: 8/21/2024 10:25:00 AM

Analyst: Childress, Susan

Asbestos Bulk PLM EPA 600/R-93/116

SanAir ID / Description	Stereoscopic	Components		Asbestos Fibers
	Appearance	% Fibrous	% Non-fibrous	
38 / 24047195-038 Sheet Vinyl Small Square Pattern/Unit 217 Bathroom Sink Area	Tan Non-Fibrous Heterogeneous	25% Cellulose	55% Other	20% Chrysotile
39 / 24047195-039 Sheet Vinyl Small Square Pattern/Unit 217 Bathroom Sink Area				Not Analyzed
40 / 24047195-040 Sheet Vinyl 4" Square Pattern/Unit 216 Bathroom	Cream Non-Fibrous Heterogeneous	25% Cellulose	55% Other	20% Chrysotile
41 / 24047195-041 Sheet Vinyl 4" Square Pattern/Unit 216 Bathroom				Not Analyzed
42 / 24047195-042 Sheet Vinyl/Unit 215 Bathroom, Sheet Vinyl	Brown Non-Fibrous Homogeneous		100% Other	None Detected
42 / 24047195-042 Sheet Vinyl/Unit 215 Bathroom, Mastic	Yellow Non-Fibrous Homogeneous	< 1% Cellulose	100% Other	None Detected
43 / 24047195-043 Sheet Vinyl/Unit 215 Bathroom, Sheet Vinyl	Brown Non-Fibrous Homogeneous		100% Other	None Detected
43 / 24047195-043 Sheet Vinyl/Unit 215 Bathroom, Mastic	Yellow Non-Fibrous Homogeneous	< 1% Cellulose	100% Other	None Detected
44 / 24047195-044 Drywall W/ Joint Compound/Unit 215 Ceiling, Drywall Amended: Additional analysis; Samples 13, 23, 32, 44, 48, & 49 added as a composite. JT 8.22.24	White Non-Fibrous Homogeneous	6% Cellulose	94% Other	None Detected

Analyst: *Susan P. Childress*

Approved Signatory:

[Signature]

Analysis Date: 8/22/2024

Date: 8/22/2024



SanAir ID Number

24047195

FINAL REPORT

8/22/2024 2:44:47 PM

Name: 3 Kings Environmental Inc.
Address: PO Box 280
Battle Ground, WA 98604
Phone: 360-666-5464

Project Number: 224137
P.O. Number: 12024-318
Project Name: Port Of Kalama Hotel-Amended Report JT 8.22.24
Collected Date: 8/14/2024
Received Date: 8/21/2024 10:25:00 AM

Analyst: Childress, Susan

Asbestos Bulk PLM EPA 600/R-93/116

SanAir ID / Description	Stereoscopic	Components		Asbestos Fibers
	Appearance	% Fibrous	% Non-fibrous	
44 / 24047195-044 Drywall W/ Joint Compound/Unit 215 Ceiling, Joint Compound	White Non-Fibrous Homogeneous		98% Other	2% Chrysotile
44 / 24047195-044 Drywall W/ Joint Compound/Unit 215 Ceiling, Composite	Various Non-Fibrous Heterogeneous	< 1% Cellulose	100% Other	< 1% Chrysotile
45 / 24047195-045 Sheet Vinyl Backing Over Leveling Compound/Unit 212 Bathroom, Sheet Vinyl Backing	Grey Fibrous Homogeneous	80% Cellulose	20% Other	None Detected
45 / 24047195-045 Sheet Vinyl Backing Over Leveling Compound/Unit 212 Bathroom, Leveling Compound	Grey Non-Fibrous Homogeneous		100% Other	None Detected
46 / 24047195-046 Ceramic Tile And Mortar/Unit 211 Bathroom Behind FRP, Ceramic Tile	Yellow Non-Fibrous Homogeneous		100% Other	None Detected
46 / 24047195-046 Ceramic Tile And Mortar/Unit 211 Bathroom Behind FRP, Mortar	White Non-Fibrous Homogeneous		100% Other	None Detected
46 / 24047195-046 Ceramic Tile And Mortar/Unit 211 Bathroom Behind FRP, Mastic	Yellow Non-Fibrous Homogeneous		100% Other	None Detected
46 / 24047195-046 Ceramic Tile And Mortar/Unit 211 Bathroom Behind FRP, Joint Compound	White Non-Fibrous Homogeneous		98% Other	2% Chrysotile
47 / 24047195-047 Sheet Vinyl Backing/Unit 209 Bathroom Floor, Sheet Vinyl Backing	Grey Fibrous Homogeneous	25% Cellulose	55% Other	20% Chrysotile

Amended: Additional analysis; Samples 13, 23, 32, 44, 48, & 49 added as a composite. JT 8.22.24

Analyst: *Susan P. Childress*

Approved Signatory:

[Signature]

Analysis Date: 8/22/2024

Date: 8/22/2024



SanAir ID Number

24047195

FINAL REPORT

8/22/2024 2:44:47 PM

Name: 3 Kings Environmental Inc.
Address: PO Box 280
Battle Ground, WA 98604
Phone: 360-666-5464

Project Number: 224137
P.O. Number: 12024-318
Project Name: Port Of Kalama Hotel-Amended Report JT 8.22.24
Collected Date: 8/14/2024
Received Date: 8/21/2024 10:25:00 AM

Analyst: Childress, Susan

Asbestos Bulk PLM EPA 600/R-93/116

SanAir ID / Description	Stereoscopic	Components		Asbestos Fibers
	Appearance	% Fibrous	% Non-fibrous	
47 / 24047195-047 Sheet Vinyl Backing/Unit 209 Bathroom Floor, Mastic	Brown Non-Fibrous Homogeneous		100% Other	None Detected
48 / 24047195-048 Drywall W/ Joint Compound/Unit 205 Closet, Drywall	White Non-Fibrous Homogeneous	6% Cellulose	94% Other	None Detected
48 / 24047195-048 Drywall W/ Joint Compound/Unit 205 Closet, Joint Compound	White Non-Fibrous Homogeneous		98% Other	2% Chrysotile
48 / 24047195-048 Drywall W/ Joint Compound/Unit 205 Closet, Composite	Various Non-Fibrous Heterogeneous	< 1% Cellulose	100% Other	< 1% Chrysotile
49 / 24047195-049 Drywall W/ Joint Compound/Unit 203 By Night Stand, Drywall	White Non-Fibrous Homogeneous	6% Cellulose	94% Other	None Detected
49 / 24047195-049 Drywall W/ Joint Compound/Unit 203 By Night Stand, Joint Compound	White Non-Fibrous Homogeneous		98% Other	2% Chrysotile
49 / 24047195-049 Drywall W/ Joint Compound/Unit 203 By Night Stand, Composite	Various Non-Fibrous Heterogeneous	< 1% Cellulose	100% Other	< 1% Chrysotile
50 / 24047195-050 Wood Fiber Board Behind Drywall/Unit 203	Tan Fibrous Homogeneous	85% Cellulose	15% Other	None Detected
51 / 24047195-051 Wood Fiber Board Behind Drywall/Unit 206	Tan Fibrous Homogeneous	85% Cellulose	15% Other	None Detected
52 / 24047195-052 Paper Uneven Vinyl Siding/Unit 204	Brown Fibrous Homogeneous	60% Cellulose	40% Other	None Detected

Amended: Additional analysis; Samples 13, 23, 32, 44, 48, & 49 added as a composite. JT 8.22.24

Analyst: *Susan Childress* Approved Signatory: *[Signature]*

Analysis Date: 8/22/2024

Date: 8/22/2024



SanAir ID Number

24047195

FINAL REPORT

8/22/2024 2:44:47 PM

Name: 3 Kings Environmental Inc.
Address: PO Box 280
Battle Ground, WA 98604
Phone: 360-666-5464

Project Number: 224137
P.O. Number: 12024-318
Project Name: Port Of Kalama Hotel-Amended Report JT 8.22.24
Collected Date: 8/14/2024
Received Date: 8/21/2024 10:25:00 AM

Analyst: Childress, Susan

Asbestos Bulk PLM EPA 600/R-93/116

SanAir ID / Description	Stereoscopic	Components		Asbestos Fibers
	Appearance	% Fibrous	% Non-fibrous	
53 / 24047195-053 Paper Uneven Vinyl Siding/Unit 219	Brown Fibrous Homogeneous	60% Cellulose	40% Other	None Detected
54 / 24047195-054 Window Caulk/Unit 204	White Non-Fibrous Homogeneous		100% Other	None Detected
55 / 24047195-055 Window Caulk/Unit 219	White Non-Fibrous Homogeneous		100% Other	None Detected
56 / 24047195-056 Built Up Roof System 11/2" To 2" Thick/Lower Roof, Shingle	Black Non-Fibrous Heterogeneous	5% Glass	95% Other	None Detected
56 / 24047195-056 Built Up Roof System 11/2" To 2" Thick/Lower Roof, Tar	Black Non-Fibrous Heterogeneous	8% Cellulose	92% Other	None Detected
56 / 24047195-056 Built Up Roof System 11/2" To 2" Thick/Lower Roof, Roofing	Black Non-Fibrous Heterogeneous	10% Synthetic	90% Other	None Detected
56 / 24047195-056 Built Up Roof System 11/2" To 2" Thick/Lower Roof, Felt	Black Non-Fibrous Heterogeneous	10% Glass	90% Other	None Detected
57 / 24047195-057 Built Up Roof System 1/4" Thick/Upper Roof, Roofing	Black Non-Fibrous Heterogeneous	10% Synthetic	90% Other	None Detected
57 / 24047195-057 Built Up Roof System 1/4" Thick/Upper Roof, Felt	Black Non-Fibrous Heterogeneous	10% Glass	90% Other	None Detected
58 / 24047195-058 Exterior Brick/Outside Unit 120	Red Non-Fibrous Homogeneous		100% Other	None Detected

Amended: Additional analysis; Samples 13, 23, 32, 44, 48, & 49 added as a composite. JT 8.22.24

Analyst: *Susan P. Childress*

Approved Signatory:

[Signature]

Analysis Date: 8/22/2024

Date: 8/22/2024



SanAir ID Number

24047195

FINAL REPORT

8/22/2024 2:44:47 PM

Name: 3 Kings Environmental Inc.
Address: PO Box 280
Battle Ground, WA 98604
Phone: 360-666-5464

Project Number: 224137
P.O. Number: 12024-318
Project Name: Port Of Kalama Hotel-Amended Report JT 8.22.24
Collected Date: 8/14/2024
Received Date: 8/21/2024 10:25:00 AM

Analyst: Childress, Susan

Asbestos Bulk PLM EPA 600/R-93/116

SanAir ID / Description	Stereoscopic	Components		Asbestos Fibers
	Appearance	% Fibrous	% Non-fibrous	
59 / 24047195-059 Exterior Brick/Outside Unit 112	Red Non-Fibrous Homogeneous		100% Other	None Detected
60 / 24047195-060 Exterior Mortar/Outside Unit 120	Grey Non-Fibrous Homogeneous		100% Other	None Detected
61 / 24047195-061 Exterior Mortar/Outside Unit 112	Grey Non-Fibrous Homogeneous		100% Other	None Detected
62 / 24047195-062 Felt Paper Under Wood Siding/1st Floor Housekeeping	Black Fibrous Homogeneous	50% Cellulose	50% Other	None Detected
63 / 24047195-063 Felt Paper Under Wood Siding/1st Floor Housekeeping	Black Fibrous Homogeneous	50% Cellulose	50% Other	None Detected

Amended: Additional analysis; Samples 13, 23, 32, 44, 48, & 49 added as a composite. JT 8.22.24

Analyst: *Susan P. Childress*

Approved Signatory:

Analysis Date: 8/22/2024

Date: 8/22/2024

Disclaimer

This report is the sole property of the client named on the SanAir Technologies Laboratory chain-of-custody (COC). Results in the report are confidential information intended only for the use by the customer listed on the COC. Neither results nor reports will be discussed with or released to any third party without our client's written permission. The final report shall not be reproduced except in full without written approval of the laboratory to assure that parts of the report are not taken out of context. This report and any information contained within shall not be edited, altered, or modified in any way by any persons or agencies receiving, viewing, distributing, or otherwise possessing a copy of this final report. The laboratory reserves the right to perform amendments to any finalized report, of which shall supersede and make obsolete any previous editions. Such changes, modifications, additions, or deletions shall be effective immediately upon notice thereof, which may be given by means including but not limited to posting on the SanAir client portal website, electronic or conventional mail, or by any other means. The information provided in this report applies only to the samples submitted and is relevant only for the date, time, and location of sampling. The accuracy of the results is dependent upon the client's sampling procedure and information provided to the laboratory by the client on the COC. SanAir assumes no responsibility for the sampling procedure and will provide evaluation reports based solely on the sample(s) in the condition in which they arrived at the laboratory and information provided by the client on the COC, such as: project number, project name, collection dates, po number, special instructions, samples collected by, sample numbers, sample identifications, sample type, selected analysis type, flow rate, total volume or area, and start stop times that may affect the validity of the results in this report. Samples were received in good condition unless otherwise noted on the report. SanAir assumes no responsibility or liability for the manner in which the results are used or interpreted. This report does not constitute nor shall not be used by the client to claim product, process, system, or person certification, approval, or endorsement by NVLAP, NIST, NELAC, AIHA LAP, LLC or any other U.S. governmental agencies and may not be accredited by every local, state, and federal regulatory agencies. Samples are held for a period of 60 days. Fibers smaller than 5 microns cannot be seen with this method due to scope limitations. For NY state samples, method EPA 600/M4-82-020 is performed.

NYELAP Disclaimer:

Polarized- light microscopy is not consistently reliable in detecting asbestos in floor covering and similar non-friable organically bound materials. Quantitative transmission electron microscopy is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos containing.

Asbestos Accreditations

National Voluntary Laboratory Accreditation Program (NVLAP) Lab Code 200870-0
City of Philadelphia Department of Public Health Air Management Services, Certification#ALL-460
Commonwealth of Pennsylvania Department of Environmental Protection Number 68-05397
California State Environmental Laboratory Accreditation Program Certificate Number 2915
Colorado Department of Public Health and Environment Registration Number AL-23143
Connecticut Department of Public Health Environmental Laboratory Registration Number PH-0105
Massachusetts Department of Labor Standards Asbestos Analytical Services License Number: AA000222
State of Maine Department of Environmental Protection License Number: LB-0075, LA-0084
New York State Department of Health Laboratory ID: 11983
State of Rhode Island Department of Health Certification No.: PCM00126, PLM00126, TEM00126
Texas Department of State Health Services License Number: 300440
Commonwealth of Virginia Department of Professional and Occupational Regulation Number: 3333000323
State of Washington Department of Ecology Laboratory ID: C989
State of West Virginia Bureau for Public Health Analytical Laboratory Number: LT000616
Vermont Department of Health License Number: Asb-Co-An-000006
Louisiana Department of Environmental Quality AI Number 212253, Certificate #05088



10501 Trade Ct., Suite 100
N. Chesterfield, VA 23236
804.897.1177 / 888.895.1177
Fax 804.897.0070
sanair.com

Asbestos
Chain of Custody
Form 140, Rev 7, 10/20/2022

SanAir ID Number

24047195

Company: 3 Kings Environmental, Inc.		Project #: 224137	Collected by: JHawks
Address: PO Box 280		Project Name: Port of Kalama Hotel	Phone #: 253-750-4143
City, St., Zip: Battle Ground, WA 98604		Date Collected: 08/14/2024	Fax #: 360-666-8202
State of Collection: WA	Account#: 2344	P.O. Number: 12024-318	Email: jhawks@3kingsinc.com

Bulk

ABB	PLM EPA 600/R-93/116	<input checked="" type="checkbox"/>
	Positive Stop	<input checked="" type="checkbox"/>
ABEPA	PLM EPA 400 Point Count	<input type="checkbox"/>
ABB1K	PLM EPA 1000 Point Count	<input type="checkbox"/>
ABBE	PLM EPA NOB**	<input type="checkbox"/>
ABBCH	TEM Chatfield**	<input type="checkbox"/>
ABBTM	TEM EPA NOB**	<input type="checkbox"/>
ABQ	PLM Qualitative	<input type="checkbox"/>

** Available on 24-hr. to 5-day TAT

Air

ABA	PCM NIOSH 7400	<input type="checkbox"/>
ABA-2	OSHA w/ TWA*	<input type="checkbox"/>
ABTEM	TEM AHERA	<input type="checkbox"/>
ABATN	TEM NIOSH 7402	<input type="checkbox"/>
ABT2	TEM Level II	<input type="checkbox"/>
Other:		<input type="checkbox"/>

New York ELAP

ABEPA2	NY ELAP 198.1	<input type="checkbox"/>
ABENY	NY ELAP 198.6 PLM NOB	<input type="checkbox"/>
ABBNY	NY ELAP 198.4 TEM NOB	<input type="checkbox"/>
	Positive Stop	<input type="checkbox"/>

Soil

ABSE	PLM EPA 600/R-93/116 (Qual.)	<input type="checkbox"/>
------	------------------------------	--------------------------

Vermiculite

ABB	PLM EPA 600/R-93/116	<input type="checkbox"/>
ABEPA3	PLM EPA 400 Point Count	<input type="checkbox"/>
ABCM	Cincinnati Method	<input type="checkbox"/>

Dust

ABWA	TEM Wipe ASTM D-6480	<input type="checkbox"/>
ABDMV	TEM Microvac ASTM D-5755	<input type="checkbox"/>

Matrix	Other	<input type="checkbox"/>
--------	-------	--------------------------

Water

ABHE	EPA 100.2	<input type="checkbox"/>
------	-----------	--------------------------

Turn Around Times	3 HR (4 HR TEM) <input type="checkbox"/>	6 HR (8HR TEM) <input type="checkbox"/>	12 HR <input type="checkbox"/>	1 Day <input checked="" type="checkbox"/>
	<input type="checkbox"/> 2 Days	<input type="checkbox"/> 3 Days	<input type="checkbox"/> 4 Days	<input type="checkbox"/> 5 Days

Special Instructions

Sample #	Sample Identification/Location	Volume or Area	Sample Date	Flow Rate*	Start - Stop Time*
01	Drywall w. Joint Compound & Oragne Peel Texture / Unit 101 - Ceiling				
02	Beige Sheet Vinyl / Unit 101 Bathroom Floor				
03	Beige Sheet Vinyl / Unit 101 Bathroom Floor				
04	Yellow Carpet Adhesive - Unit 101 Entry				
05	Sheet Vinyl Backing / Unit 102 Bathroom				
06	Sheet Vinyl Backing / Unit 102 Bathroom				
07	Tan Rubber Covebase w/Tan Mastic / Unit 102 Bathroom				
08	Tan Rubber Covebase w/Tan Mastic / Unit 102 by Bed				
09	Blue Grey 12x12 Tile w/Yellow Mastic / 1st Floor Store room				
10	Blue Grey 12x12 Tile w/Yellow Mastic / 1st Floor Store room				
11	Sheet Vinyl Backing / Unit 103 Bathroom				
12	Sheet Vinyl Backing / Unit 103 Bathroom				

Relinquished by	Date	Time	Received by	Date	Time
JH	8/14	12PM	EDR	8/21/24	10:25 a.m.

If no technician is provided, then the primary contact for your account will be selected. Unless scheduled, the turnaround time for all samples received after 3 pm EST will be logged in the next business day. Weekend or holiday work must be scheduled ahead of time and is charged at 150% of the 3hr TAT or a minimum charge of \$150. A courier charge will be applied for same day and one-day turnaround times for offsite work. SanAir covers Ground and Next Day Air shipping. Shipments billed to SanAir with a faster shipping rate will result in additional charges.

24047195

Sample #	Sample Identification/Location	Volume or Area	Sample Date	Flow Rate*	Start – Stop Time*
13	Drywall w/ Joint Compound / Unit 103				
14	White Laminate w/Brown Mastic / Unit 103 Sink Surround				
15	White Laminate w/Tan Mastic / Unit 106 Sink Surround				
16	Cementitious Leveling Compound / Unit 106 Bathroom				
17	Cementitious Leveling Compound / Unit 106 Bathroom				
18	Sheet Vinyl Backing / Unit 109 Bathroom				
19	Slate Pattern Sheet Vinyl / Unit 110 Bathroom				
20	Slate Pattern Sheet Vinyl / Unit 110 Bathroom				
21	Sheet Vinyl Backing / Unit 117 Bathroom				
22	Brown Mastic - Sink Surround / Unit 118 Bathroom				
23	Drywall w/ Joint Compound & Orange Peel Texture / Unit 118 Living area wall				
24	Orange Sheet Vinyl / Counter - Housekeeping Room				
25	Orange Sheet Vinyl / Counter - Housekeeping Area				
26	Beige Tile w/Black Mastic / Housekeeping Area				
27	Beige Tile w/Black Mastic / Housekeeping Area				
28	Brown Wood Pattern Sheet Vinyl / Housekeeping Area				
29	Brown Wood Pattern Sheet Vinyl / Housekeeping Area				
30	White Tile Mortar / Lobby Floor				
31	White Tile Mortar / Lobby Floor				
32	Drywall w/ Joint Compound / Unit 222				
33	Ceramic Tile w/White Mortar / Unit 219 Shower Surround				
34	Beige 9x9 w/Black Mastic / 2nd Floor Housekeeping				
35	Beige 9x9 w/Black Mastic / 2nd Floor Housekeeping				
36	Sheet Vinyl Backing w/Brown Mastic / Unit 218 Bathroom				
37	Tan Covebase w/Tan&Brown Mastic / Unit 218 Bathroom				
38	Tan Sheet Vinyl Small Square Pattern / Unit 217 Bathroom Sink Area				
39	Tan Sheet Vinyl Small Square Pattern / Unit 217 Bathroom Sink Area				
40	Cream Sheet Vinyl 4" Square Pattern / Unit 216 Bathroom				
41	Cream Sheet Vinyl 4" Square Pattern / Unit 216 Bathroom				
42	Dark Brown Sheet Vinyl / Unit 215 Bathroom				
43	Dark Brown Sheet Vinyl / Unit 215 Bathroom				

Special Instructions

Relinquished by	Date	Time	Received by	Date	Time
JH	8/14	12pm	EDR	8/21/24	10:25 a.m.

If no technician is provided, then the primary contact for your account will be selected. Unless scheduled, the turnaround time for all samples received after 3 pm EST will be logged in the next business day. Weekend or holiday work must be scheduled ahead of time and is charged at 150% of the 3hr TAT or a minimum charge of \$150. A courier charge will be applied for same day and one-day turnaround times for offsite work. SanAir covers Ground and Next Day Air shipping. Shipments billed to SanAir with a faster shipping rate will result in additional charges. Page 2 of 3

[illegible]

Special Instructions

Relinquished by	Date	Time	Received by	Date	Time
JH	8/14	12pm	EDR	8/21/24	10:25 a.m.

If no technician is provided, then the primary contact for your account will be selected. Unless scheduled, the turnaround time for all samples received after 3 pm EST will be logged in the next business day. Weekend or holiday work must be scheduled ahead of time and is charged at 150% of the 3hr TAT or a minimum charge of \$150. A courier charge will be applied for same day and one-day turnaround times for offsite work. SanAir covers Ground and Next Day Air shipping. Shipments billed to SanAir with a faster shipping rate will result in additional charges. Page of 3 3



The Identification Specialists

Analysis Report
prepared for
3 Kings Environmental Inc.

Report Date: 9/4/2024

Project Name: Port Of Kalama Hotel. Amended Report JW 9.3.24

Project #: 224137

SanAir ID#: 24049551



NVLAP LAB CODE 200870-0

10501 Trade Court | North Chesterfield, Virginia 23236
888.895.1177 | 804.897.1177 | fax: 804.897.0070 | IAQ@SanAir.com | SanAir.com



SanAir ID Number

24049551

FINAL REPORT

9/4/2024 8:56:40 AM

Name: 3 Kings Environmental Inc.
Address: PO Box 280
Battle Ground, WA 98604
Phone: 360-666-5464

Project Number: 224137
P.O. Number: 12024-330
Project Name: Port Of Kalama Hotel. Amended Report JW
9.3.24
Collected Date: 8/28/2024
Received Date: 8/30/2024 10:00:00 AM

Dear Jason Hawks,

We at SanAir would like to thank you for the work you recently submitted. The 10 sample(s) were received on Friday, August 30, 2024 via UPS. The final report(s) is enclosed for the following sample(s): MO - 01, MO - 02, MO - 03, MO - 04, MO - 05, MO - 06, MO - 07, MO - 08, 201 - 01, 201 - 02.

These results only pertain to this job and should not be used in the interpretation of any other job. This report is only complete in its entirety. Refer to the listing below of the pages included in a complete final report.

Sincerely,

A handwritten signature in black ink that reads "Sandra Sobrino".

Sandra Sobrino
Asbestos & Materials Laboratory Manager
SanAir Technologies Laboratory

Final Report Includes:

- Cover Letter
- Analysis Pages
- Disclaimers and Additional Information

Sample conditions:

- 10 samples in Good condition.



SanAir ID Number
24049551
FINAL REPORT
9/4/2024 8:56:40 AM

Name: 3 Kings Environmental Inc.
Address: PO Box 280
Battle Ground, WA 98604
Phone: 360-666-5464

Project Number: 224137
P.O. Number: 12024-330
Project Name: Port Of Kalama Hotel. Amended Report JW 9.3.24
Collected Date: 8/28/2024
Received Date: 8/30/2024 10:00:00 AM

Analyst: Jones, Virginia

Asbestos Bulk PLM EPA 600/R-93/116

SanAir ID / Description	Stereoscopic	Components		Asbestos Fibers
	Appearance	% Fibrous	% Non-fibrous	
MO - 01 / 24049551-001 Drywall With Joint Compound & Heavy Knockdown Ceiling, Drywall	White Non-Fibrous Heterogeneous	10% Cellulose	90% Other	None Detected
MO - 01 / 24049551-001 Drywall With Joint Compound & Heavy Knockdown Ceiling, Joint Compound	Off-White Non-Fibrous Homogeneous		98% Other	2% Chrysotile
MO - 01 / 24049551-001 Drywall With Joint Compound & Heavy Knockdown Ceiling, Texture	White Non-Fibrous Homogeneous		100% Other	None Detected
MO - 01 / 24049551-001 Drywall With Joint Compound & Heavy Knockdown Ceiling, Composite	Off-White Non-Fibrous Homogeneous	5% Cellulose	95% Other	< 1% Chrysotile
MO - 02 / 24049551-002 Drywall With Joint Compound & Heavy Knockdown Ceiling, Drywall	White Non-Fibrous Heterogeneous	10% Cellulose	90% Other	None Detected
MO - 02 / 24049551-002 Drywall With Joint Compound & Heavy Knockdown Ceiling, Joint Compound	Off-White Non-Fibrous Homogeneous		98% Other	2% Chrysotile
MO - 02 / 24049551-002 Drywall With Joint Compound & Heavy Knockdown Ceiling, Texture	White Non-Fibrous Homogeneous		100% Other	None Detected
MO - 02 / 24049551-002 Drywall With Joint Compound & Heavy Knockdown Ceiling, Composite	Off-White Non-Fibrous Homogeneous	5% Cellulose	95% Other	< 1% Chrysotile
MO - 03 / 24049551-003 Heavy Knockdown Ceiling Texture / Managers Office	White Non-Fibrous Homogeneous		100% Other	None Detected

Amended: Additional Composite Analysis JW 9.3.24

Analyst: *Virginia Jones*

Approved Signatory: *[Signature]*

Analysis Date: 9/4/2024

Date: 9/4/2024



SanAir ID Number

24049551

FINAL REPORT

9/4/2024 8:56:40 AM

Name: 3 Kings Environmental Inc.
Address: PO Box 280
Battle Ground, WA 98604
Phone: 360-666-5464

Project Number: 224137
P.O. Number: 12024-330
Project Name: Port Of Kalama Hotel. Amended Report JW 9.3.24
Collected Date: 8/28/2024
Received Date: 8/30/2024 10:00:00 AM

Analyst: Jones, Virginia

Asbestos Bulk PLM EPA 600/R-93/116

SanAir ID / Description	Stereoscopic	Components		Asbestos Fibers
	Appearance	% Fibrous	% Non-fibrous	
MO - 04 / 24049551-004 Drywall With Joint Compound & Orange Peel Texture / Managers, Drywall	White Non-Fibrous Heterogeneous	10% Cellulose	90% Other	None Detected
MO - 04 / 24049551-004 Drywall With Joint Compound & Orange Peel Texture / Managers, Joint Compound	Off-White Non-Fibrous Homogeneous		98% Other	2% Chrysotile
MO - 04 / 24049551-004 Drywall With Joint Compound & Orange Peel Texture / Managers, Texture	White Non-Fibrous Homogeneous		100% Other	None Detected
MO - 04 / 24049551-004 Drywall With Joint Compound & Orange Peel Texture / Managers, Composite	Off-White Non-Fibrous Homogeneous	5% Cellulose	95% Other	< 1% Chrysotile
MO - 05 / 24049551-005 Drywall With Joint Compound & Orange Peel Texture / Managers, Drywall	White Non-Fibrous Heterogeneous	10% Cellulose	90% Other	None Detected
MO - 05 / 24049551-005 Drywall With Joint Compound & Orange Peel Texture / Managers, Joint Compound	Off-White Non-Fibrous Homogeneous		98% Other	2% Chrysotile
MO - 05 / 24049551-005 Drywall With Joint Compound & Orange Peel Texture / Managers, Texture	White Non-Fibrous Homogeneous		100% Other	None Detected
MO - 05 / 24049551-005 Drywall With Joint Compound & Orange Peel Texture / Managers, Composite	Off-White Non-Fibrous Homogeneous	5% Cellulose	95% Other	< 1% Chrysotile

Amended: Additional Composite Analysis JW 9.3.24

Analyst: *Virginia Jones*Approved Signatory: *[Signature]*

Analysis Date: 9/4/2024

Date: 9/4/2024



SanAir ID Number

24049551

FINAL REPORT

9/4/2024 8:56:40 AM

Name: 3 Kings Environmental Inc.
Address: PO Box 280
Battle Ground, WA 98604
Phone: 360-666-5464

Project Number: 224137
P.O. Number: 12024-330
Project Name: Port Of Kalama Hotel. Amended Report JW 9.3.24
Collected Date: 8/28/2024
Received Date: 8/30/2024 10:00:00 AM

Analyst: Jones, Virginia

Asbestos Bulk PLM EPA 600/R-93/116

SanAir ID / Description	Stereoscopic	Components		Asbestos Fibers
	Appearance	% Fibrous	% Non-fibrous	
MO - 06 / 24049551-006 Orange Peel Texture / Managers Office	White Non-Fibrous Homogeneous		100% Other	None Detected
MO - 07 / 24049551-007 Sheet Vinyl / Secondary Bathroom	White Non-Fibrous Heterogeneous	10% Cellulose	90% Other	None Detected
MO - 08 / 24049551-008 Sheet Vinyl / Secondary Bathroom	White Non-Fibrous Heterogeneous	10% Cellulose	90% Other	None Detected
201 - 01 / 24049551-009 Wood Pattern Sheet Vinyl Over Pebble Pattern Sheet Vinyl, Sheet Vinyl	Brown Non-Fibrous Heterogeneous	15% Cellulose	85% Other	None Detected
201 - 01 / 24049551-009 Wood Pattern Sheet Vinyl Over Pebble Pattern Sheet Vinyl, Mastic	Brown Non-Fibrous Homogeneous		100% Other	None Detected
201 - 01 / 24049551-009 Wood Pattern Sheet Vinyl Over Pebble Pattern Sheet Vinyl, Sheet Vinyl	Beige Non-Fibrous Heterogeneous		90% Other	10% Chrysotile
201 - 02 / 24049551-010 Wood Pattern Sheet Vinyl Over Pebble Pattern Sheet Vinyl, Sheet Vinyl	Brown Non-Fibrous Heterogeneous	15% Cellulose	85% Other	None Detected
201 - 02 / 24049551-010 Wood Pattern Sheet Vinyl Over Pebble Pattern Sheet Vinyl, Mastic	Brown Non-Fibrous Homogeneous		100% Other	None Detected
201 - 02 / 24049551-010 Wood Pattern Sheet Vinyl Over Pebble Pattern Sheet Vinyl, Sheet Vinyl				Not Analyzed

Amended: Additional Composite Analysis JW 9.3.24

Analyst: *Virginia Jones*

Approved Signatory:

Analysis Date: 9/4/2024

Date: 9/4/2024



Name: 3 Kings Environmental Inc.
Address: PO Box 280
Battle Ground, WA 98604
Phone: 360-666-5464

SanAir ID Number
24049551
FINAL REPORT
9/4/2024 8:56:40 AM

Project Number: 224137
P.O. Number: 12024-330
Project Name: Port Of Kalama Hotel. Amended Report JW
9.3.24
Collected Date: 8/28/2024
Received Date: 8/30/2024 10:00:00 AM

Disclaimer

This report is the sole property of the client named on the SanAir Technologies Laboratory chain-of-custody (COC). Results in the report are confidential information intended only for the use by the customer listed on the COC. Neither results nor reports will be discussed with or released to any third party without our client's written permission. The final report shall not be reproduced except in full without written approval of the laboratory to assure that parts of the report are not taken out of context. This report and any information contained within shall not be edited, altered, or modified in any way by any persons or agencies receiving, viewing, distributing, or otherwise possessing a copy of this final report. The laboratory reserves the right to perform amendments to any finalized report, of which shall supersede and make obsolete any previous editions. Such changes, modifications, additions, or deletions shall be effective immediately upon notice thereof, which may be given by means including but not limited to posting on the SanAir client portal website, electronic or conventional mail, or by any other means. The information provided in this report applies only to the samples submitted and is relevant only for the date, time, and location of sampling. The accuracy of the results is dependent upon the client's sampling procedure and information provided to the laboratory by the client on the COC. SanAir assumes no responsibility for the sampling procedure and will provide evaluation reports based solely on the sample(s) in the condition in which they arrived at the laboratory and information provided by the client on the COC, such as: project number, project name, collection dates, po number, special instructions, samples collected by, sample numbers, sample identifications, sample type, selected analysis type, flow rate, total volume or area, and start stop times that may affect the validity of the results in this report. Samples were received in good condition unless otherwise noted on the report. SanAir assumes no responsibility or liability for the manner in which the results are used or interpreted. This report does not constitute nor shall not be used by the client to claim product, process, system, or person certification, approval, or endorsement by NVLAP, NIST, NELAC, AIHA LAP, LLC or any other U.S. governmental agencies and may not be accredited by every local, state, and federal regulatory agencies. Samples are held for a period of 60 days. Fibers smaller than 5 microns cannot be seen with this method due to scope limitations. For NY state samples, method EPA 600/M4-82-020 is performed.

NYELAP Disclaimer:

Polarized- light microscopy is not consistently reliable in detecting asbestos in floor covering and similar non-friable organically bound materials. Quantitative transmission electron microscopy is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos containing.

Asbestos Accreditations

National Voluntary Laboratory Accreditation Program (NVLAP) Lab Code 200870-0
City of Philadelphia Department of Public Health Air Management Services, Certification#ALL-460
Commonwealth of Pennsylvania Department of Environmental Protection Number 68-05397
California State Environmental Laboratory Accreditation Program Certificate Number 2915
Colorado Department of Public Health and Environment Registration Number AL-23143
Connecticut Department of Public Health Environmental Laboratory Registration Number PH-0105
Massachusetts Department of Labor Standards Asbestos Analytical Services License Number: AA000222
State of Maine Department of Environmental Protection License Number: LB-0075, LA-0084
New York State Department of Health Laboratory ID: 11983
State of Rhode Island Department of Health Certification No.: PCM00126, PLM00126, TEM00126
Texas Department of State Health Services License Number: 300440
Commonwealth of Virginia Department of Professional and Occupational Regulation Number: 3333000323
State of Washington Department of Ecology Laboratory ID: C989
State of West Virginia Bureau for Public Health Analytical Laboratory Number: LT000616
Vermont Department of Health License Number: Asb-Co-An-000006
Louisiana Department of Environmental Quality AI Number 212253, Certificate #05088



10501 Trade Ct., Suite 100
N. Chesterfield, VA 23236
804.897.1177 / 888.895.1177
Fax 804.897.0070
sanair.com

Asbestos
Chain of Custody
Form 140, Rev 7, 10/20/2022

SanAir ID Number

24049551

Company: 3 Kings Environmental, Inc.		Project #: 224137	Collected by: J. Hawks
Address: PO Box 280		Project Name: Port of Kalama Hotel	Phone #: 253-750-4143
City, St., Zip: Battle Ground, WA 98604		Date Collected: 08/28/2024	Fax #: 360-666-8202
State of Collection: WA	Account#: 2344	P.O. Number: 12024-330	Email: jhawks@3kingsinc.com

Bulk		Air		Soil	
ABB	PLM EPA 600/R-93/116 <input checked="" type="checkbox"/>	ABA	PCM NIOSH 7400 <input type="checkbox"/>	ABSE	PLM EPA 600/R-93/116 (Qual.) <input type="checkbox"/>
	Positive Stop <input checked="" type="checkbox"/>	ABA-2	OSHA w/ TWA* <input type="checkbox"/>	Vermiculite	
ABEPA	PLM EPA 400 Point Count <input type="checkbox"/>	ABTEM	TEM AHERA <input type="checkbox"/>	ABB	PLM EPA 600/R-93/116 <input type="checkbox"/>
ABB1K	PLM EPA 1000 Point Count <input type="checkbox"/>	ABATN	TEM NIOSH 7402 <input type="checkbox"/>	ABEPA3	PLM EPA 400 Point Count <input type="checkbox"/>
ABBN	PLM EPA NOB** <input type="checkbox"/>	ABT2	TEM Level II <input type="checkbox"/>	ABCM	Cincinnati Method <input type="checkbox"/>
ABBCH	TEM Chatfield** <input type="checkbox"/>	Other:	<input type="checkbox"/>	Dust	
ABBTM	TEM EPA NOB** <input type="checkbox"/>	New York ELAP		ABWA	TEM Wipe ASTM D-6480 <input type="checkbox"/>
ABQ	PLM Qualitative <input type="checkbox"/>	ABEPA2	NY ELAP 198.1 <input type="checkbox"/>	ABDMV	TEM Microvac ASTM D-5755 <input type="checkbox"/>
		ABENY	NY ELAP 198.6 PLM NOB <input type="checkbox"/>		
		ABBNY	NY ELAP 198.4 TEM NOB <input type="checkbox"/>		
			Positive Stop <input type="checkbox"/>	Matrix	Other <input type="checkbox"/>

** Available on 24-hr. to 5-day TAT

Water	
ABHE	EPA 100.2 <input type="checkbox"/>

Turn Around Times	3 HR (4 HR TEM) <input type="checkbox"/>	6 HR (8HR TEM) <input type="checkbox"/>	12 HR <input type="checkbox"/>	1 Day <input checked="" type="checkbox"/>
	<input type="checkbox"/> 2 Days	<input type="checkbox"/> 3 Days	<input type="checkbox"/> 4 Days	<input type="checkbox"/> 5 Days

Special Instructions	
-----------------------------	--

Sample #	Sample Identification/Location	Volume or Area	Sample Date	Flow Rate*	Start - Stop Time*
MO - 01	Drywall with Joint Compound & Heavy Knockdown Ceiling Texture / Managers Office				
MO - 02	Drywall with Joint Compound & Heavy Knockdown Ceiling Texture / Managers Office				
MO - 03	Heavy Knockdown Ceiling Texture / Managers Office				
MO - 04	Drywall with Joint Compound & Orange Peel Texture / Managers Office				
MO - 05	Drywall with Joint Compound & Orange Peel Texture / Managers Office				
MO - 06	Orange Peel Texture / Managers Office				
MO - 07	Cream Sheet Vinyl / Secondary Bathroom				
MO - 08	Cream Sheet Vinyl / Secondary Bathroom				
201 - 01	Wood Pattern Sheet Vinyl over Pebble Pattern Sheet Vinyl / Kitchen				
201 - 02	Wood Pattern Sheet Vinyl over Pebble Pattern Sheet Vinyl / Kitchen				

Relinquished by	Date	Time	Received by	Date	Time
JH	8/29/24	3pm	EDR	8/30/24	10:00 a.m.

If no technician is provided, then the primary contact for your account will be selected. Unless scheduled, the turnaround time for all samples received after 3 pm EST will be logged in the next business day. Weekend or holiday work must be scheduled ahead of time and is charged at 150% of the 3hr TAT or a minimum charge of \$150. A courier charge will be applied for same day and one-day turnaround times for offsite work. SanAir covers Ground and Next Day Air shipping. Shipments billed to SanAir with a faster shipping rate will result in additional charges.

CERTIFICATION

AHERA

CERTIFICATE

This is to certify that

Jason Hawks

has attended and satisfactorily completed all requirements to maintain accreditation as an AHERA Building Inspector in accordance with the Toxic Substance Control Act Title (Section 206) and 40 CFR 763.

Accreditation No. BI/R-NES-12-01-23-07

Course Date: December 1st, 2023

Valid through: December 1st 2024



NOW Environmental Services, Inc.
34004 – 9th Avenue South, Suite # 12
Federal Way, Washington 98003
(253) 927-5233