



11815 NE 99th Street, Suite 1294
Vancouver, WA 98662
Voice: 360-574-3058
Fax: 360-576-0925
Web: <https://www.swcleanair.gov>
Email: Tina@swcleanair.gov

Notice of Intent to Remove Asbestos

Case #: 24-666

Amendment: 0

Date Received: 9/26/2024

Date Paid: 9/26/2024

SWCAA Fee: \$0.00

Receipt #:

This notification MUST be present at all times at the asbestos project sit

*** EMERGENCY NOTICE ***

Quantity to be removed: 12 Square Feet 0 Linear Feet

Workshift days: Th

Project starting date: 9/26/2024 Project Completion date: 9/26/2024

Workshift hours: 12:30pm-4:30PM

Site Name: Martha Weeks phase 2

Site address: 100 NE 107th St

Location of Asbestos: bathroom 2

City/State/Zip: Vancouver

WA 98685

☐ Demolition of Structure (Notification of Demolition required)

County: CLARK COUNTY

☒ Asbestos survey conducted?

No survey reason:

AHERA Inspector: Nick Kateley

Certification #: IR-22-8916B

Material to be Removed:

☐ Fireproofing ☐ Popcorn Ceiling ☐ CAB ☐ Sheet Vinyl ☐ Boiler Insulation ☐ Duct Tape

☐ Duct Paper ☐ Mag Pipe Insulation ☐ Air Cell ☐ CA Pipe ☐ VAT

☒ Other Drywall

Control Methods:

☒ N.P Enclosure ☐ Glove Bag ☐ Mini Enclosure ☐ Wrap and Cut ☒ Water ☒ HEPA Vac

☐ Other

Asbestos Contractor: Abatement Services of Washington

Phone: 503-765-5257

Mailing Address: PO Box 747, Beaver Creek, OR, 97004

Email: tristan@abateservices.com

Certification ##: ABCN00001610

Supervisor: Yessica Grgeorio

Phone: 971-287-1419

Property Owner: Martha Weeks phase 2

Phone: 360-608-6862

Mailing Address: 100 NE 107th St, Vancouver WA 98685

Asbestos Disposal Site: Hillsboro Landfill: 3205 SE Minter Bridge Rd, Hillsboro, OR, 97123-

**I DO HEREBY CERTIFY THAT THE INFORMATION CONTAINED IN THIS NOTIFICATION IS,
TO THE BEST OF MY KNOWLEDGE, ACCURATE AND COMPLETE.**

Submitter Name: Ashley Morales

Representing: Asi

Submitter Title:

Date Submitted: 9/26/2024

Reviewed by SWCAA: Brian Fallon

☒ Approved



11815 NE 99th Street, Suite 1294
Vancouver, WA 98662
Voice: 360-574-3058
Fax: 360-576-0925
Web: <https://www.swcleanair.gov>
Email: Tina@swcleanair.gov

Notice of Intent to Remove Asbestos

Case #: 24-666

Amendment: 0

Date Received: 9/26/2024

Date Paid: 9/26/2024

SWCAA Fee: \$0.00

Receipt #:

This notification MUST be present at all times at the asbestos project sit



Limited Asbestos Survey Report

Owner/Operator Name:

Eagle Restoration

Owner/Operator Number:

503-785-9824

Limited Survey Date:

8/13/24

Survey Address:

100 NE 107th St.
Vancouver WA 98685

Survey Location:

Interior Living Room, Bedroom1, Bedroom2, & Bathroom

What is the building's description?

Residence

What is this structure's current use?

Residential

What is this structure's past use?

Residential

Building Square Footage:

1110

Number of Floors:

2



Area Surveyed:

Living Room Wall, Bedroom 1 Wall (flooring homogenous with bedroom 2), Hallway Wall & Floor, Bathroom Wall & Floor, Bedroom 2 Wall & Floor.

Approximate Build Date:

1961

Purpose of the Survey:

Remediation due to damages.

Survey Limitations: Samples are collected based on a visual inspection of the work area as defined in the analysis report. Samples were collected from accessible, representative construction materials, which were suspected to contain asbestos. If additional materials are found during the demolition process that were inaccessible at time of inspection that are not listed in this report please have materials tested before they are impacted. Survey is subject to direction from contractor, homeowner or owners agent.


completed attached analysis report.

**Please see the*

Recommended Response Action Plan:**Contact a Licensed Abatement Contractor or OREGON DEQ**

The Oregon Department of Environmental Quality regulates the handling, removal and disposal of asbestos-containing material to protect public health and the environment.
<https://www.oregon.gov/deq/Hazards-and-Cleanup/Pages/Asbestos-Information.aspx>




A copy of this survey report must be kept onsite during any remediation, renovation or demolition activities, as required by Oregon DEQ OAR 340-248-027(2).



Name / Company Name: Eagle Restoration	Phone:
Contact Email:	
Job Name: Mrths Weeks	Job/Project:
Address/Project Location: 100 NE 107th St. Vancouver WA 98685	

	Asbestos PLM
	Lead Paint
	Other

[illegible]

Client Sign Here: 		Date: 8/14/24	Time:
Atlas: Accepted By: Kathy Katona		Date: 8.14.2024	Time: 10:
Credit Card:	Cash:	Check #	Amount: \$
Lab Results Completed By: 		Date Sent Out: 8-14-2024	Email/Mail 

*Atlas charges a per sample fee and not by layer. One sample fee equals four layers. Additional layers will result in an additional sample fee.



Batch # 2022 *

22-1499901

Analysis Date *

08/14/2024

Project #

Name / Company *

Eagle Restoration

Project Name

Martha Weekes

PO #

Analyst *

Dillon Lafever

Project Location *

100 NE 107th St.,
Vancouver, WA 98685

Turnaround Time *

Rush

Asbestos Analysis of Bulk Material by Polarized Light Microscopy

Sample*	Layer*	Description*	Non Asbestos*	Asbestos Type*	Asbestos %*
1	1	Vinyl (Beige) - Bathroom Floor	Cellulose	None Present	N/D
1	2	Mastic (Tan) - Bathroom Floor	Cellulose	None Present	N/D
1	3	Leveling Compound (Grey) - Bathroom Floor	Cellulose	None Present	N/D
2	1	VCT (Tan / Brown / Green) - Bedroom 2 Floor	Cellulose	Chrysotile	3%
2	2	Mastic (Black) - Bedroom 2 Floor	Cellulose	Chrysotile	2%
2	3	Leveling Compound (Grey) - Bedroom 2 Floor	Cellulose	Chrysotile	<1%

To Be Filled by the Technician

Technician *

A handwritten signature in black ink, consisting of a stylized, cursive 'A' followed by a long, sweeping horizontal line that tapers to the right.

Atlas Laboratories maintains liability to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full without written permission by Atlas. Atlas bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval or endorsement by NVLAP, NIST, NIOSH or any other agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore Atlas recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Transmission Electron Microscopy asbestos identification and lead paint analysis will be available and performed by laboratories by proxy. Original analysis documents are available upon request of the client.

THIS IS TO CERTIFY THAT

NICHOLAS KATELEY

HAS SUCCESSFULLY COMPLETED THE TRAINING COURSE

for

ONLINE AHERA ASBESTOS INSPECTOR REFRESHER

In accordance with TSCA Title II, Part 763, Subpart E, Appendix C of 40 CFR

Course Date: 06/18/2024

Course Location: Online

Certificate: IRO-24-9353B



CCB #SRA0615 4-Hr Training

4-Hour Online AHERA Inspector Refresher Training; AHERA is the Asbestos Hazard Emergency Response Act enacting Title II of Toxic Substance Control Act (TSCA)

Expiration Date: 06/18/2025

For verification of the authenticity of this certificate contact:
PBS Engineering and Environmental Inc.
4412 S Corbett Avenue
Portland, OR 97239
503.248.1939

A handwritten signature in black ink, reading "Andy Fridley", is written over a horizontal line.

Andy Fridley, Instructor

Name / Company Name:	martha weeks	Phone:	503 - 785 - 9824
Contact Email:	accounting@eaglecrestorationpx.com		
Job Name:		Job/Project:	
Address/Project Location:	100 NE 107th St, Vancouver, WA, 98685		

Please check box that applies

<input checked="" type="checkbox"/>	Rush	*Samples turned in by 2PM will be processed the same day	<input checked="" type="checkbox"/>	Asbestos PLM
<input type="checkbox"/>	Next Day		<input checked="" type="checkbox"/>	Lead Paint
<input type="checkbox"/>	2-Day		<input type="checkbox"/>	Other
<input type="checkbox"/>	5-Day			

[illegible]

Special Instructions:

Client Sign Here: <i>[Signature]</i>		Date: 8/13/2024	Time: 9:51 am
Atlas: Accepted By: <i>[Signature]</i>		Date: 8/13/24	Time: 10am
Credit Card:	Cash:	Check #	Amount: \$
Lab Results Completed By: <i>[Signature]</i>		Date Sent Out: 8/13/2024	Email/Mail

*Atlas charges a per sample fee and not by layer. One sample fee equals four layers. Additional layers will result in an additional sample fee.



Batch # 2022 *

22-1496901

Analysis Date *

08/13/2024

Project #

Name / Company *

Eagle Restoration

Project Name

Martha Weeks

PO #

Analyst *

Dillon Lafever

Project Location *

100 NE 107th St.,
Vancouver, WA 98685

Turnaround Time *

Rush

Asbestos Analysis of Bulk Material by Polarized Light Microscopy

Sample*	Layer*	Description*	Non Asbestos*	Asbestos Type*	Asbestos %*
001	1	Drywall (White) - Living Room Wall	Cellulose / Fiberglass	None Present	N/D
001	2	Texture (White) - Living Room Wall	Cellulose	Chrysotile	2%
001	3	Joint Compound (White) - Living Room Wall	Cellulose	Chrysotile	2%
002	1	Drywall (White) - Hallway Wall	Cellulose / Fiberglass	None Present	N/D
002	2	Texture (White) - Hallway Wall	Cellulose	Chrysotile	2%
002	3	Joint Compound (White) - Hallway Wall	Cellulose	Chrysotile	2%
003	1	VCT (Brown) - Hallway Floor	Cellulose	Chrysotile	3%
003	2	Mastic (Black) - Hallway Floor	Cellulose	Chrysotile	2%
004	1	Drywall (White) - Bathroom Wall	Cellulose / Fiberglass	None Present	N/D
004	2	Texture (White) - Bathroom Wall	Cellulose	Chrysotile	2%
004	3	Joint Compound (White) - Bathroom Wall	Cellulose	Chrysotile	2%
004	4	Cove Base (Grey) - Bathroom Wall	Cellulose	None Present	N/D
004	5	Mastic (Yellow) - Bathroom Wall	Cellulose	None Present	N/D

Sample*	Layer*	Description*	Non Asbestos*	Asbestos Type*	Asbestos %*
005	1	Drywall (White) - Bedroom 1 Wall	Cellulose / Fiberglass	None Present	N/D
005	2	Texture (White) - Bedroom 1 Wall	Cellulose	Chrysotile	2%
005	3	Joint Compound (White) - Bedroom 1 Wall	Cellulose	Chrysotile	2%
006	1	Drywall (White) - Bedroom 2 Wall	Cellulose / Fiberglass	None Present	N/D
006	2	Texture (White) - Bedroom 2 Wall	Cellulose	Chrysotile	2%
006	3	Joint Compound (White) - Bedroom 2 Wall	Cellulose	Chrysotile	2%

To Be Filled by the Technician

Technician *



Atlas Laboratories maintains liability to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full without written permission by Atlas. Atlas bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval or endorsement by NVLAP, NIST, NIOSH or any other agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore Atlas recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Transmission Electron Microscopy asbestos identification and lead paint analysis will be available and performed by laboratories by proxy. Original analysis documents are available upon request of the client.



SanAir ID Number

24045267

FINAL REPORT

8/14/2024 4:10:50 PM

Name: Atlas Labs, Inc.

Address: 14795 SW 72nd Ave. Suite B

Portland, OR 97224

Phone: 360-852-8936

Project Number: 100 NE 107th St.

P.O. Number:

Project Name: Eagle Restoration - Martha Weeks

Collected Date: 8/13/2024

Received Date: 8/14/2024 10:25:00 AM

Analyst: Rivera, Shirley

Test Method: SW846/M3050B/7000B

Lead Paint Analysis

PAINT Sample	Description	$\mu\text{g Pb}$ In Sample	Sample Size (grams)	Calculated RL	Sample Results	Sample Results
24045267 - 1	001 Paint - Living Room Wall	< 10	0.1007	99.3	<99.3 $\mu\text{g/g (ppm)}$	<0.010 % By Weight
24045267 - 2	002 Paint - Hallway Wall	< 10	0.1133	88.3	<88.3 $\mu\text{g/g (ppm)}$	<0.009 % By Weight
24045267 - 3	004 Paint - Bathroom Wall	36	0.1117	89.5	321.7 $\mu\text{g/g (ppm)}$	0.032 % By Weight
24045267 - 4	005 Paint - Bedroom 1 Wall	266	0.1223	81.8	2171 $\mu\text{g/g (ppm)}$	0.217 % By Weight
24045267 - 5	006 Paint - Bedroom 2 Wall	42	0.1053	95	401.3 $\mu\text{g/g (ppm)}$	0.040 % By Weight

Method Reporting Limit <10 $\mu\text{g}/0.1\text{ g}$ paint

All samples contained substrate

Signature: 

Date: 8/14/2024

Reviewed: 

Date: 8/14/2024

THIS IS TO CERTIFY THAT

DMITRI DUERR

HAS SUCCESSFULLY COMPLETED THE TRAINING COURSE

for

ONLINE AHERA ASBESTOS INSPECTOR REFRESHER

In accordance with TSCA Title II, Part 763, Subpart E, Appendix C of 40 CFR

Course Date: 05/02/2024

Course Location: Online

Certificate: IRO-24-8208B



CCB #SRA0615 4-Hr Training

4-Hour Online AHERA Inspector Refresher Training; AHERA is the Asbestos Hazard Emergency Response Act enacting Title II of Toxic Substance Control Act (TSCA)

Expiration Date: 05/02/2025

For verification of the authenticity of this certificate contact:
PBS Engineering and Environmental Inc.
4412 S Corbett Avenue
Portland, OR 97239
503.248.1939

A handwritten signature in black ink, appearing to read 'Andy Fridley', is written over a horizontal line.

Andy Fridley, Instructor