

### **Notice of Intent to Remove Asbestos**

Case #: 24-676

11815 NE 99th Street, Suite 1294

Vancouver, WA 98662 Voice: 360-574-3058 Fax: 360-576-0925

Web: https://www.swcleanair.gov Email: Tina@swcleanair.gov

Reviewed by SWCAA: Mihai Voivod

Date Received: 10/2/2024

Amendment: 0

Date Paid:

SWCAA Fee:

10/2/2024

Approved

\$0.00

This notification MUST be present at all times at the asbestos project sit

Receipt #:

Quantity to be removed: 16 Square Feet	0 Linear Feet	Workshift days:	Th
Project starting date: 10/3/2024 Project Comp	oletion date: 10/3/2024	Workshift hours:	12-4
Site Name: W353_ServproEWCC_11904NeMaj	Site address: 11	904 NE Major St. Vancou	ıver WA 98684
Location of Asbestos: Hallway/dining room	City/State/Zip: Va	ncouver	WA 98684
☐ Demolition of Structure (Notification of Demolition	required)	County: CLARK COUNTY	(
✓ Asbestos survey conducted? No sur	vey reason:		
AHERA Inspector: Dalton LaFever		Certification #: IRO-24	1-0908C
Material to be Removed:  ☐ Fireproofing ☐ Popcorn Ceiling ☐ CAB ☐ Duct Paper ☐ Mag Pipe Insulation ☐ Other Texture  Control Methods: ☐ N.P Enclosure ☐ Glove Bag ☐ Mini Enclose	☐ Sheet Vinyl ☐ Air Cell  Sure ☐ Wrap and Cut	<ul><li>□ Boiler Insulation</li><li>□ CA Pipe</li><li>✓ Water</li></ul>	☐ Duct Tape ☐ VAT  ✓ HEPA Vac
✓ Other 6-Mil Poly, Wet, Labeled	'		
Asbestos Contractor: Alpine Abatement Associates Inc Mailing Address: PO Box 1557, Bend, OR, 97709 Certification ##: ABCN00001215 Supervisor: Jose Vera		Phone: 541-388-2672  Email: annmarie@alpir  e: 541-388-2672	neabatement.con
Property Owner: Shirly Neet	Phon	e: 509-818-9399	
Mailing Address: 11904 NE Major St., Vancouver W	VA 98684		

I DO HEREBY CERTIFY THAT THE INFORMATION CONTAINED IN THIS NOTIFICATION IS TO THE BEST OF MY KNOWLEDGE, ACCURATE AND COMPLETE.

<b>Submitter Name:</b>	Bo Davidson	Representing:	Alpine Abatement
Submitter Title:	VP Operations	Date Submitted:	10/2/2024



## **Notice of Intent to Remove Asbestos**

Case #: 24-676

11815 NE 99th Street, Suite 1294 Vancouver, WA 98662

Voice: 360-574-3058 Fax: 360-576-0925

Web: https://www.swcleanair.gov Email: Tina@swcleanair.gov Date Received: 10/2/2024

Amendment: 0

Date Paid: 10/2/2024

SWCAA Fee: \$0.00

This notification MUST be present at all times at the asbestos project sit

Receipt #:



## **Limited Asbestos Survey Report**

Owner/Operator Name: ServPro of Vancouver
Owner/Operator Number: (360) 254-0049
Limited Survey Date: 09/11/2024
Survey Address: 11904 NE Major St, Vancouver, WA 98684
Survey Location: Interior Dining Room & Hallway
What is the building's description? Residence
What is this structure's current use? Residential Home
What is this structure's past use? Residential Home
Building Square Footage: 1,344'
Number of Floors:



#### Area Surveyed:

Interior Dining Room Ceiling, Floor, and Wall(s). Hallway Wall(s).

#### **Approximate Build Date:**

1969

#### **Purpose of the Survey:**

Remediation due to damages.

**Survey Limitations:** Samples are collected based on a visual inspection of the work area as defined in the analysis report. Samples were collected from accessible, representative construction materials, which were suspected to contain asbestos. If additional materials are found during the demolition process that were inaccessible at time of inspection that are not listed in this report please have materials tested before they are impacted. Survey is subject to direction from the contractor, homeowner or owners agent.

# Asbestos Containing Building Material Identified During Survey: \*Please see the completed attached analysis report.

Sample #	Location	Asbestos Containing Material	Description (Color, Texture &	Asbestos % & Asbestiform	Approx. Sq. Footage	Friable Y/N	Condition
1-A	Dining	Donoorn	Pattern) White	15%	90'	Y	Good
Layer 2	Dining Room Ceiling	Popcorn Texture	vviile	Chrysotile	90	ī	Good
1-B	Dining	Popcorn	White	15%	-	Υ	Good
Layer 2	Room Ceiling	Texture		Chrysotile			
1-C	Dining	Popcorn	White	15%	-	Υ	Good
Layer 2	Room Ceiling	Texture		Chrysotile			
3-A	Hallway	Texture	Tan	3%	6 LF	Υ	Good
Layer 3	Wall			Chrysotile			
4-C	Dining	2nd Layer	Tan	3%	15'	Υ	Good
Layer 4	Room Wall	Texture		Chrysotile			



#### **Recommended Response Action Plan:**

#### **Contact a Licensed Abatement Contractor or SW Clean Air Agency**

Sw Clean Air Agency regulates the handling, removal and disposal of asbestos-containing material to protect public health and the environment. <a href="https://www.lni.wa.gov/licensing-permits/other-licenses-permits/asbestos-certification#certified-contractors-list">https://www.lni.wa.gov/licensing-permits/other-licenses-permits/asbestos-certification#certified-contractors-list</a>. For more information on asbestos removal, please refer to <a href="https://www.asbestos-certification#certified-contractors-list">SWCAA 476-050</a>. If you have any questions, please contact us at 360-574-3058

A copy of this survey report must be kept onsite during any remediation, renovation or demolition activities, as required by Southwest Clean Air Agency.

#### **Surveyed Performed By:**

Dalton Lafever
Of
Atlas Labs Inc.
Environmental Testing Services
Dalton@atlaslabinc.com

(503) 430-4112 AHERA Cert #: IRO-24-0908C CCB #: 231684



Atlas Laboratories Inc. 14795 SW 72nd Ave, STE B Portland, OR 97224 (503) 430-5290 www.atlaslabsinc.com CCB #231684



Limited Survey Chain of Custody

	LIII	inted Survey Chain	or Custody			
Nam	e / Company Name: ServPro of Vanco	uver		Phone: (360)	254-0049	
Cont	act Email: ServproVancouver@comca	st.net				
Proje	ect Name: Neet Claim #4773C826F			Batch: 22	-155 28	01
Job/	Project Address: 11904 NE Major St, V	ancouver, WA 98684				
Insp	ector: Dalton Lafever Ph: (503) 430-4112	2 AHERA Cert. # IRO-24-	0908C Lead RRP (	Cert. # R-I-41R	036-22-00070	
Surv	ey Area Use: Residential App	prox. Year Built: 1969	Reason for	Survey: Rem	ediation	
X	Rush Next Day 2-Day 5-Day		X Asbestos X Lead Paint Other			
#	Material Description	Friable Y/N	Loca	tion	Condition	Approx. SQ FT.
1-A	Drywall (Popcorn Texture)	Υ	Dining Roo	Dining Room Ceiling		90'
	Drywall (Popcorn Texture)	Y	Dining Roo	Dining Room Ceiling		-
1-C	Drywall (Popcorn Texture)	Y	Dining Roo	Dining Room Ceiling		-
2-A	Vinyl	Y	Dining Ro	Dining Room Floor		90'
3-A	Cove Base Mastic	N	Hallway Wall		Good	6 LF
4-A	Drywall	Υ	Dining Ro	om Wall	Good	15'
4-B	Drywall	Υ	Dining Ro	om Wall	Good	-
4-C	Drywall	Y	Dining Ro	Dining Room Wall		-
Pb-1 Note	Paint - Interior Base on Dining Rooms:	Ceiling				
Insp	ector Signature: Dullon	Luter	Date: 9///	1/24	Time: 2	24
Acce	epted By:		Date: 9/11	24	Time: 2:1	llopm
Lab	Results Completed By:		Date Sent Out:	7/11/24	Email	/ Mail
	tations of Inspection: Atlas Labs Inc. AHER					

limited to areas defined on the Chain of Custody form.

General NESHAPS Bulk Sampling Guidelines: Material sampling areas were grouped based on homogenous materials. A homogeneous area is one which contains material that seems by texture, color and surface wear to be uniform and applied during the same general time period. Samples are collected based on a visual survey of the work area as defined in this report. Samples were collected from accessible, representative construction materials, which were suspected to contain asbestos. If additional materials are found during the demolition process that were inaccessible at time of inspection that are not listed in this report please test before you cut. Survey is subject to direction from contractor, homeowner or owners agent.



Approx. SQ FT.

#	Material Description	Friable Y/N	Location	Condition	FI.
0-2	Paint - Interior Base on Dining Room Wall				
	J				
_					
_					
_					
-					
_					
-	The state of the s				
-					
	al Instructions:				

# Atlas Labs

Batch # 2022 \* Name / Company \*

22-1552801 ServPro of Vancouver

Analysis Date \* Project Name

09/11/2024 Neet

Project # PO #

Claim #4773C826F

Analyst \* Project Location \*

Crossland Kapaun 11904 NE Major St., Vancouver, WA 98684

Turnaround Time \*

Rush

#### Asbestos Analysis of Bulk Material by Polarized Light Microscopy

Sample*	Layer*	Description*	Non Asbestos*	Asbestos Type*	Asbestos %*
1-A	1	Drywall (White) - Dining Room Ceiling	Cellulose	None Present	N/D
1-A	2	Popcorn Texture (White) - Dining Room Ceiling	Cellulose	Chrysotile	15%
1-B	1	Drywall (White) - Dining Room Ceiling	Cellulose	None Present	N/D
1-B	2	Popcorn Texture (White) - Dining Room Ceiling	Cellulose	Chrysotile	15%
1-C	1	Drywall (White) - Dining Room Ceiling	Cellulose	None Present	N/D
1-C	2	Popcorn Texture (White) - Dining Room Ceiling	Cellulose	Chrysotile	15%
2-A	1	Vinyl (Grey) - Dining Room Floor	Cellulose	None Present	N/D
2-A	2	Mastic (White) - Dining Room Floor	Cellulose	None Present	N/D
3-A	1	Cove Base Mastic (Yellow) - Hallway Wall	Cellulose	None Present	N/D
3-A	2	Drywall (White) - Hallway Wall	Cellulose	None Present	N/D
3-A	3	Texture (Tan) - Hallway Wall	Cellulose	Chrysotile	3%
4-A	1	Drywall (White) - Dining Room Wall	Cellulose	None Present	N/D
4-A	2	Texture (White) - Dining Room Wall	Cellulose	None Present	N/D
4-B	1	Drywall (White) - Dining Room Wall	Cellulose	None Present	N/D

Sample*	Layer*	Description*	Non Asbestos*	Asbestos Type*	Asbestos %*
4-B	2	Texture (White) - Dining Room Wall	Cellulose	None Present	N/D
4-C	1	Drywall (White) - Dining Room Wall	Cellulose	None Present	N/D
4-C	2	1st Layer Texture (White) - Dining Room Wall	Cellulose	None Present	N/D
4-C	3	Joint Compound (White) - Dining Room Wall	Fiberglass	None Present	N/D
4-C	4	2nd Layer Texture (Tan) - Dining Room Wall	Cellulose	Chrysotile	3%

#### To Be Filled by the Technician

Technician \*

مل

Atlas Laboratories maintains liability to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full without written permission by Atlas. Atlas bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval or endorsement by NVLAP, NIST, NIOSH or any other agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore Atlas recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Transmission Electron Microscopy asbestos identification and lead paint analysis will be available and performed by laboratories by proxy. Original analysis documents are available upon request of the client.