



Notice of Intent to Remove Asbestos

Case #: 24-827

Amendment: 0

11815 NE 99th Street, Suite 1294
Vancouver, WA 98662
Voice: 360-574-3058
Fax: 360-576-0925
Web: <https://www.swcleanair.gov>
Email: Tina@swcleanair.gov

Date Received: 12/5/2024

Date Paid: 12/5/2024

SWCAA Fee: \$294.00

Receipt #: 167227365

This notification MUST be present at all times at the asbestos project sit

***** EMERGENCY NOTICE *****

Quantity to be removed: 56 Square Feet 0 Linear Feet Workshift days: F

Project starting date: 12/6/2024 Project Completion date: 12/6/2024 Workshift hours: 8am - 4:30pm

Site Name: Farb Residence	Site address: 7603 NW Anderson Ave.
Location of Asbestos: Bathroom	City/State/Zip: Vancouver WA 98665
<input type="checkbox"/> Demolition of Structure (Notification of Demolition required)	County: CLARK COUNTY

Asbestos survey conducted? No survey reason:

AHERA Inspector: Dalton LaFever Certification #: IRO-24-0908C

Material to be Removed:

- Fireproofing Popcorn Ceiling CAB Sheet Vinyl Boiler Insulation Duct Tape
- Duct Paper Mag Pipe Insulation Air Cell CA Pipe VAT
- Other Drywall texture

Control Methods:

- N.P Enclosure Glove Bag Mini Enclosure Wrap and Cut Water HEPA Vac
- Other

Asbestos Contractor: Environmental Resources Inc - ABCN0001664 Phone: 503-930-8996
 Mailing Address: PO BOX 5954, Salem, OR, 97304 Email: admin@enviroresinc.com
 Certification ##:
 Supervisor: Esbanyeli Zazueta Phone: 503-705-7097

Property Owner: Jeffery Farb Phone: 503-867-9781
 Mailing Address: 7603 NW Anderson Ave, Van WA 98665

Asbestos Disposal Site: Hillsboro Landfill: 3205 SE Minter Bridge Rd, Hillsboro, OR, 97123-

I DO HEREBY CERTIFY THAT THE INFORMATION CONTAINED IN THIS NOTIFICATION IS, TO THE BEST OF MY KNOWLEDGE, ACCURATE AND COMPLETE.

Submitter Name: Andy Dellaripa **Representing:** ERI

Submitter Title: Project Manager **Date Submitted:** 12/5/2024

Reviewed by SWCAA: Mihai Voivod Approved



11815 NE 99th Street, Suite 1294
Vancouver, WA 98662
Voice: 360-574-3058
Fax: 360-576-0925
Web: <https://www.swcleanair.gov>
Email: Tina@swcleanair.gov

Notice of Intent to Remove Asbestos

Case #: 24-827

Amendment: 0

Date Received: 12/5/2024

Date Paid: 12/5/2024

SWCAA Fee: \$294.00

Receipt #: 167227365

This notification MUST be present at all times at the asbestos project sit

Limited Asbestos Survey Report

Owner/Operator Name:

Roto-Rooter

Owner/Operator Number:

(971) 286-8452

Limited Survey Date:

11/18/24

Survey Address:

7603 NW Anderson Ave, Vancouver, WA 98665

Survey Location:

Interior Bathroom & Bedroom

What is the building's description?

Residence

What is this structure's current use?

Residential Home

What is this structure's past use?

Residential Home

Building Square Footage:

2,488'

Number of Floors:

2

Area Surveyed:

Interior Bathroom Wall(s) and Flooring, Bedroom Wall and Flooring

Approximate Build Date:

1961

Purpose of the Survey:

Remediation due to damages.

Survey Limitations: Samples are collected based on a visual inspection of the work area as defined in the analysis report. Samples were collected from accessible, representative construction materials, which were suspected to contain asbestos. If additional materials are found during the demolition process that were inaccessible at time of inspection that are not listed in this report please have materials tested before they are impacted. Survey is subject to direction from contractor, homeowner or owners agent.

Asbestos Containing Building Material Identified During Survey: **Please see the completed attached analysis report.*

Sample #	Location	Asbestos Containing Material	Description (Color, Texture & Pattern)	Asbestos % & Asbestiform	Approx. Sq. Footage	Friable Y/N	Condition
1-B Layer 2	Downstairs Bathroom Wall	Texture	Tan	2% Chrysotile	100'	Y	Good
3-A Layer 4	Downstairs Bathroom Wall	Texture	Tan	2% Chrysotile	25 LF	N	Good

Recommended Response Action Plan:

Contact a Licensed Abatement Contractor or OREGON DEQ

The Oregon Department of Environmental Quality regulates the handling, removal and disposal of asbestos-containing material to protect public health and the environment. <https://www.oregon.gov/deq/Hazards-and-Cleanup/Pages/Asbestos-Information.aspx>

A copy of this survey report must be kept onsite during any remediation, renovation or demolition activities, as required by Oregon DEQ OAR 340-248-027(2).

Surveyed Performed By:

Dalton Lafever
Of
Atlas Labs Inc.
Environmental Testing Services
Dalton@atlaslabinc.com
(503) 430-4112
AHERA Cert #: IRO-24-0908C
CCB #: 231684



Atlas Laboratories Inc.
 14795 SW 72nd Ave, STE B Portland, OR 97224
 (503) 430-5290 www.atlaslabsinc.com
 CCB #231684



Limited Survey Chain of Custody

Name / Company Name: Roto-Rooter		Phone: (971) 286-8452
Contact Email: bryan.becker@rrsc.com, justin.cvitkovich@rrsc.com, Abenz@rrsc.com		
Project Name: Jeffrey Farb		Batch: 22-1671501
Job/Project Address: 7603 NW Anderson Ave, Vancouver, WA 98665		
Inspector: Dalton Lafever Ph: (503) 430-4112 AHERA Cert. # IRO-24-0908C Lead RRP Cert. # R-I-41R036-22-00070		
Survey Area Use: Residential	Approx. Year Built: 1961	Reason for Survey: Remediation

<input checked="" type="checkbox"/> Rush	<input checked="" type="checkbox"/> Asbestos PLM
<input type="checkbox"/> Next Day	<input type="checkbox"/> Lead Paint
<input type="checkbox"/> 2-Day	<input type="checkbox"/> Other
<input type="checkbox"/> 5-Day	

#	Material Description	Friable Y/N	Location	Condition	Approx. SQ FT.
1-A	Drywall	Y	Downstairs Bathroom Wall	Good	100'
1-B	Drywall	Y	Downstairs Bathroom Wall	Good	-
1-C	Drywall	Y	Downstairs Bedroom Wall	Good	-
2-A	Tile	N	Downstairs Bathroom Floor	Good	45'
3-A	Cove Base Mastic	N	Downstairs Bathroom Wall	Good	25 LF
4-A	Vinyl	Y	Downstairs Bedroom Floor	Good	120'

Notes:

Inspector Signature: <i>Dalton Lafever</i>	Date: 11/18/24	Time: 10:50
Accepted By: <i>[Signature]</i>	Date: 11/18/24	Time: 11am
Lab Results Completed By: <i>[Signature]</i>	Date Sent Out: 11/18/24	Email / Mail

Limitations of Inspection: Atlas Labs Inc. AHERA certified inspector performed a limited survey at the site, date, time and cause as stated above in this document along with lab analysis of possible asbestos and/or lead containing material. Atlas Labs Inc. survey is limited to areas defined on the Chain of Custody form.

General NESHAPS Bulk Sampling Guidelines: Material sampling areas were grouped based on homogenous materials. A homogeneous area is one which contains material that seems by texture, color and surface wear to be uniform and applied during the same general time period. Samples are collected based on a visual survey of the work area as defined in this report. Samples were collected from accessible, representative construction materials, which were suspected to contain asbestos. If additional materials are found during the demolition process that were inaccessible at time of inspection that are not listed in this report please test before you cut. Survey is subject to direction from contractor, homeowner or owners agent.



Batch # 2022 *

22-1671501

Analysis Date *

11/18/2024

Project #

Name / Company *

Roto-Rooter

Project Name

Jeffrey Farb

PO #

Analyst *

Crossland Kapoun

Project Location *

7603 NW Anderson Ave.,
Vancouver, WA 98665

Turnaround Time *

Rush

Asbestos Analysis of Bulk Material by Polarized Light Microscopy

Sample*	Layer*	Description*	Non Asbestos*	Asbestos Type*	Asbestos %*
1-A	1	Drywall (White) - Downstairs Bathroom Wall	Cellulose / Fiberglass	None Present	N/D
1-B	1	Drywall (White) - Downstairs Bathroom Wall	Cellulose / Fiberglass	None Present	N/D
1-B	2	Texture (Tan) - Downstairs Bathroom Wall	Cellulose	Chrysotile	2%
1-C	1	Drywall (White) - Downstairs Bedroom Wall	Cellulose / Fiberglass	None Present	N/D
1-C	2	Texture (White) - Downstairs Bedroom Wall	Cellulose	None Present	N/D
2-A	1	Tile (White) - Downstairs Bathroom Floor	None Present	None Present	N/D
2-A	2	Mortar (Grey) - Downstairs Bathroom Floor	Cellulose	None Present	N/D
2-A	3	Grout (Grey) - Downstairs Bathroom Floor	Cellulose	None Present	N/D
2-A	4	Mastic (Black) - Downstairs Bathroom Floor	Cellulose	None Present	N/D
3-A	1	Cove Base (White) - Downstairs Bathroom Wall	Cellulose	None Present	N/D

Sample*	Layer*	Description*	Non Asbestos*	Asbestos Type*	Asbestos %*
3-A	2	Mastic (Clear) - Downstairs Bathroom Wall	Cellulose	None Present	N/D
3-A	3	Mastic (Brown) - Downstairs Bathroom Wall	Cellulose	None Present	N/D
3-A	4	Texture (Tan) - Downstairs Bathroom Wall	Cellulose	Chrysotile	2%
4-A	1	Vinyl (White) - Downstairs Bedroom Floor	Cellulose / Fiberglass	None Present	N/D
4-A	2	Mastic (Yellow) - Downstairs Bedroom Floor	Cellulose	None Present	N/D
4-A	3	Carpet Pad (White) - Downstairs Bedroom Floor	Synthetic	None Present	N/D
4-A	4	Carpet Mastic (Yellow) - Downstairs Bedroom Floor	Cellulose	None Present	N/D

To Be Filled by the Technician
Technician *

Atlas Laboratories maintains liability to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full without written permission by Atlas. Atlas bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval or endorsement by NVLAP, NIST, NIOSH or any other agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore Atlas recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Transmission Electron Microscopy asbestos identification and lead paint analysis will be available and performed by laboratories by proxy. Original analysis documents are available upon request of the client.