Notice of Intent to Remove As Southwest Clean Air Agency Notice of Intent to Remove As Notice of Intent to Remove As Not	Date Received: Date Paid: SWCAA Fee: sit Receipt #: Workshift days: F Workshift hours: 104	12/12/2024 12/12/2024 \$294.00 16767567
Vancouver, WA 98662 Voice: 360-574-3058 Fax: 360-576-0925 Web: https://www.swcleanair.gov This notification MUST be present at all times at the asbestos project *** EMERGENCY NOTICE *** Quantity to be removed: 55 Square Feet O Linear Feet Project starting date: 12/13/2024 Project Completion date: 12/13/2024 Site Name: James Hayes Site address: 2333	Date Paid: SWCAA Fee: sit Receipt #: Workshift days: F Workshift hours: 104	12/12/2024 \$294.00 16767567
Fax: 360-576-0925 Web: https://www.swcleanair.gov This notification MUST be present at all times at the asbestos project *** EMERGENCY NOTICE *** Quantity to be removed: 55 Square Feet OLinear Feet Project starting date: 12/13/2024 Project Completion date: 12/13/2024 Site Name: James Hayes Site address: 2333	SWCAA Fee: sit Receipt #: Workshift days: F Workshift hours: 104	\$294.00 16767567
Email: Tina@swcleanair.gov   This notification MUST be present at all times at the asbestos project   *** EMERGENCY NOTICE ***   Quantity to be removed: 55   Site Name: James Hayes	sit Receipt #: Workshift days: F Workshift hours: 104	167675673
*** EMERGENCY NOTICE ***   Quantity to be removed: 55 Square Feet 0 Linear Feet   Project starting date: 12/13/2024 Project Completion date: 12/13/2024   Site Name: James Hayes Site address: 2333	Workshift days: F Workshift hours: 104	
Quantity to be removed: 55 Square Feet 0 Linear Feet   Project starting date: 12/13/2024 Project Completion date: 12/13/2024   Site Name: James Hayes Site address: 2333	Workshift hours: 10A	AM-2PM
Project starting date: 12/13/2024 Project Completion date: 12/13/2024   Site Name: James Hayes Site address: 2333	Workshift hours: 10A	AM-2PM
Site Name: James Hayes Site address: 2333		AM-2PM
	3 NW Galaxy St	
Location of Asbestos: Closet, garage City/State/Zip: Cam	as WA	98607
Demolition of Structure (Notification of Demolition required)	County: CLARK COUNTY	
Asbestos survey conducted? No survey reason:		
AHERA Inspector: Jamaica Caudle	Certification #: IRO-24-10	79C
Material to be Removed:   Fireproofing Popcorn Ceiling CAB Sheet Vinyl   Duct Paper Mag Pipe Insulation Air Cell		Duct Tape VAT
✓ Other Drywall		
Control Methods:   ✓ N.P Enclosure Glove Bag Mini Enclosure Wrap and Cut   Other	✔ Water ✔	HEPA Vac
Asbestos Contractor: Abatement Services of Washington Pl	hone: 503-765-5257	
	mail: tristan@abateservic	es.com
Certification ##: ABCN00001610	074 740 0056	
	971-710-8856	
	808-724-9979	
Mailing Address: 2333 NW Galaxy St,Camas WA 98607	07400	
Asbestos Disposal Site: Hillsboro Landfill: 3205 SE Minter Bridge Rd, Hillsboro, OR,	9/123-	

Submitter Name:	Ashley Morales	Representing:	Asi
Submitter Title:		Date Submitted	: 12/12/2024



## Notice of Intent to Remove Asbestos

Case #: 24-847 Amendment: 0

11815 NE 99th Street, Suite 1294 Vancouver, WA 98662	Date Received:	12/12/2024
Voice: 360-574-3058 Fax: 360-576-0925 Web: https://www.swcleanair.gov	Date Paid:	12/12/2024
Email: Tina@swcleanair.gov	SWCAA Fee:	\$294.00
This notification MUST be present at all times at the asbestos project sit	Receipt #:	167675671



### Limited Asbestos Survey Report

Owner/Operator Name: Robinson restoration

Owner/Operator Number: 3609472738

Limited Survey Date 11/29/2024

What is the structure's past use? Residential home.

**Building Square Footage: 1874** 

Survey Address: 2333 NW Galaxy St Camas, WA, 98607

Survey Location: garage and closet under stairs

What is the building's description? residential

What is this structure's current use? residential

Number of Floors: 2

Area Surveyed: garage and closet under stairs

**Approximate Build Date:1977** 

Purpose of the Survey: water damage

### Survey Limitations: only drywall

Robinson Restoration - 10616 NE 124th Ave Vancouver, WA 98682 - (360) 947-2738 - www.robinsonrestore.com

area as defined in the analysis report. Samples were collected from accessible, representative construction materials, which were suspected to contain asbestos. If additional materials are found during the demolition process that were inaccessible at the time of inspection that are not listed in this report, please have materials tested before they are impacted. Survey is subject to direction from contractor, homeowner or owners agent.

The Oregon Department of Environmental Quality regulates the handling, removal and disposal of asbestos-containing material to protect public health and the Environment.

https://www.oregon.gov/deq/Hazards-and-cleanup/pages/asbestos-information.as Px



# A copy of this survey report must be kept onsite during any remediation, renovation or demolition activities, as required by Oregon DEQ OAR 340-248-027(2).

Robinson Restoration - 10616 NE 124th Ave Vancouver, WA 98682 - (360) 947-2738 - www.robinsonrestore.com

Survey Performed By: ------ Jamaica Caudle ------Of Robinson Restoration, LLC. AHERA Cert# IRO-24-1079C\_\_\_\_\_ CCB#:\_\_\_\_\_SRA0615\_\_\_\_\_\_



Page 1 of 1

#### 9317 NE Hwy 99, Suite D, Vancouver, WA 98665 | 360-356-7628 Polarized Light Microscopy Results

Layers Analyzed 4 City, S			Property Address City, State, Zip Job Number	<b>p</b> Camas, WA, 98607			
Date Received Received By Date Analyzed Analyzed By		12/2/2024 Julie Walch 12/2/2024 Jonathan Gomes	Client Name Client Address City, State, Zip		Robinson Restoration   5900 NE 152nd Ave   Vancouver, WA   360-947-2738 info@robinsonrestore.com		
AEI Sample ID	Client Sample ID	Composition	Color/ Description	Asbestos (%)	Non-Asbestos Fiber (%)	Non Fibrous	
001	1	Layered	White Joint Compound	Asbestos Not Present	<1% Cellulose	CaCO3-Mica	
001A	Layered White Drywall Asbe		Asbestos Not Present	12% Cellulose 3% Glass Fibers	Gypsum		
002	2	Layered	Off-White Texture 2% Chrysotile <1% Cellulose (Wh		(White) Paint-CaCO3- Mica		
002A	002A Layered White D		White Drywall	Asbestos Not Present	15% Cellulose	Gypsum-Sand	

## Disclaimer

• EPA Method 600/M4-82-020 (1982) was used to determine the presence or absence of asbestos fibers in all materials referenced in the above report. PLM analysis is based on visual estimation, and due to limitations of PLM analysis NESHAP regulations recommend that any material determined to contain less than 10% asbestos by the above referenced method should either be assumed to contain greater than 1% asbestos by the owner/operator, or be verified by PLM Point Count or TEM analysis as containing less than 1% asbestos.

• We recommend that TEM analysis be conducted for confirmation of negative PLM analytical results of vinyl floor tiles and vermiculite. These materials may contain asbestos fibers that cannot be detected by PLM analysis due to their size (<0.25 microns in diameter)

• This report may not be used to represent any materials not analyzed and listed in the included report. Advantage Environmental Inc. cannot be held responsible for the interpretation of the results shown. This report may not be reproduced in part and may only be reproduced in full without prior written consent from Advantage Environmental Inc.



ADVANTAGE Environmental INC.

## ASBESTOS CHAIN OF CUSTODY

9317 NE Hwy 9D. Suite D = (360) 356-7628 LEGAL DOCUMENT - PLEASE PRINT LEGIBLY

L	ab Us	e Only	
Survey		Lab No.	147377
Walk-In	X	Accept	Reject

Sampled By - Please fill out yellow highlighted areas Project Information - Please fill out yellow highlighted areas									
Date		24			Project Name:	James	Hayes		
Nami	e/Company	Name: Robin	sonRestoration		Address (where m	James eterial was pulled irom) :	2333 NW	Galaxy.	st
Phon	e: 360 )	949 - 5574	/		City, State, Zip:	Camas, u	A 98607	7	-
Email	: James	S @ Robinso	n Restore, com		P.O. #:				
	RELIA	QUISHED BY	DATE & TIME		VIA	REC	CEIVED BY	Dr	TE & TIME
Name	Jamai	sa Coudle	Date 11/29/24	Dre	op Box	Aul	o la ale	l to	2-2
Sign	4 (	P	Time 8AM			0	4.000000	8	2-2 3.29 AM
	/			RI	QUESTED SERVIC	CES.			
(		PLM			TURN.	AROUND TIME - Plea	ise choose a turnarou	und theid	
		Bulk Analysi	S		Verbal	Rush	[_] Same Day	24-Hour	[_] 3-Daγs
No.	Sample ID	Color	De	escription		Volume / Area (as applicable)	Com	ments / Notes	
1	01		Garage -	DW1:	TC				
2	02		Garage - under stair	C-Dul	T/				
3				s vwj	JC	•			
4								an an an the second	
5									
6									
7									
8				e name and the second back to be a					
9									
10								a de la ferra de	
11									
1		1							



