



11815 NE 99th Street, Suite 1294  
Vancouver, WA 98662  
Voice: 360-574-3058  
Fax: 360-576-0925  
Web: <https://www.swcleanair.gov>  
Email: [Tina@swcleanair.gov](mailto:Tina@swcleanair.gov)

## Notice of Intent to Remove Asbestos

Case #: 24-848

Amendment: 0

Date Received: 12/12/2024

Date Paid: 12/12/2024

SWCAA Fee: \$294.00

Receipt #: 167676262

**This notification MUST be present at all times at the asbestos project sit**

### \*\*\* EMERGENCY NOTICE \*\*\*

Quantity to be removed: 83 Square Feet 0 Linear Feet

Workshift days: F

Project starting date: 12/13/2024 Project Completion date: 12/13/2024

Workshift hours: 8:30-2:30

Site Name: Park Side Apartments

Site address: 231 SW 11th St

Location of Asbestos: Kitchen

City/State/Zip: Chehalis

WA

98532

☐ Demolition of Structure (Notification of Demolition required)

County: LEWIS COUNTY

☒ Asbestos survey conducted?

No survey reason:

AHERA Inspector: Raymond Ware

Certification #: NES-BIR-20240715-04

#### Material to be Removed:

☐ Fireproofing

☐ Popcorn Ceiling

☐ CAB

☐ Sheet Vinyl

☐ Boiler Insulation

☐ Duct Tape

☐ Duct Paper

☐ Mag Pipe Insulation

☐ Air Cell

☐ CA Pipe

☐ VAT

☒ Other Wall Texture

#### Control Methods:

☒ N.P Enclosure

☒ Glove Bag

☐ Mini Enclosure

☐ Wrap and Cut

☒ Water

☒ HEPA Vac

☒ Other Manual Removal

Asbestos Contractor: Tacoma Abatement Company LLC

Phone: 253-830-5945

Mailing Address: 5111 S Burlington Way, Tacoma, WA, 98409

Email: [mgosselin@tacomaabatement.com](mailto:mgosselin@tacomaabatement.com)

Certification ##: ABCN00001532

Supervisor: matthew ware

Phone: 253-985-0165

Property Owner: SPL Properties LLC

Phone: 206-383-8233

Mailing Address: 7525 SE 24th St Suite 520, Mercer Island WA 98040

Asbestos Disposal Site: Land Recovery Inc - Hidden Valley Landfill: 17295 Meridian Street E, Puyallup, WA, 98373

**I DO HEREBY CERTIFY THAT THE INFORMATION CONTAINED IN THIS NOTIFICATION IS,  
TO THE BEST OF MY KNOWLEDGE, ACCURATE AND COMPLETE.**

Submitter Name: Matthew Ware

Representing: Tacoma Abatement Company

Submitter Title:

Date Submitted: 12/12/2024

Reviewed by SWCAA: Brian Fallon

☒ Approved



11815 NE 99th Street, Suite 1294  
Vancouver, WA 98662  
Voice: 360-574-3058  
Fax: 360-576-0925  
Web: <https://www.swcleanair.gov>  
Email: [Tina@swcleanair.gov](mailto:Tina@swcleanair.gov)

## Notice of Intent to Remove Asbestos

Case #: 24-848

Amendment: 0

Date Received: 12/12/2024

Date Paid: 12/12/2024

SWCAA Fee: \$294.00

Receipt #: 167676262

**This notification MUST be present at all times at the asbestos project sit**



30620 Pacific Hwy S, #103,  
Federal Way, WA 98003  
(253) 941-4343



Enclosed please find the analytical report for one or more samples submitted for analysis by Polarized Light Microscopy.

**The six types of asbestos fibers are chrysotile, amosite, crocidolite, tremolite, anthophyllite and actinolite. A sample which contains more than 1% asbestos is considered positive and is defined by the EPA as an Asbestos Containing Material (ACM).**

The samples were analyzed in accordance with EPA method 600/R-93/116 and 600/M4-82-020 which has a detection limit of approximately 1%. The analyst used a stereomicroscope to visually inspect the sample to determine homogeneity and material descriptions. The sample was then viewed under a polarized light microscope to determine the presence and percentage of asbestos and non-asbestos fibers.

After analysis is complete, all paperwork is filed together, and kept in a secure locked filing cabinet. Asbestos Northwest ensures that the files will not be tampered with at any time and will only be removed if the client requests reanalysis or a modification to the report. If you have any concerns or comments, contact us at [feedback@asbestosnw.com](mailto:feedback@asbestosnw.com) or fill out our survey at [asbestosnw.com/survey](http://asbestosnw.com/survey)

Thank you,

*Cathy Butler*

-These results are only applicable to the **samples enclosed** with information provided by the client. This report may not be reproduced, except in full, without the approval of the laboratory. This report may not be used to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the U.S. Government.-

Appt 6

# Bulk Sample Log / Chain of Custody

Client Company: **Tacoma Abatement Company, LLC**

Client Address: 3829 S. M St

Tacoma, WA 98418

Phone #: (253) 830-5945

Fax #:

LAB: Asbestos NW

LAB Job #: 202414712

# of Samples: \_\_\_\_\_

Job Name: 231 Project

Job Address: 231 SW 11th St Apt 6  
Chenails WA, 98532

## Type of Analysis (Check One)

### ASBESTOS

☐ PCM (air)

☐ Micro-vac

☒ PCM (bulk)

☐ Air (volume)

### LEAD

☐ Paint

☐ Soil

☐ Dust/Wipe (area)

☐ TCLP

☐ REGULAR ☒ RUSH 1 hour

Severe Damage (Spillage)

Condition of Package: Good Damaged (no spillage)

Lab ID	Sample ID	Type	Location
1		SC/TX	Kitchen
2		TX	"
3		TX	Closet
4		S.V.	Kitchen
5		S.V.	"
6		P.C.	"
7		P.C.	"
8		P.C.	L.R.
9			
10			
11			
12			
13			
14			
15			

Signature	Date	Time
Sampled By: <u>[Signature]</u>	11.2.24	
Delivered By: <u>[Signature]</u>	11.2.24	
Received By: <u>[Signature]</u>	12.3.24	9am
Analyzed By: <u>Dan Laffey</u>	12/3/24	9:25
Special: _____	ONLY if Sample # _____	is Greater Than .01f/cc



Asbestos Northwest, LLC  
30620 Pacific Hwy S, #103, Federal Way, WA 98003  
Ph: (253) 941-4343



**Batch Number: 202414712**

**PLM Analysis by EPA Method 600/M4-82-020 and 600/R-93/116**

This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the U.S. Government.

**Attn: Matt Ware**  
**Tacoma Abatement Company**  
**5111 S Burlington Way Tacoma WA 98409**

**Date Received: 12/3/2024**  
**Date Analyzed: 12/3/2024**  
**Samples Received: 8**  
**Samples Analyzed: 8**

**Project: 231 Project**  
**Location: 231 SW 11th St Apt 6 Chehalis WA 98532**

Client Sample ID	Lab Sample ID	Layer	Description	Matrix	% Non-Asbestos Fibers	% Asbestos Fibers and Type
1		1	White powdery material with paint and paper	Binder/filler, Paint	10% Cellulose	2% Chrysotile
		2	White chalky material with paper	Filler/binder, Gypsum	25% Cellulose	None Detected
2		1	White powdery material with paint and paper	Binder/filler, Paint	10% Cellulose	2% Chrysotile
		2	White chalky material with paper	Filler/binder, Gypsum	25% Cellulose	None Detected
3		1	White powdery material with paint	Binder/filler, Paint	2% Cellulose	None Detected
		2	White chalky material with paper	Filler/binder, Gypsum	25% Cellulose	None Detected
4		1	Tan mastic	Mastic/binder	8% Cellulose	None Detected
5		1	Beige sheet vinyl	Vinyl/binder	None Detected	None Detected
		2	Gray fibrous material with mastic	Filler, Mastic/binder	65% Cellulose, Glass fibers	None Detected
6		1	White soft/lumpy material with paint	Filler/binder, Paint	3% Cellulose	6% Chrysotile
7		1	White soft/lumpy material with paint	Filler/binder, Paint	3% Cellulose	6% Chrysotile
8		1	White soft/lumpy material with paint	Filler/binder, Paint	3% Cellulose	6% Chrysotile





30620 Pacific Hwy S, #103,  
Federal Way, WA 98003  
(253) 941-4343



Enclosed please find the analytical report for one or more samples submitted for analysis by Polarized Light Microscopy.

**The six types of asbestos fibers are chrysotile, amosite, crocidolite, tremolite, anthophyllite and actinolite. A sample which contains more than 1% asbestos is considered positive and is defined by the EPA as an Asbestos Containing Material (ACM).**

The samples were analyzed in accordance with EPA method 600/R-93/116 and 600/M4-82-020 which has a detection limit of approximately 1%. The analyst used a stereomicroscope to visually inspect the sample to determine homogeneity and material descriptions. The sample was then viewed under a polarized light microscope to determine the presence and percentage of asbestos and non-asbestos fibers.

After analysis is complete, all paperwork is filed together, and kept in a secure locked filing cabinet. Asbestos Northwest ensures that the files will not be tampered with at any time and will only be removed if the client requests reanalysis or a modification to the report. If you have any concerns or comments, contact us at [feedback@asbestosnw.com](mailto:feedback@asbestosnw.com) or fill out our survey at [asbestosnw.com/survey](http://asbestosnw.com/survey)

Thank you,

*Cathy Butler*

-These results are only applicable to the **samples enclosed** with information provided by the client. This report may not be reproduced, except in full, without the approval of the laboratory. This report may not be used to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the U.S. Government.-

Ap 7

# Bulk Sample Log / Chain of Custody

Client Company: **Tacoma Abatement Company, LLC**

Client Address: 3829 S. M St

Tacoma, WA 98418

Phone #: (253) 830-5945

Fax #:

LAB:

Asbestos NW

LAB Job #:

208414713

# of Samples:

Job Name:

231 Project

Job Address:

231 Southwest 11th St Apt 7  
Chehalis, WA 98532

Type of Analysis (Check One)

ASBESTOS

LEAD

☐ PCM (air)

☐ Paint

☐ Micro-vac

☐ Soil

☒ PCM (bulk)

☐ Dust/Wipe (area)

☐ Air (volume)

☐ TCLP

☐ REGULAR

☒ RUSH

1 hour

Severe Damage (Spillage)

Condition of Package:

Good

Damaged (no spillage)

Lab ID	Sample ID	Type	Location
1		JC / TX	Kitchen Closet
2		TX	to R. Kitchen
3		TX	closet Kitchen
4		SV	Kitchen
5		SV	"
6		PC	"
7		PC	"
8		PL	L.R.
9		tile/Mastic	
10			
11			
12			
13			
14			
15			

Signature

Date

Time

Sampled By:	<i>[Signature]</i>	12.2.24	
Delivered By:	<i>[Signature]</i>	12.2.24	
Received By:	<i>[Signature]</i>	12/3/24	9am
Analyzed By:	<i>[Signature]</i>	12/3	9:30am
Special:	Read Abatement Sample # _____ ONLY if Sample # _____ is Greater Than .01f/cc		



Asbestos Northwest, LLC  
30620 Pacific Hwy S, #103, Federal Way, WA 98003  
Ph: (253) 941-4343



**Batch Number: 202414713**

**PLM Analysis by EPA Method 600/M4-82-020 and 600/R-93/116**

This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the U.S. Government.

**Attn: Matt Ware**  
**Tacoma Abatement Company**  
**5111 S Burlington Way Tacoma WA 98409**

**Date Received: 12/3/2024**  
**Date Analyzed: 12/3/2024**  
**Samples Received: 9**  
**Samples Analyzed: 9**

**Project: 231 Project**  
**Location: 231 SW 11th St Apt 7 Chehalis WA 98532**

Client Sample ID	Lab Sample ID	Layer	Description	Matrix	% Non-Asbestos Fibers	% Asbestos Fibers and Type
1	1	1	White powdery material with paint	Binder/filler, Paint	5% Cellulose	3% Chrysotile
		2	White powdery material with paper	Filler/binder	15% Cellulose	3% Chrysotile
		3	White chalky material with paper	Filler/binder, Gypsum	25% Cellulose	None Detected
2	2	1	White chalky material with paint and paper	Filler/binder, Gypsum, Paint	25% Cellulose	None Detected
3	3	1	White powdery material with paint	Binder/filler, Paint	5% Cellulose	3% Chrysotile
4	4	1	Wood patterned sheet vinyl	Vinyl/binder	None Detected	None Detected
		2	Gray fibrous material with mastic	Filler, Mastic/binder	55% Cellulose	None Detected
5	5	1	Wood patterned sheet vinyl	Vinyl/binder	None Detected	None Detected
		2	Gray fibrous material with mastic	Filler, Mastic/binder	55% Cellulose	None Detected
6	6	1	White soft/lumpy material with paint	Filler/binder, Paint	7% Cellulose	5% Chrysotile
7	7	1	White soft/lumpy material with paint	Filler/binder, Paint	7% Cellulose	5% Chrysotile





Asbestos Northwest, LLC  
 30620 Pacific Hwy S, #103, Federal Way, WA 98003  
 Ph: (253) 941-4343



**Batch Number: 202414713**

**PLM Analysis by EPA Method 600/M4-82-020 and 600/R-93/116**

This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the U.S. Government.

**Attn: Matt Ware**  
**Tacoma Abatement Company**  
**5111 S Burlington Way Tacoma WA 98409**

**Date Received: 12/3/2024**  
**Date Analyzed: 12/3/2024**  
**Samples Received: 9**  
**Samples Analyzed: 9**

**Project: 231 Project**  
**Location: 231 SW 11th St Apt 7 Chehalis WA 98532**

Client Sample ID	Lab Sample ID	Layer	Description	Matrix	% Non-Asbestos Fibers	% Asbestos Fibers and Type
8	8	1	White soft/lumpy material with paint	Filler/binder, Paint	5% Cellulose	<b>5% Chrysotile</b>
9	9	1	Tan sheet vinyl	Vinyl/binder	5% Cellulose	<b>None Detected</b>
		2	Black asphaltic fibrous material with Mastic	Asphalt/binder, Mastic	45% Cellulose	<b>None Detected</b>