



11815 NE 99th Street, Suite 1294  
Vancouver, WA 98662  
Voice: 360-574-3058  
Fax: 360-576-0925  
Web: <https://www.swcleanair.gov>  
Email: Tina@swcleanair.gov

## Notification of Demolition

Case #: 24-857

Amendment: 0

Date Received: 12/18/2024

Date Paid: 12/18/2024

SWCAA Fee: \$74.00

Receipt #: 167958607

**10 day waiting period from date submitted**

**1. Type of Notification:** Original

**2. Type of Operation:** Demolition

**3. Facility Description:** Washougal

Commercial Name or Description: 730 S A St

Address: 730 S A St

City/State/Zip/County: Washougal, WA 98671 CLARK COUNTY

Present Use: Residence

Previous Use: Residence

**4. Facility Information**

Property Owner:

Property Owner: Alexander Trolese

**5. Name and AHERA Certification Number of Asbestos Inspector:**

Name: Frankie Kurtz

Certification #: R23-1553-AI-MO

**6. Asbestos Removal Contractor (if applicable):**

Name: No asbestos

**7. Dates Asbestos Removal Occurred:**

Start:

Complete:

Asbestos Case No.: 00-000-0

**8. Dates Demolition Will Occur:**

Start: 1/1/2025

Complete: 2/10/2025

**9. Demolition Contractor:**

Name: Alex Trolese

**10. Asbestos Disposal Site:** No Landfill Location:



**11. Description of planned demolition work, method(s) to be used:**

Plan is to use a backhoe or similar equipment to demo house and place material in waste management bins.

**12. Fugitive Emissions/dust from Demolition Activities MUST BE Controlled/Prevented during all phases of the project**

There will be no sources of fugitive emissions present during demo. Refrigerate will be pumped out prior to demo and lines vacated.

**13. If unexpected Asbestos containing Material (ACM) is found during demolition, Stop Work, Notify SWCAA and Consult/Hire a Certified Asbestos Abatement Contractor**

None present.

**14. If demolition is ordered by a Government Agent:**

**15. For Emergency Demolitions (Contact SWCAA prior to work):** ☐ **Emergency Demolition**

**Date and Time of Emergency:**

**Description of Sudden, Unexpected Event:**

**Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable burden:**

**16. I Certify that the above information is correct:**

**Submitter Name:** Alex Trolese

**Representing:** Self

**Submitter Title:** Owner

**Date Submitted:** 12/18/2024

**Email Address:** alex.r.trolese@gmail.com

**Reviewed by SWCAA:** Mihai Voivod

☒ **Approved**

The Washington State Dangerous Waste Regulations (WAC 173-303) require that demolition debris be evaluated to determine if it is dangerous. The evaluation should be completed before demolition to ensure that hazardous constituents are not released to the environment and do not present a risk to human health during or after demolition. These requirements apply to all buildings being demolished and are the responsibility of the property owner. The Washington Department of Ecology's website, <https://ecology.was.gov/Regulations-Permits/Guidance-technical-assistance/Dangerous-waste-guidance/Common-dangerous-waste/Construction-and-demolition>, provides more information about the requirements and about sampling and testing construction materials to determine if they present a risk. For more information please contact a Hazardous Waste Inspector at the Washington Department of Ecology Southwest Regional Office: (360) 407-6300.



# **Viable Earth Consulting LLC**

## **Asbestos Building Survey Report For Full-Scale Demolition**

**Prepared by**  
Frankie Kurtz  
Viable Earth Consulting LLC  
360-843-9728

**On**  
12/13/24

**For**  
Alex Trolese  
Property Owner

**-Project Site Address-**  
730 S A St,  
Washougal, WA 98671

Single Family Residence  
Built in 1998

Single Floor  
Three Bedroom/Two & half Baths  
2,436 sq. ft  
Three Car Garage



**VIABLE EARTH CONSULTING**

Quality Air Testing Done Right

# Table of Contents

|         |   |
|---------|---|
| Page 1  | Survey Information                      |
| Page 2  | Table of Contents                       |
| Page 3  | Introduction                            |
| Page 4  | Structural Description                  |
| Page 5  | Asbestos PLM Results                    |
| Page 6  | Asbestos PLM Results Continued-         |
| Page 7  | Asbestos PLM Results Continued          |
| Page 8  | Asbestos PLM Results Continued          |
| Page 9  | Asbestos PLM Results Continued          |
| Page 10 | Asbestos PLM Results Continued          |
| Page 11 | {COC} Chain of Custody Report           |
| Page 12 | {COC} Chain of Custody Report Continued |
| Page 13 | {COC} Chain of Custody Report Continued |
| Page 14 | AHERA Accreditation Certificate         |



**VIABLE EARTH CONSULTING**

Quality Air Testing Done Right

# Introduction-

On 12/12/24

Our office Viable Earth Consulting LLC was hired by Alex Trolese.

Property owner of the above-mentioned site address.

To conduct an asbestos building survey, for full-scale demolition.

A total of 36 samples were collected,

A total of 104 layers were analyzed.

Results from PLM Microscopy Analysis determine that asbestos is not present in any of the 63 samples collected.

No [ACM] or Asbestos Containing Materials were found in the any of the 104 layers analyzed.

Results were documented and then forwarded to the appropriate parties.

AHERA Building Inspector

Frankie Kurtz

A consultant with Viable Earth Consulting LLC

360-843-9728

[Viableearthllc@gmail.com](mailto:Viableearthllc@gmail.com)



## Structural Description

The building was in good shape when we arrived.  
None of the building material were damaged.  
Structure had all of its doors & windows.  
Both inside and out.  
Gutters and downspouts were intact.  
Siding appeared to be stucco and was in good shape.  
The roof was slate tile, none seemed to be missing or damaged.  
The carpet in the living areas, was old but not damaged.  
There was padding underneath, but no tile, mastic or sheet vinyl.  
The attic had blown in insulation throughout.  
The interior walls were undamaged.

The building is planned for full scale demolition,  
Once PLM results are acquired.

Structure was built in 1998  
3-Bedroom-2.5Bath-3Car Garage  
2,436 sq. ft  
Single Family Residential.

Frankie Kurtz  
Viable Earth Consulting LLC  
[Viableearth00llc@gmail.com](mailto:Viableearth00llc@gmail.com)  
360-843-9728



**VIABLE EARTH CONSULTING**

Quality Air Testing Done Right





# ADVANTAGE Environmental INC.

Page 1 of 6

Clean your world.

9317 NE Hwy 99, Suite D, Vancouver, WA 98665 | 360-356-7628  
Polarized Light Microscopy Results

Lab No 147493  
Layers Analyzed 104  
Date Received 12/12/2024  
Received By Talia Carroll  
Date Analyzed 12/13/2024  
Analyzed By Nathan Blondino

Property Address 730 S A St  
City, State, Zip Washougal, WA  
Job Number  
Client Name Viable Earth Consulting  
Client Address  
City, State, Zip  
Phone & E-mail (360) 843-9728

| AEI<br>Sample ID | Client<br>Sample ID | Composition | Color/<br>Description | Asbestos (%)         | Non-Asbestos<br>Fiber (%)         | Non Fibrous              |
|------------------|---------------------|-------------|-----------------------|----------------------|-----------------------------------|--------------------------|
| 001              | 1-A                 | Layered     | White Texture         | Asbestos Not Present | N/A                               | (White) Paint-CaCO3-Mica |
| 001A             |                     | Layered     | White Drywall         | Asbestos Not Present | 12% Cellulose<br>3% Glass Fibers  | Gypsum                   |
| 001B             |                     | Layered     | Tan Insulation        | Asbestos Not Present | 98% Cellulose                     | Debris                   |
| 002              | 1-B                 | Layered     | White Texture         | Asbestos Not Present | N/A                               | (White) Paint-CaCO3-Mica |
| 002A             |                     | Layered     | White Drywall         | Asbestos Not Present | 12% Cellulose<br>3% Glass Fibers  | Gypsum                   |
| 003              | 1-C                 | Layered     | Brown Ceramic Tile    | Asbestos Not Present | N/A                               | CaCO3-Clay               |
| 003A             |                     | Layered     | Gray Grout            | Asbestos Not Present | N/A                               | CaCO3-Sand               |
| 004              | 2-A                 | Layered     | White Texture         | Asbestos Not Present | N/A                               | (White) Paint-CaCO3-Mica |
| 004A             |                     | Layered     | White Drywall         | Asbestos Not Present | 12% Cellulose<br>3% Glass Fibers  | Gypsum                   |
| 004B             |                     | Layered     | Tan Insulation        | Asbestos Not Present | 98% Cellulose                     | Debris                   |
| 005              | 2-B                 | Layered     | Tan Ceramic Tile      | Asbestos Not Present | N/A                               | CaCO3-Clay               |
| 005A             |                     | Layered     | Tan Mastic            | Asbestos Not Present | N/A                               | Glue                     |
| 005B             |                     | Layered     | White Texture         | Asbestos Not Present | N/A                               | (White) Paint-CaCO3-Mica |
| 005C             |                     | Layered     | White Drywall         | Asbestos Not Present | 12% Cellulose<br><1% Glass Fibers | Gypsum                   |
| 006              | 2-C                 | Homogeneous | Black Felt Paper      | Asbestos Not Present | 30% Cellulose                     | Tar                      |
| 007              | 3-A                 | Layered     | White Texture         | Asbestos Not Present | N/A                               | (White) Paint-CaCO3-Mica |
| 007A             |                     | Layered     | White Drywall         | Asbestos Not Present | 12% Cellulose<br>3% Glass Fibers  | Gypsum                   |
| 007B             |                     | Layered     | Tan Insulation        | Asbestos Not Present | 99% Cellulose                     | Debris                   |
| 008              | 3-B                 | Layered     | White Texture         | Asbestos Not Present | N/A                               | (White) Paint-CaCO3-Mica |



Lab No 147493

Property Address 730 S A St Washougal, WA

| AEI Sample ID | Client Sample ID | Composition | Color/Description    | Asbestos (%)         | Non-Asbestos Fiber (%)            | Non Fibrous              |
|---------------|------------------|-------------|----------------------|----------------------|-----------------------------------|--------------------------|
| 008A          |                  | Layered     | White Joint Compound | Asbestos Not Present | N/A                               | CaCO3-Mica               |
| 008B          |                  | Layered     | White Drywall        | Asbestos Not Present | 12% Cellulose<br>3% Glass Fibers  | Gypsum                   |
| 008C          |                  | Layered     | Yellow Insulation    | Asbestos Not Present | 99% Glass Fibers                  | Debris                   |
| 009           | 3-C              | Layered     | Tan Sheet Flooring   | Asbestos Not Present | 20% Cellulose<br><1% Glass Fibers | Vinyl-Foam-Binder-CaCO3  |
| 009A          |                  | Layered     | Tan Flooring Mastic  | Asbestos Not Present | N/A                               | Glue                     |
| 010           | 4-A              | Layered     | White Texture        | Asbestos Not Present | N/A                               | (White) Paint-CaCO3-Mica |
| 010A          |                  | Layered     | White Joint Compound | Asbestos Not Present | N/A                               | CaCO3-Mica               |
| 010B          |                  | Layered     | White Drywall        | Asbestos Not Present | 12% Cellulose<br>3% Glass Fibers  | Gypsum                   |
| 010C          |                  | Layered     | Tan Insulation       | Asbestos Not Present | 99% Cellulose                     | Debris                   |
| 011           | 4-B              | Layered     | White Texture        | Asbestos Not Present | N/A                               | (White) Paint-CaCO3-Mica |
| 011A          |                  | Layered     | White Drywall        | Asbestos Not Present | 12% Cellulose<br>3% Glass Fibers  | Gypsum                   |
| 012           | 5-A              | Layered     | White Texture        | Asbestos Not Present | N/A                               | (White) Paint-CaCO3-Mica |
| 012A          |                  | Layered     | White Joint Compound | Asbestos Not Present | N/A                               | CaCO3-Mica               |
| 012B          |                  | Layered     | White Drywall        | Asbestos Not Present | 12% Cellulose<br>3% Glass Fibers  | Gypsum                   |
| 012C          |                  | Layered     | Tan Insulation       | Asbestos Not Present | 99% Cellulose                     | Debris                   |
| 013           | 5-B              | Layered     | White Texture        | Asbestos Not Present | N/A                               | (White) Paint-CaCO3-Mica |
| 013A          |                  | Layered     | White Drywall        | Asbestos Not Present | 12% Cellulose<br>3% Glass Fibers  | Gypsum                   |
| 014           | 5-C              | Layered     | White Texture        | Asbestos Not Present | N/A                               | (White) Paint-CaCO3-Mica |
| 014A          |                  | Layered     | White Drywall        | Asbestos Not Present | 12% Cellulose<br>3% Glass Fibers  | Gypsum                   |
| 014B          |                  | Layered     | Tan Insulation       | Asbestos Not Present | 99% Cellulose                     | Debris                   |
| 015           | 5-D              | Layered     | White Texture        | Asbestos Not Present | N/A                               | (White) Paint-CaCO3-Mica |



Lab No 147493

Property Address 730 S A St Washougal, WA

| AEI Sample ID | Client Sample ID | Composition | Color/Description            | Asbestos (%)         | Non-Asbestos Fiber (%)           | Non Fibrous              |
|---------------|------------------|-------------|------------------------------|----------------------|----------------------------------|--------------------------|
| 015A          |                  | Layered     | White Joint Compound         | Asbestos Not Present | N/A                              | CaCO3-Mica               |
| 015B          |                  | Layered     | White Drywall                | Asbestos Not Present | 12% Cellulose<br>3% Glass Fibers | Gypsum                   |
| 015C          |                  | Layered     | Yellow Insulation            | Asbestos Not Present | 99% Glass Fibers                 | Debris                   |
| 016           | 6-A              | Layered     | White Texture                | Asbestos Not Present | N/A                              | (White) Paint-CaCO3-Mica |
| 016A          |                  | Layered     | White Drywall                | Asbestos Not Present | 12% Cellulose<br>3% Glass Fibers | Gypsum                   |
| 016B          |                  | Layered     | Light Gray Insulation        | Asbestos Not Present | 99% Cellulose                    | Debris                   |
| 017           | 6-B              | Layered     | White Ceramic Tile           | Asbestos Not Present | N/A                              | CaCO3-Clay               |
| 017A          |                  | Layered     | Tan Mastic                   | Asbestos Not Present | N/A                              | Glue                     |
| 017B          |                  | Layered     | White Texture                | Asbestos Not Present | N/A                              | (White) Paint-CaCO3-Mica |
| 017C          |                  | Layered     | White Joint Compound         | Asbestos Not Present | N/A                              | CaCO3-Mica               |
| 017D          |                  | Layered     | White Drywall                | Asbestos Not Present | 12% Cellulose<br>3% Glass Fibers | Gypsum                   |
| 018           | 6-C              | Layered     | Light Tan Sheet Flooring     | Asbestos Not Present | 10% Cellulose<br>4% Glass Fibers | Vinyl-Foam-Binder-CaCO3  |
| 018A          |                  | Layered     | Light TanTan Flooring Mastic | Asbestos Not Present | N/A                              | Glue                     |
| 019           | 7-A              | Layered     | White Texture                | Asbestos Not Present | N/A                              | (White) Paint-CaCO3-Mica |
| 019A          |                  | Layered     | White Joint Compound         | Asbestos Not Present | N/A                              | CaCO3-Mica               |
| 019B          |                  | Layered     | White Drywall                | Asbestos Not Present | 12% Cellulose<br>3% Glass Fibers | Gypsum                   |
| 019C          |                  | Layered     | Tan Insulation               | Asbestos Not Present | 99% Cellulose                    | Debris                   |
| 020           | 7-B              | Layered     | White Texture                | Asbestos Not Present | N/A                              | (White) Paint-CaCO3-Mica |
| 020A          |                  | Layered     | White Joint Compound         | Asbestos Not Present | N/A                              | CaCO3-Mica               |
| 020B          |                  | Layered     | White Drywall                | Asbestos Not Present | 12% Cellulose<br>3% Glass Fibers | Gypsum                   |
| 021           | 8-A              | Layered     | White Texture                | Asbestos Not Present | N/A                              | (White) Paint-CaCO3-Mica |



**Lab No** 147493

**Property Address** 730 S A St Washougal, WA

| AEI Sample ID | Client Sample ID | Composition | Color/Description        | Asbestos (%)         | Non-Asbestos Fiber (%)            | Non Fibrous              |
|---------------|------------------|-------------|--------------------------|----------------------|-----------------------------------|--------------------------|
| 021A          |                  | Layered     | White Drywall            | Asbestos Not Present | 12% Cellulose<br>3% Glass Fibers  | Gypsum                   |
| 021B          |                  | Layered     | Tan Insulation           | Asbestos Not Present | 99% Cellulose                     | Debris                   |
| 022           | 8-B              | Layered     | White Ceramic Tile       | Asbestos Not Present | N/A                               | CaCO3-Clay               |
| 022A          |                  | Layered     | Tan Mastic               | Asbestos Not Present | N/A                               | Glue                     |
| 022B          |                  | Layered     | White Texture            | Asbestos Not Present | N/A                               | (White) Paint-CaCO3-Mica |
| 022C          |                  | Layered     | White Joint Compound     | Asbestos Not Present | N/A                               | CaCO3-Mica               |
| 022D          |                  | Layered     | White Drywall            | Asbestos Not Present | 12% Cellulose<br>3% Glass Fibers  | Gypsum                   |
| 023           | 8-C              | Layered     | Light Tan Sheet Flooring | Asbestos Not Present | 4% Cellulose                      | Vinyl-Foam-Binder-CaCO3  |
| 023A          |                  | Layered     | Tan Flooring Mastic      | Asbestos Not Present | N/A                               | Glue                     |
| 024           | 9-A              | Layered     | White Texture            | Asbestos Not Present | N/A                               | (White) Paint-CaCO3-Mica |
| 024A          |                  | Layered     | White Joint Compound     | Asbestos Not Present | N/A                               | CaCO3-Mica               |
| 024B          |                  | Layered     | White Drywall            | Asbestos Not Present | 12% Cellulose<br>3% Glass Fibers  | Gypsum                   |
| 024C          |                  | Layered     | Tan Insulation           | Asbestos Not Present | 99% Cellulose                     | Debris                   |
| 025           | 9-B              | Layered     | White Texture            | Asbestos Not Present | N/A                               | (White) Paint-CaCO3-Mica |
| 025A          |                  | Layered     | White Drywall            | Asbestos Not Present | 12% Cellulose<br><1% Glass Fibers | Gypsum                   |
| 026           | 10-A             | Layered     | White Texture            | Asbestos Not Present | N/A                               | (White) Paint-CaCO3-Mica |
| 026A          |                  | Layered     | White Drywall            | Asbestos Not Present | 12% Cellulose<br>3% Glass Fibers  | Gypsum                   |
| 026B          |                  | Layered     | Tan Insulation           | Asbestos Not Present | 99% Cellulose                     | Debris                   |
| 027           | 10-B             | Layered     | White Texture            | Asbestos Not Present | N/A                               | (White) Paint-CaCO3-Mica |
| 027A          |                  | Layered     | White Drywall            | Asbestos Not Present | 12% Cellulose<br>3% Glass Fibers  | Gypsum                   |
| 028           | 11-A             | Layered     | White Texture            | Asbestos Not Present | N/A                               | (White) Paint-CaCO3-Mica |



Lab No 147493

Property Address 730 S A St Washougal, WA

| AEI Sample ID | Client Sample ID | Composition | Color/Description              | Asbestos (%)         | Non-Asbestos Fiber (%)            | Non Fibrous              |
|---------------|------------------|-------------|--------------------------------|----------------------|-----------------------------------|--------------------------|
| 028A          |                  | Layered     | White Drywall                  | Asbestos Not Present | 12% Cellulose<br>3% Glass Fibers  | Gypsum                   |
| 029           | 11-B             | Layered     | Tan Sheet Flooring             | Asbestos Not Present | 20% Cellulose<br><1% Glass Fibers | Vinyl-Foam-Binder-CaCO3  |
| 029A          |                  | Layered     | Tan Flooring Mastic            | Asbestos Not Present | N/A                               | Glue                     |
| 030           | 12-A             | Layered     | White Texture                  | Asbestos Not Present | N/A                               | (White) Paint-CaCO3-Mica |
| 030A          |                  | Layered     | White Joint Compound           | Asbestos Not Present | N/A                               | CaCO3-Mica               |
| 030B          |                  | Layered     | White Drywall                  | Asbestos Not Present | 12% Cellulose<br>3% Glass Fibers  | Gypsum                   |
| 030C          |                  | Layered     | Pink Insulation                | Asbestos Not Present | 99% Glass Fibers                  | Debris                   |
| 031           | 12-B             | Layered     | White Joint Compound           | Asbestos Not Present | N/A                               | CaCO3-Mica               |
| 031A          |                  | Layered     | Light Gray Drywall             | Asbestos Not Present | 12% Cellulose<br><1% Glass Fibers | Gypsum                   |
| 031B          |                  | Layered     | Brown Insulation Paper Backing | Asbestos Not Present | 70% Cellulose                     | Tar                      |
| 032           | 12-C             | Layered     | White Texture                  | Asbestos Not Present | N/A                               | (White) Paint-CaCO3-Mica |
| 032A          |                  | Layered     | White Drywall                  | Asbestos Not Present | 12% Cellulose<br><1% Glass Fibers | Gypsum                   |
| 032B          |                  | Layered     | Pink Insulation                | Asbestos Not Present | 99% Glass Fibers                  | Debris                   |
| 032C          |                  | Layered     | Brown Paper Backing            | Asbestos Not Present | 70% Cellulose                     | Tar                      |
| 033           | 13-A             | Layered     | White Texture                  | Asbestos Not Present | N/A                               | (White) Paint-CaCO3-Mica |
| 033A          |                  | Layered     | White Drywall                  | Asbestos Not Present | 12% Cellulose<br><1% Glass Fibers | Gypsum                   |
| 033B          |                  | Layered     | Tan Insulation                 | Asbestos Not Present | 99% Cellulose                     | Debris                   |
| 034           | 13-B             | Homogeneous | White Drywall                  | Asbestos Not Present | 12% Cellulose<br><1% Glass Fibers | Gypsum                   |
| 035           | 14-A             | Homogeneous | Black Felt Paper               | Asbestos Not Present | 30% Cellulose                     | Tar                      |
| 036           | 15-A             | Layered     | White Skim Coat                | Asbestos Not Present | N/A                               | CaCO3-Sand               |
| 036A          |                  | Layered     | Gray Stucco                    | Asbestos Not Present | N/A                               | CaCO3-Sand               |



**Lab No** 147493

**Property Address** 730 S A St Washougal, WA

| AEI<br>Sample ID | Client<br>Sample ID | Composition | Color/<br>Description | Asbestos (%)         | Non-Asbestos<br>Fiber (%) | Non Fibrous |
|------------------|---------------------|-------------|-----------------------|----------------------|---------------------------|-------------|
| 036B             |                     | Layered     | Black Felt Paper      | Asbestos Not Present | 75% Cellulose             | Tar         |

## Disclaimer

- EPA Method 600/M4-82-020 (1982) was used to determine the presence or absence of asbestos fibers in all materials referenced in the above report. PLM analysis is based on visual estimation, and due to limitations of PLM analysis NESHAP regulations recommend that any material determined to contain less than 10% asbestos by the above referenced method should either be assumed to contain greater than 1% asbestos by the owner/operator, or be verified by PLM Point Count or TEM analysis as containing less than 1% asbestos.
- We recommend that TEM analysis be conducted for confirmation of negative PLM analytical results of vinyl floor tiles and vermiculite. These materials may contain asbestos fibers that cannot be detected by PLM analysis due to their size (<0.25 microns in diameter)
- This report may not be used to represent any materials not analyzed and listed in the included report. Advantage Environmental Inc. cannot be held responsible for the interpretation of the results shown. This report may not be reproduced in part and may only be reproduced in full without prior written consent from Advantage Environmental Inc.



**ASBESTOS CHAIN OF CUSTODY**  
9317 NE Hwy 99, Suite D • (360) 356-7628  
LEGAL DOCUMENT - PLEASE PRINT LEGIBLY

| Lab Use Only                                |  |
|---|--|
| Survey <input type="checkbox"/>             | Lab No. <b>147493</b>  |
| Walk-In <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> Accept <input type="checkbox"/> Reject |

| Sampled By - Please fill out yellow highlighted areas    |           |                      |                           | Project Information - Please fill out yellow highlighted areas  |                             |                      |  |
|--|-----------|----------------------|---------------------------|---|-----------------------------|----------------------|--|
| Date: <b>12/12/24</b>                                    |           |                      |                           | Project Name:   |                             |                      |  |
| Company Name OR Name: <b>Viable Earth Consulting LLC</b> |           |                      |                           | Address (where material was pulled from): <b>730 S A St.</b>  |                             |                      |  |
| Phone: <b>360-843-9728</b>                               |           |                      |                           | City, State, Zip: <b>Washougal WA 98671</b>   |                             |                      |  |
| Email: <b>Viableearth LLC@gmail.com</b>                  |           |                      |                           | P.O. #:   |                             |                      |  |
| RELINQUISHED BY  |           | DATE & TIME          |                           | VIA   |                             | RECEIVED BY          |  |
| Name <b>Frankie Hunte</b>                                |           | Date <b>12/12/24</b> |                           | Drop Box/Drop Off   |                             |                      |  |
| Sign   |           | Time <b>4:30 PM</b>  |                           |   |                             | <b>12-12-24 4:55</b> |  |
| REQUESTED SERVICES                                       |           |                      |                           |   |                             |                      |  |
| PLM  |           |                      |                           | TURNAROUND TIME - Please choose a turnaround time   |                             |                      |  |
| Bulk Analysis  |           |                      |                           | <input type="checkbox"/> Verbal <input type="checkbox"/> Rush <input type="checkbox"/> Same Day <input type="checkbox"/> 24-Hour <input checked="" type="checkbox"/> 3-Days |                             |                      |  |
| No.  | Sample ID | Color                | Description               | Volume / Area (as applicable)   | Comments / Notes            |                      |  |
| 1  | 1-A       | white                | Drywall & Insulation      | 800'SQ  | Living Area - Ceiling       |                      |  |
| 2  | 1-B       | white                | Drywall                   | 800'SQ  | Living Area - Wall          |                      |  |
| 3  | 1-C       | Grey                 | Tile                      | 40'SQ   | Living Area - Fireplace     |                      |  |
| 4  | 2-A       | white                | Drywall & Insulation      | 400'SQ  | Kitchen - Ceiling           |                      |  |
| 5  | 2-B       | white                | Drywall & Tile Backsplash | 350'SQ  | Kitchen Wall & Backsplash   |                      |  |
| 6  | 2-C       | Black                | Flooring Felt Paper       | 1200'SQ   | Kitchen & Dining Floor      |                      |  |
| 7  | 3-A       | white                | Drywall & Insulation      | 200'SQ  | Laundry Area - Ceiling      |                      |  |
| 8  | 3-B       | white                | Drywall & Insulation      | 800'SQ  | Laundry Area - Walls        |                      |  |
| 9  | 3-C       | Tan                  | Vinyl Sheet Flooring      | 220'SQ  | Laundry Area - Floor        |                      |  |
| 10   | 4-A       | white                | Drywall & Insulation      | 400'SQ  | South Living Area - Ceiling |                      |  |
| 11   | 4-B       | white                | Drywall                   | 1000'SQ   | South Living Area - Wall    |                      |  |



| Company: |           |           | Project Name:             |                                  | Project Location:               |  |
|----------|-----------|-----------|---------------------------|----------------------------------|---------------------------------|--|
| No.      | Sample ID | Color     | Description               | Volume / Area<br>(as applicable) | Comments / Notes                |  |
| 12       | 5-A       | white     | Drywall & Insulation      | 400'sq                           | Master Bedroom - Ceiling        |  |
| 13       | 5-B       | white     | Drywall                   | 1000'sq                          | Master Bedroom - Wall           |  |
| 14       | 5-C       | white     | Drywall & Insulation      | 50'ssq                           | Master Bedroom Closet - Ceiling |  |
| 15       | 5-D       | white     | Drywall & Insulation      | 50'ssq                           | Master Bedroom closet - Wall    |  |
| 16       | 6-A       | white     | Drywall & Insulation      | 500'ssq                          | Master Restroom - Ceiling       |  |
| 17       | 6-B       | Tan/white | Drywall & Tile Backsplash | 500'ssq                          | Master Restroom - Wall          |  |
| 18       | 6-C       | Tan       | Vinyl                     | 200'ssq                          | Master Restroom - Floor         |  |
| 19       | 7-A       | white     | Drywall & Insulation      | 300'ssq                          | 2nd Bedroom - Ceiling           |  |
| 20       | 7-B       | white     | Drywall                   | 500'ssq                          | 2nd Bedroom - Wall              |  |
| 21       | 8-A       | white     | Drywall & Insulation      | 200'ssq                          | 2nd Restroom - Ceiling          |  |
| 22       | 8-B       | white     | Drywall & Tile Backsplash | 380'ssq                          | 2nd Restroom Wall               |  |
| 23       | 8-C       | Tan       | Vinyl Flooring            | 120'ssq                          | 2nd Restroom - Floor            |  |
| 24       | 9-A       | white     | Drywall & Insulation      | 300'ssq                          | Office Ceiling                  |  |
| 25       | 9-B       | white     | Drywall                   | 500'ssq                          | Office Wall                     |  |
| 26       | 10-A      | white     | Drywall & Insulation      | 200'ssq                          | Water Heater Room - Ceiling     |  |
| 27       | 10-B      | white     | Drywall                   | 400'ssq                          | Water Heater Room - Wall        |  |
| 28       | 11-A      | white     | Drywall                   | 100'ssq                          | 1/2 Bath - Wall                 |  |
| 29       | 11-B      | Tan       | Vinyl                     | 60'ssq                           | 1/2 Bath - Floor                |  |
| 30       | 12-A      | white     | Drywall                   | 200'ssq                          | 3rd Bedroom - Ceiling           |  |
| 31       | 12-B      | white     | Drywall & Insulation      | 300'ssq                          | 3rd Bedroom Hallway - Ceiling   |  |
| 32       | 12-C      | white     | Drywall & Insulation      | 600'ssq                          | 3rd Bedroom Hallway - Wall      |  |
| 33       | 13-A      | white     | Drywall & Insulation      | 1200'ssq                         | Garage Ceiling                  |  |



| Company: |           |       | Project Name:  |                                  | Project Location:    |  |
|----------|-----------|-------|----------------|----------------------------------|----------------------|--|
| No.      | Sample ID | Color | Description    | Volume / Area<br>(as applicable) | Comments / Notes     |  |
| 12       | 13-B      | White | Drywall        | 1200'SQ                          | Garage - Wall        |  |
| 13       | 14-A      | Black | Felt Paper     | 200'SQ                           | Roofing - Felt Paper |  |
| 14       | 15A       | White | Plaster/Stucco | 500'SQ                           | Upper Roof - Siding  |  |
| 15       |           |       |                |                                  |                      |  |
| 16       |           |       |                |                                  |                      |  |
| 17       |           |       |                |                                  |                      |  |
| 18       |           |       |                |                                  |                      |  |
| 19       |           |       |                |                                  |                      |  |
| 20       |           |       |                |                                  |                      |  |
| 21       |           |       |                |                                  |                      |  |
| 22       |           |       |                |                                  |                      |  |
| 23       |           |       |                |                                  |                      |  |
| 24       |           |       |                |                                  |                      |  |
| 25       |           |       |                |                                  |                      |  |
| 26       |           |       |                |                                  |                      |  |
| 27       |           |       |                |                                  |                      |  |
| 28       |           |       |                |                                  |                      |  |
| 29       |           |       |                |                                  |                      |  |
| 30       |           |       |                |                                  |                      |  |
| 31       |           |       |                |                                  |                      |  |
| 32       |           |       |                |                                  |                      |  |
| 33       |           |       |                |                                  |                      |  |



BetterCertify  
Certification & Compliance Solutions  
www.bettercertify.com  
303.412.6360  
855.60.CERTIFY

CHC Training, LLC. is now BetterCertify, LLC. (Ef ect. 5/1/2024)

1775 West 55th Avenue  
Denver, Colorado 80221  
United States of America

# Certificate of Achievement

This certificate is awarded to:

**Frankie Kurtz**

In recognition of satisfactory completion of the EPA-approved annual asbestos refresher training (online-asynchronous) provided in accordance with the Model Accreditation Plan (MAP) (40 CFR Part 763, Subpart E, Appendix C) and AHERA (Subchapter II) of the Toxic Substances Control Act (TSCA) entitled:

Building Inspector

Course Completion Date: November 13, 2024    Expiration Date: November 13, 2025  
Examination Date: November 13, 2024    Course Hours: 4.0



Verify Credential

**Danaya N. Wilson**  
CEO & Training Program Manager

Credential License ID:  
122677134



**Aaron I. Hix**  
Instructor

Certificate No.:  
R24-1392-AI-0



Renew Credential