



# Notice of Intent to Remove Asbestos

Case #: 25-020

Amendment: 0

11815 NE 99th Street, Suite 1294  
Vancouver, WA 98662  
Voice: 360-574-3058  
Fax: 360-576-0925  
Web: https://www.swcleanair.gov  
Email: Tina@swcleanair.gov

Date Received: 1/7/2025

Date Paid: 1/7/2025

SWCAA Fee: \$768.00

Receipt #: 168935523

**This notification MUST be present at all times at the asbestos project sit**

**\*\*\* EMERGENCY NOTICE \*\*\***

Quantity to be removed: 4383 Square Feet 0 Linear Feet

Workshift days: M T W Th F

Project starting date: 1/8/2025 Project Completion date: 1/22/2025

Workshift hours: 8-4

Site Name: W381\_SarkinenRestoration\_4610N Site address: 4610 NE 26th Ave Vancouver WA

Location of Asbestos: Throughout City/State/Zip: Vancouver WA 98663

Demolition of Structure (Notification of Demolition required) County: CLARK COUNTY

Asbestos survey conducted? No survey reason:

AHERA Inspector: Dustin Berry

Certification #: IR-23-5437B

**Material to be Removed:**

- Fireproofing  Popcorn Ceiling  CAB  Sheet Vinyl  Boiler Insulation  Duct Tape
- Duct Paper  Mag Pipe Insulation  Air Cell  CA Pipe  VAT
- Other Texture

**Control Methods:**

- N.P Enclosure  Glove Bag  Mini Enclosure  Wrap and Cut  Water  HEPA Vac
- Other 6-Mil Poly, Wet, Labeled

**Asbestos Contractor:** Alpine Abatement Associates Inc. Phone: 541-388-2672

Mailing Address: PO Box 1557, Bend, OR, 97709 Email: annmarie@alpineabatement.com

Certification ##: ABCN00001215

Supervisor: Jose Vera Phone: 541-388-2672

**Property Owner:** John Hircock Phone: 360-589-2626

Mailing Address: 4610 NE 26th Ave WA, Vancouver WA 98663

**Asbestos Disposal Site:** Hillsboro Landfill: 3205 SE Minter Bridge Rd, Hillsboro, OR, 97123-

**I DO HEREBY CERTIFY THAT THE INFORMATION CONTAINED IN THIS NOTIFICATION IS, TO THE BEST OF MY KNOWLEDGE, ACCURATE AND COMPLETE.**

**Submitter Name:** Bo Davidson

**Representing:** Alpine Abatement

**Submitter Title:** VP Operations

**Date Submitted:** 1/7/2025

**Reviewed by SWCAA:** Brian Fallon

Approved



11815 NE 99th Street, Suite 1294  
Vancouver, WA 98662  
Voice: 360-574-3058  
Fax: 360-576-0925  
Web: <https://www.swcleanair.gov>  
Email: [Tina@swcleanair.gov](mailto:Tina@swcleanair.gov)

## Notice of Intent to Remove Asbestos

Case #: 25-020

Amendment: 0

Date Received: 1/7/2025

Date Paid: 1/7/2025

SWCAA Fee: \$768.00

Receipt #: 168935523

**This notification MUST be present at all times at the asbestos project sit**

---

Atlas Laboratories Inc  
 14795 SW 72nd Ave, Ste B, Portland, OR 97224  
 (503) 430-5290 www.atlaslabsinc.com



**CHAIN OF CUSTODY**

Name / Company Name: Sarkinen/Dustin Berry Phone: 360-253-4063  
 Contact Email: RESULTS@Sarkinenrestoration.com  
 Job Name: John HIRCOCK Job / Project:  
 Address / Project Location: 4616 NE 26th Ave Vancouver wa 98663

Please check box that applies

Rush Samples turned in by 2PM will be processed the same day  
 Next Day  
 2-Day  
 5-Day

Please check box that applies

Asbestos PLM  
 Lead Paint  
 Other

#	Material Description	Sample Location	Office Use Only
	Ceiling Drywall	Man Cave	
	Drywall	Man Cave	
	Drywall	Master Bed	
	Ceiling	Living Rm	
	Drywall	Living Rm	
	Ceiling	Master Bath	
	Drywall	Master Bath	
	Drywall	Hall Bath	
	Ceiling	Hall Bath	
	Drywall	Bed Rm	
	Drywall	Hallway	
	Drywall	garage	
	Ceiling	garage	
	Drywall	Plant Rm	
	Ceiling	Plant Rm	
	Drywall	Kitchen	

Special Instructions:

Client Sign Here: [Signature] Date: 12-26 Time: 12:23  
 Atlas: Accepted By: [Signature] Date: 12/26/24 Time: 12:30pm  
 Credit Card: Cash: Check # Amount: \$  
 Lab Results Completed By: [Signature] Date Sent Out: 12/26/24  Email/Mail

\*Atlas charges a per sample fee and not by layer. One sample fee equals four layers. Additional layers will result in an additional sample fee.



Batch # 2022 \*

2448201

Analysis Date \*

12/26/2024

Project #

Name / Company \*

Sarkinen/Dustin Berry

Project Name

John Hircock

PO #

Analyst \*

Stephanie Meikle

Project Location \*

4610 NE 26th Ave.,  
Vancouver, WA 98663

Turnaround Time \*

Rush

**Asbestos Analysis of Bulk Material by Polarized Light Microscopy**

Sample*	Layer*	Description*	Non Asbestos*	Asbestos Type*	Asbestos %*
1	1	Drywall (White) - Man Cave	Cellulose	None Present	N/D
1	2	Texture (White) - Man Cave	Cellulose	None Present	N/D
1	3	Joint Compound (White) - Man Cave	Cellulose	None Present	N/D
2	1	Drywall (White) - Man Cave	Cellulose	None Present	N/D
2	2	Texture (White) - Man Cave	Cellulose	None Present	N/D
3	1	Drywall (White) - Master Bed	Cellulose	None Present	N/D
3	2	Texture (White) - Master Bed	Cellulose	Chrysotile	3%
4	1	Drywall (White) - Living Rm	Cellulose	None Present	N/D
4	2	Texture (White) - Living Rm	Cellulose	Chrysotile	3%
5	1	Drywall (White) - Living Rm	Cellulose	None Present	N/D
5	2	Texture (White) - Living Rm	Cellulose	Chrysotile	3%
6	1	Drywall (White) - Master Bath	Cellulose	None Present	N/D
6	2	Texture (White) - Master Bath	Cellulose	Chrysotile	3%
7	1	Drywall (White) - Master Bath	Cellulose	None Present	N/D
7	2	Texture (White) - Master Bath	Cellulose	Chrysotile	3%

Sample*	Layer*	Description*	Non Asbestos*	Asbestos Type*	Asbestos %*
8	1	Drywall (White) - Hall Bath	Cellulose	None Present	N/D
8	2	Texture (White) - Hall Bath	Cellulose	Chrysotile	3%
9	1	Drywall (White) - Hall Bath	Cellulose	None Present	N/D
9	2	Texture (White) - Hall Bath	Cellulose	Chrysotile	3%
10	1	Drywall (White) - Bed Rm	Cellulose	None Present	N/D
10	2	Texture (White) - Bed Rm	Cellulose	Chrysotile	3%
11	1	Drywall (White) - Hallway	Cellulose	None Present	N/D
11	2	Texture (White) - Hallway	Cellulose	None Present	N/D
12	1	Drywall (White) - Garage	Cellulose / Fiberglass	None Present	N/D
13	1	Drywall (White) - Garage	Cellulose / Fiberglass	None Present	N/D
13	2	Joint Compound (White) - Garage	Cellulose	Chrysotile	3%
14	1	Drywall (White) - Plant Rm	Cellulose	None Present	N/D
14	2	Texture (White) - Plant Rm	Cellulose	Chrysotile	3%
15	1	Drywall (White) - Plant Rm	Cellulose	None Present	N/D
15	2	Texture (White) - Plant Rm	Cellulose	Chrysotile	3%
16	1	Drywall (White) - Kitchen	Cellulose	None Present	N/D
16	2	Texture (White) - Kitchen	Cellulose	Chrysotile	3%

To Be Filled by the Technician  
Technician \*

Atlas Laboratories maintains liability to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full without written permission by Atlas. Atlas bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval or endorsement by NVLAP, NIST, NIOSH or any other agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore Atlas recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Transmission Electron Microscopy asbestos identification and lead paint analysis will be available and performed by laboratories by proxy. Original analysis documents are available upon request of the client.