



# Notice of Intent to Remove Asbestos

Case #: 25-071

Amendment: 0

11815 NE 99th Street, Suite 1294  
Vancouver, WA 98662  
Voice: 360-574-3058  
Fax: 360-576-0925  
Web: https://www.swcleanair.gov  
Email: Tina@swcleanair.gov

Date Received: 1/22/2025

Date Paid: 1/22/2025

SWCAA Fee: \$384.00

Receipt #: 169704164

**This notification MUST be present at all times at the asbestos project sit**

Quantity to be removed: 1990 Square Feet 0 Linear Feet

Workshift days: M T W Th F

Project starting date: 2/3/2025 Project Completion date: 2/7/2025

Workshift hours: 8-4

Site Name: W386\_PRP\_10009NeHeronCir\_986 Site address: 10009 NE Heron Cir. Vancouver WA 98664

Location of Asbestos: Kitchen, Dining room, Living Room, City/State/Zip: Vancouver WA 98664

Demolition of Structure (Notification of Demolition required) County: CLARK COUNTY

Asbestos survey conducted? No survey reason:

AHERA Inspector: Robert Burns

Certification #: IRO-24-4095A

### Material to be Removed:

- Fireproofing  Popcorn Ceiling  CAB  Sheet Vinyl  Boiler Insulation  Duct Tape
- Duct Paper  Mag Pipe Insulation  Air Cell  CA Pipe  VAT
- Other Wallboard/Joint Compound and Light Texture

### Control Methods:

- N.P Enclosure  Glove Bag  Mini Enclosure  Wrap and Cut  Water  HEPA Vac
- Other 6-Mil Poly, Wet, Labeled

Asbestos Contractor: Alpine Abatement Associates Inc.

Phone: 541-388-2672

Mailing Address: PO Box 1557, Bend, OR, 97709

Email: annmarie@alpineabatement.com

Certification ##: ABCN00001215

Supervisor: Miguel Resendiz

Phone: 541-388-2672

Property Owner: Richard and Sharon Graham

Phone: 971-910-0806

Mailing Address: 10009 NE Heron Cir. WA, Vancouver WA 98664

Asbestos Disposal Site: Hillsboro Landfill: 3205 SE Minter Bridge Rd, Hillsboro, OR, 97123-

**I DO HEREBY CERTIFY THAT THE INFORMATION CONTAINED IN THIS NOTIFICATION IS, TO THE BEST OF MY KNOWLEDGE, ACCURATE AND COMPLETE.**

Submitter Name: Bo Davidson

Representing: Alpine Abatement

Submitter Title: VP Operations

Date Submitted: 1/22/2025

Reviewed by SWCAA: Danielle Kreps

Approved



11815 NE 99th Street, Suite 1294  
Vancouver, WA 98662  
Voice: 360-574-3058  
Fax: 360-576-0925  
Web: <https://www.swcleanair.gov>  
Email: [Tina@swcleanair.gov](mailto:Tina@swcleanair.gov)

## Notice of Intent to Remove Asbestos

Case #: 25-071

Amendment: 0

Date Received: 1/22/2025

Date Paid: 1/22/2025

SWCAA Fee: \$384.00

Receipt #: 169704164

**This notification MUST be present at all times at the asbestos project sit**

---

December 20, 2024

Jesse Koonce

Premier Restoration Partners  
7170 SW 76th Avenue  
Portland, OR

Cascade Environmental LLC

4346 NE 73rd Avenue  
Portland, Oregon 97218

Phone 503 984 9737

[www.cascadenviro.com](http://www.cascadenviro.com)

**Re: Pre-Restoration Asbestos Survey and Lead Paint Investigation  
Residence  
10009 NE Heron Circle  
Vancouver, Washington  
Cascade Environmental Project No.: 12162024-01**

Dear Jesse:

Cascade Environmental has prepared this Pre-Restoration Asbestos Survey and Lead Paint Investigation report for the location referenced above. It should be noted that the survey was limited to areas and materials that were planned for restoration. If the scope of work is expanded, including but not limited to the bathroom and hallway, further sampling may be required.

### **SCOPE OF WORK**

Cascade Environmental conducted asbestos-containing materials (ACMs) sampling and lead-based paint (LBP) sampling to determine the presence of asbestos or lead that may be impacted during the planned restoration of the residence. The two-story, with attached garage, approximately 1,740 square foot residence was constructed in 1977. Cascade Environmental's Asbestos Hazard Emergency Response Act (AHERA) Certified Asbestos Inspector and Lead Renovator, Robert Burns, conducted the survey on December 16, 2024 accordance with federal, state and local regulations.

### **ASBESTOS SURVEY**

#### **Sampling and Analysis**

Cascade Environmental's asbestos survey was performed following the sampling protocols outlined under applicable United States Environmental Protection Agency (EPA) and the Southwest Washington Clean Air Agency regulations.

Bulk samples of suspect ACMs were collected and sent to QuanTEM Laboratories for analysis using Polarized Light Microscopy (PLM) in accordance with EPA "Method for the Determination of Asbestos in Bulk Building Materials" (EPA/600/R-93/116, July 1993). QuanTEM Laboratories is located in Oklahoma City, Oklahoma, and is registered as an American Industrial Hygiene Association-accredited and National Voluntary Lab Accreditation Participation (#101959)-accredited laboratory. Routinely, the amount of asbestos is determined using a semi-quantitative technique, which involves calibrated visual area estimation. This quantitative method expresses the amount of asbestos as percent area and has a limit of detection of less than one percent. When required, the amount of asbestos can be estimated using another semi-quantitative area estimation technique called point counting. In combination with gravimetric sample reduction procedures, point counting can achieve limits of less than one percent (<1%), when 400 points are counted and less than a tenth of a percent (<0.10%) if at least 1,000 points are counted

ACM's as defined by the EPA and the Southwest Washington Clean Air Agency are materials with an asbestos concentration greater than one percent (>1%). However, the Occupational Safety and Health Administration (OSHA) regulates all materials containing any detectable levels of asbestos.

## FINDINGS

A summary of Cascade Environmental's asbestos inspection, including analytical results, sample numbers, material descriptions, material's friability and sample locations is provided in the following table. Analytical results and chain-of-custody documentation is included in Appendix A.

<b>Table 1</b> <b>ACM Sample Results</b> <b>10009 NE Heron Circle</b> <b>Vancouver, Washington</b>						
HA #	Sample #	Homogeneous Material	Sample Location	Friable	Est. Quantity*	Asbestos Content
01	HC-01	<b>Ceiling Texture, Knock Down, Heavy</b>	<b>Front Entry</b>	<b>Yes</b>	<b>1,000</b>	<b>3% Chrysotile</b>
01	HC-02	<b>Ceiling Texture, Knock Down, Heavy</b>	<b>Dining Area</b>	<b>Yes</b>	“	<b>Not Analyzed**</b>
01	HC-03	<b>Ceiling Texture, Knock Down, Heavy</b>	<b>Living Room</b>	<b>Yes</b>	“	<b>Not Analyzed**</b>
01	HC-04	<b>Ceiling Texture, Knock Down, Heavy</b>	<b>Stairwell</b>	<b>Yes</b>	“	<b>Not Analyzed**</b>
01	HC-05	<b>Ceiling Texture, Knock Down, Heavy</b>	<b>2<sup>nd</sup> Floor North Bedroom</b>	<b>Yes</b>	“	<b>Not Analyzed**</b>
02	HC-06	Wall Texture, Knock Down, Heavy	Front Closet Alcove	Yes	120 SF	ND
02	HC-07	Wall Texture, Knock Down, Heavy	Living Room	Yes	“	ND
02	HC-08	Wall Texture, Knock Down, Heavy	Front Entry	Yes	“	ND
03	HC-09	<b>Wallboard/Joint Compound and Light Texture</b>	<b>Front Entry</b>	<b>Yes</b>	<b>400 SF</b>	<b>Joint Compound-2% Chrysotile, Texture - 3% Chrysotile</b>
03	HC-10	<b>Wallboard/Joint Compound and Light Texture</b>	<b>Dining Area</b>	<b>Yes</b>	“	<b>Not Analyzed**</b>
03	HC-11	<b>Wallboard/Joint Compound and Light Texture</b>	<b>Kitchen</b>	<b>Yes</b>	“	<b>Not Analyzed**</b>
04	HC-12	Composite Shingle Roofing, Top Layer-Black, Bottom Layer-Brown, and Tarpaper	Unit 24 Front Hallway	Yes	1,700 SF	ND
04	HC-13	Composite Shingle Roofing, Top Layer-Black, Bottom Layer-Brown, and Tarpaper	Unit 26 Dining Area	Yes	“	ND

ND - Non-Detect

HA – Homogeneous Area (Material)

**Bold** – Indicates at least one layer of the material sampled contains greater than one percent asbestos.

All materials were noted to be in fair to good condition at the time of the survey unless noted.

\*All quantities are rough estimates only and should not be used for bidding purposes.

\*\* The laboratory was instructed to stop at the first positive result for asbestos per homogeneous material. All of the identified asbestos containing homogeneous material are assumed to be asbestos containing.

### Results/Discussion/Recommendations:

The laboratory analytical results for this survey indicated that eight of the thirteen samples collected during this survey contained greater than one percent asbestos, or are assumed to contain asbestos and are considered ACMs. It should be noted the identified ACMs were observed as significantly damaged with potential contamination of personal contents. The identified ACMs should be removed per local, state and federal regulations prior to disturbance. In addition, the personal contents should be cleaned or disposed of as asbestos containing.

Caution should be used during restoration activities as concealed building materials that have not previously been analyzed for asbestos' may be encountered. If suspect ACMs located in accessible and/or inaccessible areas of the facility are encountered during restoration activities, further sampling will be required to characterize those materials, prior to any disturbance.

## LEAD PAINT SAMPLING

### Sampling and Analysis

Paint chip samples were collected from representative components from the interior and exterior of the structures. Bulk samples of paint were collected and submitted to QuanTEM Laboratories for analysis per Method P EPA 7000B.

## FINDINGS

A summary of Cascade Environmental's lead paint sampling, including analytical results, sample numbers, material descriptions and sample locations is provided in the following table. Analytical results and chain-of-custody documentation is included in Appendix A.

<b>Table 2</b> <b>Lead Paint Sampling Results</b> <b>2313 SE 106th Avenue</b> <b>Vancouver, Washington</b>			
<b>Sample #</b>	<b>Material Description</b>	<b>Sample Location</b>	<b>Results Wt%</b>
LHC-01	White, Wallboard Ceiling, Light Texture	2 <sup>nd</sup> Floor Hallway	BRL
LHC-02	White, Wallboard, Ceiling, Heavy Texture	Living Room	BRL
LHC-03	White, Wallboard, Wall	Dining Area	BRL
LHC-04	Glossy White, Wallboard, Wall	Kitchen	BRL
LHC-05	White, Wallboard, Ceiling	Kitchen	BRL

**Bold** – Indicates the paint contained detectible levels of lead.

BRL – Below Reporting Limits

### Results/Discussion/Recommendations:

The laboratory analytical results for this survey indicated that none of the five samples contained measurable quantities of lead.

### LIMITATIONS

Reasonable effort was made by Cascade Environmental personnel to locate and sample suspect materials at the location. However, the existence of unique or concealed ACM, LBP, other hazardous materials or associated debris is a possibility within any facility. If additional suspect ACM, LBP or other hazardous material is discovered during restoration it should be assumed to be hazardous until sampling and analysis proves otherwise. Cascade



Environmental does not warrant, guarantee or profess to have the ability to locate or identify all hazardous materials within a facility.

If you have any questions regarding this report or require further clarification, please do not hesitate to contact our office at (503) 984-9737.

Sincerely,

**Cascade Environmental**

A handwritten signature in black ink, appearing to read "Robert Burns".

Robert Burns

Principal

AHERA Inspector # IRO-24-4095A

RRP # R-I-41R036-22-00160

Appendices: Appendix A – Laboratory Analytical Results, Chain-of-Custody Documentation and Inspector Certificates

APPENDIX A  
LABORATORY ANALYTICAL RESULTS  
CHAIN-OF-CUSTODY DOCUMENTATION  
& INSPECTOR CERTIFICATES

APPENDIX A  
LABORATORY ANALYTICAL RESULTS  
CHAIN-OF-CUSTODY DOCUMENTATION  
& INSPECTOR CERTIFICATES





2033 HERITAGE PARK DR, OKLAHOMA CITY, OK 73120 | 1.800.822.1650

### Polarized Light Microscopy Asbestos Analysis Report

Quantem Lab No. 375051	Client: Cascade Environmental LLC
Account Number: C059	4346 NE 73rd Ave
	Portland, OR 97218
Date Received: 12/17/2024	
Received By: Baylie Longstreth	
Date Analyzed: 12/17/2024	Project: 10009 NE Heron Circle Vancouver, WA
Analyzed By: Cassie Sanborn	Project Location: N/A
Methodology: EPA/600/R-93/116	Project Number: N/A

Quantem Sample ID	Client Sample ID	Composition	Color / Description	Asbestos (%)	Non-Asbestos Fiber (%)	Non Fibrous
001	HC- 01	Layered	Tan Ceiling Texture	Asbestos Present Chrysotile 3	NA	CaCO3 Sand Paint
001a		Layered	Tan Wallboard	Asbestos Not Present	Cellulose 10	Gypsum
002	HC- 02	Homogeneous	** Ceiling Texture	**	Not Analyzed	
Positive Stop						
003	HC- 03	Layered	** Ceiling Texture	**	Not Analyzed	
Positive Stop						
003a		Layered	White Wallboard	Asbestos Not Present	Cellulose 10	Gypsum
004	HC- 04	Layered	** Ceiling Texture	**	Not Analyzed	
Positive Stop						
004a		Layered	White Wallboard	Asbestos Not Present	Cellulose 10	Gypsum

Unless otherwise noted, upon receipt the condition of the sample was acceptable for analysis.

Quantem is a NVLAP accredited Testing PLM laboratory (Lab Code: 101959-0). This report relates only to the specific items tested. NVLAP accreditation applies only to analysis performed utilizing EPA—40 CFR Appendix E to Subpart E of Part 763 and EPA/600/R-93/116 methods. This report may not be used to claim product endorsement by NVLAP or any agency of the US Government. This report may not be reproduced except in full, without the written approval of the laboratory.



2033 HERITAGE PARK DR, OKLAHOMA CITY, OK 73120 | 1.800.822.1650

### Polarized Light Microscopy Asbestos Analysis Report

Quantem Lab No. 375051	Client: Cascade Environmental LLC
Account Number: C059	4346 NE 73rd Ave
	Portland, OR 97218
Date Received: 12/17/2024	
Received By: Baylie Longstreth	
Date Analyzed: 12/17/2024	Project: 10009 NE Heron Circle Vancouver, WA
Analyzed By: Cassie Sanborn	Project Location: N/A
Methodology: EPA/600/R-93/116	Project Number: N/A

Quantem Sample ID	Client Sample ID	Composition	Color / Description	Asbestos (%)	Non-Asbestos Fiber (%)	Non Fibrous
005	HC- 05	Layered	** Ceiling Texture	**		Not Analyzed
Positive Stop						
005a		Layered	White Wallboard	Asbestos Not Present	Cellulose 10	Gypsum
006	HC- 06	Homogeneous	Tan Wall Texture	Asbestos Not Present	NA	CaCO3 Paint
007	HC- 07	Homogeneous	Tan Wall Texture	Asbestos Not Present	NA	CaCO3 Paint
008	HC- 08	Layered	Tan Wall Texture	Asbestos Not Present	NA	CaCO3 Paint
008a		Layered	White Wallboard	Asbestos Not Present	Cellulose 10	Gypsum

Unless otherwise noted, upon receipt the condition of the sample was acceptable for analysis.

Quantem is a NVLAP accredited Testing PLM laboratory (Lab Code: 101959-0). This report relates only to the specific items tested. NVLAP accreditation applies only to analysis performed utilizing EPA—40 CFR Appendix E to Subpart E of Part 763 and EPA/600/R-93/116 methods.

This report may not be used to claim product endorsement by NVLAP or any agency of the US Government.

This report may not be reproduced except in full, without the written approval of the laboratory.



2033 HERITAGE PARK DR, OKLAHOMA CITY, OK 73120 | 1.800.822.1650

### Polarized Light Microscopy Asbestos Analysis Report

Quantem Lab No. 375051	Client: Cascade Environmental LLC
Account Number: C059	4346 NE 73rd Ave
	Portland, OR 97218
Date Received: 12/17/2024	
Received By: Baylie Longstreth	
Date Analyzed: 12/17/2024	Project: 10009 NE Heron Circle Vancouver, WA
Analyzed By: Cassie Sanborn	Project Location: N/A
Methodology: EPA/600/R-93/116	Project Number: N/A

Quantem Sample ID	Client Sample ID	Composition	Color / Description	Asbestos (%)	Non-Asbestos Fiber (%)	Non Fibrous
009	HC- 09	Layered	White Texture	Asbestos Present Chrysotile 2	NA	CaCO3 Paint
009a		Layered	White Joint Compound	Asbestos Present Chrysotile 3	NA	CaCO3
009b		Layered	White Wallboard	Asbestos Not Present	Cellulose 10	Gypsum
010	HC- 10	Layered	** Texture	**	Not Analyzed	
Positive Stop						
010a		Layered	** Joint Compound	**	Not Analyzed	
Positive Stop						
010b		Layered	White Wallboard	Asbestos Not Present	Cellulose 10	Gypsum
011	HC- 11	Layered	** Texture	**	Not Analyzed	

Unless otherwise noted, upon receipt the condition of the sample was acceptable for analysis.

Quantem is a NVLAP accredited Testing PLM laboratory (Lab Code: 101959-0). This report relates only to the specific items tested. NVLAP accreditation applies only to analysis performed utilizing EPA—40 CFR Appendix E to Subpart E of Part 763 and EPA/600/R-93/116 methods. This report may not be used to claim product endorsement by NVLAP or any agency of the US Government. This report may not be reproduced except in full, without the written approval of the laboratory.



2033 HERITAGE PARK DR, OKLAHOMA CITY, OK 73120 | 1.800.822.1650

### Polarized Light Microscopy Asbestos Analysis Report

Quantem Lab No. 375051	Client: Cascade Environmental LLC
Account Number: C059	4346 NE 73rd Ave
	Portland, OR 97218
Date Received: 12/17/2024	
Received By: Baylie Longstreth	
Date Analyzed: 12/17/2024	Project: 10009 NE Heron Circle Vancouver, WA
Analyzed By: Cassie Sanborn	Project Location: N/A
Methodology: EPA/600/R-93/116	Project Number: N/A

Quantem Sample ID	Client Sample ID	Composition	Color / Description	Asbestos (%)	Non-Asbestos Fiber (%)	Non Fibrous
Positive Stop						
011a		Layered	** Joint Compound	**	Not Analyzed	
Positive Stop						
011b		Layered	White Wallboard	Asbestos Not Present	Cellulose 10	Gypsum
012	HC- 12	Layered	Black Shingle	Asbestos Not Present	Glass Fiber 20	Tar Sand CaCO3
012a		Layered	Brown Shingle	Asbestos Not Present	Cellulose 30	Tar Sand
012b		Layered	Black Tar Paper	Asbestos Not Present	Cellulose 60	Tar
013	HC- 13	Layered	Black Shingle	Asbestos Not Present	Glass Fiber 20	Tar Sand CaCO3

Unless otherwise noted, upon receipt the condition of the sample was acceptable for analysis.

Quantem is a NVLAP accredited Testing PLM laboratory (Lab Code: 101959-0). This report relates only to the specific items tested. NVLAP accreditation applies only to analysis performed utilizing EPA—40 CFR Appendix E to Subpart E of Part 763 and EPA/600/R-93/116 methods. This report may not be used to claim product endorsement by NVLAP or any agency of the US Government. This report may not be reproduced except in full, without the written approval of the laboratory.



2033 HERITAGE PARK DR, OKLAHOMA CITY, OK 73120 | 1.800.822.1650

### Polarized Light Microscopy Asbestos Analysis Report

Quantem Lab No. 375051	Client: Cascade Environmental LLC
Account Number: C059	4346 NE 73rd Ave
	Portland, OR 97218
Date Received: 12/17/2024	
Received By: Baylie Longstreth	
Date Analyzed: 12/17/2024	Project: 10009 NE Heron Circle Vancouver, WA
Analyzed By: Cassie Sanborn	Project Location: N/A
Methodology: EPA/600/R-93/116	Project Number: N/A

Quantem Sample ID	Client Sample ID	Composition	Color / Description	Asbestos (%)	Non-Asbestos Fiber (%)	Non Fibrous
013a		Layered	Brown Shingle	Asbestos Not Present	Cellulose 30	Tar Sand
013b		Layered	Black Tar Paper	Asbestos Not Present	Cellulose 60	Tar

*Cassie Sanborn*

Cassie Sanborn, Laboratory Analyst

12/17/2024

Date of Report

Unless otherwise noted, upon receipt the condition of the sample was acceptable for analysis.

Quantem is a NVLAP accredited Testing PLM laboratory (Lab Code: 101959-0). This report relates only to the specific items tested. NVLAP accreditation applies only to analysis performed utilizing EPA—40 CFR Appendix E to Subpart E of Part 763 and EPA/600/R-93/116 methods. This report may not be used to claim product endorsement by NVLAP or any agency of the US Government.

This report may not be reproduced except in full, without the written approval of the laboratory.



PROJECT INFORMATION

Turnaround:

Same Day

Next Day

3-5 day

Company/Customer: Cascade Environmental	Project Name: 10809 NE Heron St. Circle
Address: 4346 NE 73 <sup>rd</sup> Avenue	Collection Date: 12-16-24 Vancouver, WA
Address: Portland, Or 97218	Customer Number/P.O.:
Phone: 503.984.9737	Collection Address:
Customer Contact: Bob Burns	Email: bob@cascadenviro.com

Special Instructions: PLM (EPA 600/R-93/116, Please composite all Wallboard/Joint Compound samples

(Sample #s) Please stop at first positive per HA, Thanks

BULK SAMPLE LOCATION please cc tylor@prp247.com Page 1 of 1

HA	Sample Number	Sample Material	Sample Location	Friable ?	App. Qty.
01	HC-01	Ceiling Texture, Knock Down Heavy	Front Entry	Y	1,000 SF
	-02		Dining Area	Y	21
	-03		Living Room	Y	21
	-04		Stairwell	Y	15
	-05		2nd Fl. N. Bedroom	Y	10
02	-06	Wall Texture, Heavy Knock Down Heavy	Front Closet	Y	100 SF
	-07		Living Room	Y	
	-08		Front Entry	Y	
05	-09	Wallboard/Joint Compound & Light Texture	Front Entry	Y	400 SF
	-10		Dining Area	Y	11
	-11		Kitchen	Y	11

Note: Sample collector is responsible for ensuring that all samples have been preserved and prepared to the appropriate and applicable methodology. If package has sustained damage during transit, notify collector and shipper. Turnaround time begins upon receipt of sample (s) by laboratory. All material was considered in good condition unless otherwise noted.

CHAIN OF CUSTODY

Relinquished By:	Date:	Time:	Received By:	Date:	Time:
<i>R Burns</i>	12-16-24	1330	<i>Ambrose</i>	12/17/24	10:00

~~104/12 Composite Shingle Roofing, Top Layer~~ ~~Roof~~ ~~N~~ ~~1800 SF~~  
~~104/13 Black, Bottom Brown, and Dark~~ ~~Roof~~ ~~N~~ ~~1500 SF~~




2033 HERITAGE PARK DR, OKLAHOMA CITY, OK 73120 | 1.800.822.1650

## Environmental Chemistry Analysis Report

**QuanTEM Set ID:** 375052  
**Date Received:** 12/17/24  
**Received By:** Eric Caves  
**Date Sampled:**  
**Time Sampled:**  
**Analyst:**  
**Date of Report:** 12/17/24  
 AIHA LAP, LLC: 101352

**Client:** Cascade Environmental LLC  
 4346 NE 73rd Ave  
 Portland, OR 97218  
  
**Acct. No.:** C059  
  
**Project:** 10009 NE Heron Circle  
**Location:** Vancouver, WA  
**Project No.:** N/A

QuanTEM ID	Client ID	Matrix	Parameter	Results	Reporting Limits	Units	Date/Time Analyzed	Method
001	CHC-01	Paint	Lead	<0.0050	0.005	%	12/17/24 13:26	P EPA 7000B (1)
002	CHC-02	Paint	Lead	<0.0049	0.0049	%	12/17/24 13:26	P EPA 7000B (1)
003	CHC-03	Paint	Lead	<0.0050	0.005	%	12/17/24 13:26	P EPA 7000B (1)
004	CHC-04	Paint	Lead	<0.0049	0.0049	%	12/17/24 13:26	P EPA 7000B (1)
005	CHC-05	Paint	Lead	<0.0050	0.005	%	12/17/24 13:26	P EPA 7000B (1)

**Authorized Signature:**   
 Eric Caves, Chemistry Technical Manager

Note: Sample results have not been corrected for blank values.

This report applies only to the standards or procedures indicated and to the specific samples tested. It is not indicative of the qualities of apparently identical or similar products or procedures, nor does it represent an ongoing assurance program unless so noted. These reports are for the exclusive use of the client and are not to be reproduced without specific written permission. QuanTEM is not responsible for user-supplied data used in calculations. Customer provided data such as volumes, areas, etc., cannot be verified by QuanTEM Laboratories, LLC.

Unless otherwise noted, upon receipt the condition of the sample was acceptable for analysis.

Wipe materials must meet ASTM E1792 criteria. Method detection limits and resultant reporting limits may not be valid for non-ASTM E1792 wipe material.

EPA Method 7000B (1) = EPA 600/R-93/200 Preparation Modified. EPA 7000B Analysis Modified

EPA Method 7082 (2) = EPA 600/R-93/200 Preparation Modified. EPA 7082 Analysis Modified

# Supplemental Report

## QAQC Results

QA ID: 21392  
Test: Lead

Date: 12/17/2024  
Matrix: Paint

Lab Number: 375052  
Approved By: Eric Caves  
Date Approved: 12/17/2024

### Notes:

### Blank Data:

Type of Blank	Blank Value
FCB	0
ICB	0

### Standards Data:

Standard	Low Limit	Obtained	High Limit
FCV	2.2	2.59	2.8
CCV	2.2	2.54	2.8
RLVS	0.05	0.11	0.15
ICV	0.9	1.03	1.1

### Duplicate Data:

Sample Number	Result	Duplicate	% RPD
375038-001	0.200	0.210	4.9

### Recovery Data:


Sample Number	Result	Spike Level	Result + Spike	% Recovery	Dup. Result + Spike	% Dup. Recovery	% Spike RPD
LCS-P	0.000	2.010	2.050	102.0	2.010	100.0	2.0
375038-001	0.200	2.000	2.000	90.0			

Authorized Signature: \_\_\_\_\_



Eric Caves, Chemistry Technical Manager





# LEAD CHAIN OF CUSTODY

2033 Heritage Park Drive, Oklahoma City, OK 73120-7502  
 (800) 822-1650 • (405) 755-7272 • Fax: (405) 755-2058

## LEGAL DOCUMENT - PLEASE PRINT LEGIBLY

Contact Information		Project Information	
Company: Cascade Environmental LLC	Phone: (503) 984-9737	Project Name: 10008 NE Algonquin	Report Results ( <input checked="" type="checkbox"/> one box )
Contact: Bob Burns	Cell Phone: (503) 984-9737	Project Location: Vanouver WA	Quantem Website
Account #:	E-mail: bob@cascadenviron.com	Project ID:	Email bob@cascadenviron.com
SAMPLED BY: Name: Bob Burns	Date:	cc Taylor @ p.p. 247.18 m	Other

RELINQUISHED BY	VIA	RECEIVED BY	DATE & TIME
<i>[Signature]</i>	FedEx	<i>[Signature]</i>	12/17/24 10:00

### REQUESTED SERVICES (Please the Appropriate Boxes)

No.	Sample ID (10 Characters Max)	Sample Description	Volume (Liters)	Volume Area (Length x Width)	Sample Matrix (see matrix code box)	Analysis						Sample Matrix Codes	
						PPM	Wt %	mg / l	µg / ft <sup>2</sup>	µg / m <sup>3</sup>	mg / cm <sup>2</sup>		
1												A	Soil
2												B	Paint Chips
3												C	Surface / Dust Wipes
4												D	Bulk Miscellaneous
5												E	Air Cassette
6													
7													
8													
9													
10													
11													
12													

*See Page 2*

TURNAROUND TIME
<input checked="" type="checkbox"/> Same Day
<input type="checkbox"/> 24 - Hour
<input type="checkbox"/> 3 - Day
<input type="checkbox"/> 5 - Day



# LEAD CHAIN OF CUSTODY

2033 Heritage Park Drive, Oklahoma City, OK 73120-7502  
 (800) 822-1650 • (405) 755-7272 • Fax: (405) 755-2058

**LEGAL DOCUMENT - PLEASE PRINT LEGIBLY**

Page 2 of 2

For Lab Use Only
Lab No. _____
Accept <input type="checkbox"/> Reject <input type="checkbox"/>

Project Information	
Company: Cascade Environmental LLC	Project Name: <u>10009 NE Heron Circle</u>
	Project Location: <u>Van Couver, WA</u>

**REQUESTED SERVICES (Please  the Appropriate Boxes)**

No.	Sample ID (10 Characters Max)	Sample Description	Volume (Liters)	Volume Area (Length x Width)	Sample Matrix (see matrix code box)	Analysis	Units ( <input checked="" type="checkbox"/> ONE box only)					Sample Matrix Codes
							Pb	Pb	mg / l	µg / ft <sup>2</sup>	µg / m <sup>3</sup>	
13	<u>CHC-01</u>	<u>white, wallboard ceiling, light fixture</u>										
14	<u>-02</u>	<u>ceiling heavy textured living room</u>										
15	<u>-03</u>	<u>white wall board wall   Dining</u>										
16	<u>-04</u>	<u>Gloss white wall board wall   Kitchen</u>										
17	<u>05</u>	<u>white wallboard ceiling   Kitchen</u>										
18												
19												
20												
21												
22												
23												
24												
25												
26												
27												
28												
29												
30												



THIS IS TO CERTIFY THAT

**ROBERT BURNS**

**HAS SUCCESSFULLY COMPLETED THE TRAINING COURSE**

for

**ONLINE AHERA ASBESTOS INSPECTOR REFRESHER**

In accordance with TSCA Title II, Part 763, Subpart E, Appendix C of 40 CFR

Course Date: 08/13/2024

Course Location: Online

Certificate: IRO-24-4095A



**CCB #SRA0615 4-Hr Training**

4-Hour Online AHERA Inspector Refresher Training; AHERA is the Asbestos Hazard Emergency Response Act enacting Title II of Toxic Substance Control Act (TSCA)

**Expiration Date:** 08/13/2025

For verification of the authenticity of this certificate contact:  
PBS Engineering and Environmental Inc.  
4412 S Corbett Avenue  
Portland, OR 97239  
503.248.1939

A handwritten signature in black ink that reads 'Andy Fridley'.

Andy Fridley, Instructor



**LEAD**  
**CLASSES.COM**

EPA HUD & STATE RRP LEAD PAINT CERTIFICATION

10350 N Vancouver Way, 1021  
Portland OR 97217  
Info@LeadClasses.com

**1-888-840-8388**

## Certificate of Attendance and Successful Completion Renovator Initial - English

Issued per OAC 333-070 and 40 CFR Part 745.225

**Robert Burns**  
**4346 NE 73rd Ave**  
**Portland , OR 97218**  
**Certificate # R-I-41R036-22-00160**

Course Date: 03/24/2022  
Exam Date: 03/24/2022  
Expiration Date: 03/24/2027

3/24/2022

Steven Hoff      Training Manager  
Crosswall Training / LeadClasses.com

Date

