

### **Notification of Demolition**

Case #: 25-089

11815 NE 99th Street, Suite 1294

Vancouver, WA 98662 Voice: 360-574-3058 Fax: 360-576-0925

Web: https://www.swcleanair.gov Email: Tina@swcleanair.gov Date Received: 1/30/2025

Date Paid: 1/30/2025

SWCAA Fee: \$77.00

Receipt #: 170137863

Amendment: 0

### 10 day waiting period from date submitted

Type of Notification: Original
 Type of Operation: Demolition

3. Facility Description: House and detached garage

Commercial Name or Description: 13018 NE 71st Avenue

Address: 13018 NE 71st Avenue

City/State/Zip/County: Vancouver, WA 98686 CLARK COUNTY

Present Use: Vacant Previous Use: Residence

Property Owner:

4. Facility Information

Property Owner: MAJ Development

Mailing Address: 1500 D St, Vancouver WA 98663

Phone: 3608235102

5. Name and AHERA Certification Number of Asbestos Inspector:

Name: Jason Hawks Certification #: BI/R-NES-12-01-23-07

6. Asbestos Removal Contractor (if applicable):

Name: No asbestos

7. Dates Asbestos Removal Occurred:

Start: Complete: Asbestos Case No.: 00-000-0

8. Dates Demolition Will Occur:

Start: 2/10/2025 Complete: 2/28/2025

9. Demolition Contractor:

Name: Global Pacific Environmental Inc.
Mailing Address: PO Box 2759, Vancouver, WA, 98668

Contact Kevin Crouse Phone: 360-772-6402

10. Asbestos Disposal Site: No Landfill Location:

11. Description of	planned demolition work, method(s) to be used:	
Demolition and	d cleanup of site using excavator and end dump truck	S.
12. Fugitive Emssi	ons/dust from Demolition Activites MUST BE Contro	olled/Prevented during all phases of the project
Water tanker		
•	Asbestos containing Material (ACM) is found during rtified Asbestos Abatement Contractor	demolition, Stop Work, Notify SWCAA and
Survey conduct	ted and composite sampling methods used to detern	nine all materials are <1% asbestos by weight.
14. If demolition i	s ordered by a Government Agent:	
15. For Emergency	y Demolitions (Contact SWCAA prior to work):	Emergency Demolition
Date and Time	of Emergency:	
Description of	Sudden, Unexpected Event:	
Explanation of burden:	f how the event caused unsafe conditions or would	cause equipment damage or an unreasonable
16. I Certify that t	he above information is correct:	
Submitter Name:	Kevin Crouse / Global Pacific Environmental	Representing: Global Pacific Environmental
Submitter Title:	VP Operations	Date Submitted: 1/30/2025
Email Address:	kevin@globalpacific.info	
Reviewed by SWC	CAA: Mihai Voivod	<b>✓</b> Approved

The Washington State Dangerous Waste Regulations (WAC 173-303) require that demolition debris be evaluated to determine if it is dangerous. The evaluation should be completed before demolition to ensure that hazardous constituents are not released to the environment and do not present a risk to human health during or after demolition. These requirements apply to all buildings being demolished and are the responsibility of the property owner. The Washington Department of Ecology's website, https://ecology.was.gov/Regulations-Permits/Guidance-technical-assistance/Dangerous-waste-guidance/Common-dangerous-waste/Construction-and-demolition, provides more information about the requirements and about sampling and testing construction materials to detemine if they present a risk. For more information please contact a Hazardous Waste Inspector at the Washington Department of Ecology Southwest Regional Office: (360) 407-6300.



3 Kings Environmental, Inc.

### Asbestos Containing Materials Inspection

Good Faith Inspection



January 14, 2025

MAJ Development Corporation 300 West 15<sup>th</sup> Street, Suite 200 Prepared For:

Vancouver. WA 98660

13018 NE 71st Ave. Project:

Vancouver, WA 98686

RE: Pre-Demolition Good Faith Asbestos Survey

### FRONT OF STRUCTURE





### **INSPECTION REPORT**



### **BACKGROUND**

On January 9<sup>th</sup>, 2024, 3 Kings Environmental, Inc. performed a Pre-Demolition Good Faith Asbestos Inspection of the above mentioned project to determine the presence of asbestos containing materials (ACMs). The intent of this inspection is to ensure that the property owner is in compliance with the regulatory requirements for the identification of ACMs prior to any demolition or renovation activities.

### **BUILDING DESCRIPTION**

The structure was a wood framed single family residence. The home was on a concrete foundation with a attached garage with a concrete slab.

Year Built: 1977

Approximate Size: Home 1,380 SF with a 420 SF attached garage. Barn was approx. 2,000 SF

### **Interior Finishes:**

The interior of the home was primarily drywall walls and ceiling. Floors were primarily laminate plank with carpet in the bedrooms. Sheet vinyl floors were found under sections of the laminate in the kitchen, bathroom and entry.

### **Exterior Finishes:**

The exterior of home consisted of vinyl windows, wood siding, wood trim and asphalt type roofing shingles.

### **SAMPLING PROCESS**

All accessible areas of the specific work area were sampled during the inspection. Inaccessible areas are those defined as requiring select demolition, fall protection, repair to the structure i.e. weather protection or water proofing or are considered a confined space entry. If during the course of asbestos abatement or demolition suspect materials are discovered that are not identified on this report stop work immediately. These materials need to be treated as asbestos containing until the material can be tested by an AHERA Building Inspector and determined otherwise.

Suspect materials were collected by an AHERA certified building inspector. Samples are then given a unique identification number. Sample information such as type of material and its locations are then placed on the chain of custody that accompany the samples to the testing laboratory. Once the samples are delivered to an asbestos laboratory for analysis. Samples are analyzed by polarized light microscopy (PLM) with dispersion staining in accordance with USEPA 600/M-82/020, which has a reliable limit of quantification of one percent asbestos by volume.

Samples were collected following EPA guidelines. The suspect materials are broken down into three categories: Surfacing Materials, Thermal System Insulation, and Miscellaneous Materials. Each of these categories have a set of guidelines that were followed that include the number of samples required for that particular category based on the quantity of the material, how the material was applied and what was the intent of the material. All these factors are accounted for during the time of inspection.

### **AHERA Certified Building Inspector**



Certified AHERA Building Inspector was Jason Hawks Certification # BI/R-NES-12-01-23-07, Expiration December 1, 2024

### **SURVEY FINDINGS**

Materials found to contain asbestos in concentrations greater than one percent (>1%) as part of this investigation and estimated quantities for removal:

Sample #	Material Description	Sample Location	Friability /	Lab Result	Quantity
			Condition		
			/ Category		
06	Orange Peel Texture;	Living Room – Found	F / Good	2%	Not
	Gypsum Wall Board	throughout		Chrysotile	Quantified
	& Joint Compound			in the Joint	
				Compound.	
				Less than	
				1% as a	
				composite	
				per WRD	
				23.30.	



The following is a summary of all the suspect bulk asbestos sampled during the inspection.

Sample #	Material Description & Location	Friability & Condition	Material Category	Lab Result
01	Popcorn Ceiling Texture; Plaster Skim & Gypsum Wall Board / Dining Room	F / Good	S	NAD
02	Popcorn Ceiling Texture; Plaster Skim & Gypsum Wall Board / Living Room	F / Good	S	NAD
03	Popcorn Ceiling Texture; Plaster Skim & Gypsum Wall Board / Bedroom 1	F / Good	S	NAD
04	Popcorn Ceiling Texture; Plaster Skim & Gypsum Wall Board / Bedroom 2	F / Good	S	NAD
05	Popcorn Ceiling Texture; Plaster Skim & Gypsum Wall Board /	F / Good	S	NAD



06	Orange Peel Texture; Gypsum Wall Board & Joint Compound / Living Room	F / Good	S	2% Chrysotile
07	Orange Peel Texture; Gypsum Wall Board & Joint Compound / Kitchen	F / Good	S	PACM
08	Orange Peel Texture; Gypsum Wall Board & Joint Compound / Hall	F / Good	S	PACM
09	Orange Peel Texture; Gypsum Wall Board & Joint Compound / Front Entry	F / Good	S	PACM
10	Orange Peel Texture; Gypsum Wall Board & Joint Compound / Master Bedroom	F / Good	S	PACM
11	Wall Panel Mastic / Living Room	NF / Good	M	NAD
12	Wall Panel Mastic / Living Room	NF / Good	M	NAD
13	White Marble Sheet Vinyl Flooring & Mastic / Kitchen	NF / Good	M	NAD
14	White Marble Sheet Vinyl Flooring & Mastic / Kitchen	NF / Good	M	NAD
15	Black Squeak Sheet / Kitchen	NF / Good	M	NAD
16	Black Squeak Sheet / Kitchen	NF / Good	M	NAD
17	Cream/Floral Sheet Vinyl Flooring / Halle Bathroom	NF / Good	M	NAD
18	Cream/Floral Sheet Vinyl Flooring / Halle Bathroom	NF / Good	M	NAD
19	Multilayer Multicolor Sheet Vinyl Flooring & Mastic / Master Bathroom	NF / Good	M	NAD
20	Multilayer Multicolor Sheet Vinyl Flooring & Mastic / Master Bathroom	NF / Good	M	NAD
21	Sink Undercoat / Kitchen	NF / Good	M	NAD
22	Sink Undercoat / Kitchen	NF / Good	M	NAD
23	"X" Pattern Sheet Vinyl Flooring & Mastic / Entry	NF / Good	M	NAD
24	"X" Pattern Sheet Vinyl Flooring & Mastic / Entry	NF / Good	M	NAD
25	Cream w/Blue Squares Sheet Vinyl Flooring / Living Room	NF / Good	M	NAD
26	Cream w/Blue Squares Sheet Vinyl Flooring / Living Room	NF / Good	M	NAD
27	Roofing / Shed 1	NF / Good	M	NAD
28	Roofing / Shed 1	NF / Good	M	NAD
29	Roof Felt / Shed 1	NF / Good	M	NAD
30	Roof Felt / Shed 1	NF / Good	M	NAD
31	House Roof	NF / Good	M	NAD
32	House Roof	NF / Good	M	NAD
33	House Roof Felt	NF / Good	M	NAD
34	House Roof Felt	NF / Good	M	NAD



35	Window Caulking	NF / Good	M	NAD
36	Window Caulking	NF / Good	M	NAD
37	Roof / Shed 2	NF / Good	M	NAD
38	Roof / Shed 2	NF / Good	M	NAD
39	Roof Felt / Shed 2	NF / Good	M	NAD
40	Roof Felt / Shed 2	NF / Good	M	NAD

Legend:	Category:
NAD – No Asbestos Detected	S – Surfacing Material
F – Friable (can be pulverized by hand pressure)	TSI – Thermal System Insulation
NF – Non-Friable	M – Miscellaneous Material
PACM – Presumed Asbestos Containing Material	

### **ADDITIONAL OBSERVATIONS**

### **Lead Paint and Other Metals**

Lead-based paint was not sampled as part of this survey. Based on the age of the structure lead based paints should be assumed.

Lead safe work practices and appropriate precautions should be utilized during all work impacting painted surfaces.

### **Microbial Growth**

Water damage and potential microbial growth were not observed as part of this sampling. Appropriate precautions should be utilized during work.

### PCBs, Mercury Bulbs and Mercury Thermostats

PCBs, Mercury Bulbs and Mercury Thermostats were not tested or examined as part of this survey. Appropriate precautions should be utilized during work.

### **Inaccessible Components**

No inaccessible components spaces were observed at the time of the inspection.

### **RESULTS AND RECOMMENDATIONS**

Of the <u>forty</u> (40) suspect bulk materials sampled <u>one</u> (1) tested positive for asbestos with a concentration greater than 1%. Samples were composited as the asbestos was found in the joint compound layer. Four additional samples are noted as presumed asbestos containing materials (PACM) as they were designated for positive stop and later composited to less than 1% per WRD 23.30.



3 Kings Environmental, Inc. recommends that any ACM or PACM to be impacted during the course of the renovation or demolition be removed by a licensed, bonded, and insured asbestos abatement firm. Removal and disposal of asbestos containing materials should only be performed by certified firms following all local, state, and federal guidelines. Should materials not noted in this report be discovered during the course of the work, stop all demolition and have the newly discovered materials tested for asbestos or treat the materials as an asbestos containing material. Be sure to notify the governing authorities and clean-air agencies prior to disturbing materials over the recordable limits.

The conclusions/ recommendations of the report are professional opinions based solely on visual observations and interpretation of sample results from our third-party laboratory. Re-use of this document for other than its intended purpose is at the sole risk of said user. 3 Kings Environmental, Inc. cannot be held responsible for the interpretation by others of the data contained in this report as site conditions or regulations may have changed. 3 Kings Environmental makes no warranty, expressed or implied for information found in this report.

If you have any questions regarding this asbestos survey/inspection report, please contact me at (360) 949-5822, or email: jhawks@3kingsinc.com

Respectfully submitted,

3 Kings Environmental, Inc.

Jason Hawks

Certified AHERA Building Inspector



### LAB RESULTS



### The Identification Specialists

Analysis Report prepared for 3 Kings Environmental Inc.

Report Date: 1/20/2025

**Project Name: MAJ-Loti LLC ACM Survey-Amended Report JT** 

1.20.25

Project #: 224206

SanAir ID#: 25002215



NVLAP LAB CODE 200870-0

10501 Trade Court, North Chesterfield, Virginia 23236 888.895.1177 | 804.897.1177 | fax: 804.897.0070 | LabReports@SanAir.com | SanAir.com



Name: 3 Kings Environmental Inc.

Address: PO Box 280

Battle Ground, WA 98604

Phone: 360-666-5464

Project Number: 224206 P.O. Number: 12025-011

Project Name: MAJ-Loti LLC ACM Survey-Amended Report

JT 1.20.25

Collected Date: 1/9/2025

Received Date: 1/13/2025 10:35:00 AM

Dear Emily Weiss,

We at SanAir would like to thank you for the work you recently submitted. The 40 sample(s) were received on Monday, January 13, 2025 via UPS. The final report(s) is enclosed for the following sample(s): 01, 02, 03, 04, 05, 06, 07, 08, 09, 10, 11, 12, 13, 14, 15, 16, 17, 18, 19, 20, 21, 22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40.

These results only pertain to this job and should not be used in the interpretation of any other job. This report is only complete in its entirety. Refer to the listing below of the pages included in a complete final report.

Sincerely,

Sandra Sobrino

Asbestos & Materials Laboratory Manager SanAir Technologies Laboratory

Sandra Sobiino

Final Report Includes:

- Cover Letter

- Analysis Pages

- Disclaimers and Additional Information

Sample conditions:

- 40 samples in Good condition.



Name: 3 Kings Environmental Inc.

Address: PO Box 280

Battle Ground, WA 98604

Phone: 360-666-5464

Project Number: 224206 P.O. Number: 12025-011

Project Name: MAJ-Loti LLC ACM Survey-Amended Report

JT 1.20.25

Collected Date: 1/9/2025

Received Date: 1/13/2025 10:35:00 AM

Analyst: Pisula, Nicholas

### Asbestos Bulk PLM EPA 600/R-93/116

	Stereoscopic	Com	ponents	
SanAir ID / Description	Appearance	% Fibrous	% Non-fibrous	Asbestos Fibers
01 / 25002215-001 Popcorn Ceiling Texture; Plaster Skim; GWB/Dining, Wallboard	Grey Non-Fibrous Homogeneous	5% Cellulose	95% Other	None Detected
01 / 25002215-001 Popcorn Ceiling Texture; Plaster Skim; GWB/Dining, Skim Coat	White Non-Fibrous Homogeneous		100% Other	None Detected
01 / 25002215-001 Popcorn Ceiling Texture; Plaster Skim; GWB/Dining, Texture	White Non-Fibrous Homogeneous		100% Other	None Detected
02 / 25002215-002 Popcorn Ceiling Texture; Plaster Skim; GWB/Living, Wallboard	Grey Non-Fibrous Homogeneous	5% Cellulose	95% Other	None Detected
02 / 25002215-002 Popcorn Ceiling Texture; Plaster Skim; GWB/Living, Skim Coat	White Non-Fibrous Homogeneous		100% Other	None Detected
02 / 25002215-002 Popcorn Ceiling Texture; Plaster Skim; GWB/Living, Texture	White Non-Fibrous Homogeneous		100% Other	None Detected
03 / 25002215-003 Popcorn Ceiling Texture; Plaster Skim; GWB/Bed 1, Wallboard	Grey Non-Fibrous Homogeneous	5% Cellulose	95% Other	None Detected
03 / 25002215-003 Popcorn Ceiling Texture; Plaster Skim; GWB/Bed 1, Skim Coat	White Non-Fibrous Homogeneous		100% Other	None Detected
03 / 25002215-003 Popcorn Ceiling Texture; Plaster Skim; GWB/Bed 1, Texture	White Non-Fibrous Homogeneous		100% Other	None Detected
04 / 25002215-004 Popcorn Ceiling Texture; Plaster Skim; GWB/Bed 2, Wallboard	Grey Non-Fibrous Homogeneous	5% Cellulose	95% Other	None Detected
Amended: Additional analysis; Composite analysis added for samples 06, 07, 08, 09 & 10. JT 1.20.25				

Analyst: Ah lil

Analysis Date:

1/20/2025

Approved Signatory:



Name: 3 Kings Environmental Inc.

Address: PO Box 280

Battle Ground, WA 98604

Phone: 360-666-5464

Project Number: 224206 P.O. Number: 12025-011

Project Name: MAJ-Loti LLC ACM Survey-Amended Report

JT 1.20.25

Collected Date: 1/9/2025

Received Date: 1/13/2025 10:35:00 AM

Analyst: Pisula, Nicholas

### Asbestos Bulk PLM EPA 600/R-93/116

	Stereoscopic	Comp	onents	
SanAir ID / Description	Appearance	% Fibrous	% Non-fibrous	Asbestos Fibers
04 / 25002215-004 Popcorn Ceiling Texture; Plaster Skim; GWB/Bed 2, Skim Coat	White Non-Fibrous Homogeneous		100% Other	None Detected
04 / 25002215-004 Popcorn Ceiling Texture; Plaster Skim; GWB/Bed 2, Texture	White Non-Fibrous Homogeneous		100% Other	None Detected
05 / 25002215-005 Popcorn Ceiling Texture; Plaster Skim; GWB/Bed 3, Wallboard	Grey Non-Fibrous Homogeneous	5% Cellulose	95% Other	None Detected
05 / 25002215-005 Popcorn Ceiling Texture; Plaster Skim; GWB/Bed 3, Skim Coat	White Non-Fibrous Homogeneous		100% Other	None Detected
05 / 25002215-005 Popcorn Ceiling Texture; Plaster Skim; GWB/Bed 3, Texture	White Non-Fibrous Homogeneous		100% Other	None Detected
06 / 25002215-006 Peel Texture;GWB;Joint Compound/Living Room, Wallboard	Grey Non-Fibrous Homogeneous	5% Cellulose	95% Other	None Detected
06 / 25002215-006 Peel Texture;GWB;Joint Compound/Living Room, Joint Compound	White Non-Fibrous Homogeneous		98% Other	2% Chrysotile
06 / 25002215-006 Peel Texture;GWB;Joint Compound/Living Room, Texture	White Non-Fibrous Homogeneous		100% Other	None Detected
06 / 25002215-006 Peel Texture;GWB;Joint Compound/Living Room, Composite	Various Non-Fibrous Heterogeneous	5% Cellulose	95% Other	< 1% Chrysotile

Amended: Additional analysis; Composite analysis added for samples 06, 07, 08, 09 & 10. JT 1.20.25

Analyst: Shih lil

Approved Signatory:

Analysis Date: 1/20/2025



Name: 3 Kings Environmental Inc.

Address: PO Box 280

Battle Ground, WA 98604

Phone: 360-666-5464

Project Number: 224206 P.O. Number: 12025-011

Project Name: MAJ-Loti LLC ACM Survey-Amended Report

JT 1.20.25

Collected Date: 1/9/2025

Received Date: 1/13/2025 10:35:00 AM

Analyst: Pisula, Nicholas

### Asbestos Bulk PLM EPA 600/R-93/116

	Stereoscopic	Com	ponents	
SanAir ID / Description	Appearance	% Fibrous	% Non-fibrous	Asbestos Fibers
07 / 25002215-007 Peel Texture;GWB;Joint Compound/Kitchen, Wallboard	Grey Non-Fibrous Homogeneous	5% Cellulose	95% Other	None Detected
07 / 25002215-007 Peel Texture;GWB;Joint Compound/Kitchen, Joint Compound				Not Analyzed
07 / 25002215-007 Peel Texture;GWB;Joint Compound/Kitchen, Texture	White Non-Fibrous Homogeneous		100% Other	None Detected
07 / 25002215-007 Peel Texture;GWB;Joint Compound/Kitchen, Composite	Various Non-Fibrous Heterogeneous	5% Cellulose	95% Other	< 1% Chrysotile
08 / 25002215-008 Peel Texture;GWB;Joint Compound/Hall, Wallboard	Grey Non-Fibrous Homogeneous	5% Cellulose	95% Other	None Detected
08 / 25002215-008 Peel Texture;GWB;Joint Compound/Hall, Joint Compound				Not Analyzed
08 / 25002215-008 Peel Texture;GWB;Joint Compound/Hall, Texture	White Non-Fibrous Homogeneous		100% Other	None Detected
08 / 25002215-008 Peel Texture;GWB;Joint Compound/Hall, Composite	Various Non-Fibrous Heterogeneous	5% Cellulose	95% Other	< 1% Chrysotile
09 / 25002215-009 Peel Texture;GWB;Joint Compound/Front Entry, Wallboard Amended: Additional analysis: Com	Grey Non-Fibrous Homogeneous	5% Cellulose	95% Other	None Detected

Amended: Additional analysis; Composite analysis added for samples 06, 07, 08, 09 & 10. JT 1.20.25

Analyst: Ah lil

Approved Signatory:

Analysis Date: 1/

1/20/2025



Name: 3 Kings Environmental Inc.

Address: PO Box 280

Battle Ground, WA 98604

Phone: 360-666-5464

Project Number: 224206 P.O. Number: 12025-011

Project Name: MAJ-Loti LLC ACM Survey-Amended Report

JT 1.20.25

Collected Date: 1/9/2025

**Received Date:** 1/13/2025 10:35:00 AM

Analyst: Pisula, Nicholas

### Asbestos Bulk PLM EPA 600/R-93/116

	Stereoscopic	Com	ponents	
SanAir ID / Description	Appearance	% Fibrous	% Non-fibrous	Asbestos Fibers
09 / 25002215-009 Peel Texture;GWB;Joint Compound/Front Entry, Joint Compound				Not Analyzed
09 / 25002215-009 Peel Texture;GWB;Joint Compound/Front Entry, Texture	White Non-Fibrous Homogeneous		100% Other	None Detected
09 / 25002215-009 Peel Texture;GWB;Joint Compound/Front Entry, Composite	Various Non-Fibrous Heterogeneous	5% Cellulose	95% Other	< 1% Chrysotile
10 / 25002215-010 Peel Texture;GWB;Joint Compound/Master Bed, Wallboard	Grey Non-Fibrous Homogeneous	5% Cellulose	95% Other	None Detected
10 / 25002215-010 Peel Texture;GWB;Joint Compound/Master Bed, Joint Compound				Not Analyzed
10 / 25002215-010 Peel Texture;GWB;Joint Compound/Master Bed, Texture	White Non-Fibrous Homogeneous		100% Other	None Detected
10 / 25002215-010 Peel Texture;GWB;Joint Compound/Master Bed, Composite	Various Non-Fibrous Heterogeneous	5% Cellulose	95% Other	< 1% Chrysotile
11 / 25002215-011 Wall Panel Mastic/Living Room	Tan Non-Fibrous Homogeneous		100% Other	None Detected
12 / 25002215-012 Wall Panel Mastic/Living Room	Tan Non-Fibrous Homogeneous	for complex OC 07, 08	100% Other	None Detected

Amended: Additional analysis; Composite analysis added for samples 06, 07, 08, 09 & 10. JT 1.20.25

Analyst: Nich Cil

Analysis Date:

1/20/2025

Approved Signatory:



Name: 3 Kings Environmental Inc.

Address: PO Box 280

Battle Ground, WA 98604

Phone: 360-666-5464

Project Number: 224206 P.O. Number: 12025-011

Project Name: MAJ-Loti LLC ACM Survey-Amended Report

JT 1.20.25

Collected Date: 1/9/2025

Received Date: 1/13/2025 10:35:00 AM

Analyst: Pisula, Nicholas

### Asbestos Bulk PLM EPA 600/R-93/116

	Stereoscopic	Components		
SanAir ID / Description	Appearance	% Fibrous	% Non-fibrous	Asbestos Fibers
13 / 25002215-013 Marble Sheet Vinyl Flooring & Mastic/Kitchen, Sheet Vinyl	White Non-Fibrous Homogeneous	20% Cellulose	80% Other	None Detected
13 / 25002215-013 Marble Sheet Vinyl Flooring & Mastic/Kitchen, Mastic	Tan Non-Fibrous Homogeneous		100% Other	None Detected
14 / 25002215-014 Marble Sheet Vinyl Flooring & Mastic/Kitchen, Sheet Vinyl	White Non-Fibrous Homogeneous	20% Cellulose	80% Other	None Detected
14 / 25002215-014 Marble Sheet Vinyl Flooring & Mastic/Kitchen, Mastic	Tan Non-Fibrous Homogeneous		100% Other	None Detected
15 / 25002215-015 Squeek Sheet/Kitchen	Black Fibrous Homogeneous	60% Cellulose	40% Other	None Detected
16 / 25002215-016 Squeek Sheet/Kitchen	Black Fibrous Homogeneous	60% Cellulose	40% Other	None Detected
17 / 25002215-017 Floral SVF/Hall Bathroom, Sheet Vinyl	Cream Non-Fibrous Homogeneous	20% Cellulose	80% Other	None Detected
17 / 25002215-017 Floral SVF/Hall Bathroom, Mastic	Tan Non-Fibrous Homogeneous		100% Other	None Detected
18 / 25002215-018 Floral SVF/Hall Bathroom, Sheet Vinyl	Cream Non-Fibrous Homogeneous	20% Cellulose	80% Other	None Detected
18 / 25002215-018 Floral SVF/Hall Bathroom, Mastic	Tan Non-Fibrous Homogeneous		100% Other	None Detected

Amended: Additional analysis; Composite analysis added for samples 06, 07, 08, 09 & 10. JT 1.20.25

Analyst: Nich Cil

Approved Signatory:

Analysis Date: 1/20/2025 Date: 1/20/2025



Name: 3 Kings Environmental Inc.

Address: PO Box 280

Battle Ground, WA 98604

Phone: 360-666-5464

Project Number: 224206 P.O. Number: 12025-011

Project Name: MAJ-Loti LLC ACM Survey-Amended Report

JT 1.20.25

Collected Date: 1/9/2025

Received Date: 1/13/2025 10:35:00 AM

Analyst: Pisula, Nicholas

### Asbestos Bulk PLM EPA 600/R-93/116

	Stereoscopic	Com	ponents	
SanAir ID / Description	Appearance	% Fibrous	% Non-fibrous	Asbestos Fibers
19 / 25002215-019 Multilayer Multicolor SVF & Mastic/Master Bathroom, Sheet Vinyl	Brown Non-Fibrous Homogeneous		100% Other	None Detected
19 / 25002215-019 Multilayer Multicolor SVF & Mastic/Master Bathroom, Sheet Vinyl	White Non-Fibrous Homogeneous	20% Cellulose	80% Other	None Detected
19 / 25002215-019 Multilayer Multicolor SVF & Mastic/Master Bathroom, Mastic	Tan Non-Fibrous Homogeneous		100% Other	None Detected
20 / 25002215-020 Multilayer Multicolor SVF & Mastic/Master Bathroom, Sheet Vinyl	Brown Non-Fibrous Homogeneous		100% Other	None Detected
20 / 25002215-020 Multilayer Multicolor SVF & Mastic/Master Bathroom, Sheet Vinyl	White Non-Fibrous Homogeneous	20% Cellulose	80% Other	None Detected
20 / 25002215-020 Multilayer Multicolor SVF & Mastic/Master Bathroom, Mastic	Tan Non-Fibrous Homogeneous		100% Other	None Detected
21 / 25002215-021 Sink Undercoat/Kitchen	Tan Non-Fibrous Homogeneous		100% Other	None Detected
22 / 25002215-022 Sink Undercoat/Kitchen	Tan Non-Fibrous Homogeneous		100% Other	None Detected
23 / 25002215-023 "X" Pattern SVF & Mastic/Entry, Sheet Vinyl	Cream Non-Fibrous Homogeneous	20% Cellulose	80% Other	None Detected
Amended: Additional analysis; Cor		for samples 06, 07, 08,	09 & 10. JT 1.20.25	

initiated. Additional disapposite disapposite disapposite and place and plac

Analyst: Nich Cil

Approved Signatory:

Analysis Date: 1/20/2025 Date: 1/20/20



Name: 3 Kings Environmental Inc.

Address: PO Box 280

Battle Ground, WA 98604

Phone: 360-666-5464

**Project Number:** 224206 **P.O. Number:** 12025-011

Project Name: MAJ-Loti LLC ACM Survey-Amended Report

JT 1.20.25

Collected Date: 1/9/2025

Received Date: 1/13/2025 10:35:00 AM

Analyst: Pisula, Nicholas

### Asbestos Bulk PLM EPA 600/R-93/116

	Stereoscopic	Comp	oonents	
SanAir ID / Description	Appearance	% Fibrous	% Non-fibrous	Asbestos Fibers
23 / 25002215-023 "X" Pattern SVF & Mastic/Entry, Mastic	Tan Non-Fibrous Homogeneous		100% Other	None Detected
24 / 25002215-024 "X" Pattern SVF & Mastic/Entry, Sheet Vinyl	Cream Non-Fibrous Homogeneous	20% Cellulose	80% Other	None Detected
24 / 25002215-024 "X" Pattern SVF & Mastic/Entry, Mastic	Tan Non-Fibrous Homogeneous		100% Other	None Detected
25 / 25002215-025 Squares SVF/Living Room, Sheet Vinyl	Cream Non-Fibrous Homogeneous	20% Cellulose	80% Other	None Detected
25 / 25002215-025 Squares SVF/Living Room, Mastic	Tan Non-Fibrous Homogeneous		100% Other	None Detected
26 / 25002215-026 Squares SVF/Living Room, Sheet Vinyl	Cream Non-Fibrous Homogeneous	20% Cellulose	80% Other	None Detected
26 / 25002215-026 Squares SVF/Living Room, Mastic	Tan Non-Fibrous Homogeneous		100% Other	None Detected
27 / 25002215-027 Roofing/Shed 1	Black Non-Fibrous Heterogeneous		100% Other	None Detected
28 / 25002215-028 Roofing/Shed 1	Black Non-Fibrous Heterogeneous		100% Other	None Detected
29 / 25002215-029 Roofing Felt/Shed 1	Black Fibrous Homogeneous	60% Cellulose	40% Other	None Detected

Amended: Additional analysis; Composite analysis added for samples 06, 07, 08, 09 & 10. JT 1.20.25

Analyst: Mh lil

Analysis Date:

1/20/2025

Approved Signatory:



Name: 3 Kings Environmental Inc.

Address: PO Box 280

Battle Ground, WA 98604

Phone: 360-666-5464

Project Number: 224206 P.O. Number: 12025-011

Project Name: MAJ-Loti LLC ACM Survey-Amended Report

JT 1.20.25

Collected Date: 1/9/2025

Received Date: 1/13/2025 10:35:00 AM

Analyst: Pisula, Nicholas

### Asbestos Bulk PLM EPA 600/R-93/116

Stereoscopic Components			ponents				
SanAir ID / Description	Appearance	% Fibrous	% Non-fibrous	Asbestos Fibers			
30 / 25002215-030 Roofing Felt/Shed 1	Black Fibrous Homogeneous	60% Cellulose	40% Other	None Detected			
31 / 25002215-031 House Roof	Black Non-Fibrous Heterogeneous		100% Other	None Detected			
32 / 25002215-032 House Roof	Black Non-Fibrous Heterogeneous		100% Other	None Detected			
33 / 25002215-033 House Roof Felt	Black Fibrous Homogeneous	60% Cellulose	40% Other	None Detected			
34 / 25002215-034 House Roof Felt	Black Fibrous Homogeneous	60% Cellulose	40% Other	None Detected			
35 / 25002215-035 Window Caulking	Grey Non-Fibrous Homogeneous		100% Other	None Detected			
36 / 25002215-036 Window Caulking	Grey Non-Fibrous Homogeneous		100% Other	None Detected			
37 / 25002215-037 Roof/Shed 2	Black Non-Fibrous Heterogeneous		100% Other	None Detected			
38 / 25002215-038 Roof/Shed 2	Black Non-Fibrous Heterogeneous		100% Other	None Detected			
39 / 25002215-039 Roof Felt/Shed 2	Black Fibrous Homogeneous	60% Cellulose	40% Other	None Detected			

Amended: Additional analysis; Composite analysis added for samples 06, 07, 08, 09 & 10. JT 1.20.25

Analyst: Ah lil

Analysis Date:

1/20/2025

Approved Signatory:



Name: 3 Kings Environmental Inc.

Address: PO Box 280

Battle Ground, WA 98604

Phone: 360-666-5464

Project Number: 224206 P.O. Number: 12025-011

Project Name: MAJ-Loti LLC ACM Survey-Amended Report

JT 1.20.25

Collected Date: 1/9/2025

Received Date: 1/13/2025 10:35:00 AM

Analyst: Pisula, Nicholas

### Asbestos Bulk PLM EPA 600/R-93/116

	Stereoscopic	Com	ponents	
SanAir ID / Description	Appearance	% Fibrous	% Non-fibrous	Asbestos Fibers
40 / 25002215-040 Roof Felt/Shed 2	Black Fibrous Homogeneous	60% Cellulose	40% Other	None Detected

Amended: Additional analysis; Composite analysis added for samples 06, 07, 08, 09 & 10. JT 1.20.25

Analyst: Mike like

Approved Signatory:

Analysis Date: 1/20/2025

### Disclaimer and Additional Information: Asbestos Bulk PLM EPA 600/R-93/116

This report is the sole property of the client named on the chain-of-custody (COC) submitted to SanAir Technologies Laboratory, Inc. (SanAir). Results in the report are confidential information intended only for the use by the customer listed on the COC. Neither results nor reports will be discussed with or released to any third party without our client's written permission. The final report shall not be reproduced, except in full, without written approval of the laboratory to assure that parts of the report are not taken out of context. This report and any information contained within shall not be edited, altered, or modified in any way by any persons or agencies receiving, viewing, distributing, or otherwise possessing a copy of this final report. The laboratory reserves the right to perform amendments to any finalized report, of which shall supersede and make obsolete any previous editions. Such changes, modifications, additions, or deletions shall be effective immediately upon notice thereof, which may be given by means including but not limited to posting on the SanAir client portal website, electronic or conventional mail, or by any other means.

The information provided in this report applies only to the samples submitted and is relevant only for the date, time, and location of sampling. The accuracy of the results is dependent upon the client's sampling procedure and information provided to the laboratory by the client on the COC. SanAir assumes no responsibility for the sampling procedure and will provide evaluation reports based solely on the sample(s) in the condition received at the laboratory and information provided by the client on the COC, such as: project number, project name, collection dates, P.O. number, special instructions, samples collected by, sample numbers, sample identifications, sample type, selected analysis type, flow rate, total volume or area, and start-stop times that may affect the validity of the results in this report. Samples were received in good condition unless otherwise noted on the report. When the client requires samples to be tested that deviates from a specific method or condition, all reported results may be affected by the deviation. SanAir assumes no responsibility or liability for the manner in which the results are used or interpreted.

This report does not constitute nor shall not be used by the client to claim product, process, system, or person certification, approval, or endorsement by NVLAP, NIST, NELAC, AIHA LAP, LLC or any other U.S. governmental agencies; all or somet tests contained in this report may not be accredited by every local, state, and federal regulatory agencies. Refer to the SanAir website at www.sanair.com for copies of current certificates and scopes of various accreditations, certifications, and licenses or contact the laboratory for inquiries regarding the status or scope of an accreditation or certification.

Samples are held for a period of 60 days. Fibers smaller than 5 microns cannot be seen with this method due to scope limitations. For NY state samples, method EPA 600/M4-82-020 is performed.

### NYELAP Disclaimer:

Polarized-light microscopy is not consistently reliable in detecting asbestos in floor covering and similar non-friable organically bound materials. Quantitative transmission electron microscopy is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos containing.

### Asbestos Accreditations, Certifications, and Licenses

National Voluntary Laboratory Accreditation Program (NVLAP) Lab Code 200870-0
City of Philadelphia Department of Public Health Air Management Services, Certification#ALL-460
Commonwealth of Pennsylvania Department of Environmental Protection Number 68-05397
California State Environmental Laboratory Accreditation Program Certificate Number 2915
Colorado Department of Public Health and Environment Registration Number AL-23143
Connecticut Department of Public Health Environmental Laboratory Registration Number PH-0105
Massachusetts Department of Labor Standards Asbestos Analytical Services License Number:
AA000222

State of Maine Department of Environmental Protection License Number: LB-0075

New York State Department of Health Laboratory ID: 11983

State of Rhode Island Department of Health Certification No.: PLM00126

Texas Department of State Health Services License Number: 300440

Commonwealth of Virginia Department of Professional and Occupational Regulation Number: 3333000323

State of Washington Department of Ecology Laboratory ID: C989

State of West Virginia Bureau for Public Health Analytical Laboratory Number: LT000616

Vermont Department of Health License Number: Asb-Co-An-000006

Louisiana Department of Environmental Quality Al Number 212253, LELAP Lab ID #05088

Revision#03, 10/3/2024 Page 12 of 14



10501 Trade Ct., Suite 100 N. Chesterfield, VA 23236 804.897.1177 / 888.895.1177 Fax 804.897.0070

Asbestos Chain of Custody Form 140, Rev 7, 10/20/2022 2500 2215

SanAir ID Number

Technologies Laboratory	sanair.com	2 3.11 1.10, 220 1, 10, 20, 20, 20	
Company: 3 Kings Envi	ronmental, Inc.	Project #:224206	Collected by.E.Weiss
Address: PO Box 280		Project Name: MAJ - Loti LLC ACM Survey	Phone #: 253-750-4143
City, St., Zip: Battlr Grou	nd, WA 98604	Date Collected; 01/09/2025	Fax #: 360-666-8202
10/0	2244	4000E 044	

State of C	ollection:WA	Account#: 23	344	P.O	Number: 12025-011	Email: eweiss@3kingsinc.com			
	Bulk				Air		Soil		
ABB	PLM EPA 600/R-	93/116	7	ABA	PCM NIOSH 7400	ABSE	PLM EPA 60	00/R-93/116 (Qual.)	
	Positive Stop	<b>V</b>		ABA-2	OSHA w/ TWA*		Vern	niculite	
ABEPA	PLM EPA 400 Po	nt Count		ABTEM	TEM AHERA	ABB	PLM EPA 60	00/R-93/116	
ABB1K	PLM EPA 1000 P	oint Count		ABATN	TEM NIOSH 7402	ABEPA3	PLM EPA 40	0 Point Count	
ABBEN	PLM EPA NOB**			ABT2	TEM Level II	ABCM	BCM Cincinnati Method		
ABBCH	TEM Chatfield**			Other:		Dust			
ABBTM	TEM EPA NOB**				New York ELAP	ABWA	TEM Wipe A	STM D-6480	
ABQ	PLM Qualitative			ABEPA2	NY ELAP 198.1	ABDMV	TEM Microv	ac ASTM D-5755	
**	Available on 24-hr.	to 5-day TAT		ABENY	NY ELAP 198.6 PLM NOB				
	Water			ABBNY	NY ELAP 198.4 TEM NOB	Matrix	Other	T	
ABHE	EPA 100.2				Positive Stop				
Tu	ırn Around	3 HR (4 H	R TE	M) □	6 HR (8HR TEM) □	12 HR		l Day 🖪	
	Times	□ 2	Days	3	☐ 3 Days	□ 4 D	ays	☐ 5 Days	

### **Special Instructions**

Sample #	Sample Identification/Location	Volume or Area	Sample Date	Flow Rate*	Start – Stop Time*
01	Popcorn Ceiling Texture; Plaster Skim; GWB / Dining				
02	Popcom Ceiling Texture; Plaster Skim; GWB / Living Room				
03	Popcorn Ceiling Texture; Plaster Skim; GWB / Bed 1				
04	Popcom Ceiling Texture; Plaster Skim; GWB / Bed 2				
05	Popcorn Ceiling Texture; Plaster Skim; GWB / Bed 3				
06	Orange Peel Texture; GWB; Joint Compound / Living Room		,		
07	Orange Peel Texture; GWB; Joint Compound / Kitchen				
08	Orange Peel Texture; GWB; Joint Compound / Hall				
09	Orange Peel Texture; GWB; Joint Compound / Front Entry				
10	Orange Peel Texture; GWB; Joint Compound / Master Bed				
11	Wall Panel Mastic / Living Room				
12	Wall Panel Mastic / Living Room				

Relinquished by	Date	Time	Received by	Date	Time
EW	01/09/2025	5pm	SM	11325	1035Am

If no technician is provided, then the primary contact for your account will be selected. Unless scheduled, the turnaround time for all samples received after 3 pm EST will be logged in the next business day. Weekend or holiday work must be scheduled ahead of time and is charged at 150% of the 3hr TAT or a minimum charge of \$150. A courier charge will be applied for same day and one-day turnaround times for offsite work. SanAir covers Ground and Next Day Air shipping. Shipments age 13 of 14

2500 2215

Sample #	Sample Identification/Location	Volume or Area	Sample Date	Flow Rate*	Start – S Time*	_
13	White Marble Sheet Vinyl Flooring & Mastic / Kitchen					
14	White Marble Sheet Vinyl Flooring & Mastic / Kitchen					
15	Black Squeek Sheet / Kitchen					
16	Black Squeek Sheet / Kitchen					
17	Cream Floral SVF / Hall Bathroom					
18	Cream Floral SVF / Hall Bathroom					
19	Multilayer MultiColor SVF & Mastic / Master Bathroom					
20	Multilayer MultiColor SVF & Mastic / Master Bathroom					
21	Sink Undercoat / Kitchen					
22	Sink Undercoat / Kitchen					
23	"X" Pattern SVF & Mastic / Entry					
24	"X" Pattern SVF & Mastic / Entry					
25	Cream w/ Blue Squares SVF / Living Room					
26	Cream w/ Blue Squares SVF / Living Room					
27	Roofing / Shed 1					
28	Roofing / Shed 1					
29	Roof Felt / Shed 1					
30	Roof Felt / Shed 1					
31	House Roof			-		
32	House Roof					
33	House Roof Felt					
34	House Roof Felt					
35	Window Caulking					
36	Window Caulking					
37	Roof / Shed 2					
38	Roof / Shed 2					
39	Roof Felt / Shed 2					
40	Roof Felt / Shed 2					
		-				

		 · · · · · · · · · · · · · · · · · · ·	<u> </u>
Special Instructions			

Relinquished by	Date	Time	Received by	Date	Time
EW	01/09/2025	5pm	Shc	1/13/25	10357

If no technician is provided, then the primary contact for your account will be selected. Unless scheduled, the turnaround time for all samples received after 3 pm EST will be logged in the next business day. Weekend or holiday work must be scheduled ahead of time and is charged at 150% of the 3hr TAT or a minimum charge of \$150. A courier charge will be applied for same day and one-day turnaround times for offsite work. SanAir covers Ground and Next Day Air shipping. Shipments billed to SanAir with a faster shipping rate will result in additional charges.

Page of Pege 44 of 14



### **CERTIFICATION**

# CERTIFICATE OF COMPLETION

### **AHERA Building Inspector**

This is to certify that

## Jason Hawks

AHERA Building Inspector. This 4-hour refresher training has been successfully completed in accordance with the Toxic Substance Control Act Title (Section 206) and 40 CFR 763. has attended and satisfactorily completed all requirements to obtain accreditation as an

Accreditation Number: NES-BIR-20041204-06

Course Date 12/04/2024

Certification Expiration 12/04/2025



CONSULTING & COMPLIANCE

Now Environmental Services, Inc 34004 - 9th Avenue South, Ste A5 Federal Way, WA 98003 253.927.5233 Jamie Switras