



11815 NE 99th Street, Suite 1294
Vancouver, WA 98662
Voice: 360-574-3058
Fax: 360-576-0925
Web: <https://www.swcleanair.gov>
Email: Tina@swcleanair.gov

Notice of Intent to Remove Asbestos

Case #: 25-091

Amendment: 0

Date Received: 1/31/2025

Date Paid: 1/31/2025

SWCAA Fee: \$306.00

Receipt #: 170182435

This notification MUST be present at all times at the asbestos project sit

*** EMERGENCY NOTICE ***

Quantity to be removed: 50 Square Feet 0 Linear Feet

Workshift days: M

Project starting date: 2/3/2025 Project Completion date: 2/3/2025

Workshift hours: 8:30 am - 5:30 pm

Site Name: Mark White Residence Site address: 164 Niblett Way
Location of Asbestos: Basement Living Area City/State/Zip: Longview WA 98632
☐ Demolition of Structure (Notification of Demolition required) County: COWLITZ COUNTY

☐ Asbestos present?

☐ Asbestos presumed?

☒ Asbestos survey conducted?

No survey reason:

AHERA Inspector: Ryan Englegau

Certification #: IRO-24-1269C

Material to be Removed:

☐ Fireproofing ☐ Popcorn Ceiling ☐ CAB ☐ Sheet Vinyl ☐ Boiler Insulation ☐ Duct Tape
☐ Duct Paper ☐ Mag Pipe Insulation ☐ Air Cell ☐ CA Pipe ☐ VAT
☒ Other Drywall/Texture-Ceiling

Control Methods:

☒ N.P Enclosure ☐ Glove Bag ☐ Mini Enclosure ☐ Wrap and Cut ☒ Water ☒ HEPA Vac
☒ Other manual methods

Asbestos Contractor: Chinook Restoration dba Paul Davis Restoration

Phone: 800-951-9283

Mailing Address: 1800 W Fourth Plain Blvd Sute 120B, Vancouver, WA, 986

Email: tony.altamirano@pauldavis.com

Certification ##: ABCN00001738

Supervisor: Lucio Ramirez

Phone: 360-500-3595

Property Owner: Mark White

Phone: 564-208-8629

Mailing Address: 164 Niblett Way, Longview WA 98623

Asbestos Disposal Site: Hillsboro Landfill: 3205 SE Minter Bridge Rd, Hillsboro, OR, 97123-

**I DO HEREBY CERTIFY THAT THE INFORMATION CONTAINED IN THIS NOTIFICATION IS,
TO THE BEST OF MY KNOWLEDGE, ACCURATE AND COMPLETE.**

Submitter Name: Bonifacio Altamirano

Representing: Chinook Restoration dba Paul

Submitter Title: Project Manager

Date Submitted: 1/31/2025

Reviewed by SWCAA: Brian Fallon

☒ Approved

CHAIN OF CUSTODY

Name / Company Name: Paul Davis Restoration - Vancouver	Phone: (800) 951-9283
Contact Email: cody.parsley@pauldavis.com, kyle.greene@pauldavis.com, gvwaesd@pauldavis.com, switter@pauldavis.com, aocegeda@pauldavis.com, joel.carlson@pauldavis.com, jose.botello@pauldavis.com, ahaskell@pauldavis.com, ali.wood@pauldavis.com, dustin.berry@pauldavis.com, jordan.peterson@pauldavis.com, artur.sklyaruk@pauldavis.com, jared.ketchmark@pauldavis.com	
Project Name: Mark White	Job/Project #: 0156-E
Job/Project Address: 164 Niblett Way Longview, WA	

Please check box that applies

- ☒ Rush
☐ Next Day
☐ 2-Day
☐ 5-Day

*Samples turned in by 2 pm will be processed the same day

Please check box that applies

- ☒ Asbestos PLM
☐ Lead Paint
☐ Other

#	Material Description	Sample Location	Office Use Only
1	Drywall, texture, joint comp	Basement Ceiling	
2	↓	↓	
3	↓	↓	
4	↓	Basement Wall	
5	↓	↓	
6	↓	↓	
7	↓	Bathroom Wall	
8	↓	↓	
9	↓	↓	

Special Instructions:

Client Sign Here:

Ryan Engelgau

Date: 01/27/25

Time: 10:00AM

Atlas Accepted By:

Kelly Katona

Date: 01-27-2025

Time: 9:55am

Credit Card:

Cash:

Check #

Amount: \$

Lab Results Completed By:

[Signature]

Date Sent Out: 1/27/25

Email/Fax/Mail

*Atlas charges a per sample fee and not by layer. One sample fee equals four layers. Additional layers will result in an additional sample fee.



Batch # 2022 *

25-1783601

Name / Company *

Paul Davis Restoration of
Vancouver/Portland

Analysis Date *

01/27/2025

Project Name

Mark White

Project #

0156-E

PO #

Analyst *

Crossland Kapaun

Project Location *

164 Niblett Way, Longview,
WA

Turnaround Time *

Rush

Asbestos Analysis of Bulk Material by Polarized Light Microscopy

Sample*	Layer*	Description*	Non Asbestos*	Asbestos Type*	Asbestos %*
1	1	Drywall (White) - Basement Ceiling	Cellulose / Fiberglass	None Present	N/D
1	2	Texture (White) - Basement Ceiling	Cellulose	None Present	N/D
1	3	Joint Compound (White) - Basement Ceiling	Fiberglass	None Present	N/D
2	1	Drywall (White) - Basement Ceiling	Cellulose / Fiberglass	None Present	N/D
2	2	Texture (White) - Basement Ceiling	Cellulose	None Present	N/D
2	3	Joint Compound (White) - Basement Ceiling	Fiberglass	None Present	N/D
3	1	Drywall (White) - Basement Ceiling	Cellulose / Fiberglass	None Present	N/D
3	2	Texture (White) - Basement Ceiling	Cellulose	None Present	N/D
4	1	Drywall (White) - Basement Wall	Cellulose	None Present	N/D
4	2	Texture (White) - Basement Wall	Cellulose	None Present	N/D
5	1	Drywall (White) - Basement Wall	Cellulose	None Present	N/D
5	2	1st Layer Texture (White) - Basement Wall	Cellulose	None Present	N/D

Sample*	Layer*	Description*	Non Asbestos*	Asbestos Type*	Asbestos %*
5	3	2nd Layer Texture (White) - Basement Wall	Cellulose	Chrysotile	2%
5	4	Joint Compound (White) - Basement Wall	Cellulose	Chrysotile	2%
6	1	Drywall (White) - Basement Wall	Cellulose	None Present	N/D
6	2	1st Layer Texture (White) - Basement Wall	Cellulose	None Present	N/D
6	3	2nd Layer Texture (White) - Basement Wall	Cellulose	Chrysotile	2%
6	4	Joint Compound (White) - Basement Wall	Cellulose	Chrysotile	2%
7	1	Drywall (White) - Bathroom Wall	Cellulose	None Present	N/D
7	2	Texture (Tan) - Bathroom Wall	Cellulose	Chrysotile	5%
8	1	Drywall (White) - Bathroom Wall	Cellulose	None Present	N/D
8	2	Texture (Tan) - Bathroom Wall	Cellulose	Chrysotile	5%
9	1	Drywall (White) - Bathroom Wall	Cellulose	None Present	N/D
9	2	1st Layer Texture (White) - Bathroom Wall	Cellulose	None Present	N/D
9	3	2nd Layer Texture (Tan) - Bathroom Wall	Cellulose	Chrysotile	5%
9	4	Joint Compound (Tan) - Bathroom Wall	Cellulose	Chrysotile	3%

To Be Filled by the Technician
Technician *

Atlas Laboratories maintains liability to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full without written permission by Atlas. Atlas bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval or endorsement by NVLAP, NIST, NIOSH or any other agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore Atlas recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Transmission Electron Microscopy asbestos identification and lead paint analysis will be available and performed by laboratories by proxy. Original analysis documents are available upon request of the client.



SanAir ID Number

25005551

FINAL REPORT

1/28/2025 3:58:49 PM

Name: Atlas Labs, Inc.

Address: 14795 SW 72nd Ave. Suite B

Portland, OR 97224

Phone: 360-852-8936

Project Number: 164 Niblett Way

P.O. Number: 0156-E

Project Name: Paul Davis Restoration Of
Vancouver/Portland

Collected Date: 1/27/2025

Received Date: 1/28/2025 10:40:00 AM

Analyst: Baird, Marti

Test Method: SW846/M3050B/7000B

Lead Paint Analysis

PAINT Sample	Description	$\mu\text{g Pb}$ In Sample	Sample Size (grams)	Calculated RL	Sample Results	Sample Results
25005551 - 1	1 Paint - Basement Ceiling	< 10	0.1148	87.1	<87.1 $\mu\text{g/g (ppm)}$	<0.009 % By Weight
25005551 - 2	4 Paint - Basement Wall	< 10	0.1184	84.5	<84.5 $\mu\text{g/g (ppm)}$	<0.009 % By Weight
25005551 - 3	7 Paint - Bathroom Wall	< 10	0.124	80.6	<80.6 $\mu\text{g/g (ppm)}$	<0.008 % By Weight

Method Reporting Limit <10 $\mu\text{g}/0.1\text{ g}$ paint

Sample 7 contained substrate.

Signature:

Date: 1/28/2025

Reviewed:

Date: 1/28/2025