



11815 NE 99th Street, Suite 1294  
Vancouver, WA 98662  
Voice: 360-574-3058  
Fax: 360-576-0925  
Web: <https://www.swcleanair.gov>  
Email: [Tina@swcleanair.gov](mailto:Tina@swcleanair.gov)

## Notice of Intent to Remove Asbestos

Case #: 24-158

Amendment: 0

Date Received: 3/13/2024

Date Paid: 3/13/2024

SWCAA Fee: \$147.00

Receipt #: 152727528

**This notification MUST be present at all times at the asbestos project sit**

Quantity to be removed: 144 Square Feet 0 Linear Feet

Workshift days: Sa

Project starting date: 3/23/2024 Project Completion date: 3/23/2024

Workshift hours: 8:00AM - 4:30PM

Site Name: Aleigha Anderson

Site address: 154 Monticello Dr

Location of Asbestos: Bedroom

City/State/Zip: Longview WA 98682

☐ Demolition of Structure (Notification of Demolition required)

County: COWLITZ COUNTY

☒ Asbestos survey conducted?

No survey reason:

AHERA Inspector: Unknown. Bulk Sampling Provided b

Certification #: Non Listed.

### Material to be Removed:

- ☐ Fireproofing ☐ Popcorn Ceiling ☐ CAB ☐ Sheet Vinyl ☐ Boiler Insulation ☐ Duct Tape  
☐ Duct Paper ☐ Mag Pipe Insulation ☐ Air Cell ☐ CA Pipe ☐ VAT  
☒ Other Sheetrock Mud

### Control Methods:

- ☒ N.P Enclosure ☐ Glove Bag ☐ Mini Enclosure ☐ Wrap and Cut ☒ Water ☐ HEPA Vac  
☒ Other Manual Methods

Asbestos Contractor: Keystone Contracting, Inc.

Phone: 360-887-0868

Mailing Address: 417 NW 209th St, Ridgefield, WA, 98642

Email: [keystone417@tds.net](mailto:keystone417@tds.net)

Certification ##: ABCN00001024

Supervisor: Martin Ortiz

Phone: 360-353-6423

Property Owner: Aleigha Anderson

Phone: 360-513-3503

Mailing Address: 154 Monticello Dr, Longview WA 98682

Asbestos Disposal Site: Wasco County Landfill: 2550 Steele Rd, The Dalles, OR, 97058-

**I DO HEREBY CERTIFY THAT THE INFORMATION CONTAINED IN THIS NOTIFICATION IS,  
TO THE BEST OF MY KNOWLEDGE, ACCURATE AND COMPLETE.**

Submitter Name: Kamala Lopez

Representing: Keystone Contracting, Inc

Submitter Title: Office Manager

Date Submitted: 3/13/2024

Reviewed by SWCAA: Brian Fallon

☒ Approved



11815 NE 99th Street, Suite 1294  
Vancouver, WA 98662  
Voice: 360-574-3058  
Fax: 360-576-0925  
Web: <https://www.swcleanair.gov>  
Email: [Tina@swcleanair.gov](mailto:Tina@swcleanair.gov)

## Notice of Intent to Remove Asbestos

Case #: 24-158

Amendment: 0

Date Received: 3/13/2024

Date Paid: 3/13/2024

SWCAA Fee: \$147.00

Receipt #: 152727528

**This notification MUST be present at all times at the asbestos project sit**



9317 NE Hwy 99, Suite D, Vancouver, WA 98665 | 360-356-7628

**Polarized Light Microscopy Results**

**Lab No** 143529  
**Layers Analyzed** 6  
**Date Received** 3/11/2024  
**Received By** Talia Carroll  
**Date Analyzed** 3/11/2024  
**Analyzed By** Nathan Blondino

**Property Address** 154 Monticello Dr  
**City, State, Zip** Longview, WA  
**Job Number** Aleigha Anderson 24-391  
**Client Name** Prestige NW  
**Client Address**  
**City, State, Zip**  
**Phone & E-mail**

AEI Sample ID	Client Sample ID	Composition	Color/Description	Asbestos (%)	Non-Asbestos Fiber (%)	Non Fibrous
001	1	Layered	White Texture	2% Chrysotile	N/A	(White) Paint-CaCO3-Sand
001A		Layered	White Joint Compound	Asbestos Not Present	N/A	CaCO3-Perlite
002	2	Layered	White Texture	2% Chrysotile	N/A	(White) Paint-CaCO3-Sand
002A		Layered	White Joint Compound	Asbestos Not Present	N/A	CaCO3-Perlite
003	3	Layered	White Texture	2% Chrysotile	N/A	(White) Paint-CaCO3-Sand
003A		Layered	White Joint Compound	Asbestos Not Present	N/A	CaCO3-Perlite

## Disclaimer

- EPA Method 600/M4-82-020 (1982) was used to determine the presence or absence of asbestos fibers in all materials referenced in the above report. PLM analysis is based on visual estimation, and due to limitations of PLM analysis NESHAP regulations recommend that any material determined to contain less than 10% asbestos by the above referenced method should either be assumed to contain greater than 1% asbestos by the owner/operator, or be verified by PLM Point Count or TEM analysis as containing less than 1% asbestos.
- We recommend that TEM analysis be conducted for confirmation of negative PLM analytical results of vinyl floor tiles and vermiculite. These materials may contain asbestos fibers that cannot be detected by PLM analysis due to their size (<0.25 microns in diameter)
- This report may not be used to represent any materials not analyzed and listed in the included report. Advantage Environmental Inc. cannot be held responsible for the interpretation of the results shown. This report may not be reproduced in part and may only be reproduced in full without prior written consent from Advantage Environmental Inc.



**ADVANTAGE**  
Environmental INC.

**ASBESTOS CHAIN OF CUSTODY**  
9317 NE Hwy 99, Suite D • (360) 356-7628  
**LEGAL DOCUMENT - PLEASE PRINT LEGIBLY**

Lab Use Only	
Survey <input type="checkbox"/>	Lab No. 143529
Walk-In <input checked="" type="checkbox"/>	<u>Accept</u> Reject

Sampled By - Please fill out yellow highlighted areas				Project Information - Please fill out yellow highlighted areas					
Date:				Project Name: Aleigha Anderson 24-391					
Company Name OR Name: Presnige				Address (where material was pulled from): 154 Monticello Dr					
Phone:				City, State, Zip: Longview, WA 98632					
Email:				P.O. #:					
RELINQUISHED BY		DATE & TIME		VIA		RECEIVED BY		DATE & TIME	
Name Tyler Long		Date 3/11		Drop Box/Drop Off				3-11	
Sign		Time 9:30						10:57	
REQUESTED SERVICES									
PLM				TURNAROUND TIME - Please choose a turnaround time					
Bulk Analysis				<input type="checkbox"/> Verbal <input type="checkbox"/> Rush <input checked="" type="checkbox"/> Same Day <input type="checkbox"/> 24-Hour <input type="checkbox"/> 3-Days					
No.	Sample ID	Color	Description	Volume / Area (as applicable)	Comments / Notes				
1		white	Texture + compound		Bedroom Ceiling				
2		white	Texture + compound		Bedroom Ceiling				
3		white	Texture + compound		Bedroom Ceiling				
4									
5									
6									
7									
8									
9									
10									
11									