



Notice of Intent to Remove Asbestos

Case #: 24-274

Amendment: 0

11815 NE 99th Street, Suite 1294
Vancouver, WA 98662
Voice: 360-574-3058
Fax: 360-576-0925
Web: <https://www.swcleanair.gov>
Email: Tina@swcleanair.gov

Date Received: 4/25/2024

Date Paid: 4/25/2024

SWCAA Fee: \$0.00

Receipt #:

This notification MUST be present at all times at the asbestos project sit

***** EMERGENCY NOTICE *****

Quantity to be removed: 12 Square Feet 0 Linear Feet Workshift days: F

Project starting date: 4/26/2024 Project Completion date: 4/26/2024 Workshift hours: 12-4

Site Name: W307_ServProEWCC_2808E8thSt_9	Site address: 2808 E 8th St. Vancouver 98661
Location of Asbestos: Bedroom	City/State/Zip: Vancouver WA 98661
<input type="checkbox"/> Demolition of Structure (Notification of Demolition required)	County: CLARK COUNTY

Asbestos survey conducted? No survey reason:

AHERA Inspector: Dalton LaFever Certification #: IRO-24-0908C

Material to be Removed:

- Fireproofing Popcorn Ceiling CAB Sheet Vinyl Boiler Insulation Duct Tape
- Duct Paper Mag Pipe Insulation Air Cell CA Pipe VAT
- Other Skim Coat

Control Methods:

- N.P Enclosure Glove Bag Mini Enclosure Wrap and Cut Water HEPA Vac
- Other 6-Mil Poly, Wet, Labeled

Asbestos Contractor: Alpine Abatement Associates Inc. Phone: 541-388-2672
Mailing Address: PO Box 1557, Bend, OR, 97709 Email: annmarie@alpineabatement.com
Certification ##: ABCN00001215
Supervisor: Miguel Manzo Phone: 541-388-2672

Property Owner: VENVERTLOH ANNE Phone: 360-254-0049
Mailing Address: 2808 E 8th St. Vancouver, Vancouver WA 98661

Asbestos Disposal Site: Hillsboro Landfill: 3205 SE Minter Bridge Rd, Hillsboro, OR, 97123-

I DO HEREBY CERTIFY THAT THE INFORMATION CONTAINED IN THIS NOTIFICATION IS, TO THE BEST OF MY KNOWLEDGE, ACCURATE AND COMPLETE.

Submitter Name: Bo Davidson **Representing:** Alpine Abatement

Submitter Title: Senior Project Manager **Date Submitted:** 4/25/2024

Reviewed by SWCAA: Brian Fallon Approved



11815 NE 99th Street, Suite 1294
Vancouver, WA 98662
Voice: 360-574-3058
Fax: 360-576-0925
Web: <https://www.swcleanair.gov>
Email: Tina@swcleanair.gov

Notice of Intent to Remove Asbestos

Case #: 24-274

Amendment: 0

Date Received: 4/25/2024

Date Paid: 4/25/2024

SWCAA Fee: \$0.00

Receipt #:

This notification MUST be present at all times at the asbestos project sit

Limited Asbestos Survey Report

Owner/Operator Name:

ServPro of Vancouver

Owner/Operator Number:

360-254-0049

Limited Survey Date:

March 13, 2024

Survey Address:

2808 E 8th St, Vancouver, WA 98661

Survey Location:

Interior Upstairs Bedroom

What is the building's description?

Residence

What is this structure's current use?

Residential Home

What is this structure's past use?

Residential Home

Building Square Footage:

2,154

Number of Floors:

2 with Basement

Area Surveyed:

Interior Upstairs Bedroom Wall(s), & Interior Upstairs Bedroom Ceiling

Approximate Build Date:

1935

Purpose of the Survey:

Remediation due to damages

Survey Limitations: Samples are collected based on a visual inspection of the work area as defined in the analysis report. Samples were collected from accessible, representative construction materials, which were suspected to contain asbestos. If additional materials are found during the demolition process that were inaccessible at time of inspection that are not listed in this report please have materials tested before they are impacted. Survey is subject to direction from contractor, homeowner or owners agent.

Asbestos Containing Building Material Identified During Survey: **Please see the completed attached analysis report.*

Sample #	Location	Asbestos Containing Material	Description (Color, Texture & Pattern)	Asbestos % & Asbestiform	Approx. Sq. Footage	Friable Y/N	Condition
1-A Layer 2	Upstairs Bedroom Ceiling	Skim Coat	Tan	2% Chrysotile	30'	Y	Good

Recommended Response Action Plan:

Contact a Licenced Abatement Contractor or SW Clean Air Agency

Sw Clean Air Agency regulates the handling, removal and disposal of asbestos-containing material to protect public health and the environment.

<https://www.lni.wa.gov/licensing-permits/other-licenses-permits/asbestos-certification#certified-contractors-list> . For more information on asbestos removal, please refer to

SWCAA 476, specifically SWCAA 476-050. If you have any questions, please contact us at 360-574-3058

A copy of this survey report must be kept onsite during any remediation, renovation or demolition activities, as required by Southwest Clean Air Agency.

Surveyed Performed By:

Dalton Lafever
Of
Atlas Labs Inc.
Environmental Testing Services
Dalton@atlaslabinc.com
(503) 430-4112
AHERA Cert #: IRO-24-0908C
CCB #: 231684



Atlas Laboratories Inc.
 14795 SW 72nd Ave, STE B Portland, OR 97224
 (503) 430-5290 www.atlaslabsinc.com
 CCB #231684



Limited Survey Chain of Custody

Name / Company Name: ServPro of Vancouver		Phone: 360-254-0049
Contact Email: servprovancouver@comcast.net		
Project Name: Ann Edquist State Farm Claim# 4762S553Q		Batch: 22-1234001
Job/Project Address: 2808 E 8th St, Vancouver, WA 98661		
Inspector: Dalton Lafever Ph: (503) 430-4112 AHERA Cert. # IRO-24-0908C Lead RRP Cert. # R-I-41R036-22-00070		
Survey Area Use: Residential	Approx. Year Built: 1935	Reason for Survey: Remediation

<input checked="" type="checkbox"/>	Rush
<input type="checkbox"/>	Next Day
<input type="checkbox"/>	2-Day
<input type="checkbox"/>	5-Day

<input checked="" type="checkbox"/>	Asbestos PLM
<input checked="" type="checkbox"/>	Lead Paint
<input type="checkbox"/>	Other

#	Material Description	Friable Y/N	Location	Condition	Approx. SQ FT.
1-A	Plaster	Y	Upstairs Bedroom Ceiling	Good	30'
1-B	Plaster	Y	Upstairs Bedroom Ceiling	Good	-
1-C	Plaster	Y	Upstairs Bedroom Wall	Good	-
1-D	Plaster	Y	Upstairs Bedroom Wall	Good	-
Pb-1	Paint - Interior Base on Upstairs Bedroom Ceiling				
Pb-2	Paint - Interior Base on Upstairs Bedroom Wall				

Notes: Walls and ceilings appeared homogenous. Samples taken near the Chimney/Fireplace.

Inspector Signature: <i>Dalton Lafever</i>	Date: 3/13/24	Time: 4:28
Accepted By: <i>[Signature]</i>	Date: 3/13/24	Time: 4:28 PM
Lab Results Completed By: <i>[Signature]</i>	Date Sent Out: 03-14-24	<input checked="" type="radio"/> Email / <input type="radio"/> Mail

Limitations of Inspection: Atlas Labs Inc. AHERA certified inspector performed a limited survey at the site, date, time and cause as stated above in this document along with lab analysis of possible asbestos and/or lead containing material. Atlas Labs Inc. survey is limited to areas defined on the Chain of Custody form.

General NESHAPS Bulk Sampling Guidelines: Material sampling areas were grouped based on homogeneous materials. A homogeneous area is one which contains material that seems by texture, color and surface wear to be uniform and applied during the same general time period. Samples are collected based on a visual survey of the work area as defined in this report. Samples were collected from accessible, representative construction materials, which were suspected to contain asbestos. If additional materials are found during the demolition process that were inaccessible at time of inspection that are not listed in this report please test before you cut. Survey is subject to direction from contractor, homeowner or owners agent.



Batch # 2022 *

22-1234001

Analysis Date *

03/13/2024

Project #

State Farm Claim#
4762S553Q

Analyst *

Ryan Carpenter

Name / Company *

ServPro of Vancouver

Project Name

Ann Edquist

PO #

Project Location *

2808 E 8th St., Vancouver,
WA 98661

Turnaround Time *

Rush

Asbestos Analysis of Bulk Material by Polarized Light Microscopy

Sample*	Layer*	Description*	Non Asbestos*	Asbestos Type*	Asbestos %*
1-A	1	Plaster (Grey) - Upstairs Bedroom Ceiling	Cellulose / Horsehair	None Present	N/D
1-A	2	Skim Coat (Tan) - Upstairs Bedroom Ceiling	Cellulose	Chrysotile	2%
1-B	1	Plaster (Grey) - Upstairs Bedroom Ceiling	Cellulose / Horsehair	None Present	N/D
1-B	2	Texture (Tan) - Upstairs Bedroom Ceiling	Cellulose	None Present	N/D
1-C	1	Plaster (Grey) - Upstairs Bedroom Wall	Cellulose / Horsehair	None Present	N/D
1-C	2	Texture (White / Tan) - Upstairs Bedroom Wall	Cellulose	None Present	N/D
1-D	1	Plaster (Grey) - Upstairs Bedroom Wall	Cellulose / Horsehair	None Present	N/D
1-D	2	Texture (White / Tan) - Upstairs Bedroom Wall	Cellulose	None Present	N/D
1-D	3	Skim Coat (Grey) - Upstairs Bedroom Wall	Cellulose	None Present	N/D

To Be Filled by the Technician

Technician *



Atlas Laboratories maintains liability to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full without written permission by Atlas. Atlas bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval or endorsement by NVLAP, NIST, NIOSH or any other agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore Atlas recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Transmission Electron Microscopy asbestos identification and lead paint analysis will be available and performed by laboratories by proxy. Original analysis documents are available upon request of the client.