



11815 NE 99th Street, Suite 1294  
Vancouver, WA 98662  
Voice: 360-574-3058  
Fax: 360-576-0925  
Web: <https://www.swcleanair.gov>  
Email: [Tina@swcleanair.gov](mailto:Tina@swcleanair.gov)

## Notice of Intent to Remove Asbestos

Case #: 24-107

Amendment: 0

Date Received: 2/20/2024

Date Paid: 2/20/2024

SWCAA Fee: \$0.00

Receipt #:

**This notification MUST be present at all times at the asbestos project sit**

Quantity to be removed: 45 Square Feet 0 Linear Feet

Workshift days: Th

Project starting date: 2/29/2024 Project Completion date: 2/29/2024

Workshift hours: 8:00AM - 4:30PM

Site Name: Marie Vallentyne	Site address: 19409 NE 232nd Ave
Location of Asbestos: Mud room	City/State/Zip: Battle Ground WA 98604
<input type="checkbox"/> Demolition of Structure (Notification of Demolition required)	County: CLARK COUNTY

☒ Asbestos survey conducted? No survey reason:

AHERA Inspector: Unknown. Bulk Sampling Provided b Certification #: Non Listed.

### Material to be Removed:

- |                                       |  |                                   |   |  |                                    |
|---------------------------------------|--|-----------------------------------|---|--|------------------------------------|
| <input type="checkbox"/> Fireproofing | <input type="checkbox"/> Popcorn Ceiling     | <input type="checkbox"/> CAB      | <input checked="" type="checkbox"/> Sheet Vinyl | <input type="checkbox"/> Boiler Insulation | <input type="checkbox"/> Duct Tape |
| <input type="checkbox"/> Duct Paper   | <input type="checkbox"/> Mag Pipe Insulation | <input type="checkbox"/> Air Cell | <input type="checkbox"/> CA Pipe                | <input type="checkbox"/> VAT               |                                    |
| <input type="checkbox"/> Other        |  |                                   |   |  |                                    |

### Control Methods:

- |   |                                    |   |                                       |   |                                   |
|---|------------------------------------|---|---------------------------------------|---|-----------------------------------|
| <input checked="" type="checkbox"/> N.P Enclosure | <input type="checkbox"/> Glove Bag | <input type="checkbox"/> Mini Enclosure | <input type="checkbox"/> Wrap and Cut | <input checked="" type="checkbox"/> Water | <input type="checkbox"/> HEPA Vac |
| <input checked="" type="checkbox"/> Other         | Manual Methods                     |   |                                       |   |                                   |

Asbestos Contractor: Keystone Contracting, Inc.	Phone: 360-887-0868
Mailing Address: 417 NW 209th St, Ridgefield, WA, 98642	Email: keystone417@tds.net
Certification ##: ABCN00001024	
Supervisor: Juan Villegas	Phone: 503-855-8353
Property Owner: Marie Vallentyne	Phone: 360-546-3259
Mailing Address: 19409 NE 232nd Ave, Battle Ground WA 98604	
Asbestos Disposal Site: Wasco County Landfill: 2550 Steele Rd, The Dalles, OR, 97058-	

**I DO HEREBY CERTIFY THAT THE INFORMATION CONTAINED IN THIS NOTIFICATION IS,  
TO THE BEST OF MY KNOWLEDGE, ACCURATE AND COMPLETE.**

Submitter Name: Kamala Lopez	Representing: Keystone Contracting, Inc
Submitter Title: Office Manger	Date Submitted: 2/20/2024
Reviewed by SWCAA: Brian Fallon	<input checked="" type="checkbox"/> Approved



11815 NE 99th Street, Suite 1294  
Vancouver, WA 98662  
Voice: 360-574-3058  
Fax: 360-576-0925  
Web: <https://www.swcleanair.gov>  
Email: [Tina@swcleanair.gov](mailto:Tina@swcleanair.gov)

## Notice of Intent to Remove Asbestos

Case #: 24-107

Amendment: 0

Date Received: 2/20/2024

Date Paid: 2/20/2024

SWCAA Fee: \$0.00

Receipt #:

**This notification MUST be present at all times at the asbestos project sit**



9317 NE Hwy 99, Suite D, Vancouver, WA 98665 | 360-356-7628

**Polarized Light Microscopy Results**

**Lab No** 143130  
**Layers Analyzed** 4  
**Date Received** 2/16/2024  
**Received By** Chelsea Moore  
**Date Analyzed** 2/16/2024  
**Analyzed By** Nathan Blondino

**Property Address** 19409 NE 232nd Ave  
**City, State, Zip** Battle Ground, WA  
**Job Number** Vallentyne, Marie  
**Client Name** Country Restoration  
**Client Address** \_\_\_\_\_  
**City, State, Zip** \_\_\_\_\_  
**Phone & E-mail** (360) 546-3259

AEI Sample ID	Client Sample ID	Composition	Color/ Description	Asbestos (%)	Non-Asbestos Fiber (%)	Non Fibrous
001	1	Layered	White Joint Compound	Asbestos Not Present	N/A	CaCO <sub>3</sub>
001A		Layered	White Drywall	Asbestos Not Present	15% Cellulose	Gypsum
002	2	Layered	Brown Sheet Flooring	35% Chrysotile	5% Cellulose	Vinyl-CaCO <sub>3</sub> -Binder
002A		Layered	Tan Flooring Mastic	Asbestos Not Present	N/A	Glue

## Disclaimer

- EPA Method 600/M4-82-020 (1982) was used to determine the presence or absence of asbestos fibers in all materials referenced in the above report. PLM analysis is based on visual estimation, and due to limitations of PLM analysis NESHAP regulations recommend that any material determined to contain less than 10% asbestos by the above referenced method should either be assumed to contain greater than 1% asbestos by the owner/operator, or be verified by PLM Point Count or TEM analysis as containing less than 1% asbestos.
- We recommend that TEM analysis be conducted for confirmation of negative PLM analytical results of vinyl floor tiles and vermiculite. These materials may contain asbestos fibers that cannot be detected by PLM analysis due to their size (<0.25 microns in diameter)
- This report may not be used to represent any materials not analyzed and listed in the included report. Advantage Environmental Inc. cannot be held responsible for the interpretation of the results shown. This report may not be reproduced in part and may only be reproduced in full without prior written consent from Advantage Environmental Inc.





**ADVANTAGE**  
Environmental INC.

**ASBESTOS CHAIN OF CUSTODY**  
9317 NE Hwy 99, Suite D • (360) 356-7628  
**LEGAL DOCUMENT - PLEASE PRINT LEGIBLY**

Lab Use Only	
Survey <input type="checkbox"/>	Lab No. 143130
Walk-In <input checked="" type="checkbox"/>	<b>Accept</b> <b>Reject</b>

Sampled By - Please fill out yellow highlighted areas			Project Information - Please fill out yellow highlighted areas		
Date:	02-16-24		Project Name:	Vallentyne, Marie	
Company Name OR Name:	Country Restoration		Address (where material was pulled from):	1409 NE 232nd Ave	
Phone:	360-546-3259		City, State, Zip:	Battle Ground, WA 98604	
Email:	todd@countryrestoration.com		P.O. #:		
RELINQUISHED BY		DATE & TIME	VIA	RECEIVED BY	DATE & TIME
Name: Rieren Sarkela		Date: 02-16-24	Drop Box/Drop Off	<i>Chelger Moore</i>	
Sign: <i>Rieren Sarkela</i>		Time: 4:30			
REQUESTED SERVICES					
PLM			TURNAROUND TIME - Please choose a turnaround time		
Bulk Analysis			<input checked="" type="checkbox"/> Verbal <input type="checkbox"/> Rush <input type="checkbox"/> Same Day <input type="checkbox"/> 24-Hour <input type="checkbox"/> 3-Days		
No.	Sample ID	Color	Description	Volume / Area (as applicable)	Comments / Notes
1	Laundry	White	dry wall		
2	Laundry	brown	Sheet vinyl		
3					
4					
5					
6					
7					
8					
9					
10					
11					