



11815 NE 99th Street, Suite 1294
Vancouver, WA 98662
Voice: 360-574-3058
Fax: 360-576-0925
Web: <https://www.swcleanair.gov>
Email: Tina@swcleanair.gov

Notice of Intent to Remove Asbestos

Case #: 24-109

Amendment: 0

Date Received: 2/20/2024

Date Paid: 2/20/2024

SWCAA Fee: \$37.00

Receipt #: 151525040

This notification MUST be present at all times at the asbestos project sit

OWNER OCCUPIED PERFORMED

Quantity to be removed: 1000 Square Feet 0 Linear Feet

Workshift days: Su Sa

Project starting date: 3/2/2024 Project Completion date: 3/3/2024

Workshift hours: 6:00-6:00

Site Name: West Home

Site address: 113 Cimarron Dr

Location of Asbestos: Ceiling

City/State/Zip: Kelso WA 98626

☐ Demolition of Structure (Notification of Demolition required)

County: COWLITZ COUNTY

☒ Asbestos survey conducted?

No survey reason: Owner took samples

AHERA Inspector:

Certification #:

Material to be Removed:

- | | | | | | |
|---------------------------------------|---|------------------------------|--------------------------------------|--|------------------------------------|
| <input type="checkbox"/> Fireproofing | <input checked="" type="checkbox"/> Popcorn Ceiling | <input type="checkbox"/> CAB | <input type="checkbox"/> Sheet Vinyl | <input type="checkbox"/> Boiler Insulation | <input type="checkbox"/> Duct Tape |
| <input type="checkbox"/> Duct Paper | <input type="checkbox"/> Mag Pipe Insulation | | <input type="checkbox"/> Air Cell | <input type="checkbox"/> CA Pipe | <input type="checkbox"/> VAT |
| <input type="checkbox"/> Other | | | | | |

Control Methods:

- | | | | | | |
|---|------------------------------------|---|---------------------------------------|---|-----------------------------------|
| <input type="checkbox"/> N.P Enclosure | <input type="checkbox"/> Glove Bag | <input type="checkbox"/> Mini Enclosure | <input type="checkbox"/> Wrap and Cut | <input checked="" type="checkbox"/> Water | <input type="checkbox"/> HEPA Vac |
| <input checked="" type="checkbox"/> Other Plastic Sheetting | | | | | |

Asbestos Contractor: Owner Occupant

Phone:

Mailing Address:

Email:

Certification ##:

Supervisor: Cole West

Phone: 360-703-1156

Property Owner: Cole West

Phone: 360-703-1156

Mailing Address: 113 Cimarron Dr, Kelso WA 98626

Asbestos Disposal Site: Waste Control - Longview: 1150 3rd Ave, Longview, WA, 98632-

**I DO HEREBY CERTIFY THAT THE INFORMATION CONTAINED IN THIS NOTIFICATION IS,
TO THE BEST OF MY KNOWLEDGE, ACCURATE AND COMPLETE.**

Submitter Name: Cole West

Representing: Cole West

Submitter Title: Homeowner

Date Submitted: 2/20/2024

Reviewed by SWCAA: Brian Fallon

☒ Approved



11815 NE 99th Street, Suite 1294
Vancouver, WA 98662
Voice: 360-574-3058
Fax: 360-576-0925
Web: <https://www.swcleanair.gov>
Email: Tina@swcleanair.gov

Notice of Intent to Remove Asbestos

Case #: 24-109

Amendment: 0

Date Received: 2/20/2024

Date Paid: 2/20/2024

SWCAA Fee: \$37.00

Receipt #: 151525040

This notification MUST be present at all times at the asbestos project sit



COLE WEST
113 CIMARRON DR
KELSO, WA 98626

CERTIFICATE OF BULK ASBESTOS ANALYSIS

Prepared for: COLE WEST
Phone Number:
Fax Number:
Email Address: westpointpool@gmail.com
Project Name:
Test Location: 113 CIMARRON DR
KELSO, WA 98626
Chain of Custody #: 1703550
Date Sampled: January 7, 2024
Date Reported: January 19, 2024

Andrew Pittman, Analyst

All analyses are performed using the EPA 600/R-93/116 method. The refractive index was determined by using 'Rapidly and Accurately Determining Refractive Indices of Asbestos Fibers by using Dispersion Staining Method', by S-C. Su. This report must not be reproduced in full, without written approval from PRO-LAB/SSPTM, Inc. These test results apply only to the samples actually tested. Polarized light microscopy is not always an accurate way to analyze floor tiles. When a non-detect or very low percentage of asbestos occurs, a transmission electron microscopy analysis (TEM) may be warranted. All samples will be stored for a period of thirty (30) days. The information contained in this report and any attachments is confidential information intended only for the use of the individual or entities named above. Limit of Detection (LOD) = 1%.

The effect of the results relate only to the items tested. PRO-LAB/SSPTM Inc. does not perform any sample collection. The information is supplied by the customer and can affect the validity of results. The results apply to the sample as received.

For more information please contact PRO-LAB at (954) 384-4446 or email info@prolabinc.com



1675 North Commerce Parkway, Weston, FL 33326 (954) 384-4446

113 CIMARRON DR
KELSO, WA 98626

January 7, 2024

Client ID	PRO-LAB ID	LOCATION	Asbestos Mineral Percentage							COMMENTS
			CH	AM	CR	AN	TR	AC	ND	
	011224-1339	BEIGE BATHROOM DRYWALL	0	0	0	0	0	0	ND	15% Cellulose 85% Binders
	011224-1340	WHITE BATHROOM POPCORN	3	0	0	0	0	0		4% Cellulose 20% Perlite 73% Binders

CH=Chrysotile AM=Amosite
CR=Crocidolite AN=Anthophyllite
TR=Tremolite AC=Actinolite
ND=None detected



COLE WEST
113 CIMARRON DR
KELSO, WA 98626

CERTIFICATE OF BULK ASBESTOS ANALYSIS

Prepared for: COLE WEST
Phone Number:
Fax Number:
Email Address: westpointpool@gmail.com
Project Name:
Test Location: 113 CIMARRON DR
KELSO, WA 98626
Chain of Custody #: 1703550
Date Sampled: January 7, 2024
Date Reported: January 19, 2024

Andrew Pittman, Analyst

All analyses are performed using the EPA 600/R-93/116 method. The refractive index was determined by using 'Rapidly and Accurately Determining Refractive Indices of Asbestos Fibers by using Dispersion Staining Method', by S-C. Su. This report must not be reproduced in full, without written approval from PRO-LAB/SSPTM, Inc. These test results apply only to the samples actually tested. Polarized light microscopy is not always an accurate way to analyze floor tiles. When a non-detect or very low percentage of asbestos occurs, a transmission electron microscopy analysis (TEM) may be warranted. All samples will be stored for a period of thirty (30) days. The information contained in this report and any attachments is confidential information intended only for the use of the individual or entities named above. Limit of Detection (LOD) = 1%.

The effect of the results relate only to the items tested. PRO-LAB/SSPTM Inc. does not perform any sample collection. The information is supplied by the customer and can affect the validity of results. The results apply to the sample as received.

For more information please contact PRO-LAB at (954) 384-4446 or email info@prolabinc.com



1675 North Commerce Parkway, Weston, FL 33326 (954) 384-4446

113 CIMARRON DR
KELSO, WA 98626

January 7, 2024

Client ID	PRO-LAB ID	LOCATION	Asbestos Mineral Percentage							COMMENTS
			CH	AM	CR	AN	TR	AC	ND	
	011224-1339	BEIGE BATHROOM DRYWALL	0	0	0	0	0	0	ND	15% Cellulose 85% Binders
	011224-1340	WHITE BATHROOM POPCORN	3	0	0	0	0	0		4% Cellulose 20% Perlite 73% Binders

CH=Chrysotile AM=Amosite
CR=Crocidolite AN=Anthophyllite
TR=Tremolite AC=Actinolite
ND=None detected