

11815 NE 99th Street, Suite 1294

Web: https://www.swcleanair.gov Email: Tina@swcleanair.gov

Vancouver, WA 98662 Voice: 360-574-3058 Fax: 360-576-0925

## **Notification of Demolition**

Case #: 24-122

Date Received: 2/28/2024

Date Paid: 2/28/2024

SWCAA Fee: \$74.00

Amendment: 0

10 day waiting period from date submitted

Receipt #: 151959117

1. Type of Notification: Original 2. Type of Operation: Demolition

3. Facility Description: Pomp's Tire Service, Inc.

Commercial Name or Description: Pomp's Tire Service, Inc.

Address: 1283 NW State Ave

City/State/Zip/County: Chehalis, WA 98532 LEWIS COUNTY

Present Use: Vacant Previous Use: Miscellaneous

4. Facility Information

Property Owner: Pomp's Tire Service

Mailing Address:

Contact: Phone:

5. Name and AHERA Certification Number of Asbestos Inspector:

Name: Sam Neher Certification #: BI-NES-02-08-23-05

6. Asbestos Removal Contractor (if applicable):

Name:

Mailing Address:

Phone: Contact:

7. Dates Asbestos Removal Occurred:

Complete: Asbestos Case No.: -Start:

8. Dates Demolition Will Occur:

Start: 3/9/2024 Complete: 3/12/2024

9. Demolition Contractor:

Name: Tibbits Excavating, LLC

Mailing Address:

Contact: Phone: 360-622-9062

10. Asbestos Disposal Site: N/A

nauled to the a	appropriate recycle/transfe	r station.			
12. Fugitive Emss	ions/dust from Demolition	Activites MUST BE Contro	lled/Prevented during a	II phases of the project	
NA-Electricity	for lighting was the only uti	lity ever connected to the	structure, and that has be	een disconnected.	
•	Asbestos containing Mate		demolition, Stop Work,	Notify SWCAA and	
NA-NO ASBEST	ΓOS				
14. If demolition	is ordered by a Governmen	t Agent:			
Name:			Title:		
Agency: Date of Order:			Date Ordered to Begin:		
Description of	e of Emergency:  Sudden, Unexpected Even				
Explanation o burden:	of how the event caused un	safe conditions or would o	cause equipment damag	e or an unreasonable	
16. I Certify that t	the above information is co	rrect:			
Submitter Name:			Representing:	TIBBITS EXCAVATING	
Submitter Title:	OWNER		Date Submitted:		
Email Address:	CHRIS@TIBBITSEXCAVATI	NG.C			
Reviewed by SWC	CAA: Danielle Kreps	Daull	Keps	<b>✓</b> Approved	

An excavator will be used to bring the structure down within its footprint. Material generated will then be sourced and

11. Description of planned demolition work, method(s) to be used:

The Washington State Dangerous Waste Regulations (WAC 173-303) require that demolition debris be evaluated to determine if it is dangerous. The evaluation should be completed before demolition to ensure that hazardous constituents are not released to the environment and do not present a risk to human health during or after demolition. These requirements apply to all buildings being demolished and are the responsibility of the property owner. The Washington Department of Ecology's website, https://ecology.was.gov/Regulations-Permits/Guidance-technical-assistance/Dangerous-waste-guidance/Common-dangerous-waste/Construction-and-demolition, provides more information about the requirements and about sampling and testing construction materials to detemine if they present a risk. For more information please contact a Hazardous Waste Inspector at the Washington Department of Ecology Southwest Regional Office: (360) 407-6300.



February 6, 2024

Property address: 1283 NW State Ave. Chehalis, WA 98532

On Tuesday February 6, 2024, Down to Earth Land Services, LLC did a visual inspection of the approximately 1225 sq. ft. wood and metal shop shell located at the address listed above and it was determined that there were no suspect materials to be tested for asbestos. It is my recommendation that the structure is safe to demolish.

My AHERA Building Inspector Accreditation No. is BI-NES-02-08-23-05 and expires February 8<sup>th</sup>, 2024.

Please let me know if you have questions or require further information.

Sam Neher

Owner

Down to Earth Land Services, LLC.

DOWNTOEARTHLANDSERVICES@GMAIL.COM

360-975-1163