M SWCAA				Case #: 24-154	
Southwest Clean Air Agency	Notice of Inten	it to Remove /	Asbestos A	mendment: 0	
11815 NE 99th Street, Suite 1294 Vancouver, WA 98662			Date Ree	ceived: 3/12/2024	
Voice: 360-574-3058 Fax: 360-576-0925			Dat	e Paid: 3/12/2024	
Web: https://www.swcleanair.gov Email: Tina@swcleanair.gov			SWCA	AA Fee: \$369.00	
This notification MUST be p	present at all times at t	the asbestos proje	ect sit Rec	ceipt #: 152681664	
Quantity to be removed: 710	Square Feet	0 Linear Feet	Workshift da Workshift bo	ays: T W urs: 4/2 - 10am-4pm, 4/	
Project starting date: 4/2/2024	Project Completion	on date: 4/3/2024	WORKSHITT HO	urs. 4/2 - 10am-4pm, 4/	
Site Name: The Quads Unit 161	.35	Site address: 1	613 Brandt Rd Unit 6		
Location of Asbestos: Bedroor	m 1, Bedroom 2, Hallway, L	iv City/State/Zip: V	ancouver	WA 98661	
Demolition of Structure (Noti	fication of Demolition requ	uired)	County: CLARK COL	JNTY	
Asbestos survey conducted?	No survey	reason:			
AHERA Inspector: Kyler Spears			Certification #: 18	37341	
Material to be Removed: Fireproofing Popcorn	Ceiling 🗌 CAB	Sheet Vinyl	Boiler Insulation	n 🗌 Duct Tape	
Duct Paper Mag Pipe	-	Air Cell	🗆 CA Pipe		
✓ Other Ceiling Scrape					
Control Methods:					
✓ N.P Enclosure	g 🛛 🗌 Mini Enclosure	Wrap and Cut	✓ Water	HEPA Vac	
Other					
Asbestos Contractor: Abatemen	t Services of Washington		Phone: 503-765-525	57	
Mailing Address: PO Box 74			Email: tristan@aba		
Certification ##: ABCN0000	)1610				
Supervisor: Khamari P	eusy	Pho	ne: 503-504-5047		
Property Owner: The Quads		Pho	ne: 360-882-6036		
Mailing Address: 1613 Bran	dt Rd Unit S,Vancouver WA	A 98661			
Asbestos Disposal Site: Hillsbor	o Landfill: 3205 SE Minter	Bridge Rd, Hillsboro, (	DR, 97123-		
	TIFY THAT THE INFORM IE BEST OF MY KNOWL			CATION IS,	
Submitter Name: Mckenzie Bat			Representing: ASI		
Submitter Title:			ate Submitted: 3/12/2	2024	

Reviewed by SWCAA:	Mihai Voivod



# Notice of Intent to Remove Asbestos

Case #: 24-154 Amendment: 0

11815 NE 99th Street, Suite 1294 Vancouver, WA 98662	Date Received:	3/12/2024
Voice: 360-574-3058 Fax: 360-576-0925 Web: https://www.swcleanair.gov	Date Paid:	3/12/2024
Email: Tina@swcleanair.gov	SWCAA Fee:	\$369.00
This notification MUST be present at all times at the asbestos project sit	Receipt #:	152681664

# LIMITED ASBESTOS SURVEY

For The Quad Apartments located at:

## 1613 BRANDT ROAD UNIT #S VANCOUVER, WASHINGTON

Prepared for: Al Angelo Company

CERTIFIED ENVIRONMENTAL CONSULTING, LLC 615 SE CHKALOV DRIVE SUITE 12 VANCOUVER, WASHINGTON 98683-5280

> Prepared by: Don Young Kyler Spears

## **EXECUTIVE SUMMARY**

#### Dear Mr. Smith:

Enclosed are the results of the limited asbestos survey report conducted by C.E.C., LLC, for The Quad Apartments located at, 1613 Brandt Road Unit #S, in Vancouver, Washington for renovation purposes. This survey was coordinated with you and conducted on March 5, 2024, by Kyler Spears, and Don Young, AHERA certified inspectors. Please note that this survey is limited to the areas of renovation (ceiling samples).

All samples were taken in a random manner as required by EPA AHERA rules and analyzed using polarized light microscopy with dispersion staining according to EPA and OR-OSHA Methodology. The samples were analyzed in C.E.C., LLC's laboratory at, 615 SE Chkalov Drive Suite #12, in Vancouver, Washington. As the asbestos samples were analyzed in our laboratory, the analytical data enclosed is the analysis report.

Asbestos was identified in the white sprayed on ceiling texture (See sample data sheet attached). Please note: the quantities and/or amounts listed within (Summary Data, Assessment of Materials sections) are estimates only and are not to be relied upon for estimating the removal costs. All quantities and/or amounts should be field verified by the responsible parties for the true amounts and removal costs.

The following survey is divided into the following sections:

- Summary sheet details the type and construction of the building with approximate amounts of asbestos in the building.
- Sample result sheet contains sample numbers and results, description of materials and homogeneous areas of material.
- Assessment of materials contains an assessment of asbestos materials.
- Response actions recommended contains the response actions we recommend.
- Laboratory analysis sheet contains the results of our laboratory analysis.
- ◊ Inspector's certifications.
- ◊ Photographic log.
- Asbestos chain of custody form (survey report form).

C.E.C. has investigated accessible and inaccessible areas of this facility in locating suspect ACM using destructive sampling including the interior and exterior. The current extent and condition of the ACM was detected through on-site observation and physical determination.

NOTE: This asbestos survey report is available to Al Angelo Company, and not to be reproduced in total or part without written consent of Al Angelo Company.

We appreciate the opportunity to have worked with you. If you have any questions or if we can be of any further service, please contact our office.

Sincerely, Don Young Principal

#### SUMMARY SHEET

**Owner or Representative:** Brian Smith

Address: The Quad Apartments at, 1613 Brandt Road Unit #S

City: Vancouver State: Washington

Owner's Representative: Al Angelo Company Mr. Brian Smith 400 Mill Plain Blvd Suite #500 Vancouver, Washington 98660-3244

Owner/Rep. Telephone Number: (541) 310-9387

Surveyed by: Kyler Spears-Accreditation Number: 192139 Don Young-Accreditation Number: 190124

#### **CONSTRUCTION DATA:**

Year Built: Approx.: 1960's

Size: Approx. 800 SQ FT

Construction Type: Wood, Concrete, Metal

Current/Past Use: Multi-Family-Residential/Multi-Family-Residential

Number of Floors:

Roof Construction: Not in Scope of Work

Heating System: Baseboard-Not in Scope of Work

Attic Insulation: Not in Scope of Work

Pipe Insulation: Not in Scope of Work

#### SUMMARY DATA

# THE QUAD APARTMENTS AT, 1613 BRANDT ROAD UNIT #S, VANCOUVER, WASHINGTON

PRODUCT	FUNCTIONAL SPACE	AMOUNT	FRIABLE	CONDITION	SAMPLE #	RESULTS
WHITE SPRAYED ON CEILING TEXTURE	LIVING ROOM, KITCHEN, HALLWAY, SELECTIVE THROUGHOUT	APPROX. 600 SQ FT	YES	GOOD	1, 2, 3	6% CHRYSOTILE

Please note: the quantities and/or amounts listed within (Summary Data, Assessment of Materials sections) are estimates only and are not to be relied upon for estimating the removal costs. All quantities and/or amounts should be field verified by the responsible parties for the true amounts and removal costs.

Certified Environmental Consulting, LLC, warrants that the findings contained herein have been prepared in general accordance with accepted professional practices as applied by similar professionals in the community at the time of this report preparation. Changes in the state of the art or in applicable regulations cannot be anticipated and have not been addressed in this report. The field and laboratory results reported herein are considered sufficient in detail and scope to determine presence of asbestos containing materials in or around the area(s) requested at the time of the inspection. Test results are valid only for the materials tested.

There is a distinct possibility that conditions may exist that could not be identified within the scope of the inspection or that were not apparent during the site visit. This inspection covered only those areas that were exposed or physically accessible to the inspector. The inspection is limited to the information available from the client at the time of the inspection was conducted.

## SAMPLE RESULTS

#### THE QUAD APARTMENTS AT, 1613 BRANDT ROAD UNIT #S, VANCOUVER, WASHINGTON

SAMPLE #	SAMPLE DESCRIPTION	SAMPLE LOCATION	HOMOGENEOUS AREA	ASBESTOS CONTENT
1	WHITE SPRAYED ON CEILING TEXTURE	LIVING ROOM	SELECTIVE THROUGHOUT	6% CHRYSOTILE
2	WHITE SPRAYED ON CEILING TEXTURE	KITCHEN	SELECTIVE THROUGHOUT	6% CHRYSOTILE
3	WHITE SPRAYED ON CEILING TEXTURE	HALLWAY	SELECTIVE THROUGHOUT	6% CHRYSOTILE

615 SE CHKALOV DRIVE SUITE 12 VANCOUVER, WASHINGTON 98683-5280 PORTLAND (503) 221-7904 VANCOUVER (360) 254-9385 Fax (360) 891-9633

## ASSESSMENT OF MATERIALS

#### Building: THE QUAD APARTMENTS AT, 1613 BRANDT ROAD UNIT #S, VANCOUVER, WASHINGTON

Sample #'s	Functional Space	Asbestos Type	%	Material And Condition	Comments	Sq. Ft. And/Or Linear Footage
1, 2, 3	LIVING ROOM, KITCHEN, HALLWAY, SELECTIVE THROUGHOUT	CHRYSOTILE	6%	WHITE SPRAYED ON CEILING TEXTURE (GOOD)	SEE RESPONSE ACTIONS	APPROX. 600 SQ FT

Please note: the quantities and/or amounts listed within (Summary Data, Assessment of Materials sections) are estimates only and are not to be relied upon for estimating the removal costs. All quantities and/or amounts should be field verified by the responsible parties for the true amounts and removal costs.

Inspector: Kyler Spears- Accreditation Number: 192139

Date: March 8, 2024 Signature:

#### **RESPONSE ACTIONS RECOMMENDED**

#### Building: THE QUAD APARTMENTS, 1613 BRANDT ROAD UNIT #S, VANCOUVER, WASHINGTON

MATERIAL	LOCATION	RECOMMENDED RESPONSE ACTIONS
SPRAYED ON CEILING TEXTURE (WHITE)	LIVING ROOM, KITCHEN, HALLWAY, SELECTIVE THROUGHOUT	Sprayed on ceiling texture is a friable material, which is currently in good condition and poses no health risk in its current state. It is important to keep it encapsulated with a high vehicular latex paint. Do not sand on, drill through, remove, or otherwise disturb material. Must be removed prior to renovation or demolition.

Management Planner: Don Young - Accreditation Number: 190128

1

Signature:	Du	te	3	Date March 8, 20	24
	Q	2			
		7			

#### SAMPLE ANALYSIS REPORT

CLIENT: AL ANGELO COMPANY

MR. BRIAN SMITH 400 MILL PLAIN BLVD SUITE #500 VANCOUVER, WASHINGTON 98660-3244 DATE SAMPLED: 03-05-24 DATE RECEIVED: 03-05-24 DATE COMPLETED: 03-06-24

SOURCE: THE QUAD APARTMENTS AT, 1613 BRANDT ROAD UNIT #S, VANCOUVER, WASHINGTON SAMPLED BY: KYLER SPEARS LAB/JOB #: JJ-338/24-45 ANALYZED BY: KYLER SPEARS

ANALYTICAL METHOD: EPA 600/R-93/116, 40 CFR Part 763, Subpart E, Appendix E, Section 1, PLM/Dispersion Staining

	1 DA	wir Dispersion Stanning	No. of Concession, Name	
SAMPLE ID #	SAMPLE DESCRIPTION	SAMPLE LOCATION	ASBESTOS CONTENT	OTHER MATERIAL
1	WHITE SPRAYED ON CEILING TEXTURE	LIVING ROOM	6% CHRYSOTILE	3% CELLULOSE, CALCIUM CARBONATE, SYNTHETIC FOAM, BINDER
2	WHITE SPRAYED ON CEILING TEXTURE	KITCHEN	6% CHRYSOTILE	3% CELLULOSE, CALCIUM CARBONATE, SYNTHETIC FOAM, BINDER
3	WHITE SPRAYED ON CEILING TEXTURE	HALLWAY	6% CHRYSOTILE	3% CELLULOSE, CALCIUM CARBONATE SYNTHETIC FOAM, BINDER

ANALYST:

**REVIEWED BY** 

DEVIATION FROM METHOD: NONE. PERCENTAGES ARE ESTIMATES. TEST RESULTS PERTAIN ONLY TO ITEMS TESTED. \* DETECTION LIMIT IS LESS THAN 1% ASBESTOS. NON-ASBESTOS MATERIALS ARE NOT NECESSARILY LISTED.





615 SE CHKALOV DRIVE SUITE 12 VANCOUVER, WASHINGTON 98683-5280 PORTLAND (503) 221-7904 VANCOUVER (360) 254-9385 Fax (360) 891-9633

# **Photographic Log**





CERTIFIED ENVIRONMENTAL CONSULTING, LLC. SURVEY REPORT LAB # 57-338 DATE: <u>3-5</u> SAMPLED BY: <u>45</u> COST/QUOTE \$ PO#JOB # CLIENT: <u>Al angelo COMPANY</u> CONTACT: <u>Brian Smith</u> BILLING ADDRESS: CITY/STATE: ZIP: BILLING ADDRESS: CITY/STATE: ZIP: The Quad Apartments Und #S PHONE: CELL: EMAIL/FAX: PROJECT ADDRESS: <u>1613 Brandt AD</u> <u>10ancourr</u> , WA YEAR BUILT: <u>1960'S</u> TOTAL SF: <u>8000</u> CONSTRUCTION TYPE <u>Brood</u> , const, mta/ HOW MANY FLOORS: <u>1</u> BASEMENT PRESENT: <u>100</u> ROOFING TYPE: <u>105</u> W BUILDING USE PREVIOUS/CURRENT: <u>fax</u>						
SAMPLE	DESCRIPTIÓN OF	SAMPLE LOCATION	HOMOGENEOUS AREA	SQ FOOTAGE		
#	Sport 1/2	LUR	Sto	600		
2	sport in	Kitchu	Sto.			
3	Sport white	hallway	SFD			

615 SE CHKALOV DRIVE SUITE 12, VANCOUVER, WASHINGTON 98683-5280 (503) 221-7904 (360) 254-9385