

Notice of Intent to Remove Asbestos

Case #: 24-224

4/9/2024

154148031

11815 NE 99th Street, Suite 1294

Vancouver, WA 98662 Voice: 360-574-3058 Fax: 360-576-0925

Web: https://www.swcleanair.gov Email: Tina@swcleanair.gov

Date Received: 4/9/2024

Amendment: 0

Date Paid:

Receipt #:

SWCAA Fee: \$147.00

This notification MUST be present at all times at the asbestos project sit

Quantity to be removed: 150 Square Feet 0	Linear Feet	Workshift days:	. [
Project starting date: 4/19/2024 Project Completion		•	8:00am-4:30pm
Site Name: Richter Residence	Site address: 194	37 NE 157th Ave	
Location of Asbestos: Hallway bathroom, Laundry room,	City/State/Zip: Batt	le Ground	WA 98604
☐ Demolition of Structure (Notification of Demolition requir	ed) (County: CLARK COUNT	Υ
✓ Asbestos survey conducted? No survey re	ason:		
AHERA Inspector: Occupant Owner		Certification #:	
Material to be Removed: ☐ Fireproofing ☐ Popcorn Ceiling ☐ CAB ☐ Duct Paper ☐ Mag Pipe Insulation	✓ Sheet Vinyl ☐ Air Cell	☐ Boiler Insulation☐ CA Pipe	☐ Duct Tape
Other			
Control Methods: ✓ N.P Enclosure ☐ Glove Bag ☐ Mini Enclosure	☐ Wrap and Cut	✓ Water	✓ HEPA Vac
☑ Other Regulate Area			
Asbestos Contractor: Minority Abatement Contractors, Inc. Mailing Address: 3200 NE 65th St, Vancouver, WA, 9866		hone: 360-750-1900 Email: vwhitebird@mi	norityac.com
Certification ##: ABCN00001346 Supervisor: Jesus Ortiz	Phone	: 360-605-7958	
Property Owner: Ryan Richter	Phone	: 503-807-8011	
Mailing Address: 19437 NE 157th Ave, Battle Ground WA	98604		
-		'058-	

TO THE BEST OF MY KNOWLEDGE, ACCURATE AND COMPLETE.

Submitter Name:	Guillermo Plaza	Representing:	Minority Abatement Contract
Submitter Title:	Project Manager	Date Submitted:	4/9/2024
Reviewed by SWC	AA: Mihai Voivod		✓ Approved



11815 NE 99th Street, Suite 1294

Web: https://www.swcleanair.gov Email: Tina@swcleanair.gov

Vancouver, WA 98662 Voice: 360-574-3058

Fax: 360-576-0925

Notice of Intent to Remove Asbestos

Case #: 24-224

Amendment: 0

Date Received: 4/9/2024

Date Paid: 4/9/2024

SWCAA Fee: \$147.00

This notification MUST be present at all times at the asbestos project sit

Receipt #: 154148031



Clean your world.

9317 NE Hwy 99, Suite D, Vancouver, WA 98665 | 360-356-7628 Polarized Light Microscopy Results

Lab No 139492 Layers Analyzed 31

Date Received 5/24/2023 Received By Rieanna Caliendo Date Analyzed 5/24/2023

Analyzed By Nathan Blondino

Property Address 19437 NE 157th Ave

City, State, Zip Battle Ground, WA Job Number

Bliken Construction

Client Name Viable Earth Consulting LLC

Client Address City, State, Zip

Phone & E-mail (360) 843-9728

AEI Sample ID	Client Sample ID	Composition	Color/ Description	Asbestos (%)	Non-Asbestos Fiber (%)	Non Fibrous
001	1A	Layered	White Texture	Asbestos Not Present	N/A	(White) Paint-CaCO3
001A		Layered	White Drywall	Asbestos Not Present	15% Cellulose	Gypsum
002	1B	Layered	Beige/Tan Cove Base	Asbestos Not Present	N/A	Vinyl-CaCO3
002A		Layered	White Cove Base Mastic	Asbestos Not Present	N/A	Glue
002B		Layered	White Texture	Asbestos Not Present	N/A	(Green) Paint-CaCO3
002C		Layered	White Drywall	Asbestos Not Present	15% Cellulose	Gypsum
003	1C	Layered	White Texture	Asbestos Not Present	N/A	(White) Paint-CaCO3
003A		Layered	White Drywall	Asbestos Not Present	15% Cellulose	Gypsum
004	1D	Layered	Beige/Tan Cove Base	Asbestos Not Present	N/A	Vinyl-CaCO3
004A		Layered	White Cove Base Mastic	Asbestos Not Present	N/A	Glue
004B		Layered	White Texture	Asbestos Not Present	N/A	(Green/White) Paint- CaCO3
004C		Layered	White Drywall	Asbestos Not Present	15% Cellulose	Gypsum
005	1E	Homogeneous	White Texture	Asbestos Not Present	N/A	CaCO3-Sand
006	1F	Layered	Beige/Tan Cove Base	Asbestos Not Present	N/A	Vinyl-CaCO3
006A		Layered	Tan Cove Base Mastic	Asbestos Not Present	N/A	Glue
006В		Layered	White Texture	Asbestos Not Present	N/A	(Tan) Paint-CaCO3
006C		Layered	White Joint Compound	Asbestos Not Present	N/A	CaCO3
006D		Layered	White Drywall	Asbestos Not Present	10% Cellulose	Gypsum
007	1G	Layered	Beige/Tan Cove Base	Asbestos Not Present	N/A	Vinyl-CaCO3





Lab No 139492

Property Address 19437 NE 157th Ave Battle Ground, WA

AEI Sample ID	Client Sample ID	Composition	Color/ Description	Asbestos (%)	Non-Asbestos Fiber (%)	Non Fibrous
007A		Layered	White Cove Base Mastic	Asbestos Not Present	N/A	Glue
007В		Layered	White Texture	Asbestos Not Present	N/A	(White) Paint-CaCO3
007C		Layered	White Joint Compound	Asbestos Not Present	N/A	CaCO3
007D		Layered	White Drywall	Asbestos Not Present	10% Cellulose	Gypsum
008	2A	Layered	Beige Floor Tile	Asbestos Not Present	N/A	Vinyl-CaCO3
008A		Layered	Clear Flooring Mastic	Asbestos Not Present	N/A	Silicone
008B		Layered	Green Sheet Flooring	36% Chrysotile	5% Cellulose	Vinyl-CaCO3-Binder
008C		Layered	Tan Flooring Mastic	Asbestos Not Present	N/A	Glue
009	2B	Layered	Off-White Sheet Flooring	Asbestos Not Present	35% Cellulose 7% Glass Fibers	Vinyl-CaCO3
009A		Layered	Tan Flooring Mastic	Asbestos Not Present	N/A	Glue
010	2C	Layered	Beige/Off-White Speckle Sheet Flooring	30% Chrysotile	5% Cellulose	Vinyl-CaCO3-Binder
010A		Layered	Tan Flooring Mastic	Asbestos Not Present	N/A	Glue

Disclaimer

- EPA Method 600/M4-82-020 (1982) was used to determine the presence or absence of asbestos fibers in all materials referenced in the above report. PLM analysis is based on visual estimation, and due to limitations of PLM analysis NESHAP regulations recommend that any material determined to contain less than 10% asbestos by the above referenced method should either be assumed to contain greater than 1% asbestos by the owner/operator, or be verified by PLM Point Count or TEM analysis as containing less than 1% asbestos.
- We recommend that TEM analysis be conducted for confirmation of negative PLM analytical results of vinyl floor tiles and vermiculite. These materials may contain asbestos fibers that cannot be detected by PLM analysis due to their size (<0.25 microns in diameter)
- This report may not be used to represent any materials not analyzed and listed in the included report. Advantage Environmental Inc. cannot be held responsible for the interpretation of the results shown. This report may not be reproduced in part and may only be reproduced in full without prior written consent from Advantage Environmental Inc.



AS

LEGA

Project Information - Please fill out yellow highlighted areas	Walk-In 🖳 Accept Reject	L DOCUMENT - PLEASE PRINT LEGIBLY	9317 NE Hwy 99. Suite D • (360) 356-7628	
d areas	Accept	Lab No. 13946	e Only	
	Reject	139492		

					Walk-III Accept Reject
Sample	d By - Please fill out	Sampled By - Please fill out yellow highlighted areas	eas	Project Information -	Project Information - Please fill out yellow highlighted areas
Date: 5/2:	5/23/23		Project Name:	e: Blika	as Construction
Company Name OR Name:	R Name: Viable	e Earth Consulting	ric	Address (where material was pulled from):	191
Phone: 360	1		City, State,	Zip: Rafle	Grand WA 98604
nail: Vial	ole earth 1/c	Viable enth 1/c agmail. con	7 P.O. #:	2	ZP '
RELIN	RELINQUISHED BY	DATE & TIME	VIA) RE	RECEIVED BY OME & TIME
Name Frankic	Kunte	Date 5/23/23	Drop Box/Drop Off	1 LOW	MI Call THE 5124123
Sign X	1	Time 9:4 7AM	3 _ 4	((0.00
			REQUESTED SERVICES	VICES	
	PLM		TU	RNAROUND TIME - Ple	TURNAROUND TIME - Please choose a turnaround time
	Bulk Analysis		☐ Verbal	X Rush	☐ Same Day ☐ 24-Hour ☐ 3-Days
No. Sample ID	Color	Des	Description	Volume / Area (as applicable)	Comments / Notes
1 / A	White	Drywall			/ iving voom Coiling
2 1 1/3	Great	Drywall &	Cova Base		Livingroom wall
3 1 0	Whik !	Drywall			(i) woon file
4	Cyrus	Dywa!			Play room Wall
5 15	whit	Drywell 7	xxture		Bedroom # 1 on Righ
6	MATE	Brywall 3	cove Base		Restroom wall
7 6	white	Dywall \$	Cour Bax		Fatrice Wall
8 Z Z	Sven	Vinily Tile		2 Layers	Restvoom 1
9 2 3	While	Vinyle Tile			Kitchen
10 Z C	white	Vinya Tix			Caundy Avea
11					