



Notice of Intent to Remove Asbestos

Case #: 24-241

Amendment: 0

11815 NE 99th Street, Suite 1294
Vancouver, WA 98662
Voice: 360-574-3058
Fax: 360-576-0925
Web: <https://www.swcleanair.gov>
Email: Tina@swcleanair.gov

Date Received: 4/16/2024

Date Paid: 4/16/2024

SWCAA Fee: \$369.00

Receipt #: 154629485

This notification MUST be present at all times at the asbestos project sit

Quantity to be removed: 600 Square Feet 0 Linear Feet

Workshift days: M T W Th F

Project starting date: 4/29/2024 Project Completion date: 5/2/2024

Workshift hours: 7-4

Site Name: Edward Jones Site address: 404 E 15th St., Suite 4

Location of Asbestos: Walls throughout City/State/Zip: Vancouver WA 98663

Demolition of Structure (Notification of Demolition required) County: CLARK COUNTY

Asbestos survey conducted? No survey reason:

AHERA Inspector: Certification #:

Material to be Removed:

- Fireproofing Popcorn Ceiling CAB Sheet Vinyl Boiler Insulation Duct Tape
- Duct Paper Mag Pipe Insulation Air Cell CA Pipe VAT
- Other:

Control Methods:

- N.P Enclosure Glove Bag Mini Enclosure Wrap and Cut Water HEPA Vac
- Other:

Asbestos Contractor: Willamette Construction Services Phone: 503-236-4299

Mailing Address: 8823 N Harborgate St, Portland, OR, 97203 Email: bob@gdsidemo.com

Certification ##: ABCN00001672

Supervisor: Jacon Reding Phone: 971.401.0731

Property Owner: Edward Jones Phone: 971-610-1004

Mailing Address: 404 E 15th, suite 4, Vancouver WA 98663

Asbestos Disposal Site: Hillsboro Landfill: 3205 SE Minter Bridge Rd, Hillsboro, OR, 97123-

I DO HEREBY CERTIFY THAT THE INFORMATION CONTAINED IN THIS NOTIFICATION IS, TO THE BEST OF MY KNOWLEDGE, ACCURATE AND COMPLETE.

Submitter Name: Joshua J Beauchamp **Representing:** Willamette Construction Servi

Submitter Title: Project Manager **Date Submitted:** 4/16/2024

Reviewed by SWCAA: Brian Fallon Approved



11815 NE 99th Street, Suite 1294
Vancouver, WA 98662
Voice: 360-574-3058
Fax: 360-576-0925
Web: <https://www.swcleanair.gov>
Email: Tina@swcleanair.gov

Notice of Intent to Remove Asbestos

Case #: 24-241

Amendment: 0

Date Received: 4/16/2024

Date Paid: 4/16/2024

SWCAA Fee: \$369.00

Receipt #: 154629485

This notification MUST be present at all times at the asbestos project sit

9317 NE Hwy 99, Suite D, Vancouver, WA 98665 | 360-356-7628
Polarized Light Microscopy Results

Lab No 144013
Layers Analyzed 9
Date Received 4/10/2024
Received By Chelsea Moore
Date Analyzed 4/11/2024
Analyzed By Nathan Blondino

Property Address 404 E 15th St
City, State, Zip Vancouver, WA
Job Number Edward Jones
Client Name Perlo Construction
Client Address _____
City, State, Zip _____
Phone & E-mail (971) 330-1611

AEI Sample ID	Client Sample ID	Composition	Color/Description	Asbestos (%)	Non-Asbestos Fiber (%)	Non Fibrous
001	A	Layered	White Texture	3% Chrysotile	N/A	(Tan) Paint-CaCO ₃
001A		Layered	White Drywall	Asbestos Not Present	25% Cellulose	Gypsum
002	B	Layered	Brown/Green Carpet	Asbestos Not Present	85% Synthetic Fibers	Binder
002A		Layered	Yellow Flooring Mastic	Asbestos Not Present	N/A	Glue
003	C	Layered	Dark Brown Cove Base	Asbestos Not Present	N/A	Vinyl-CaCO ₃
003A		Layered	White Cove Base Mastic	Asbestos Not Present	N/A	Glue
004	4	Layered	Tan Insulation	Asbestos Not Present	99% Glass Fibers	Debris
005A		Layered	Tan Paper Backing	Asbestos Not Present	99% Cellulose	Debris
006	5	Homogeneous	White/Yellow Ceiling Tile	Asbestos Not Present	95% Glass Fibers	(White) Paint

Disclaimer

- EPA Method 600/M4-82-020 (1982) was used to determine the presence or absence of asbestos fibers in all materials referenced in the above report. PLM analysis is based on visual estimation, and due to limitations of PLM analysis NESHAP regulations recommend that any material determined to contain less than 10% asbestos by the above referenced method should either be assumed to contain greater than 1% asbestos by the owner/operator, or be verified by PLM Point Count or TEM analysis as containing less than 1% asbestos.
- We recommend that TEM analysis be conducted for confirmation of negative PLM analytical results of vinyl floor tiles and vermiculite. These materials may contain asbestos fibers that cannot be detected by PLM analysis due to their size (<0.25 microns in diameter)
- This report may not be used to represent any materials not analyzed and listed in the included report. Advantage Environmental Inc. cannot be held responsible for the interpretation of the results shown. This report may not be reproduced in part and may only be reproduced in full without prior written consent from Advantage Environmental Inc.



ADVANTAGE
Environmental INC.

ASBESTOS CHAIN OF CUSTODY
9317 NE Hwy 99, Suite D • (360) 356-7628
LEGAL DOCUMENT - PLEASE PRINT LEGIBLY

Lab Use Only	
Survey <input type="checkbox"/>	Lab No. 144013
Walk-In <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/> Accept <input type="checkbox"/> Reject

Sampled By - Please fill out yellow highlighted areas		Project Information - Please fill out yellow highlighted areas	
Date:	4/10/2024	Project Name:	Edward Jones
Company Name OR Name:	Perlo Construction	Address (where material was pulled from):	404 E. 15th Street
Phone:	971-330-1611	City, State, Zip:	Vancouver Wa-
Email:	Tschmitz @ Perlo. Biz	P.O. #:	

RELINQUISHED BY		DATE & TIME	VIA	RECEIVED BY	DATE & TIME
Name	Travis Schmitz	Date	Drop Box/Drop Off	Julien Moore	4/10/24
Sign	Travis Schmitz	Time			12:13 PM

PLM		TURNAROUND TIME - Please choose a turnaround time			
Bulk Analysis		<input type="checkbox"/> Verbal	<input type="checkbox"/> Rush	<input type="checkbox"/> Same Day	<input type="checkbox"/> 24-Hour <input checked="" type="checkbox"/> 3-Days

No.	Sample ID	Color	Description	Volume / Area (as applicable)	Comments / Notes
1	A		Sheetrock		
2	B		Carpet		
3	C		rubber base		
4	D		Insulation		
5	E		ceiling tile		
6					
7					
8					
9					
10					
11					