



11815 NE 99th Street, Suite 1294  
Vancouver, WA 98662  
Voice: 360-574-3058  
Fax: 360-576-0925  
Web: <https://www.swcleanair.gov>  
Email: [Tina@swcleanair.gov](mailto:Tina@swcleanair.gov)

## Notice of Intent to Remove Asbestos

Case #: 24-245

Amendment: 0

Date Received: 4/17/2024

Date Paid: 4/17/2024

SWCAA Fee: \$738.00

Receipt #: 154707501

**This notification MUST be present at all times at the asbestos project sit**

### \*\*\* EMERGENCY NOTICE \*\*\*

Quantity to be removed: 1606 Square Feet 0 Linear Feet

Workshift days: W

Project starting date: 4/24/2024 Project Completion date: 4/24/2024

Workshift hours: 8:00am-4:30pm

Site Name: Vorse Residence

Site address: 422 SW 4th Ave Castle Rock, WA 98611

Location of Asbestos: Dining Room and Living Room

City/State/Zip: Castle Rock WA 98611

☐ Demolition of Structure (Notification of Demolition required)

County: COWLITZ COUNTY

☒ Asbestos survey conducted?

No survey reason:

AHERA Inspector: Occupant Owner

Certification #:

#### Material to be Removed:

☐ Fireproofing ☐ Popcorn Ceiling ☐ CAB ☐ Sheet Vinyl ☐ Boiler Insulation ☐ Duct Tape

☐ Duct Paper ☐ Mag Pipe Insulation

☐ Air Cell

☐ CA Pipe

☐ VAT

☒ Other Plaster with ACM skim coat

#### Control Methods:

☒ N.P Enclosure

☐ Glove Bag

☐ Mini Enclosure

☐ Wrap and Cut

☒ Water

☒ HEPA Vac

☒ Other Manual Methods

Asbestos Contractor: Minority Abatement Contractors, Inc.

Phone: 360-750-1900

Mailing Address: 3200 NE 65th St, Vancouver, WA, 98663

Email: [vwhitebird@minorityac.com](mailto:vwhitebird@minorityac.com)

Certification ##: ABCN00001346

Supervisor: Jose Bahena

Phone: 503-780-6691

Property Owner: Nathan Vorse

Phone: 360-261-2227

Mailing Address: 422 4th Ave SW, Castle Rock WA 98611

Asbestos Disposal Site: Wasco County Landfill: 2550 Steele Rd, The Dalles, OR, 97058-

**I DO HEREBY CERTIFY THAT THE INFORMATION CONTAINED IN THIS NOTIFICATION IS,  
TO THE BEST OF MY KNOWLEDGE, ACCURATE AND COMPLETE.**

Submitter Name: Gabriel Parra

Representing: Minority Abatement Contract

Submitter Title: Operations Manager

Date Submitted: 4/17/2024

Reviewed by SWCAA: Danielle Kreps

*Danielle Kreps*

☒ Approved



11815 NE 99th Street, Suite 1294  
Vancouver, WA 98662  
Voice: 360-574-3058  
Fax: 360-576-0925  
Web: <https://www.swcleanair.gov>  
Email: [Tina@swcleanair.gov](mailto:Tina@swcleanair.gov)

## Notice of Intent to Remove Asbestos

Case #: 24-245

Amendment: 0

Date Received: 4/17/2024

Date Paid: 4/17/2024

SWCAA Fee: \$738.00

Receipt #: 154707501

**This notification MUST be present at all times at the asbestos project sit**

 **Atlas Labs**

4/15  
9:00 AM

CHAIN OF CUSTODY	
Name / Company Name: ServiceMaster by JTS	Phone: (360) 425-3331
Contact Email: mail@servicemasterjts.com	
Job Name: Porge	Job/Project #: L24-0184
Job/Project Location: 422 SW 4th Ave Castle Rock WA 98011	

**Please check box that applies**

\*Samples turned in by 2 pm will be processed the same day

X	Abestos PLM
	Lead Paint
	Other

[illegible]

**Client Sign Here:**

Atlas: Accepted By:

**Credit Card:**

**Lab Results Completed By:**

Date: 3/16/24

Date: 3/18/24

Time: PM

Time: 11:40

Will Skolawsky

Check #

Date Sent Out: 3/18/24

Amount \$

Email/Fax/Mail

Lab Results Completed By: \_\_\_\_\_ Date Sent Out: 5/10/12  
 \*Atlas charges a per sample fee and not by layer. One sample fee equals four layers. Additional layers will result in an additional sample fee.



211P  
NAOOP



Batch # 2022 \*

22-1238701

Name / Company \*

ServiceMaster by JTS

Analysis Date \*

03/18/2024

Project Name

Vorse

Project #

L24-0184

PO #

Analyst \*

Crossland Kapaun

Project Location \*

422 SW 4th Ave., Castle  
Rock, WA 98611

Turnaround Time \*

Rush

**Asbestos Analysis of Bulk Material by Polarized Light Microscopy**

Sample*	Layer*	Description*	Non Asbestos*	Asbestos Type*	Asbestos %*
1	1	Plaster (White) - Living Room	Cellulose	None Present	N/D
1	2	1st Layer Skim Coat (Green) - Living Room	Cellulose	Chrysotile	4%
1	3	2nd Layer Skim Coat (White) - Living Room	Cellulose	None Present	N/D
2	1	Plaster (White) - Bedroom 1	Cellulose	None Present	N/D
2	2	1st Layer Skim Coat (Green) - Bedroom 1	Cellulose	Chrysotile	4%
2	3	2nd Layer Skim Coat (Pink) - Bedroom 1	Cellulose	Chrysotile	3%

**To Be Filled by the Technician**  
Technician \*



Atlas Laboratories maintains liability to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full without written permission by Atlas. Atlas bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval or endorsement by NVLAP, NIST, NIOSH or any other agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore Atlas recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Transmission Electron Microscopy asbestos identification and lead paint analysis will be available and performed by laboratories by proxy. Original analysis documents are available upon request of the client.