



# Notice of Intent to Remove Asbestos

Case #: 24-250

Amendment: 0

11815 NE 99th Street, Suite 1294  
Vancouver, WA 98662  
Voice: 360-574-3058  
Fax: 360-576-0925  
Web: <https://www.swcleanair.gov>  
Email: Tina@swcleanair.gov

Date Received: 4/18/2024

Date Paid: 4/18/2024

SWCAA Fee: \$147.00

Receipt #: 154758416

**This notification MUST be present at all times at the asbestos project sit**

Quantity to be removed: 0 Square Feet 122 Linear Feet

Workshift days: M T

Project starting date: 4/29/2024 Project Completion date: 4/30/2024

Workshift hours: 7-4

Site Name: EAST EVERGREEN APARTMENTS II, L Site address: 313 EAST 12TH STREET

Location of Asbestos: Subterranean 3&#39; brick lay City/State/Zip: Vancouver WA 98660

Demolition of Structure (Notification of Demolition required) County: CLARK COUNTY

Asbestos survey conducted? No survey reason: PACM

AHERA Inspector: [ ]

Certification #: [ ]

### Material to be Removed:

- Fireproofing  Popcorn Ceiling  CAB  Sheet Vinyl  Boiler Insulation  Duct Tape
- Duct Paper  Mag Pipe Insulation  Air Cell  CA Pipe  VAT
- Other [ ]

### Control Methods:

- N.P Enclosure  Glove Bag  Mini Enclosure  Wrap and Cut  Water  HEPA Vac
- Other [ ]

Asbestos Contractor: Willamette Construction Services Phone: 503-236-4299

Mailing Address: 8823 N Harborgate St, Portland, OR, 97203 Email: bob@gdsidemo.com

Certification ##: ABCN00001672

Supervisor: Jacob Reding Phone: 971-401-0731

Property Owner: EAST EVERGREEN APARTMENTS II, LLC Phone: 503-582-8451

Mailing Address: 30050 SW Town Center Loop W Suite 200, Wilsonville OR 97070

Asbestos Disposal Site: Waste Management: [ ]

I DO HEREBY CERTIFY THAT THE INFORMATION CONTAINED IN THIS NOTIFICATION IS, TO THE BEST OF MY KNOWLEDGE, ACCURATE AND COMPLETE.

Submitter Name: Joshua J Beauchamp

Representing: Willamette Construction Servi

Submitter Title: Project Manager

Date Submitted: 4/18/2024

Reviewed by SWCAA: Danielle Kreps

*Danielle Kreps*

Approved



11815 NE 99th Street, Suite 1294  
Vancouver, WA 98662  
Voice: 360-574-3058  
Fax: 360-576-0925  
Web: <https://www.swcleanair.gov>  
Email: [Tina@swcleanair.gov](mailto:Tina@swcleanair.gov)

## Notice of Intent to Remove Asbestos

Case #: 24-250

Amendment: 0

Date Received: 4/18/2024

Date Paid: 4/18/2024

SWCAA Fee: \$147.00

Receipt #: 154758416

**This notification MUST be present at all times at the asbestos project sit**

---



9317 NE Hwy 99, Suite D, Vancouver, WA 98665 | 360-356-7628

**Polarized Light Microscopy Results**

**Lab No** 143924  
**Layers Analyzed** 2  
**Date Received** 4/3/2024  
**Received By** Chelsea Moore  
**Date Analyzed** 4/4/2024  
**Analyzed By** Nathan Blondino

**Property Address** 313 E 12th St  
**City, State, Zip** Vancouver, WA  
**Job Number** 9931 / Aeon II  
**Client Name** Hahn & Associates, Inc.  
**Client Address** \_\_\_\_\_  
**City, State, Zip** \_\_\_\_\_  
**Phone & E-mail** (503) 312-8636

AEI Sample ID	Client Sample ID	Composition	Color/Description	Asbestos (%)	Non-Asbestos Fiber (%)	Non Fibrous
001	9931-240403-001	Homogeneous	Gray Pipe Wrap	60% Chrysotile	N/A	Binder
002	9931-240403-002	Homogeneous	Off-White Pipe Wrap	50% Chrysotile <1% Amosite	N/A	CaCO <sub>3</sub>

## Disclaimer

- EPA Method 600/M4-82-020 (1982) was used to determine the presence or absence of asbestos fibers in all materials referenced in the above report. PLM analysis is based on visual estimation, and due to limitations of PLM analysis NESHAP regulations recommend that any material determined to contain less than 10% asbestos by the above referenced method should either be assumed to contain greater than 1% asbestos by the owner/operator, or be verified by PLM Point Count or TEM analysis as containing less than 1% asbestos.
- We recommend that TEM analysis be conducted for confirmation of negative PLM analytical results of vinyl floor tiles and vermiculite. These materials may contain asbestos fibers that cannot be detected by PLM analysis due to their size (<0.25 microns in diameter)
- This report may not be used to represent any materials not analyzed and listed in the included report. Advantage Environmental Inc. cannot be held responsible for the interpretation of the results shown. This report may not be reproduced in part and may only be reproduced in full without prior written consent from Advantage Environmental Inc.



**ADVANTAGE**  
Environmental INC.

**ASBESTOS CHAIN OF CUSTODY**  
9317 NE Hwy 99, Suite D • (360) 356-7628  
**LEGAL DOCUMENT - PLEASE PRINT LEGIBLY**

Lab Use Only	
Survey <input type="checkbox"/>	Lab No. <u>143924</u>
Walk-In <input checked="" type="checkbox"/>	<u>Accept</u> Reject

Sampled By - Please fill out yellow highlighted areas		Project Information - Please fill out yellow highlighted areas	
Date:	<u>4   3   24</u>	Project Name:	<u>Aeon II</u>
Company Name OR Name:	<u>Hahn &amp; Associates, Inc.</u>	Address (where material was pulled from):	<u>313 E 124th Street</u>
Phone:	<u>Roger Brown 503-312-8636</u>	City, State, Zip:	<u>Vancouver WA</u>
Email:	<u>rogerb@hahnenv.com</u>	P.O. #:	<u>9931</u>

RELINQUISHED BY		DATE & TIME	VIA	RECEIVED BY	DATE & TIME
Name	<u>Roger E Brown</u>	Date	<u>4/3/24</u>	<u>[Signature]</u>	<u>4/3/24</u> <u>11:37 AM</u>
Sign	<u>[Signature]</u>	Time	<u>11:35</u>		

REQUESTED SERVICES	
PLM	TURNAROUND TIME - Please choose a turnaround time
Bulk Analysis	<input type="checkbox"/> Verbal <input type="checkbox"/> Rush <input type="checkbox"/> Same Day <input checked="" type="checkbox"/> 24-Hour <input type="checkbox"/> 3-Days

No.	Sample ID	Color	Description	Volume / Area (as applicable)	Comments / Notes
1	<u>9931-240403-001</u>	<u>Gray</u>	<u>soft pipe wrap</u>		
2	<u>9931-240403-002</u>	<u>Gray</u>	<u>hard pipe wrap</u>		
3					
4					
5					
6					
7					
8					
9					
10					
11					