



11815 NE 99th Street, Suite 1294
Vancouver, WA 98662
Voice: 360-574-3058
Fax: 360-576-0925
Web: <https://www.swcleanair.gov>
Email: Tina@swcleanair.gov

Notice of Intent to Remove Asbestos

Case #: 24-263

Amendment: 0

Date Received: 4/23/2024

Date Paid: 4/23/2024

SWCAA Fee: \$738.00

Receipt #: 155006785

This notification MUST be present at all times at the asbestos project sit

*** EMERGENCY NOTICE ***

Quantity to be removed: 317 Square Feet 0 Linear Feet

Workshift days: W

Project starting date: 4/24/2024 Project Completion date: 4/24/2024

Workshift hours: 10AM-3PM

Site Name: Deborah Detering

Site address: 11320 NE 10th Ave

Location of Asbestos: Living room

City/State/Zip: Vancouver

WA 98685

☐ Demolition of Structure (Notification of Demolition required)

County: CLARK COUNTY

☒ Asbestos survey conducted?

No survey reason:

AHERA Inspector: Joel Dillard

Certification #: IN-231415-C

Material to be Removed:

- ☐ Fireproofing ☐ Popcorn Ceiling ☐ CAB ☐ Sheet Vinyl ☐ Boiler Insulation ☐ Duct Tape
☐ Duct Paper ☐ Mag Pipe Insulation ☐ Air Cell ☐ CA Pipe ☐ VAT
☒ Other Drywall And Plaster

Control Methods:

- ☒ N.P Enclosure ☐ Glove Bag ☐ Mini Enclosure ☐ Wrap and Cut ☒ Water ☒ HEPA Vac
☐ Other

Asbestos Contractor: Abatement Services of Washington

Phone: 503-857-7175

Mailing Address: PO Box 747, Beavercreek, OR, 97004

Email: tristan@abateservices.com

Certification ##: ABCN00001610

Supervisor: Yessica Grgeorio

Phone: 971-287-1419

Property Owner: Deborah Detering

Phone: 760-515-0252

Mailing Address: 11320 NE 10th Ave, Vancouver WA 98685

Asbestos Disposal Site: Hillsboro Landfill: 3205 SE Minter Bridge Rd, Hillsboro, OR, 97123-

**I DO HEREBY CERTIFY THAT THE INFORMATION CONTAINED IN THIS NOTIFICATION IS,
TO THE BEST OF MY KNOWLEDGE, ACCURATE AND COMPLETE.**

Submitter Name: Ashley Morales

Representing: Asi

Submitter Title:

Date Submitted: 4/23/2024

Reviewed by SWCAA: Mihai Voivod

☒ Approved



11815 NE 99th Street, Suite 1294
Vancouver, WA 98662
Voice: 360-574-3058
Fax: 360-576-0925
Web: <https://www.swcleanair.gov>
Email: Tina@swcleanair.gov

Notice of Intent to Remove Asbestos

Case #: 24-263

Amendment: 0

Date Received: 4/23/2024

Date Paid: 4/23/2024

SWCAA Fee: \$738.00

Receipt #: 155006785

This notification MUST be present at all times at the asbestos project sit

Limited Asbestos Survey Report

Owner/Operator Name:

Farmers Insurance

Owner/Operator Number:

(503) 327-3602

Limited Survey Date:

04/16/2024

Survey Address:

11320 NE 10th Ave, Vancouver, WA 98685

Survey Location:

Interior Living Room

What is the building's description?

Residence

What is this structure's current use?

Residential Home

What is this structure's past use?

Residential Home

Building Square Footage:

3,079'

Number of Floors:

2

Area Surveyed:

Interior Living Room Ceiling

Approximate Build Date:

1972

Purpose of the Survey:

Remediation due to damage

Survey Limitations: Samples are collected based on a visual inspection of the work area as defined in the analysis report. Samples were collected from accessible, representative construction materials, which were suspected to contain asbestos. If additional materials are found during the demolition process that were inaccessible at time of inspection that are not listed in this report please have materials tested before they are impacted. Survey is subject to direction from contractor, homeowner or owners agent.

Asbestos Containing Building Material Identified During Survey: **Please see the completed attached analysis report.*

Sample #	Location	Asbestos Containing Material	Description (Color, Texture & Pattern)	Asbestos % & Asbestiform	Approx. Sq. Footage	Friable Y/N	Condition
1-A Layer 2	Living Room Ceiling	Texture	White	4% Chrysotile	50'	Y	Good
1-B Layer 2	Living Room Ceiling	Texture	White	4% Chrysotile	-	Y	Good
1-C Layer 2	Living Room Ceiling	Texture	White	4% Chrysotile	-	Y	Good

Recommended Response Action Plan:**Contact a Licenced Abatement Contractor or SW Clean Air Agency**


Sw Clean Air Agency regulates the handling, removal and disposal of asbestos-containing material to protect public health and the environment.

<https://www.lni.wa.gov/licensing-permits/other-licenses-permits/asbestos-certification#certified-contractors-list> . For more information on asbestos removal, please refer to [SWCAA 476](#), specifically SWCAA 476-050. If you have any questions, please contact us at 360-574-3058

A copy of this survey report must be kept onsite during any remediation, renovation or demolition activities, as required by Southwest Clean Air Agency.

Surveyed Performed By:

**Joel Dillard
Of
Atlas Labs Inc.
Environmental Testing Services
AHERA Cert #: IN-231415-C
CCB #: 231684**



Atlas Laboratories Inc.
14795 SW 72nd Ave, STE B Portland, OR 97224
(503) 430-5290 www.atlaslabsinc.com
CCB #231684



Limited Survey Chain of Custody



Name / Company Name: Farmers Insurance		Phone: (503) 327-3602
Contact Email: myclaim@farmersinsurance.com		
Project Name: Deborah Detering	Claim # 5028767459-1	Batch: 22-1286401
Job/Project Address: 11320 NE 10th Ave, Vancouver, WA 98685		
Inspector: Joel Dillard Ph: (360) 949-2984 AHERA Cert. # IN-231415-C Lead RRP Cert. # R-I-41R036-23-00588		
Survey Area Use: Residential	Approx. Year Built: 1972	Reason for Survey: Remediation

<input type="checkbox"/>	Rush
<input checked="" type="checkbox"/>	Next Day
<input type="checkbox"/>	2-Day
<input type="checkbox"/>	5-Day

<input checked="" type="checkbox"/>	Asbestos PLM
<input type="checkbox"/>	Lead Paint
<input type="checkbox"/>	Other

#	Material Description	Friable Y/N	Location	Condition	Approx. SQ FT.
1-A	Plaster	Y	Living Room Ceiling	Good	50'
1-B	Plaster	Y	Living Room Ceiling	Good	-
1-C	Plaster	Y	Living Room Ceiling	Good	-

Notes:

Inspector Signature: 	Date: 4/16/2024	Time: 10:44 am
Accepted By: Will Sokolowsky	Date: 4/16/24	Time: 11:01 am
Lab Results Completed By: 	Date Sent Out: 4/16/24	Email / Mail

Limitations of Inspection: Atlas Labs Inc. AHERA certified inspector performed a limited survey at the site, date, time and cause as stated above in this document along with lab analysis of possible asbestos and/or lead containing material. Atlas Labs Inc. survey is limited to areas defined on the Chain of Custody form.

General NESHAPS Bulk Sampling Guidelines: Material sampling areas were grouped based on homogeneous materials. A homogeneous area is one which contains material that seems by texture, color and surface wear to be uniform and applied during the same general time period. Samples are collected based on a visual survey of the work area as defined in this report. Samples were collected from accessible, representative construction materials, which were suspected to contain asbestos. If additional materials are found during the demolition process that were inaccessible at time of inspection that are not listed in this report please test before you cut. Survey is subject to direction from contractor, homeowner or owners agent.



Batch # 2022 *

22-1286401

Name / Company *

Farmers Insurance

Analysis Date *

04/16/2024

Project Name

Deborah Detering

Project #

Claim #5028767459-1

PO #

Analyst *

Crossland Kapaun

Project Location *

11320 NE 10th Ave.,
Vancouver, WA 98685

Turnaround Time *

1-Day

Asbestos Analysis of Bulk Material by Polarized Light Microscopy

Sample*	Layer*	Description*	Non Asbestos*	Asbestos Type*	Asbestos %*
1-A	1	Plaster (White) - Living Room Ceiling	Cellulose	None Present	N/D
1-A	2	Texture (White) - Living Room Ceiling	Cellulose	Chrysotile	4%
1-A	3	Drywall (White) - Living Room Ceiling	Cellulose	None Present	N/D
1-B	1	Plaster (White) - Living Room Ceiling	Cellulose	None Present	N/D
1-B	2	Texture (White) - Living Room Ceiling	Cellulose	Chrysotile	4%
1-B	3	Drywall (White) - Living Room Ceiling	Cellulose	None Present	N/D
1-C	1	Plaster (White) - Living Room Ceiling	Cellulose	None Present	N/D
1-C	2	Texture (White) - Living Room Ceiling	Cellulose	Chrysotile	4%
1-C	3	Drywall (White) - Living Room Ceiling	Cellulose	None Present	N/D

To Be Filled by the Technician

Technician *



Atlas Laboratories maintains liability to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full without written permission by Atlas. Atlas bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval or endorsement by NVLAP, NIST, NIOSH or any other agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore Atlas recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Transmission Electron Microscopy asbestos identification and lead paint analysis will be available and performed by laboratories by proxy. Original analysis documents are available upon request of the client.