$\sim$ SM/CAA			Case #: 24-283
Southwest Clean Air Agency Notice of Inter	nt to Remove A	Asbestos Ame	endment: 0
11815 NE 99th Street, Suite 1294 Vancouver, WA 98662		Date Receiv	ved: 4/29/2024
Voice: 360-574-3058 Fax: 360-576-0925		Date P	Paid: 4/29/2024
Web: https://www.swcleanair.gov Email: Tina@swcleanair.gov		SWCAA	Fee: \$369.00
This notification MUST be present at all times at	the asbestos projec	ct sit Receip	ot #: 155362086
Quantity to be removed: 200 Square Feet	0 Linear Feet	Workshift days	· M
	ion date: 5/13/2024	•	: 8:00AM - 4:30PM
	5, 10, 2021		
Site Name: Country Restoration	Site address: 26	812 NE 34th St	
Location of Asbestos: Bathroom, laundry room	City/State/Zip: Ca	mas	WA 98607
Demolition of Structure (Notification of Demolition req	uired)	County: CLARK COUNT	۲Y
Asbestos survey conducted? No survey	reason: PACM		
AHERA Inspector: Unknown. Bulk Sampling Provided b		Certification #: Non	Listed.
Material to be Removed:	Sheet Vinyl	Boiler Insulation	Duct Tape
Duct Paper Mag Pipe Insulation	Air Cell	🗌 CA Pipe	
✓ Other Sheetrock Mud			
Control Methods: N.P Enclosure Glove Bag Mini Enclosure	e 🗌 Wrap and Cut	☑ Water	🗌 HEPA Vac
Other Manual Methods			
Asbestos Contractor: Keystone Contracting, Inc.		Phone: 360-887-0868	
Mailing Address: 417 NW 209th St, Ridgefield, WA, 98 Certification ##: ABCN00001024	8642	Email: keystone417@	tds.net
Supervisor: Martin Ortiz	Phon	e: 360-353-6423	
Property Owner: Andy Tyler	Phon	e: 360-546-3259	
Mailing Address: 26812 NE 34th St,Camas WA 98607		2. 300-340-3233	
Asbestos Disposal Site: Wasco County Landfill: 2550 Stee		7058-	
	,		
I DO HEREBY CERTIFY THAT THE INFOR TO THE BEST OF MY KNOWI			TION IS,
Submitter Name: Kamala Lopez	R	epresenting: Keystone	Contracting. Inc

Submitter Name:	Kamala Lopez		Representing:	Keystone Contracting, In
Submitter Title:	Office Manager		Date Submitted:	4/29/2024
		-		

Reviewed by SWCAA: Danielle Kreps

Danlle Kups

Approved



# Notice of Intent to Remove Asbestos

Case #: 24-283
Amendment: 0

11815 NE 99th Street, Suite 1294 Vancouver, WA 98662 Voice: 360-574-3058	Date Received:	4/29/2024
Fax: 360-576-0925 Web: https://www.swcleanair.gov	Date Paid:	4/29/2024
Email: Tina@swcleanair.gov	SWCAA Fee:	\$369.00
This notification MUST be present at all times at the asbestos project sit	Receipt #:	155362086





#### 9317 NE Hwy 99, Suite D, Vancouver, WA 98665 | 360-356-7628 Polarized Light Microscopy Results

Lab No		144165		Property Address	26812 NE 34th St			
Layers Analyzed		3		City, State, Zip	Camas, WA			
				Job Number	Tyler, Andy			
Dat	e Received	4/22/2024		Client Name	Country Restoration			
R	eceived By	Talia Carroll		Client Address				
Date Analyzed		4/23/2024		City, State, Zip				
Analyzed By		Nathan Blondino		Phone & E-mail	(360) 601-1664			
AEI Sample ID	Client Sample ID	Composition	Color/ Description	Asbestos (%)	Non-Asbestos Fiber (%)	Non Fibrous		
001	1	Layered	White Texture	Asbestos Not Present	N/A	(Light Gray) Paint- CaCO3		
001A		Layered	White Texture 3% Chrysotile		N/A	(Beige/Light Orange) Paint-CaCO3-Mica		
001B		Layered White Drywall		Asbestos Not Present	20% Cellulose	Gypsum		

## Disclaimer

• EPA Method 600/M4-82-020 (1982) was used to determine the presence or absence of asbestos fibers in all materials referenced in the above report. PLM analysis is based on visual estimation, and due to limitations of PLM analysis NESHAP regulations recommend that any material determined to contain less than 10% asbestos by the above referenced method should either be assumed to contain greater than 1% asbestos by the owner/operator, or be verified by PLM Point Count or TEM analysis as containing less than 1% asbestos.

• We recommend that TEM analysis be conducted for confirmation of negative PLM analytical results of vinyl floor tiles and vermiculite. These materials may contain asbestos fibers that cannot be detected by PLM analysis due to their size (<0.25 microns in diameter)

• This report may not be used to represent any materials not analyzed and listed in the included report. Advantage Environmental Inc. cannot be held responsible for the interpretation of the results shown. This report may not be reproduced in part and may only be reproduced in full without prior written consent from Advantage Environmental Inc.



## ASBESTOS CHAIN OF CUSTODY

9317 NE Hwy 99. Suite D • (360) 356-7628 LEGAL DOCUMENT - PLEASE PRINT LEGIBLY Lab Use Only
Survey
Lab No. 144/65
Walk-In
K

Sampled By - Please fill out yellow highlighted areas Project Information - Please fill									ease fill out ye		ghted areas	
Date: 4/22/24					Project Name: Tyler, Andy							
Company Name OR Name: Country Restoration					Address (where material was pulled from): 268[2 NE 34th SF,							
Phone: (360) 601-1664 City, State, Zip: Camas, W.A 98607								-				
Emai	il: Spencer 6	Dcountryres	forafi	en.com		P.O. #: Tylex, Andy						
	RELIN	QUISHED BY		DATE & TIME		VIA RECEIVED BY DATE & T					& TIME	
Nam	espencer	Kalliainen	1	Date 41 22/34	Drop Box/Drop Off		4	la			4-27	2-24
Sign	San 2/4	li		Time 11:00 AM							[]÷c	20
					RE	QUESTED SER				a tribing to		
1		PLM							choose a turn			
		Bulk Analy	sis			Verbal	Volume /	Rush	Same D	ay 🔀	24-Hour	3-Days
No.	Sample ID	Color		Des	cription		(as applica		Comments / Notes			
1		white	shee	etrock								
2						- 9						
3				-								
4												
5				5 (A) A								81
6												
7												
8						2						-
9										10		
10		0										
11												



417 NW 209<sup>th</sup> Street, Ridgefield WA 98642 (360) 887-0868 office (360) 887-8157 fax WA Registration #KEYSTCI132NS Oregon CCB #64144 keystone417@tds.net

4/29/2024

Spencer Country Restoration 360-450-8091 spencer@countryrestoration.com

Andy Tyler 26812 NE 34<sup>th</sup> St Camas WA 98607

### **Asbestos Abatement Bid Proposal**

Dear Spencer,

Thank you for the opportunity to quote this work. Please accept the following as our proposal for the removal and disposal of asbestos containing materials from the above referenced job location. The scope of work is as follows:

To safely remove Build negative air containment and flood cut 3' perimeter of bathroom, laundry room, portion of hallway.

Labor \$1,370.00 Materials and Disposal \$525.00 Permits & Independent clearance \$300.00 Rental truck\$100.00

### LUMP SUM BID PRICE: .....\$ 2,295.00

#### \*Applicable sales tax will be added to bid price

Terms Net 30, 11/2% Interest Charged after 30 days

The above bid price includes all labor, materials, equipment mobilization, waste disposal and transportation, notification fee, and includes our fees for project oversight and administration.

A 10 Day waiting period is required by the local governing authorities before work can begin for any project over 10 linear feet or 48 square feet. All turn away days will be charged at \$500.00 per turn away.

Asbestos Liability Insurance at \$1,000,000 per occurrence is in effect. Work to be done under Negative Air Enclosure if required and performed by Washington Certified Abatement Workers in accordance with all applicable federal, state, and local rules and regulations governing the safe handling and disposing of asbestos containing materials. Any alteration or deviation from the above specifications involving extra cost of material or labor will be executed upon written orders from same and will become an extra charge over the sum mentioned in this bid proposal.

Keystone Contracting reserves the right to claim lien. Keystone Contracting shall be entitled to recover its reasonable attorney fees incurred to enforce or interpret this agreement, whether or not suit or arbitration is commenced, and if commenced, its reasonable attorney fees incurred at trial or in arbitration, an on any appeal, review, or reconsideration thereof, and in any bankruptcy proceeding, and the reasonable attorney fees incurred to collect or attempt to collect on any award, order or judgement.

Again, thank you for this opportunity. Please feel free to call me at (360) 887-0868 with any questions or comments you may have.

Sincerely, John Van Vessem

Accepted by: \_\_\_\_\_

Date: \_\_\_\_\_