

Notice of Intent to Remove Asbestos

Case #: 24-476

11815 NE 99th Street, Suite 1294

Vancouver, WA 98662 Voice: 360-574-3058 Fax: 360-576-0925

Web: https://www.swcleanair.gov Email: Tina@swcleanair.gov Date Received: 7/9/2024

Amendment: 0

Date Paid: 7/9/2024

SWCAA Fee: \$369.00

This notification MUST be present at all times at the asbestos project sit

Receipt #: 158939362

Quantity to be removed: 3	00 Square Feet	0 Linear Feet	Workshift days:	M F	
Project starting date: 7/19/	2024 Project Con	npletion date: 7/22/2024	Workshift hours:	7am to 330pm	
Site Name: 1201 Main Stre	et	Site address: 12	201 Main St.		
Location of Asbestos: Base	ement Vault floor	City/State/Zip: V	ancouver	WA 98660	
☐ Demolition of Structure (Notification of Demolitio	n required)	County: CLARK COUNT	Y	
✓ Asbestos survey conduct	ed? No s	urvey reason:			
AHERA Inspector: Brian Tho	ompson		Certification #: 18868	35	
	d: orn Ceiling	☐ Sheet Vinyl ☐ Air Cell	☐ Boiler Insulation☐ CA Pipe	☐ Duct Tape ✓ VAT	
✓ Other Floor Mastic					
Control Methods: ✓ N.P Enclosure ☐ Glov ✓ Other chemical stripper		osure Wrap and Cut	☑ Water	✓ HEPA Vac	
Asbestos Contractor: Globa	Pacific Environmental In	C.	Phone: 360-772-6402		
Mailing Address: PO Bo Certification ##: ABCN	x 2759, Vancouver, WA, 9	98668	Email: KEVIN@GLOBAL	PACIFIC.INFO	
Supervisor: Alex G		Phor	ne: 360-909-7614		
Property Owner: DST 150, LLC.			Phone: 888-755-0616		
Mailing Address: 210 SV	A/ \A/:laa.a Aa.aa #440 B	end OR 97702			
8	v wilson Avenue #110,B				

TO THE BEST OF MY KNOWLEDGE, ACCURATE AND COMPLETE.

Submitter Name: Kevin D Crouse		Representing:	Global Pacific Environmental I	
Submitter Title:	VP Operations	Date Submitted:	7/9/2024	

Reviewed by SWCAA: Mihai Voivod

✓ Approved



Notice of Intent to Remove Asbestos

Case #: 24-476

Amendment: 0

11815 NE 99th Street, Suite 1294 Vancouver, WA 98662

Voice: 360-574-3058 Fax: 360-576-0925

Web: https://www.swcleanair.gov Email: Tina@swcleanair.gov Date Received: 7/9/2024

Date Paid: 7/9/2024

SWCAA Fee: \$369.00

This notification MUST be present at all times at the asbestos project sit

Receipt #:

ceipt #: 158939362

Asbestos Inspection

Of The

Building on Property

at

1201 Main St

in

Vancouver, WA

January 23rd, 2024

#24-7058

presented to:

Pahlisch Commercial Rhiannon Moore **Development Coordinator** 1201 Main St Vancouver, WA 98660 RhiannonM@pahlisch.com

prepared by:

Compliance Environmental Services, LLC.

PO Box 87277 Vancouver, WA. 98687 (360) 834-3031 compensol@gmail.com

Compliance Environmental Services LLC.

PO Box 87277 Vancouver, WA 98687 Phone (360) 834-3031 e:mail:compensol@gmail.com

EPA/AHERA ASBESTOS INSPECTION CES: 24-7058							
Date: 01-23-24 Tim	e: 07:00 Client Nan	ne: Pahlisch	Commercia	1			
Inspection Address: Building @ 1201 Main St Vancouver,WA							
Client Address:	Pahlisch Commercial /	1201 Main St	Vancouver	, WA			
Phone #:	Phone #: 1-210-755-0616 e-mail / RhiannonM@pahlisch.com						
Inspector:	Brian Thompson #	188685					
Purpose: Locate, Identify & Quantify ACM Prior To Demolition							
Building Description:	Building Description: Type of structures Foundation Walls Roof Flooring						
1970s	X #1 Story #2 Story	X Concrete	X DWJC	□ 3-Tab	X Concrete		
	X Basement Trailer	□ Block	□ Wood	X Flat	□ Wood		
	□ Outbuildings	□ Wood	X Plaster	□ Shake	□ Both		
Total # Samples Including sub-Layers: #11 Total # Samples Containing 19/ on More Ashestos: #2							
Total # Samples Containing 1% or More Asbestos: #2							
Remediation Required		Yes	X No				

RESULTS

Samples were collected from selected homogeneous materials in order to evaluate the presence or absence of asbestos in each material. Determination of homogeneous materials included material type, texture, pattern, color, and size.

Samples analyzed by AHERA Protocol. -Positive Materials are in Red / More than 1%

ID#	Description / Location	Floors	Wall	Ceilings	Exterior	Total Sq/ft	% Asbestos
F-1*	FLOOR TILE / Basement - Vault	X				+/- 300 sq/ft	2% Chrysotile
F-1M	FLOOR TILE / MASTIC	X					4% Chrysotile
F-2	FLOORING / Basement Kitchen	X					None Detected
F-2M	FLOORING / MASTIC	X					None Detected
F-3	FLOORING / Main floor Bathroom	X					None Detected

^{*}ASBESTOS DETECTED IN THE BASEMENT VAULT / 9X9 FLOOR TILE & MASTIC / +/-300 SQ/FT CHRYSOTILE

-- PAGE 01 of 03 -

CONTINUED

(SWCAA)

(L & I)

ID#	Description / Location	Floors	Wall	Ceilings	Exterior	Total Sq/ft	% Asbestos
W-1	DWJC / BASEMENT		X				None Detected
W-2	DWJC / BASEMENT BATH		X				None Detected
W-3	DWJC / MAIN FLOOR EAST		X				None Detected
CT-1	CEILING TILES – MAIN FLOOR / NORTH			X			None Detected
CT-2	CEILING TILES – MAIN FLOOR / EAST			X			None Detected
R-1	ROOFING – FLAT				X		None Detected

GOVERNING AGENCIES

Asbestos containing materials are regulated in the Vancouver, Washington area by the following regulatory agencies;

(US-EPA Region 10) United States Environmental Protection Agency

NESHAPS; Reference 40 CFR Part 61 Sub-Part M

& AHERA; 40 CFR Part 763

(WISHA) Washington Industrial Safety & Health Administration

Reference; 29 CFR 1926.1101 Southwest Clean Air Agency

Southwest Clean Air Agency

Reference; SWCAA 476 Standards for Asbestos Control State Washington Department of Labor and Industries

Reference; General Occupational Health Standards Chapter 296-62-WAC

DISCUSSION & RECOMMENDATIONS

When demolition or renovation is to occur then all asbestos containing materials must be removed. The Occupational Safety and Health Administration (OSHA) & the Washington Industrial Safety and Health Administration (WISHA) classify the removal or disturbance of the above described asbestos containing materials as Class 11 asbestos abatement project. The removal or any disturbance of these materials must be undertaken by trained and qualified individuals. Furthermore, the Washington State Department of Labor and Industries (L&I) as well as the Southwest Washington Air Pollution Control Agency (SWAPCA) requires 10 days notification and the appropriate fees prior to the beginning of an asbestos abatement project of this nature.

LABORATORY INFORMATION

Samples were analyzed by Environmental Hazards Services, Inc. using Polarized Light Microscopy (PLM) with dispersion staining to identify asbestos constituents as required by EPA regulation 40 CFR, Part 763 NESHAP. EHS Laboratory is accredited by the American Industrial Hygiene Association (AIHA) and the National Voluntary Laboratory Accreditation Program (NVLAP #1882).

EHS #24-02-01731 (Analysis upon request)

-- PAGE 02 of 03 --

DISCLAIMER

Conclusions reached as the result of analysis done on suspect materials are not 100% accurate. Error can occur in two forms: 1) sampling error; and 2) non-uniform distribution of asbestos in materials that otherwise appear homogeneous. CES conclusions are based on the results of the laboratory analysis and the site inspection. Compliance Environmental Services, Inc. is not responsible for any asbestos-containing material that might be behind walls, under floors, underground, or in any area that is generally inaccessible.

DEMOLITION PERMIT

This report needs to be submitted to the following agency (SWCAA) for demolition approval.

(SWCAA) Southwest Clean Air Agency 11815 NE 99TH St. Suite #129A Vancouver, WA 98682 (360)-574-3058

Web: www.swcleanair.org

Report Prepared By:


Thompson

Brian Thompson

EPA/AHERA Building Inspector

#188685

-- PAGE 3 of 03-END OF REPORT



Certificate of Completion

This is to certify that

Brian Thompson

has satisfactorily completed 4 hours of refresher training as an


AHERA Building Inspector

to comply with the training requirements of TSCA Title II, 40 CFR 763 (AHERA)

EPA Provider # 1085

188685 Certificate Number

Instructor: Ed Edinger



EnvironmentalGeotechnicalMaterials

Apr 5, 2023 Expires in 1 year.

Date(s) of Training

Exam Score: N/A (if applicable)

TREE - DECIDUOUS

POWER TRANSFORMER

TREE - CONIFER

POWER METER

POWER POLE W/ LIGHT

POWER RISER

POWER POLE

WATER VAULT

FIRE HYDRANT

WATER METER

WATER VALVE

WATER STANDPIPE

GAS

ELECTRIC

TELEPHONE

FENCE

OVERHEAD POWER

SANITARY SEWER

PROPERTY A

TITLE REPORT SPECIAL EXCEPTIONS:

THE FOLLOWING EXCEPTIONS AFFECT THE SUBJECT PROPERTY IN A SURVEYABLE MANNER AS PER FIRST AMERICAN TITLE INSURANCE COMPANY FILE NO.: NCS-1115762-WA1, EFFECTIVE DATE FEBRUARY 24, 2022. 13. A DEED OF TRUST TO SECURE AN ORIGINAL INDEBTEDNESS OF \$NOT STATED RECORDED DECEMBER 18, 2003 AS RECORDING NO. 3768224 OF OFFICIAL RECORDS.

DATED: SEPTEMBER 29, 2003

TRUSTOR: VANCOUVER FUNERAL CHAPEL, INC., A WASHINGTON CORPORATION TRUSTEE: CHICAGO TITLE INSURANCE COMPANY, A MISSOURI CORPORATION BENEFICIARY: BANK OF AMERICA, N.A., AS ADMINISTRATIVE AGENT

A DOCUMENT RECORDED FEBRUARY 9, 2005 AS RECORDING NO. 3943964, OF OFFICIAL RECORDS PROVIDES THAT THE DEED OF TRUST/MORTGAGE OR THE OBLIGATION SECURED THEREBY HAS BEEN MODIFIED. (AFFECTS PARCEL II)

NOT A SURVEYABLE EXCEPTION

LEGAL DESCRIPTION:

FIRST AMERICAN TITLE INSURANCE COMPANY FILE NO.: NCS-1115762-WA1, EFFECTIVE DATE FEBRUARY 24,

THE LAND REFERRED TO HEREIN BELOW IS SITUATED IN THE COUNTY OF CLARK, STATE OF WASHINGTON, AND IS DESCRIBED AS FOLLOWS:

PARCEL I:

LOTS 7 AND 8, BLOCK 53, CITY OF VANCOUVER (AKA EAST VANCOUVER), ACCORDING TO THE PLAT THEREOF RECORDED IN VOLUME 'C' OF PLATS, PAGE 70, RECORDS OF CLARK COUNTY, WASHINGTON.

LOTS 7 AND 8, BLOCK 54, CITY OF VANCOUVER (AKA EAST VANCOUVER), ACCORDING TO THE PLAT THEREOF -RECORDED IN VOLUME 'C' OF PLATS, PAGE 70, RECORDS OF CLARK COUNTY, WASHINGTON.

TABLE A NOTES:

- 2) PROPERTY HAS NO SITE ADDRESS.
- 3) THE SUBJECT PROPERTY LIES WITHIN ZONE X, AREA OF MINIMAL FLOOD HAZARD, PER FEMA FLOOD INSURANCE MAP NUMBER 53011C0368D, EFFECTIVE DATE SEPTEMBER 5, 2012.
- 4) PARCEL 1: 10,023± SQ FT
- 7a) NO BUILDING EXISTS ON PROPERTY.

7b1) NO BUILDING EXISTS ON PROPERTY.

8) ALL SUBSTANTIAL FEATURES HAVE BEEN LOCATED IN THE PROCESS OF CONDUCTING THE FIELDWORK.

- 9) 7 REGULAR PARKING 2 HANDICAP PARKING
- 10 FUNERAL PROCESSION LINES 19 TOTAL PARKING

SURVEYOR'S CERTIFICATE


AND FIRST AMERICAN TITLE INSURANCE COMPANY.

OF TABLE A THEREOF. THE FIELDWORK WAS COMPLETED ON 3/23/2022.

PAHLISCH VENTURES, LLC

CAPITAL TITLE

11) THE LOCATION OF EXISTING UNDERGROUND UTILITY FACILITIES SHOWN HEREON ARE BASED ON LOCATE MARKS REQUESTED FOR THIS SURVEY PER ONE CALL PUBLIC LOCATE TICKET 22088330. THE SURVEYOR ASSUMES NO RESPONSIBILITY FOR THE ACCURACY OF THE DELINEATION OF SUCH UNDERGROUND UTILITIES BY THE RESPECTIVE UTILITY OWNERS, NOR FOR THE EXISTENCE OF BURIED OBJECTS WHICH ARE NOT SHOWN ON THE PLAN. ALL UTILITY LOCATIONS SHOULD BE FIELD VERIFIED PRIOR TO CONSTRUCTION.



PROPERTY B

VICINITY MAP (NOT TO SCALE)

TITLE REPORT SPECIAL EXCEPTIONS:

THE FOLLOWING EXCEPTIONS AFFECT THE SUBJECT PROPERTY IN A SURVEYABLE MANNER AS PER FIRST AMERICAN TITLE INSURANCE COMPANY FILE NO.: CS-1119692-WA1, EFFECTIVE DATE MARCH 18, 2022.

- EASEMENT, INCLUDING TERMS AND PROVISIONS CONTAINED THEREIN: RECORDING DATE: DECEMBER 5, 1908 RECORDING INFORMATION: BOOK 72, PAGE 364, AS RECORDING NO. 31118
 - IN FAVOR OF: ADJACENT PROPERTY OWNERS FOR: PRIVATE ALLEY
- AFFECTS: PARCEL I THE SOUTH 6 FEET OF LOT 2
- \EASEMENT, INCLUDING TERMS AND PROVISIONS CONTAINED THEREIN:
- RECORDING DATE: FEBRUARY 8, 1909
- RECORDING INFORMATION: BOOK 75, PAGE 118, AS RECORDING NO. 32082 IN FAVOR OF: ADJACENT PROPERTY OWNERS
- FOR: PRIVATE ALLEY AFFECTS: PARCEL I - THE SOUTH 6 FEET OF LOT 1
- 7. AN AGREEMENT RELATIVE TO THE JOINT USE AND MAINTENANCE OF A SEWER AS DISCLOSED IN DEED RECORDED MAY 5, 1916 IN BOOK 116, PAGE 375 AS RECORDING NO. A 6628. AFFECTS PARCEL I - LOT 2: LOCATION NOT SPECIFIED
- 8. TERMS AND PROVISIONS OF AN UNRECORDED LEASE DATED NOVEMBER 1, 2010, BY AND BETWEEN JBA PROPERTIES, LLC, A WASHINGTON LIMITED LIABILITY COMPANY AS LESSOR AND JOHNSON BIXBY & ASSOCIATES, LLC, A WASHINGTON LIMITED LIABILITY COMPANY AS LESSEE, AS DISCLOSED BY A MEMORANDUM OF LEASE RECORDED DECEMBER 3, 2010 AS RECORDING NO. 4722918 OF OFFICIAL RECORDS.

(AFFECTS PARCEL III)

9. A DEED OF TRUST TO SECURE AN ORIGINAL INDEBTEDNESS OF \$800,000.00 RECORDED SEPTEMBER 14, 2016 AS RECORDING NO. 5325337 OF OFFICIAL RECORDS. DATED: SEPTEMBER 12, 2016 TRUSTOR: JBA PROPERTIES LLC, A WASHINGTON LIMITED LIABILITY COMPANY TRUSTEE: WELLS FARGO FINANCIAL NATIONAL BANK BENEFICIARY: WELLS FARO BANK, NATIONAL ASSOCIATION

LEGAL DESCRIPTION:

(AFFECTS PARCEL III)

IRST AMERICAN TITLE INSURANCE COMPANY FILE NO.: NCS-1119692-WA1, EFFECTIVE DATE MARCH 18, 2022. REAL PROPERTY IN THE COUNTY OF CLARK, STATE OF WASHINGTON, DESCRIBED AS FOLLOWS:

PARCEL I: LOTS 1 AND 2, BLOCK 53, EAST VANCOUVER ACCORDING TO THE PLAT THEREOF RECORDED IN VOLUME 'C' OF PLATS, PAGE 70, IN CLARK COUNTY, WASHINGTON.

PARCEL II: LOTS 3, 4, 5 AND 6, BLOCK 53, EAST VANCOUVER ACCORDING TO THE PLAT THEREOF RECORDED IN VOLUME 'C' OF PLATS, PAGE 70, IN CLARK COUNTY, WASHINGTON.

PARCEL III: LOTS 5 AND 6, BLOCK 54, EAST VANCOUVER ACCORDING TO THE PLAT THEREOF RECORDED IN VOLUME 'C' OF PLATS, PAGE 70, IN CLARK COUNTY, WASHINGTON.

TABLE A NOTES:

2) ADDRESS IS: PARCEL I: N/A
PARCEL II: 1205 BROADWAY ST, VANCOUVER, WA 98663

- 3) THE SUBJECT PROPERTY LIES WITHIN ZONE X, AREA OF MINIMAL FLOOD HAZARD, PER FEMA FLOOD INSURANCE MAP NUMBER 53011C0368D, EFFECTIVE DATE SEPTEMBER 5, 2012.
- 4) TOTAL LAND AREA: PARCEL I: 10,217± SQ FT PARCEL II: 20,417± SQ FT
- 7a) BUILDING DIMENSIONS AS SHOWN HEREON.
- 7b1) AREA OF BUILDING: PARCEL I: N/A PARCEL II: 7,882 SQ FT
- 8) ALL SUBSTANTIAL FEATURES HAVE BEEN LOCATED IN THE PROCESS OF CONDUCTING THE FIELDWORK.
- 21 REGULAR PARKING O HANDICAP PARKING 21 TOTAL PARKING
- PARCEL II: 14 REGULAR PARKING 2 HANDICAP PARKING 16 TOTAL PARKING
- 11) THE LOCATION OF EXISTING UNDERGROUND UTILITY FACILITIES SHOWN HEREON ARE BASED ON LOCATE MARKS REQUESTED FOR THIS SURVEY PER ONE CALL PUBLIC LOCATE TICKET 22088330. THE SURVEYOR ASSUMES NO RESPONSIBILITY FOR THE ACCURACY OF THE DELINEATION OF SUCH UNDERGROUND UTILITIES BY THE RESPECTIVE UTILITY OWNERS, NOR FOR THE EXISTENCE OF BURIED OBJECTS WHICH ARE NOT SHOWN ON THE PLAN. ALL UTILITY LOCATIONS SHOULD BE FIELD VERIFIED PRIOR TO CONSTRUCTION.

SURVEYOR'S SIGNATURE ANDREW PLETT, WA PLS 50707 ANDREW.PLETT@SFLANDS.COM

DATE OF PLAT OR MAP:

07-29-2022

PORTLAND, VANCOUVER, BEND, SEASIDE 400 E EVERGREEN BLVD, STE 1, VANCOUVER, WA 98660

(360) 326-2334

PAHLISCH COMMERCIAL LOCATED IN


LOTS 1-8, BLOCK 53, EAST VANCOUVER

NE1/4, SECTION 27, T2N, R1E, WM VANCOUVER, CLARK COUNTY, WA

ALTA SURVEY FOR



L: INFO@SFLANDS.COM



2249501 ALTA Block 53.dwa JULY 29, 2022

THIS IS TO CERTIFY THAT THIS MAP OR PLAT AND THE SURVEY ON WHICH IT IS BASED WERE MADE IN

ACCORDANCE WITH THE 2021 MINIMUM STANDARD DETAIL REQUIREMENTS FOR ALTA/NSPS LAND TITLE SURVEYS,

JOINTLY ESTABLISHED AND ADOPTED BY ALTA AND NSPS, AND INCLUDES ITEMS 2, 3, 4, 7a, 7b, 8, 9, and 11a

2022-495-01

CHECKED

