



11815 NE 99th Street, Suite 1294  
Vancouver, WA 98662  
Voice: 360-574-3058  
Fax: 360-576-0925  
Web: <https://www.swcleanair.gov>  
Email: [Tina@swcleanair.gov](mailto:Tina@swcleanair.gov)

## Notice of Intent to Remove Asbestos

Case #: 24-477

Amendment: 0

Date Received: 7/10/2024

Date Paid: 7/10/2024

SWCAA Fee: \$0.00

Receipt #:

**This notification MUST be present at all times at the asbestos project sit**

### \*\*\* EMERGENCY NOTICE \*\*\*

Quantity to be removed: 44 Square Feet 0 Linear Feet

Workshift days: Th

Project starting date: 7/11/2024 Project Completion date: 7/11/2024

Workshift hours: 8:00AM - 4:30PM

Site Name: Nancy Odegar

Site address: 8006 NE 124th Ave

Location of Asbestos: Bedroom

City/State/Zip: Vancouver

WA

98682

☐ Demolition of Structure (Notification of Demolition required)

County: CLARK COUNTY

☒ Asbestos survey conducted?

No survey reason:

AHERA Inspector: Unknown. Bulk Sampling Provided b

Certification #: Non Listed.

#### Material to be Removed:

☐ Fireproofing

☐ Popcorn Ceiling

☐ CAB

☐ Sheet Vinyl

☐ Boiler Insulation

☐ Duct Tape

☐ Duct Paper

☐ Mag Pipe Insulation

☐ Air Cell

☐ CA Pipe

☐ VAT

☒ Other Drywall

#### Control Methods:

☒ N.P Enclosure

☐ Glove Bag

☐ Mini Enclosure

☐ Wrap and Cut

☒ Water

☐ HEPA Vac

☒ Other Manual Methods

Asbestos Contractor: Keystone Contracting, Inc.

Phone: 360-887-0868

Mailing Address: 417 NW 209th St, Ridgefield, WA, 98642

Email: [keystone417@tds.net](mailto:keystone417@tds.net)

Certification ##: ABCN00001024

Supervisor: Martin Ortiz

Phone: 360-353-6423

Property Owner: Nancy Odegard

Phone: 360-546-3259

Mailing Address: 8006 NE 124th Ave, Vancouver WA 98682

Asbestos Disposal Site: Wasco County Landfill: 2550 Steele Rd, The Dalles, OR, 97058-

**I DO HEREBY CERTIFY THAT THE INFORMATION CONTAINED IN THIS NOTIFICATION IS,  
TO THE BEST OF MY KNOWLEDGE, ACCURATE AND COMPLETE.**

Submitter Name: Kamala Lopez

Representing: Keystone Contracting, Inc

Submitter Title: Office Manager

Date Submitted: 7/10/2024

Reviewed by SWCAA: Brian Fallon

☒ Approved



11815 NE 99th Street, Suite 1294  
Vancouver, WA 98662  
Voice: 360-574-3058  
Fax: 360-576-0925  
Web: <https://www.swcleanair.gov>  
Email: [Tina@swcleanair.gov](mailto:Tina@swcleanair.gov)

## Notice of Intent to Remove Asbestos

Case #: 24-477

Amendment: 0

Date Received: 7/10/2024

Date Paid: 7/10/2024

SWCAA Fee: \$0.00

Receipt #:

**This notification MUST be present at all times at the asbestos project sit**



9317 NE Hwy 99, Suite D, Vancouver, WA 98665 | 360-356-7628

**Polarized Light Microscopy Results**

**Lab No** 145303  
**Layers Analyzed** 2  
**Date Received** 7/10/2024  
**Received By** Talia Carroll  
**Date Analyzed** 7/10/2024  
**Analyzed By** Nathan Blondino

**Property Address** 8006 NE 124th Ave  
**City, State, Zip** Vancouver, WA  
**Job Number** Odegard  
**Client Name** Country Restoration  
**Client Address**  
**City, State, Zip**  
**Phone & E-mail** (360) 546-3259

AEI Sample ID	Client Sample ID	Composition	Color/ Description	Asbestos (%)	Non-Asbestos Fiber (%)	Non Fibrous
001	1	Layered	White Texture	2% Chrysotile	N/A	(Light Green) Paint- CaCO3-Mica
001A		Layered	White Drywall	Asbestos Not Present	15% Cellulose	Gypsum

## Disclaimer

- EPA Method 600/M4-82-020 (1982) was used to determine the presence or absence of asbestos fibers in all materials referenced in the above report. PLM analysis is based on visual estimation, and due to limitations of PLM analysis NESHAP regulations recommend that any material determined to contain less than 10% asbestos by the above referenced method should either be assumed to contain greater than 1% asbestos by the owner/operator, or be verified by PLM Point Count or TEM analysis as containing less than 1% asbestos.
- We recommend that TEM analysis be conducted for confirmation of negative PLM analytical results of vinyl floor tiles and vermiculite. These materials may contain asbestos fibers that cannot be detected by PLM analysis due to their size (<0.25 microns in diameter)
- This report may not be used to represent any materials not analyzed and listed in the included report. Advantage Environmental Inc. cannot be held responsible for the interpretation of the results shown. This report may not be reproduced in part and may only be reproduced in full without prior written consent from Advantage Environmental Inc.





**ADVANTAGE**  
Environmental INC.

**ASBESTOS CHAIN OF CUSTODY**  
9317 NE Hwy 99, Suite D • (360) 356-7628  
**LEGAL DOCUMENT - PLEASE PRINT LEGIBLY**

Lab Use Only	
Survey <input type="checkbox"/>	Lab No. <b>145303</b>
Walk-In <input checked="" type="checkbox"/>	<b>Accept</b> <del>Reject</del>

Sampled By - Please fill out yellow highlighted areas		Project Information - Please fill out yellow highlighted areas	
Date:	<b>7/10/2024</b>	Project Name:	<b>Odegard</b>
Company Name OR Name:	<b>Country Restoration</b>	Address (where material was pulled from):	<b>8006 NE 124th Ave.</b>
Phone:	<b>(360) 546-3259</b>	City, State, Zip:	<b>Vancouver, WA, 98682</b>
Email:	<b>Jacob@countryrestoration.com</b>	P.O. #:	

RELINQUISHED BY		DATE & TIME	VIA	RECEIVED BY	DATE & TIME
Name	<b>Jacob Kemp</b>	Date <b>7/10/24</b>	Drop Box/Drop Off		<b>7-10-24</b>
Sign		Time <b>10:56am</b>			<b>11:06</b>

**REQUESTED SERVICES**

PLM	TURNAROUND TIME - Please choose a turnaround time
Bulk Analysis	<input type="checkbox"/> Verbal <input checked="" type="checkbox"/> Rush <input type="checkbox"/> Same Day <input type="checkbox"/> 24-Hour <input type="checkbox"/> 3-Days

No.	Sample ID	Color	Description	Volume / Area (as applicable)	Comments / Notes
1	Drywall	Green	Drywall		
2					
3					
4					
5					
6					
7					
8					
9					
10					
11					