

## **Notice of Intent to Remove Asbestos**

Case #: 24-524

7/29/2024

160071162

11815 NE 99th Street, Suite 1294 Vancouver, WA 98662

Voice: 360-574-3058 Fax: 360-576-0925

Web: https://www.swcleanair.gov Email: Tina@swcleanair.gov

**Submitter Name:** Kamala Lopez

Reviewed by SWCAA: Mihai Voivod

Office Manager

**Submitter Title:** 

Date Received: 7/29/2024

Date Paid:

Receipt #:

**Representing:** Keystone Contracting, Inc

Approved

Date Submitted: 7/29/2024

Amendment: 0

77237202

SWCAA Fee: \$369.00

φοσοιο.

## This notification MUST be present at all times at the asbestos project sit

Quantity to be removed: 175 Square Feet 0 Linear Fe	et	Workshift days:	W
Project starting date: 8/14/2024 Project Completion date: 8/	14/2024	Workshift hours:	8:00AM - 4:30PM
Site Name: Michelle Staples Site a	ıddress: 106 Le	ster Rd	
ocation of Asbestos: Utility room, bathroom City/Sta	ate/Zip: Morto	n	WA 98356
Demolition of Structure (Notification of Demolition required)	Соц	unty: LEWIS COUNT	(
✓ Asbestos survey conducted? No survey reason:			
AHERA Inspector: Unknown. Bulk Sampling Provided b	С	ertification #: Non L	isted.
		Boiler Insulation	☐ Duct Tape
☐ Duct Paper ☐ Mag Pipe Insulation ☐ Air C	Cell	CA Pipe	✓ VAT
✓ Other Mastic			
Control Methods: ☑ N.P Enclosure □ Glove Bag □ Mini Enclosure □ Wra	p and Cut 🗹	Water	☐ HEPA Vac
✓ Other Manual Methods			
sbestos Contractor: Keystone Contracting, Inc.	Pho	ne: 360-887-0868	
Mailing Address: 417 NW 209th St, Ridgefield, WA, 98642	Em	iail: keystone417@t	ds.net
Certification ##: ABCN00001024			
Supervisor: Martin Ortiz	Phone: 3	60-353-6423	
roperty Owner: Michelle Staples	Phone: 2	53-820-9202	
Mailing Address: 106 Lester Rd, Morton WA 98356			
sbestos Disposal Site: Wasco County Landfill: 2550 Steele Rd, The D	alles, OR. 9705	8-	

## ❖ CERTIFIED ENVIRONMENTAL CONSULTING, LLC ❖

## **BULK SAMPLE ANALYSIS REPORT**

CLIENT:

SERVPRO OF LONGVIEW/KELSO

SOURCE:

MICHELLE STAPLES,

106 LESTER ROAD,

MR. RYAN GRADY

**SAMPLED BY:** 

MORTON, WASHINGTON CLIENT

1425 ALABAMA STREET SUITE #G

LAB#

JJ-906

LONGVIEW, WASHINGTON 98632

ANALYZED BY:

KYLER SPEARS

DATE SAMPLED:

07-23-24

DATE RECEIVED:

07-24-24

DATE COMPLETED:

07-24-24

ANALYTICAL METHOD: EPA 600/R-93/116, 40 CFR Part 763, Subpart E, Appendix E, Section #1, PLM/Dispersion Staining

SAMPLE ID #	SAMPLE DESCRIPTION	SAMPLE LOCATION	ASBESTOS CONTENT % TYPE	OTHER MATERIAL
1	BLUE SPOTS/GOLD SPECKS/CREAM ROCK PATTERN FLOOR TILE AND BLACK MASTIC	SECOND BATHROOM	NONE DETECTED	5% CELLULOSE, CALCIUM CARBONATE, BINDER, TAR
2A	GRAY SQUARES/WHITE BACKGROUND SHEET VINYL	UTILITY	NONE DETECTED	2% CELLULOSE, VINYL, CALCITE, ADHESIVE
2B	BROWN BACK GROUND/TAN WITH BROWN SPECKS FLOOR TILE AND MASTIC	UTILITY	FLOOR TILE: 3% CHRYSOTILE MASTIC: 5% CHRYSOTILE	CALCIUM CARBONATE, BINDER, TAR
3	WHITE GYPSUM WALLBOARD WITH WHITE JOINT COMPOUND	UTILITY	NONE DETECTED	12% CELLULOSE, 5% FIBERGLASS, CALCIUM CARBONATE, CALCIUM SULFATE, BINDER
4	WHITE GYPSUM WALLBOARD WITH WHITE JOINT COMPOUND	UTILITY	NONE DETECTED	12% CELLULOSE, 5% FIBERGLASS, CALCIUM CARBONATE, CALCIUM SULFATE, BINDER
5	WHITE GYPSUM WALLBOARD WITH WHITE JOINT COMPOUND	UTILITY	NONE DETECTED	12% CELLULOSE, 5% FIBERGLASS, CALCIUM CARBONATE, CALCIUM SULFATE, BINDER

ANALYST:

DEVIATION FROM METHOD: NONE. PERCENTAGES ARE ESTIMATES.

TEST RESULTS PERTAIN ONLY TO ITEMS TESTED.

\* DETECTION LIMIT IS LESS THAN 1% ASBESTOS.

NON-ASBESTOS MATERIALS ARE NOT NECESSARILY LISTED.

REVIEWED BY-

♦ CERTIFIED ENVIRONMENTAL CONSULTING, LLC. ◆

(503) 221-7904 PHONE (360) 254-9385 FAX-(360) 891-9633						
LAB#_	53-906 CLIENT: Sorvero of Longuisia	Kelso CONTACT: Rydn Grady SAMPLE DATE: 7-23-21				
BILLING ADDRESS: 1425 PHODOMS Street South M CITY/STATE: LODONION WA ZIP CODE: 98632						
PHONE: 360-703-3884 BMAIL: Servoro, berry@gmail.com ANALYSIS REQUESTED:						
SAMPLED BY: LINCO HOPEOIECT NAME AND ADDRESS: MICHOLO Staples We Lester CITY/STATE: MONTH WA 9835/ NORMAL [] (END OF 3 PD BUSINESS DAY) RUSH (END OF NEXT BUSINESS DAY)						
SAMPLE #	DESCRIPTION OF MATERIAL  (I.E. SHEET VINYL , FLOOR TILE, CEILING TEXTURE WITH  COLOR)	SAMPLE LOCATION (WHICH ROOM OR AREA THE SAMPLE WAS COLLECTED)				
1	Blue spots, gold spects, cream Rock	and Bathroom.				
ZBB	grey square white Back ground sheet Kingl Brown Back ground Tan with Brown Specks T	be & mastic Wility				
3	white Drywall white campound	Let Thirty				
4	while Drywall ( white compand	utility				
5	white Drywall whole compand	Utility				
	(					
·						
SENT TO: CTC RELINQUISHED, BY (PRINT): LINGO HOBSON RELINQUISHED BY (SIGNATURE)						
RECEIVED BY MILE AND DATE RECEIVED: 7-24-24						
PAGEOF						