



11815 NE 99th Street, Suite 1294
Vancouver, WA 98662
Voice: 360-574-3058
Fax: 360-576-0925
Web: <https://www.swcleanair.gov>
Email: Tina@swcleanair.gov

Notice of Intent to Remove Asbestos

Case #: 24-659

Amendment: 0

Date Received: 9/24/2024

Date Paid: 9/24/2024

SWCAA Fee: \$147.00

Receipt #: 163167095

This notification MUST be present at all times at the asbestos project sit

Quantity to be removed: 125 Square Feet 0 Linear Feet

Workshift days: F

Project starting date: 10/4/2024 Project Completion date: 10/4/2024

Workshift hours: 8:00AM - 4:30PM

Site Name: Bryan Shull

Site address: 4209 NW Lavina St

Location of Asbestos: garage, ceiling, floor

City/State/Zip: Vancouver WA 98660

☐ Demolition of Structure (Notification of Demolition required)

County: CLARK COUNTY

☒ Asbestos survey conducted?

No survey reason:

AHERA Inspector: Unknown. Bulk Sampling Provided b

Certification #: Non Listed.

Material to be Removed:

- | | | | | | |
|--|--|-----------------------------------|--------------------------------------|--|------------------------------------|
| <input type="checkbox"/> Fireproofing | <input type="checkbox"/> Popcorn Ceiling | <input type="checkbox"/> CAB | <input type="checkbox"/> Sheet Vinyl | <input type="checkbox"/> Boiler Insulation | <input type="checkbox"/> Duct Tape |
| <input type="checkbox"/> Duct Paper | <input type="checkbox"/> Mag Pipe Insulation | <input type="checkbox"/> Air Cell | <input type="checkbox"/> CA Pipe | <input checked="" type="checkbox"/> VAT | |
| <input checked="" type="checkbox"/> Other Mastic | | | | | |

Control Methods:

- | | | | | | |
|--|------------------------------------|---|---------------------------------------|---|-----------------------------------|
| <input checked="" type="checkbox"/> N.P Enclosure | <input type="checkbox"/> Glove Bag | <input type="checkbox"/> Mini Enclosure | <input type="checkbox"/> Wrap and Cut | <input checked="" type="checkbox"/> Water | <input type="checkbox"/> HEPA Vac |
| <input checked="" type="checkbox"/> Other Manual Methods | | | | | |

Asbestos Contractor: Keystone Contracting, Inc.

Phone: 360-887-0868

Mailing Address: 417 NW 209th St, Ridgefield, WA, 98642

Email: keystone417@tds.net

Certification ##: ABCN00001024

Supervisor: Juan Villegas

Phone: 503-855-8353

Property Owner: Bryan Shull

Phone: 503-758-2569

Mailing Address: 4209 NW Lavina St, Vancouver WA 99660

Asbestos Disposal Site: Wasco County Landfill: 2550 Steele Rd, The Dalles, OR, 97058-

**I DO HEREBY CERTIFY THAT THE INFORMATION CONTAINED IN THIS NOTIFICATION IS,
TO THE BEST OF MY KNOWLEDGE, ACCURATE AND COMPLETE.**

Submitter Name: Kamala Lopez

Representing: Keystone Contracting, Inc

Submitter Title: Asbestos Notice Payment Conf

Date Submitted: 9/24/2024

Reviewed by SWCAA: Brian Fallon

☒ Approved



11815 NE 99th Street, Suite 1294
Vancouver, WA 98662
Voice: 360-574-3058
Fax: 360-576-0925
Web: <https://www.swcleanair.gov>
Email: Tina@swcleanair.gov

Notice of Intent to Remove Asbestos

Case #: 24-659

Amendment: 0

Date Received: 9/24/2024

Date Paid: 9/24/2024

SWCAA Fee: \$147.00

Receipt #: 163167095

This notification MUST be present at all times at the asbestos project sit


 9317 NE Hwy 99, Suite D, Vancouver, WA 98665 | 360-356-7628
Polarized Light Microscopy Results

Lab No 146248
Layers Analyzed 4
Date Received 9/11/2024
Received By Talia Carroll
Date Analyzed 9/11/2024
Analyzed By Jonathan Gomes

Property Address 4209 NW Lavina St
City, State, Zip Vancouver, WA, 98660
Job Number Shull, Bryan (24-495)
Client Name Prestige NW Restoration
Client Address 2614 Carlson Rd
City, State, Zip Vancouver, WA 98661
Phone & E-mail (360)433-2919

AEI Sample ID	Client Sample ID	Composition	Color/Description	Asbestos (%)	Non-Asbestos Fiber (%)	Non Fibrous
001	1	Layered	Light Orange Floor Tile	3% Chrysotile	<1% Cellulose	CaCO3-Vinyl
001A		Layered	Black Flooring Mastic	5% Chrysotile	N/A	CaCO3-Tar
002	2	Layered	Light Orange Floor Tile	3% Chrysotile	<1% Cellulose	CaCO3-Vinyl
002A		Layered	Black Flooring Mastic	5% Chrysotile	N/A	CaCO3-Tar

Disclaimer

- EPA Method 600/M4-82-020 (1982) was used to determine the presence or absence of asbestos fibers in all materials referenced in the above report. PLM analysis is based on visual estimation, and due to limitations of PLM analysis NESHAP regulations recommend that any material determined to contain less than 10% asbestos by the above referenced method should either be assumed to contain greater than 1% asbestos by the owner/operator, or be verified by PLM Point Count or TEM analysis as containing less than 1% asbestos.
- We recommend that TEM analysis be conducted for confirmation of negative PLM analytical results of vinyl floor tiles and vermiculite. These materials may contain asbestos fibers that cannot be detected by PLM analysis due to their size (<0.25 microns in diameter)
- This report may not be used to represent any materials not analyzed and listed in the included report. Advantage Environmental Inc. cannot be held responsible for the interpretation of the results shown. This report may not be reproduced in part and may only be reproduced in full without prior written consent from Advantage Environmental Inc.



ADVANTAGE
Environmental INC.

ASBESTOS CHAIN OF CUSTODY
9317 NE Hwy 99, Suite D • (360) 356-7628
LEGAL DOCUMENT - PLEASE PRINT LEGIBLY

Lab Use Only	
Survey <input type="checkbox"/>	Lab No. 146248
Walk-In <input checked="" type="checkbox"/>	Accept Reject

Sampled By - Please fill out yellow highlighted areas				Project Information - Please fill out yellow highlighted areas		
Date: 9/11/24		Project Name: Shull, Bryan (24-495)				
Company Name OR Name: Prestige NW (Keigan)		Address (where material was pulled from): 4209 NW Lavinia St.				
Phone: (360) 437-9237		City, State, Zip: Vancouver, WA 98660				
Email: keigan@prestige-nw.com		P.O. #:				
RELINQUISHED BY		DATE & TIME	VIA	RECEIVED BY		DATE & TIME
Name Troy J.		Date 9/11/24	Drop Box/Drop Off			9-11-24
Sign		Time 1:16pm				1:31
REQUESTED SERVICES						
PLM			TURNAROUND TIME - Please choose a turnaround time			
Bulk Analysis			<input checked="" type="checkbox"/> Verbal <input type="checkbox"/> Rush <input type="checkbox"/> Same Day <input type="checkbox"/> 24-Hour <input type="checkbox"/> 3-Days			
No.	Sample ID	Color	Description	Volume / Area (as applicable)	Comments / Notes	
1	001	Tan	FLIR Tile / Black mastic	Basement		
2	002	Tan	"	Basement		
3						
4						
5						
6						
7						
8						
9						
10						
11						