



11815 NE 99th Street, Suite 1294
Vancouver, WA 98662
Voice: 360-574-3058
Fax: 360-576-0925
Web: <https://www.swcleanair.gov>
Email: Tina@swcleanair.gov

Notice of Intent to Remove Asbestos

Case #: 24-668

Amendment: 0

Date Received: 9/27/2024

Date Paid: 9/27/2024

SWCAA Fee: \$294.00

Receipt #: 163322269

This notification MUST be present at all times at the asbestos project sit

*** EMERGENCY NOTICE ***

Quantity to be removed: 150 Square Feet 0 Linear Feet

Workshift days: Sa

Project starting date: 9/28/2024 Project Completion date: 9/28/2024

Workshift hours: 7:00 AM -2:00pm

Site Name: 8317 Fruit Valley

Site address: 8317 NW Fruit Valley RD

Location of Asbestos: basement chimney room

City/State/Zip: Vancouver WA 98665

☐ Demolition of Structure (Notification of Demolition required)

County: CLARK COUNTY

☒ Asbestos survey conducted?

No survey reason:

AHERA Inspector: Daniel A Gonzalez

Certification #: 185366

Material to be Removed:

☐ Fireproofing ☐ Popcorn Ceiling ☐ CAB ☐ Sheet Vinyl ☐ Boiler Insulation ☐ Duct Tape

☐ Duct Paper ☐ Mag Pipe Insulation

☐ Air Cell

☐ CA Pipe

☐ VAT

☒ Other vinyl tile and mastic

Control Methods:

☒ N.P Enclosure

☐ Glove Bag

☐ Mini Enclosure

☐ Wrap and Cut

☒ Water

☒ HEPA Vac

☒ Other manual methods

Asbestos Contractor: Eco Emergency Response, LLC

Phone: 503-753-1295

Mailing Address: 329 Fredrickson Rd, Woodland, WA, 98674

Email: eco.e.response@gmail.com

Certification ##: ABCN00001728

Supervisor: Baudelio Gonzalez

Phone: 503-830-4370

Property Owner: Angela kemple

Phone: 360-213-4812

Mailing Address: 8317 NW Fruit Valley RD,Vancouver WA 98665

Asbestos Disposal Site: Hillsboro Landfill: 3205 SE Minter Bridge Rd, Hillsboro, OR, 97123-

I DO HEREBY CERTIFY THAT THE INFORMATION CONTAINED IN THIS NOTIFICATION IS,
TO THE BEST OF MY KNOWLEDGE, ACCURATE AND COMPLETE.

Submitter Name: Daniel A Gonzalez

Representing: Eco Emergency Response, LLC

Submitter Title: Project Manager

Date Submitted: 9/27/2024

Reviewed by SWCAA: Danielle Kreps

Danielle Kreps

☒ Approved



11815 NE 99th Street, Suite 1294
Vancouver, WA 98662
Voice: 360-574-3058
Fax: 360-576-0925
Web: <https://www.swcleanair.gov>
Email: Tina@swcleanair.gov

Notice of Intent to Remove Asbestos

Case #: 24-668

Amendment: 0

Date Received: 9/27/2024

Date Paid: 9/27/2024

SWCAA Fee: \$294.00

Receipt #: 163322269

This notification MUST be present at all times at the asbestos project sit



9317 NE Hwy 99, Suite D, Vancouver, WA 98665 | 360-356-7628

Polarized Light Microscopy Results

Lab No 146446
Layers Analyzed 2
Date Received 9/24/2024
Received By Talia Carroll
Date Analyzed 9/24/2024
Analyzed By Nathan Blondino

Property Address 8317 NW Fruit Valley Rd
City, State, Zip Vancouver, WA
Job Number Fruit Valley - 8317
Client Name Eco Emergency Response, LLC
Client Address
City, State, Zip
Phone & E-mail (503) 753-1295

AEI Sample ID	Client Sample ID	Composition	Color/ Description	Asbestos (%)	Non-Asbestos Fiber (%)	Non Fibrous
001	1	Layered	Brown Floor Tile	3% Chrysotile	N/A	CaCO3-Vinyl
001A		Layered	Black Flooring Mastic	6% Chrysotile	N/A	Tar

Disclaimer

- EPA Method 600/M4-82-020 (1982) was used to determine the presence or absence of asbestos fibers in all materials referenced in the above report. PLM analysis is based on visual estimation, and due to limitations of PLM analysis NESHAP regulations recommend that any material determined to contain less than 10% asbestos by the above referenced method should either be assumed to contain greater than 1% asbestos by the owner/operator, or be verified by PLM Point Count or TEM analysis as containing less than 1% asbestos.
- We recommend that TEM analysis be conducted for confirmation of negative PLM analytical results of vinyl floor tiles and vermiculite. These materials may contain asbestos fibers that cannot be detected by PLM analysis due to their size (<0.25 microns in diameter)
- This report may not be used to represent any materials not analyzed and listed in the included report. Advantage Environmental Inc. cannot be held responsible for the interpretation of the results shown. This report may not be reproduced in part and may only be reproduced in full without prior written consent from Advantage Environmental Inc.



ADVANTAGE
Environmental INC.

ASBESTOS CHAIN OF CUSTODY
9317 NE Hwy 99, Suite D • (360) 356-7628
LEGAL DOCUMENT - PLEASE PRINT LEGIBLY

Lab Use Only	
Survey <input type="checkbox"/>	Lab No. <u>146446</u>
Walk-In <input checked="" type="checkbox"/>	<u>Accept</u> Reject

Sampled By - Please fill out yellow highlighted areas		Project Information - Please fill out yellow highlighted areas	
Date:	<u>9/24/2024</u>	Project Name:	<u>Fruit Valley - 8317</u>
Company Name OR Name:	<u>Eco Emergency Response, LLC</u>	Address (where material was pulled from):	<u>8317 NW Fruit Valley Rd.</u>
Phone:	<u>503-753-1285</u>	City, State, Zip:	<u>Vancouver, WA 98665</u>
Email:	<u>eco.e.response@qencil.com</u>	P.O. #:	

RELINQUISHED BY		DATE & TIME	VIA	RECEIVED BY	DATE & TIME
Name	<u>Daniel A</u>	Date	<u>9/24/24</u>	Drop Box/Drop Off	<u>9-24-24</u>
Sign	<u>[Signature]</u>	Time	<u>3:05</u>		<u>3:17</u>

REQUESTED SERVICES

PLM	TURNAROUND TIME - Please choose a turnaround time
Bulk Analysis	<input type="checkbox"/> Verbal <input checked="" type="checkbox"/> Rush <input type="checkbox"/> Same Day <input type="checkbox"/> 24-Hour <input type="checkbox"/> 3-Days

No.	Sample ID	Color	Description	Volume / Area (as applicable)	Comments / Notes
1		<u>Red/Brown</u>	<u>Floor tile w/mastic</u>		<u>found in chimney</u>
2					<u>Room, in basement</u>
3					
4					
5					
6					
7					
8					
9					
10					
11					