

Notification of Demolition

Case #: 24-850

11815 NE 99th Street, Suite 1294

Vancouver, WA 98662 Voice: 360-574-3058 Fax: 360-576-0925

Web: https://www.swcleanair.gov Email: Tina@swcleanair.gov Date Received: 12/13/2024

Date Paid: 12/13/2024

SWCAA Fee: \$148.00

Amendment: 0

10 day waiting period from date submitted

Receipt #: 167713134

Type of Notification: Original
Type of Operation: Demolition
Facility Description: Clark County

Commercial Name or Description: residential home

Address: 11712 NE 65th Ave.

City/State/Zip/County: Vancouver, WA 98686 CLARK COUNTY

Present Use: Vacant Previous Use: Residence

4. Facility Information Property Owner:

Property Owner: David & David & Imoesiri - LANLU Development LL

Phone: 360-921-7084

5. Name and AHERA Certification Number of Asbestos Inspector:

Name: Sidney Carter Certification #: ON-4644-9796-060821

6. Asbestos Removal Contractor (if applicable):

Name: Willamette Construction Services

Mailing Address: 8823 N Harborgate St, Portland, WA, 97203

Contact Bob Gordon Phone: Bob Gordon

7. Dates Asbestos Removal Occurred:

Start: 11/5/2024 Complete: 11/5/2024 Asbestos Case No.: 24-739-0

8. Dates Demolition Will Occur:

Start: 12/13/2024 Complete: 12/13/2024

9. Demolition Contractor:

Name: Scott Lee Excavation

Mailing Address: PO Box 2123, Battle Ground, WA, 98604

Phone: 360-687-5465

10. Asbestos Disposal Site: N/A

12. Fugitive Emssions/dust from Demolition Activites MUST	BE Controlled/Prevented during all phases of the project
per contractor recommendations	
L3. If unexpected Asbestos containing Material (ACM) is fou Consult/Hire a Certified Asbestos Abatement Contractor	nd during demolition, Stop Work, Notify SWCAA and
Already removed by licensed asbestos contractor.	
L4. If demolition is ordered by a Government Agent:	
L5. For Emergency Demolitions (Contact SWCAA prior to wo	rk): ✓ Emergency Demolition
Date and Time of Emergency: 12/13/2024 10:00:00 AM	
Description of Sudden, Unexpected Event:	
We have had ongoing issues with squatters. Sheriff has corecently had windows removed containing asbestos mater	ome to the property before in response to illegal trespassing. We rial, so the property is more vulnerable and vacant for
Explanation of how the event caused unsafe conditions of burden:	or would cause equipment damage or an unreasonable
· · · · · · · · · · · · · · · · · · ·	nge in getting them removed. Also neighbors have reported as) and the frequency of people coming and going
L6. I Certify that the above information is correct:	
Submitter Name: Tiffanie Imoesiri	Representing: LANLU Development LLC
Submitter Title: Managing member	Data Submitted: 12/12/2024

Submitter Title: Managing member **Date Submitted:** 12/13/2024

Email Address: propertiesbytiff@gmail.com

Reviewed by SWCAA: Brian Fallon

11. Description of planned demolition work, method(s) to be used:

Home and outbuilding shed will be demolished.

✓ Approved

The Washington State Dangerous Waste Regulations (WAC 173-303) require that demolition debris be evaluated to determine if it is dangerous. The evaluation should be completed before demolition to ensure that hazardous constituents are not released to the environment and do not present a risk to human health during or after demolition. These requirements apply to all buildings being demolished and are the responsibility of the property owner. The Washington Department of Ecology's website, https://ecology.was.gov/Regulations-Permits/Guidance-technical-assistance/Dangerous-waste-guidance/Common-dangerouswaste/Construction-and-demolition, provides more information about the requirements and about sampling and testing construction materials to detemine if they present a risk. For more information please contact a Hazardous Waste Inspector at the Washington Department of Ecology Southwest Regional Office: (360) 407-6300.