			Case #: 25-080
Southwest Clean Air Agency	Intent to Remove As	Destos Ameno	dment: 0
11815 NE 99th Street, Suite 1294 Vancouver, WA 98662		Date Receive	d: 1/28/2025
Voice: 360-574-3058 Fax: 360-576-0925		Date Pai	d: 1/28/2025
Web: https://www.swcleanair.gov Email: Tina@swcleanair.gov		SWCAA Fe	e: \$39.00
This notification MUST be present at all tir	nes at the asbestos project s	sit Receipt	#: 169996370
		OWNER OCCUP	IED PERFORMED
Quantity to be removed: 1000 Square Feet	0 Linear Feet	Workshift days:	
Project starting date: 2/3/2025 Project C	ompletion date: 2/28/2025	Workshift hours: 8	3-5
Site Name: Loff Carmody Posidonse	Site address: 2000		
Site Name: Jeff Carmody Residence	Site address: 2080		N/A 08606
Location of Asbestos: Flooring and ceiling	City/State/Zip: Brush		NA 98606
Demolition of Structure (Notification of Demolition required) County: CLARK COUNTY			
	s presumed?		
Asbestos survey conducted? No survey reason: Owner took samples to Atlas labs, test results attached			
AHERA Inspector: Occupant Owner		Certification #:	
Material to be Removed:			
Fireproofing Popcorn Ceiling CAB	Sheet Vinyl	Boiler Insulation	Duct Tape
Duct Paper Mag Pipe Insulation	Air Cell	CA Pipe	VAT
✓ Other Sheetrock/texture			
Control Methods:			
N.P Enclosure Glove Bag Mini En	nclosure 🗹 Wrap and Cut	Vater	✓ HEPA Vac
□ Other			
Asbestos Contractor: Owner Occupant	Ph	one:	
Mailing Address:	E	mail:	
Certification ##: Supervisor: Jeff Carmody	Phone	360-771-6564	
•			
Property Owner: Jeff Carmody Mailing Address: 20802 NE 122nd St,Brush Pro		360-771-6564	
			9662
Asbestos Disposal Site: Columbia Resource Comp	any - 117th Ave: 11034 NE 117th	Ave, vancouver, wA, 9	8002-
I DO HEREBY CERTIFY THAT THE TO THE BEST OF MY F	NFORMATION CONTAINED		ON IS,
Submitter Name: Jeff Carmody	Rep	esenting: Jeff Carmoo	ly
Submitter Title: Home Owner	Dates	Submitted: 1/28/2025	
Reviewed by SWCAA: Brian Fallon			✓ Approved

Case #: 25-080