



11815 NE 99th Street, Suite 1294
Vancouver, WA 98662
Voice: 360-574-3058
Fax: 360-576-0925
Web: <https://www.swcleanair.gov>
Email: Tina@swcleanair.gov

Notice of Intent to Remove Asbestos

Case #: 25-159

Amendment: 0

Date Received: 2/26/2025

Date Paid: 2/26/2025

SWCAA Fee: \$153.00

Receipt #: 171734840

This notification MUST be present at all times at the asbestos project sit

Quantity to be removed: 80 Square Feet 0 Linear Feet

Workshift days: F

Project starting date: 3/7/2025 Project Completion date: 3/7/2025

Workshift hours: 8AM - 6PM

Site Name: Kendall Residence

Site address: 3717 NW 138th St.

Location of Asbestos: Laundry Room

City/State/Zip: Vancouver WA 98685

☐ Demolition of Structure (Notification of Demolition required)

County: CLARK COUNTY

☐ Asbestos present?

☐ Asbestos presumed?

☒ Asbestos survey conducted?

No survey reason:

AHERA Inspector: Jorge Camacho

Certification #: 192797

Material to be Removed:

☐ Fireproofing

☐ Popcorn Ceiling

☐ CAB

☐ Sheet Vinyl

☐ Boiler Insulation

☐ Duct Tape

☐ Duct Paper

☐ Mag Pipe Insulation

☐ Air Cell

☐ CA Pipe

☐ VAT

☒ Other Drywall

Control Methods:

☒ N.P Enclosure

☐ Glove Bag

☐ Mini Enclosure

☐ Wrap and Cut

☒ Water

☒ HEPA Vac

☐ Other

Asbestos Contractor: Rose City Contracting, Inc

Phone: 503-376-8646

Mailing Address: 29791 SW Kinsman Rd, Wilsonville, OR, 97070

Email: DEChaff@rosecitycontracting.com

Certification ##: ABCN00001219

Supervisor: Mauricio Lopez

Phone: 503-572-8486

Property Owner: KENDALL BEGONA MARIE & TAYLOR JOHN CHARLES

Phone: 360-904-0595

Mailing Address: 3717 NW 138th St., Vancouver WA 98685

Asbestos Disposal Site: Hillsboro Landfill: 3205 SE Minter Bridge Rd, Hillsboro, OR, 97123-

**I DO HEREBY CERTIFY THAT THE INFORMATION CONTAINED IN THIS NOTIFICATION IS,
TO THE BEST OF MY KNOWLEDGE, ACCURATE AND COMPLETE.**

Submitter Name: David Chaff

Representing: Rose City Contracting

Submitter Title:

Date Submitted: 2/26/2025

Reviewed by SWCAA: Danielle Kreps

Danielle Kreps

☒ Approved